This is a digital copy of a book that was preserved for generations on library shelves before it was carefully scanned by Google as part of a project to make the world's books discoverable online.

It has survived long enough for the copyright to expire and the book to enter the public domain. A public domain book is one that was never subject to copyright or whose legal copyright term has expired. Whether a book is in the public domain may vary country to country. Public domain books are our gateways to the past, representing a wealth of history, culture and knowledge that's often difficult to discover.

Marks, notations and other marginalia present in the original volume will appear in this file - a reminder of this book's long journey from the publisher to a library and finally to you.

Usage guidelines

Google is proud to partner with libraries to digitize public domain materials and make them widely accessible. Public domain books belong to the public and we are merely their custodians. Nevertheless, this work is expensive, so in order to keep providing this resource, we have taken steps to prevent abuse by commercial parties, including placing technical restrictions on automated querying.

We also ask that you:

+ *Make non-commercial use of the files* We designed Google Book Search for use by individuals, and we request that you use these files for personal, non-commercial purposes.

+ *Refrain from automated querying* Do not send automated queries of any sort to Google's system: If you are conducting research on machine translation, optical character recognition or other areas where access to a large amount of text is helpful, please contact us. We encourage the use of public domain materials for these purposes and may be able to help.

+ *Maintain attribution* The Google "watermark" you see on each file is essential for informing people about this project and helping them find additional materials through Google Book Search. Please do not remove it.

+ *Keep it legal* Whatever your use, remember that you are responsible for ensuring that what you are doing is legal. Do not assume that just because we believe a book is in the public domain for users in the United States, that the work is also in the public domain for users in other countries. Whether a book is still in copyright varies from country to country, and we can't offer guidance on whether any specific use of any specific book is allowed. Please do not assume that a book's appearance in Google Book Search means it can be used in any manner anywhere in the world. Copyright infringement liability can be quite severe.

About Google Book Search

Google's mission is to organize the world's information and to make it universally accessible and useful. Google Book Search helps readers discover the world's books while helping authors and publishers reach new audiences. You can search through the full text of this book on the web at `http://books.google.com/`

THE

MINERAL SURVEYOR & VALUER'S COMPLETE GUIDE;

COMPRISING A

TREATISE ON IMPROVED MINING SURVEYING,

WITH

NEW TRAVERSE TABLES;

AND DESCRIPTIONS OF IMPROVED INSTRUMENTS; ALSO AN EXPOSITION OF THE CORRECT PRINCIPLES OF LAYING OUT AND VALUING HOME AND FOREIGN IRON AND COAL MINERAL PROPERTIES:

BY

WILLIAM LINTERN,
MINING AND CIVIL ENGINEER.

With Four Plates of Diagrams, Plans, &c.

LONDON
CROSBY LOCKWOOD AND CO.
7, STATIONERS' HALL COURT, LUDGATE HILL.
1877

153. g. 98.

PREFACE.

THE TRAVERSE TABLES herewith submitted to the public were computed some years ago by the author, to supply a need he had often felt in his professional duties, when engaged in laying out works for the connection of different and distant operations in collieries and mines: viz. a Set of Tables by the use of which the results of some extensive surveys may be computed, and acted upon, with greater accuracy and confidence than can be sometimes attained by the ordinary methods of plotting.

It occurred to the author that if a survey were made with great care and accuracy, the results should be capable of computation with absolute certainty; and that thus much cost in mining operations would occasionally be saved, by the drivages meeting properly, as intended: for where the cost of driving is large, in hard ground for instance, frequently costing £3, or £4, or more per yard, an error even of 5 yards may thus become an expensive matter; and frequently also there will be no inconsiderable expense in endeavouring to "straighten" a crooked driving, which has resulted from incorrect "points" having been given.

It is not claimed for these Tables that they will supersede good surveying; on the contrary, if the sur-

veying has been incorrectly done the Tables will not, and cannot, correct the error; but where the work of surveying has been done correctly, the employment of these Tables will eliminate the result much more unerringly than plotting; and thus they have often been proved by the author to be very useful and valuable.

Their application to surveys of mineral workings or openings which "pitch" highly must also be a matter of great utility, and they will supply a very ready medium, by which to ascertain the horizontal measure of the different pitches of the lines taken, which often vary very much in the same mine or colliery.

The use of the Magnetic needle is herein strongly defended, as being more generally applicable, as a rule, to mining surveying than any other system that can be suggested. But the author takes the liberty of submitting that the *magnetic meridian* is not a satisfactory "base" of working: and a description will be found herein of an improved circumferentor, by the use of which the True Meridian may be made the regular working "base," instead of the Magnetic Meridian; and by which the error occasioned by the constantly varying declination of the latter may be effectually guarded against.

A description is also given herewith of an improved protractor, by which the angles may be taken off directly from the instrument itself, instead of from points made in the paper either by the "folding arms" or pencil employed with the plainer kinds: this the author thinks must facilitate the making of a good and correct plan, and save the paper from those numerous punctures which are made in using the existing kinds of protractors.

A general description of the operations of careful mining surveying will also be found in the chapters preceding the Tables; and some of the peculiarities, both of home and foreign mining, are there pointed out for the benefit of those who may have to engage therein, and prepare plans, etc. of the same.

A chapter is also given on the Valuation of mining properties, and some examples of the varying class of property connected with mining, which may be also occasionally useful.

The work of surveying etc. enters largely into mining, and the cost of mining is sometimes affected in no slight degree by the manner in which the work of the surveyor is accomplished: and he should therefore omit no opportunity of performing his task in a manner to yield the best possible results. If the accompanying matter and Tables will in any manner facilitate the attainment of these desiderata the author will be pleased, and his anticipations realized.

Possibly some errors may hereafter be discovered in the work, but as every care has been taken to ensure accuracy, it is hoped they will not be found to be numerous.

If any justification is considered necessary for having written this treatise with the Tables for publication, it is submitted in these few words:—the author does not doubt but that others have felt the want that he himself felt, before he set about the computation of these Tables; and that there are probably many who would like to avail themselves of such assistance as they may afford, at a less cost than that of having to construct them for themselves. Of the text it may be said that it seems to be but a natural accompaniment of the Tables.

CONTENTS.

CHAPTER I.

PAGE

PAPER FOR MAPS 1

CHAPTER II.

DIVIDING AND LINING THE PAPER 3

CHAPTER III.

THE MERIDIONAL LINES 5

CHAPTER IV.

THE CHAIN, CHAINING, ETC. 7

CHAPTER V.

THE FIELD-BOOK.—ENTRIES, POINTS, ETC. 10

CHAPTER VI.

TRAVERSING 17

CHAPTER VII.

PAGE

THE TRAVERSE TABLES: THEIR CONSTRUCTION AND APPLICATION 21

CHAPTER VIII.

IMPROVED DIAL AND PROTRACTOR 38

CHAPTER IX.

PLOTTING THE SURVEY 44

CHAPTER X.

THE BUSINESS AND APPLICATION OF SURVEYING . . . 52

CHAPTER XI.

ON TRIANGULATION, ETC. 59

CHAPTER XII.

ON THE VALUATION OF MINING PROPERTIES 69

CHAPTER XIII.

TRAVERSE TABLES 89

CHAPTER I.

PAPER FOR MAPS.

When a Survey of a property is about to be made for the purpose of obtaining a correct plan, it is important to secure a sheet of good paper mounted on cloth, of about the necessary size, and to keep it in a dry and moderately cool place for some few days before anything is done towards laying down any part of the survey; if this were not attended to, but the paper ordered from the maker and the plotting proceeded with immediately on its arrival, it would soon be discovered that lines which were laid down with care at the first according to scale, shew a different length on the scale being applied to them some little time after, supposing the paper to have remained in a dry room; and it would be a hopeless task to endeavour to get lines laid down subsequently, to "come in" correctly with those laid down at the first. Paper arriving fresh from the mill is sure to be more or less damp, and after it has been exposed a little time to a dry atmosphere the damp evaporates, and, as a natural consequence, the paper shrinks; and until ample time has been allowed for this evaporation, in a medium dry and warm room, the paper should not be used, but should be occasionally unrolled and turned. It will also sometimes occur that paper which has been at hand a considerable time, has been kept in some very dry cupboard, or place in which it may have shrunk below its ordinary dimensions: in this case, if lines were to be laid down to scale immediately on

bringing it out, and the paper then left exposed to ordinary atmospheric influences, it would be found to have expanded, and on applying the scale to the lines previously laid down, it would be found that they now represented a greater length than was originally intended.

Some persons may think that these are unnecessary precautions, and that no appreciable error or difference arises from such causes, but such is far from being the case; when a plan is being made to, say, 2 chains to an inch, and the lines laid down are some of them from 20 to 30 chains each, it would then be no unusual thing to find a difference of 20 links and upwards in the longest lines, and this represents an error, multiplied over two or three such lines, sufficient in some cases to give rise to disagreeable consequences, and to law suits occasionally for infringements of boundaries, the costs of which are sometimes heavy.

This is only one of the many little points of detail which go to make up the difference between a good plan and a bad one,—between an accurate plan and an inaccurate; for with a material so absorbent of moisture as paper is, it is most natural to expect that in laying down long lines to scale, without giving any attention to the normal, or abnormal state of the paper, differences and errors are sure to arise and to accumulate.

Where the plan to be made is a permanent working plan the best paper should be procured, for inferior papers wear badly, and are easily chafed off with the action of indiarubber in the operation of cleansing them from the dust and pencil marks, which are the inevitable accompaniments of a mining plan; but an inordinate use of indiarubber only goes to destroy the face of the paper, and causes it to become the more easily soiled.

The best hot-pressed paper is considered the most durable, and best to work upon; and it should be well mounted either on white or brown cloth, and bound at the edges.

CHAPTER II.

DIVIDING AND LINING THE PAPER.

HAVING given the paper sufficient time to season properly, the next thing that should be done with it is to carefully lay down two series of lines, dividing the paper into squares of, say, 10 chains each way, or 10 acres area each; one set of these lines should represent a meridian (which of the meridians it should be we will hereafter discuss), and the other set should traverse the first at right angles. This operation should be performed with scrupulous care, and to do it properly and accurately a large beam compass is necessary, and a long thin true straight-edge; if one of steel is at hand so much the better,—there are few things more useful and valuable to the surveyor.

If a hand compass (or ordinary dividers) is used to mark off on the two base lines (which a person of experience would at once recognise as the first step) traversing each other, it should be so set that it will accurately divide such a sufficient number of tens, taken together, as shall ensure the accuracy of each division; since it is, in a matter of this kind, unwise to trust to the setting of the compass to one single measure on the scale:—for instance, if a divided beam compass is used the hand compass should be passed over such a number of the multiples of the division determined on for the side of the squares on the paper, as shall ensure its dividing accurately over the length and breadth of the paper.

The lines should then be finely and truly drawn through the points so marked with faint red ink, or some other colour that will be sufficiently distinguishable from the other lines to be drawn upon the plan.

It will be necessary to determine, before the lines are laid down, what direction on the paper the meridional lines must take so as to ensure the plan of the property being got fairly

into the body of the paper, or else the conformation of the outline of the boundary to the edges of the paper will never have a pleasing effect on the eye; this may usually be ascertained from some old plan, or by taking the bearing of some distant object with the theodolite from one of the angles of the boundary, or a combination of two or three such lines across the middle of the property. The correct laying down of these sets of lines is a matter of great importance, as instances are frequently met with where plans of properties of 300 or 400 acres area, or more are made, and the magnetic meridian is represented by a short line in one corner of the paper of about 14 or 16 inches in length; and to plot a series of lines at different points on the paper from this one meridional line is a matter of no little difficulty, and such an operation involves almost certain errors to a greater or less extent; for whether a rolling parallel ruler, or angle and straight edge are used (the latter being decidedly the most accurate) in the operation, errors under such circumstances cannot be wholly avoided; but with these rectangular and parallel lines the protractor can be laid down on the part of the map most convenient for easy plotting, and greater accuracy can be thus ensured. These lines are also useful in another way, for if proper attention has been paid to the preliminary work of the seasoning of the paper; and next, to the marking of the distances, these lines afford a ready gauge at all times, by applying the scale to them, to ascertain whether the Map has been left about in a damp place, and is unduly expanded with moisture; or whether from having been in a very dry and warm place, it has contracted below its normal dimensions.

We have noticed the fact that when a Map has lain open on the table in a warm sunlight for some time the contraction has been sufficiently marked to be distinctly appreciable in a line of 5 inches long; and thus it becomes wise to have regard to influences likely to affect, in a marked manner, the expansion or contraction of the paper.

By having the plan so divided into squares of 10 acres each they also assist the eye in forming a rough estimate of

the quantity of ground exhausted of any particular vein—supposing the ground to have been worked regular and uniform; they also assist the computation, when a more accurate estimate is to be made.

CHAPTER III.

THE MERIDIONAL LINES.

In respect of the "Meridional" lines it has hitherto been generally, or, so far as we know, universally the practice to represent the *magnetic* meridian as the working base line of the plan, from which, at all subsequent times the workings or additions to the plan have been marked off; and this practice has continued in consequence perhaps of, first, a want of due consideration of the actual difference the magnetic variation really makes from year to year in lines of even moderate length; and, secondly, from an absence of a readily and simply adjustable instrument with which to take the angles with the differences corrected.

The western declination of the magnetic meridian is now decreasing at the rate of about 1° in 8 years, or about $7\frac{1}{2}$ minutes per annum.

If we may suppose the case of a plan made, say, 8 years ago, with a particular instrument to take the angles, and that in the meantime no addition has been made to some particular part of it; but that now, from a resumption of mining operations or some other cause, an addition is to be made to it from surveys now taken; and if we further suppose a portion of the new workings to be a continuation of a straight engine plane, and that the part to be added measures, say, 850 links; and, further, if the length be laid upon the plan according to a magnetic angle taken *now* with the instrument, we shall find that instead of the present angle corresponding with the last taken 8 years ago, and so showing a continuous straight

line, there will be a lateral deviation from a straight line to the extent of 14·83 links to the *left*, looking in the direction in which the extension has been made. But if it is an addition to be made after one year instead of eight years, during which time, at the ordinary rate of decrease, the deviation will have been 7½ minutes; and if the addition to the plan be, say, 630 links, the lateral deviation will amount to 1·36 links for this length; and when we consider that a mining plan is frequently being added to for 16 years or 20 years, and often more, the importance of taking the magnetic variation into consideration cannot well be disputed; for in 20 years the lateral extreme deviation in a line of 20 chains in length, would amount to no less than 87·2 links; and in the simpler case of a 12 *month's* work being added at one survey at the end of the year, and where the aggregate of the lines in one direction has been 9 chains, the accumulating error would amount to 1·96 links, or about 16 inches.

These things fairly considered it will readily be seen what an unsatisfactory base of operations the line of magnetic meridian really is, if treated as an *invariable* line, while it is, as a matter of fact, *constantly variable* and changing.

The plan of taking the angles with the magnetic needle is so general, and answers the purpose of a good mining plan so well, that it is not intended to say anything here in disparagement of its utility and general applicability; indeed we do not conceive that there is, at the present time at least, any other system known, that can be brought into successful competition with it. It is quite right and proper to be able at times to dispense with the use of the needle, when a surveyor is compelled by force of circumstances to fix the instrument in some locality likely to disarrange the polarity of the needle, and to interfere with its proper action, and in such cases it becomes absolutely necessary to dispense with the use of the needle; but we conceive it to be in such cases only that it is found advantageous to dispense with its use, for we hold that with a thoroughly good instrument used and handled with care—the needle being set each time

to zero, and the angle being read on the verniers—the use of the needle affords the most correct results that can be attained in mining surveys, and thus the errors which are *instrumental* can be reduced to a minimum.

But as no instruments hitherto in common use have any adjustable zero to alter with the alteration of the magnetic meridian, either once or twice a year, as may be deemed necessary, it has been usual to set the needle to the common zero of the dial-plate, and to work from this line as though it was *invariable*.

Bearing in mind the foregoing facts, we advance the opinion that the meridional lines to be laid down on the plans should represent the *true* meridian, and not the *magnetic* meridian; and the second series of lines will of course cross these at right angles, and represent the East and West lines upon the plan.

The way in which we propose to provide for the adjustment of the instrument to the True Meridian, and the adoption of that meridian as the working base line instead of the magnetic meridian, will be found described in Chapter VIII. of the present treatise.

CHAPTER IV.

CHAIN, CHAINING, ETC.

THE proper handling of the chain is scarcely of less importance, in mining as in every other surveying, than that of the instrument; and it should not for a moment be supposed that the surveyor can delegate the affairs of the chain altogether to his chainmen.

It is of first importance to have the chain correct in length, and the stretching corrected regularly as found necessary. A correct datum for proving the chain should be at hand, and should frequently be resorted to, to ensure the detection of any extension that may have occurred. It is

not sufficient that this should be done at stated periods, it should rather be done whilst bearing in mind the work the chain has been used in; for it will often occur that the chain will have been strained and stretched more with one or two days' operations in some bad place or ground, than in ordinarily good positions in as many months' use; and hence the chain should be tested whenever there is reason for suspecting it necessary, in fact, it should be done often, so that the surveyor may be assured of its accuracy at all times.

This having been done, it should be constantly kept in mind that no amount of care exercised in the taking of the angles with the instrument will compensate for a want of care in taking the lengths of the lines; for a correct angle and incorrect line, or *vice versa*, cannot possibly go to make up a correct plan; hence, however good an assistant the surveyor may have to take the chain-lengths, he should never wholly lose sight of the work himself, but should always give such an amount of attention to it as would ensure a constant diligence in his assistant, to take off the true lengths of the lines; for, especially in underground work, if the chain is very dirty, the difficulty of recognizing the divisions is greatly increased; and, in the like proportion, the vigilance necessary to obtain the correct lengths. As arrows can seldom or never be used underground, the assistant that draws the chain forward has to supply the substitute, in the manner of marking the chain-ends; and as this man will generally be found to be a man picked up in the colliery or mine for the occasion, and with no particular idea of chaining, or any appreciation of the necessity for nicety in marking the lengths, the greater is the danger that it will be thought by him sufficient if he marks somewhere within three inches of the proper place. We have generally found it necessary to give this leading man a short lesson before commencing operations, with the view to ensure his attention and care: and we have found the most accurate way to mark the ends of the chain to be, to cause the leading man, after he has drawn the chain

forward the whole length, and has been put properly into *line*, to turn around to face the man at the other or "following" end of the chain; and having strained the chain properly into line, to bring the *toe* of his right foot to the handle of the chain,—the handle being held edgewise, and the foot being placed wholly on the ground; if this be carefully done there can be no error so far. Note is then taken of any headings, stalls, faults, threads, soft or inferior coals, commencement of solid rib, or of gob, or of any other thing on the way requiring to be booked down, and the man at the "following" end then walks forward and places the toe of his right foot to the toe of his companion, who then again proceeds forward another length, and the hindmost handle of the chain being brought and held to the toe of the foot the chain is again properly strained, set in line, and again brought to the right toe of the leading man, and so on to the end of the line. Where this is regularly and carefully done, there need be no error of practical moment occurring in the operation of chaining.

Where arrows are and can be used, the number we have found to be best is *eleven;* by using eleven there is always one in the ground, ten being given up to the leading man when the eleventh has been put into the ground, and it thus becomes the first in the next ten. This we think to be better than walking forward when the tenth has been put into the ground, and then draw it out, so that it may be given up with the nine others, and the place of the tenth marked with the foot, as in this way there is the position of the tenth always without its permanent mark: and so great is the convenience of using eleven arrows instead of ten, that we conceive the practice would at once commend itself to any surveyor who should determine to adopt it in preference of using ten only.

It is occasionally found very convenient and advantageous, when chaining over land on which long coarse grass, rushes, or other tall plants are growing, to have a strip of coloured cloth or a small white flag fastened into the handle eye of the arrows, so that they may be the more readily distinguishable amongst the tall *herbage;* and the practice in such cases affords

a means of frequently expediting the work, in avoiding the loss of time which would sometimes be taken up in searching for the arrows, and enables the eye to catch them readily.

CHAPTER V.

FIELD-BOOK.—ENTRIES, POINTS, ETC.

THE method of keeping the surveying book is a matter deserving of more attention than is often given to it, and a looseness or otherwise in this part of the operations indicates, more or less, the kind of attention bestowed on the business generally.

There is a divided practice in the matter of ruling the Field-book, some using two lines within which to write the chain-lengths, &c., and another and less general method is to have one line only,—this line being an ideal representation of the line chained, and the different lengths being written on it. We must give a decided preference to the latter method, as we have found it more generally convenient to have one line only than two; and in this method the sides of the book are left more clear and open for drawing such lines as may be necessary to illustrate the figures entered down; and the sketching can be more clearly done than when two lines are used.

In underground surveys, having the book lined ready, and being assured of the correct length of the chain, and having an instrument of good quality, the surveyor having selected the first position to set the dial, will carefully level the same and set the needle to zero after it has become steady; and before taking the angles the needle should be disturbed by a slight tap on one of the legs of the stand, or, which is quite as well, by lifting the needle off the pivot with the "rest-piece," and lowering it again, so that it may be seen if it will again return to zero, and if it does the reading off the angle may be proceeded with; if it does not return correctly to zero it should be again slightly disturbed, and if it still varies the first setting

was not correct, or something attracts it, and the zero should be moved a little so as to meet that point at which it will permanently set. The limb will now be worked around so that the light may be correctly seen through the sights, and this being done the angle will be read off and entered in the book, with the number of the line set under it: if the limb has two verniers so much the better (in fact any instrument fit for correct surveying is not without two), and these, divided either to 1′ or 3′, the former being much the best, will enable the angle and its opposite reading to be both taken; and we hold to, and strongly recommend to others, the practice of entering the readings of both verniers in the book, and after they are entered add 180° to the less (mentally), or subtract 180° from the greater reading, and if the sum or difference, as the case may be, makes the other reading as entered in the book, the angles may be considered as correctly entered. Some may think this to be quite unnecessary, but we hold it to be not so, as without it there is no check upon the correct reading of the angle; and there is no person practising this method but will at times find that an error has been made in entering either one or the other of the readings; and without the system of check there would be no certainty, and perhaps no probability, of the error being discovered in time to correct it; but when the two readings are entered, and their difference then computed, there is a strong safeguard against error in this respect.

The two angles of the first two lines having been taken, and the chaining proceeded with, notes are made of anything in the way of headings, faults, or other things occurring in the route, so that the book may be a correct representation of all that will be necessary to be shewn upon the plan: the instrument is then moved forward to beyond the light of the second line, and the operator having gone so far as the back light can be clearly seen, the instrument is again set up, and the operation of setting repeated as before described, and the lines again taken, and so on in succession.

It should be a maxim in working that nothing should be left to memory that can be entered down in the book, for when that is practised the memory will occasionally be overloaded,

and confusion of things will ensue, and error will be the consequence: therefore all things required to be put upon the plan should be distinctly entered in the book, in such order that were it to be put aside for seven years, and then taken up for the purpose of making a Plan of the work described therein, there would be no difficulty in following the particulars entered, and of making a correct plotting of the same.

An abrupt turn to one side or the other will require a mark to indicate the direction in which to continue the plotting or else it may be as natural under certain conditions to think it should be continued in one direction as the other: for the purpose of indicating the change in direction we recommend the making of a mark thus <———, under the figures (for instance <—$\frac{90}{}$—) giving the number of the line *commencing at the turn.* The horizontal line is simply that line which is drawn between the figures expressing the *total length* of the preceding, and the *number* of the succeeding line; and the mark either < or > indicates,—the former a turn to the *right* and the latter a turn to the *left*, it being in the latter case placed on *the right* of the horizontal line, and in the former case on *the left.* This mark must not be confounded with the *arrow* or else it will mislead: thus, the mark <———, here recommended, indicating a turn to the right, and ———> indicating a turn to the left, may, if made into arrows thus <———, or ———>, be made to indicate the opposite; but no difficulty on this head will arise when the distinction in the marks is remembered;—the idea being that the point joining the two short lines of the mark <, or >, represents the *position of the instrument* in reference to the two adjoining lines, and the short lines meeting in that point shew the *relative directions* of the lines so meeting, of which they are the representatives.

Note must also be taken of the "rise" or "pitch" of the measures in which the chaining is being done, so as to allow for the same, and to eliminate the true horizontal measure.

An example is given on Plate 4 of a book made upon these principles, with some descriptive entries, and a plotting of the same for the guidance of students.

It will sometimes occur that a survey is required to be made so as to give "points" to headings being driven towards each other, from distant parts of the workings, and it may be of great importance that they should meet well in line, not only to save the cost of driving about (perhaps in hard ground) to get "loose," but to ensure the working being subsequently usable for a heading, engine plane, or some other important work; or it may be to find the relative position which a proposed pit, either for air or otherwise, occupies, or where it will come down when sunk from some overlying measures or veins; or it may be to ascertain the proper position and direction for a drivage into a pit in some measures through which the pit has passed, for drainage or for ventilation: in these and similar cases it will be advisable to make an entire survey around, from one face of the work to the other, or so far as it is practicable to go; and in such surveys it will seldom be necessary to make notes of anything particular on the way, except for the purposes of a check at a few points. These lines will require to be plotted with great care, so as to be able to determine the "point" that will have to be given to the drivages, so that they may meet well. It is in such cases and similar to these, that the method of working out the line of survey by the Traverse Tables is so important, and of such utility; for if the survey has been correctly made, and the lines worked out by the Tables, the *terminal* positions can be determined with much greater accuracy by this combined operation than by plotting. We would not indeed recommend that the plotting should not be done; but where the survey was both worked out by the Tables and plotted, and some little difference resulted in the two methods (which may certainly be looked for), we would unhesitatingly give the preference for accuracy to the result obtained by the Tables. If the difference should be very considerable there may be some error either in the plotting, or in the taking out the figures of the Tables, or in not placing them in their proper columns, and a search should be made to discover it, so that the greater confidence may be given to the result *obtained*. But we have had a difference between

the plotted and the computed plan (or the terminal points of such plan) of considerable length, of upwards of 30 links; and having failed to discover any error in either the operation of plotting, or working by the Tables, we have decided in favour of the result obtained by using the Tables, and have found the center of the sinking (the matter in hand in that case) to come down within two feet of the mark made for it, although the *route* of the survey lay through very crooked and uneven ground, and through a pit from one measure to the other. This is not given as an unusually good result, for better could be added, but only as a proof that had the plotted survey been acted upon—although it was laid down with the greatest care—instead of the result obtained by the Tables, the error in this case would have been considerable; but as a rule the difference would be less, except in long and difficult surveys when it would perhaps be even more. And it is only what would justly be expected in such cases, if we consider the method of computation to be more correct than plotting could possibly be; for there are no thick compass points, no little accumulating errors in the setting the lines from point to point, the thickness of pencil lines etc., but the rectangular co-ordinates of each line are joined by absolute mathematical points.

If the opposite drivages are to be a heading or drift in hard ground, instead of following a vein of coal or other mineral, it will then be necessary to "level" the headings around from one point of driving to the other, so that the difference of level may be also known, and the "pitch" the new drivages are to be set to, worked out. The miners should then be supplied with teebobs, inclined to the proper angle at the foot, with which they should set the plates or rails of their roads; and as this is only an approximation to the true pitch, the surveyor should take his Spirit-level and try the accuracy of the floors occasionally, as well as examine the "points" by the dial, to ensure against error in either pitch or points.

Great caution should be exercised in making use of timber for holding the points; it will often happen that in con-

sequence of one side of the heading being a little "tighter" than the other, at the place where timber has been selected to hold the point marks, the squeeze of the ground will cause a slight (and sometimes a considerable) lateral movement in one or both of the colar pieces so selected; and possibly they may have motion imparted to them in opposite directions, as is frequently seen; and if such should occur to two colars used for carrying the "point," or even to one of them, the consequence may be serious if not detected in time to rectify the error. Therefore the solid ground should, if possible, carry the points, even if it should be necessary to stand timber for the sole purpose of preventing the roof scaling off, or for supporting the ground from falling while the drivages are in operation, or until the "points" can be moved to more secure ground.

In moving "points" forward great care should be practised, so as to ensure the continuance of the work in the desired alignment. If it is a drivage going to meet another coming from the other side, or a single drivage going to some particular position in some workings ahead of the new heading, the instrument should be used to move the "points" forward when it becomes necessary: and the dial being placed under the first of the former point-marks, others can be set up near the face of the workings for further guidance; or, which is better, a mark should be put at about every 30 yards along the heading or drift, and from these the men should try their work. It is much more sure to drive with points 30 yards apart, if they are carefully put in position, than with those at 10 feet apart; and in the former arrangement it is only necessary to shift one mark at one time, and they are always within easy reach of the workmen.

When two marks are to be shifted forward to the "face" without the application of the dial, the accuracy of the new marks should be carefully tested; and to do this proceed by setting up the new points near the face by plumbing marks to the roof, from lights put in position by looking through the original mark lines: then, first, have a light placed in the "face," by using the *original* mark lines; next, by using the

new lines see if they and that in the "face" still coincide (which they should do); next, take *one* of the old lines and *one* of the new, and again see if they coincide with that in the "face"; if they do this last operation will be a proof that the new lines will correctly continue the alignment given with the old lines, and the marks will have been correctly shifted.

As to the kind of appliance that is best for holding the *light*, we may remark that we have found it the better way to have no appliance at all for suspending the light, but simply to weight the cord, soundly fastened to the roof, sufficiently to draw it out straight and free from kinks. If then the light be held right in front of it, if marks 30 yards distant be used; or by the side and at two inches from it, if the marks are about 10 feet apart,—for at the latter distance the string itself will be plainly visible with the candle two inches off,—the arrangement will admit of very easy and correct working.

If however safety lamps are exclusively used, and open lights are inadmissible, it is then better to suspend the safety lamps from the lines by their handles, and use them in that way to move the mark forward; but in all cases more care will be necessary in driving with safety lamps, than with free lights, as it is more difficult in that case both to "try" and also to keep the point.

The benefit which should and would result to the employer or owner, as well as the satisfaction felt by the surveyor at seeing the work "meet" correctly, will more than compensate for what some may be disposed to look upon, but which we do not, as excessive nicety in the matter of "points" and "pitches"; and not only in these matters, but in every other matter connected with correct surveying, it is the attention to the small details, and the care with which they are executed, that make the difference between a good plan and a comparatively worthless one: for even mining surveying (the roughest-done work of any perhaps in the way of surveying) consists in something more than in being able to tell, within an half degree, the division on the dial to which the needle points, though this is often looked upon as all that is necessary to

enable a person to survey a colliery; but the "snakelike" contortions and windings often to be met with in collieries and mines, as the consequence of not being able to get opposite drivings *loose* in the way they were intended to meet, testify to the rough off-hand methods too often practised, as well as to the expensiveness of such a class of surveying.

CHAPTER VI.

TRAVERSING.

HAVING passed in review the field-book, setting of the dial, reading off the angles, taking the notes, and other things necessary to supply the data and particulars requisite to the making of a correct plan of what will be met with in the mine or colliery, we will next proceed to show what entries are requisite and essential, in order that the Traverse Tables may be used in the computation of a survey.

In the first place we will refer to the accompanying diagram, No. 1, and would recommend a very careful perusal of the whole of the lines comprising the same, and especially of the red lines, and the directions in which the "arrows" point. Let it be supposed that the positions *A* and *B* represent two pits or other objects, and that the black lines represent the lines chained in passing, in the operation of surveying, from *A* to *B*; note also the direction of the meridional line with its transverse axis, and the point that represents the north. The black lines 1, 2, 3 will be observed to go nearly eastward; lines 4, 5, and 6 nearly northward; 7, and 8, have a northern departure from the west, and 9 goes to the south of west; 10, 11, and 12 then go nearly to the north; 13 goes nearly east, and 14 nearly southward. Now it is possible to define the relative positions of *A* and *B* without plotting the lines at all, by the use of the Tables, and the simple operations of addition and subtraction.

In conjunction with each black line representing the chained lengths, will be noticed two red lines, each containing an arrow, and forming with the black line a right-angled triangle. All the *red* lines parallel with the *meridian* line of the diagram are represented by figures in the columns of the Tables headed Lat. (a contraction of "Latitude") and Per. (a contraction of "Perpendicular"), and their values will be taken out from that column; and all red lines parallel with the *transverse* axis of the meridian, being parallel with the equatorial line, are represented by figures in the columns headed Dep. (a contraction of "Departure"), and Base, and their values will be obtained from those columns. Next observe that some of the arrows in the red lines parallel with the meridian point to the North, and some to the South, accordingly as the line to which they stand points northward or southward of the east and west line that may be conceived to pass through the zero or starting-point of the line in question, of the diagram: some of the arrows parallel with the equatorial line point eastward, and some point westward, accordingly as the line to which they stand points eastward, or westward of the corresponding ideal meridian line. Now if we first take the equivalents of the red lines parallel with the meridian, and separate those pointing to the north from those pointing to the south, or, which is the same thing, place them in separate columns, and take the total of each column, we shall see in which direction the working has progressed by observing which column has the higher total; and if the less be subtracted from the greater, the difference or resultant will be the actual distance between the two terminal points, *taken in a line parallel with the meridian.* Also it will be similarly observed that of the lines parallel with the equator —some pointing to the east, and some to the west—if we separate the equivalents of these into distinct columns as we did the other, and take the totals of each, and their difference, we shall find what is the resultant sum of the progress in a line parallel with the equator, and whether it has been to the east or to the west.

These two differences will now give the data with which

to define the relative positions of *A* and *B*. Making a mark to represent *A*, and from this mark drawing a straight line of sufficient length to enable us to prick off on it by some scale (any may be chosen) the first found difference, make a fine and distinct mark; then with a set square or other accurate instrument, draw carefully at right angles from this point a line, either to the right or to the left as required by the *second resultant*, and on this line mark off with the same scale as before the second difference; this distance from the first line will be the position of *B*. The former of these lines will be a north and south line, and the latter will be an east and west line; thus the required relative positions are determined, and the lines with which it is done form the perpendicular and base of a right-angled triangle.

The thorough digestion of the remarks and explanations here given, in reference to the diagram and its several lines, will make the apprehension of what follows comparatively easy; and it is essential that it should be thoroughly understood, before proceeding to attempt to work out any series of lines by the Tables.

Traversing Entries in Field Book. The next thing will be to shew how the angle is to be entered in the book, so that there may be no difficulty in easily determining the proper reading.

The plate forming the *bottom* of a dial is usually divided and figured in each quadrant distinct, from 1° to 90°; two quadrants commencing to reckon from the *N.* point in the box, and two commencing at the *S.* point; two finishing at the *W.* point, and two finishing at *E.* This division of the circle into quadrants shews at once, in their respective initial and terminal points of division, *the points from which*, and the *direction in which* each quadrant must be read, in order to the workings being computed by the Traverse Tables.

The first quadrant therefore, embracing the horizon from north to east, will be read *from* north *to* east; the second quadrant, embracing the horizon from east to south, will be read *from* south *to* east; the third quadrant, embracing the horizon from south to west, will be read from south to west;

and the fourth quadrant, *from* north *to* west. This must be the *invariable practice* for traverse working, and where the readings cannot be obtained from the verniers, as they cannot be in more than the first quadrant, the angles must be carefully computed: and for this purpose the readings should be severally entered in the surveying-book as before described, as though it was intended to make use of them in plotting a survey as ordinarily: then, the traversing angle in the first quadrant will be the ordinary reading of the instrument; the traversing angle in the second quadrant will be the difference between the ordinary reading and 180°, thus 100° 42′ in the ordinary reading will be 79° 18′ for traversing, and 146° 27′ in the ordinary reading will be 33° 33′ for working by the Tables; the traversing angle in the third quadrant will be the ordinary reading of the instrument, *less* 180°, thus 212° 30′ in the ordinary reading becomes 32° 30′ for traversing, and 254° 12′ will become 74° 12′ for working by the Tables; and the traversing angle in the fourth quadrant will be the difference between the ordinary reading and 360°, thus 293° 45′ will become 66° 15′ for traversing, and 357° 21′ will become 2° 39′ for working with the Tables; and so on of all other angles, in whichever quadrant they may be situate. There is here no great difficulty in comprehending this part of the matter clearly, close diligence and thought being only necessary.

The next thing to be mastered is the *description* to be given in the traversing to the *co-ordinates* of each line: by the description to be given them is to be understood the entering with each angle distinctively whether its co-ordinates are a northing and a westing, or a southing and a westing; a southing and an easting, or a northing and an easting. Thus the angle in the first quadrant (remembering the order given in the instructions above in reference to the angles) will have a northing and an easting for its co-ordinates; the angle in the second quadrant will have a southing and an easting for its co-ordinates; the angle in the third quadrant will have a southing and a westing for its co-ordinates; and the angle in the fourth quadrant will have a northing and a

westing for its co-ordinates; and these rules hold good for every angle in the respective quadrants in succession. Of course if the line should be *exactly* due north, or due south, it will neither have an eastern nor a western co-ordinate, but it will be a northing or a southing entire, without reference to the Tables at all; and in the case of a due east or a due west line, there would be no northing or southing co-ordinate, but the line would be an entire easting or westing as the case may be, without any reference to the Tables, the lengths of the lines to which they refer being entered in full.

These explanations and instructions embrace the whole that need be said to enable any person of ordinary intelligence, and who will try, to understand the theory and practice of working with the Traverse Tables; but the instructions here given should be thoroughly mastered, so that the Tables may be correctly worked, and errors avoided in the operation.

The entry of the particulars for traversing should be made upon the same sheet or leaf of the field-book with the ordinary entries, and will simply consist of the number of the line, the traversing angle, the initials of its descriptive co-ordinates, and the total length; and these can be placed in the side of the book, as in the example we give herewith of a field-book, with both entries placed in juxtaposition.

CHAPTER VII.

THE TRAVERSE TABLES: THEIR CONSTRUCTION, AND APPLICATION.

THESE Tables were constructed by the author some years ago for use in his professional duties, and they are based on the same principles as the Traverse Tables for seamen's practice as given in "Hutton's Mathematical Tables." It will however

be found, on reference to that book, that the Tables there given are worked out for degrees and quarter-points only, and to radii from 1 to 10; and as a Table not less minute than this is inapplicable to surveying we determine to proceed to the construction of tables to every 3 minutes of the quadrant, and to 10 different radii of hundreds, commencing with 100, and ending with 1000. It will be readily seen that thus constructed the Tables are applicable to any base of measurement, either English or Foreign, that may be most convenient; it may be a link, foot, yard, furlong, mile, metre, kilometre, or league, in fact any measure desirable or necessary; but it is of course requisite that the measure of the *angle* should be taken according to the *English* system of 90 degrees in the quadrant, and 60 minutes in the degree.

The figures in the Table, and the positions of the decimal points, are applicable to the lengths represented at the top and bottom of each pair of columns, and marked "Dist."; these are each hundreds. But the computations are perfectly correct and applicable if the "Dist." is multiplied by 10, or considered as thousands; and when this is done it is only requisite to shift the decimal point as in the Tables, or conceive it to be shifted, one figure to the *right*, when the result will be obtained true to one place of decimals. If the "Dist." be *divided* by 10, the figures as in the Tables will in like manner be divided by 10 by shifting the decimal point one figure, or conceiving it to be shifted, to the *left;* and if divided by 100 (say by counting 600 as 6) the figures as in the Tables will be in like manner divided by 100 by shifting the decimal point *two places* to the left: hence the Tables are applicable to the computation of the co-ordinates of a line of any measurement or length whatever, from 1 link to 100,000 links, or from 1 metre to 100,000 metres, or kilometres, or miles. The Tables being computed to every 3 minutes of the quadrant will in general be sufficiently minute for all classes of surveying; but in the case of very long lines, if it should be found or thought necessary to obtain the co-ordinates to a single minute, it can be done to very near the truth (even when the decimal point is moved one figure to the right) by

ation, taking either ½ or ⅓ of the difference as may be
d, between those two lines of figures within which the
) be computed lies (in doing this remember that the
ıates of each line *increase* in opposite directions, one
ng down the column, and the other up the column).

degrees from 1° to 45° will be found along the top,
) minutes down the left side of the tables; and from
)0° the degrees will be found along the bottom, and
ıutes up the right side of the Tables, as in Trigonome-
ables generally. If the angle therefore is less than 45°
be found at the top and left side of the Tables, and
per order for tabulating the co-ordinates of the angle
ewise be found at the top; if the angle is greater
5° it will be found at the bottom and right side,
e order for tabulating the co-ordinates at the bottom
).

s, if we wanted to find the co-ordinates of a line 600
ı length, and whose ∠ is 33° 42′, we have on the page
and on the line for 42′ the quantities sought; viz—
499·17., and Base = 332·90; also, if we want the
ıates of ∠ 56° 18′ (or the comp. of 33° 42′), and a line
same length as before, we have Per. = 332·90, and
499·17;—being the same figures as by the first
)n, *but with their relative positions reversed.*

he lines had been each of them 666 links, instead of
should have had in the first case, viz. ∠ 33° 42′ and
)6, as follows.

	Per.		Base
600 =	499·17	and	332·90
60 =	49·92	„	33·29
6 =	4·99	„	3·33
Per. =	554·08	Base =	369·52

ı the second case we should have ∠ 56° 18′ and
)6.

	Per.		Base
Ex. 2.	600 = 332·90	and	499·17
	60 = 33·29	„	49·92
	6 = 3·33	„	4·99
	Totals = 369·52	and	554·08

Again, suppose the case of ∠ 20° 39′, and Dist. 745; then look along the Tables until you find 20° and down the left side to 39′, and on that line take out the figures for 700, 40, and 5 respectively, thus:—

Ex. 3. Angle 20° 39′, and Dist. 745.

Per.		Base
700 = 655·02	and	246·86
40 = 37·43	„	14·11
5 = 4·68	„	1·76
Totals = 697.13	and	262·73

Take one more example. ∠ 76° 45′, Dist. 1789 links. In this case the degrees will be found along the bottom, and the minutes on the right side thus:

	Per.		Base
Ex. 4.	1000 = 229·20	and	973·38
	700 = 160·44	„	681·36
	80 = 18·34	„	77·87
	9 = 2·06	„	8·76
	Totals = 410·04	and	1741·37

The foregoing examples will clearly indicate the methods of taking out the co-ordinates for traverse surveying.

It will be perhaps advisable to draw attention to the last example, and to point out that in consequence of the Tables having computations for 1000, no shifting of the decimal point is called for in this case in reference to that number; but for every 1000 above the first there will be a shifting of the decimal point;—for instance, the co-ordinates for 2000 will be found in the columns for 200, with the decimal point placed

one figure to the right, and so on for the others as each case may require.

It should also be the invariable practice to place the figures coming under the designation of "Per." *first* in position, as they are above, and those coming under the designation of "Base" *last*. It should also be remembered to consider the co-ordinate designated "Per.", as that ordinate *parallel with the meridian;* and the co-ordinate designated "Base" as that *parallel with the equator:* by following these instructions there will be no confusion of the co-ordinates, nor any misconception of the true positions for the termini to be described from the results obtained.

We will now adduce proof of the foregoing examples by working out corresponding results by the ordinary rules applicable to the computation of right-angled trigonometry, as in the following.

RULE: *Add the logarithm of the given side to the sine of the angle opposite to the side required, and from the sum subtract the sine of the angle opposite to the given side: the remainder will be the logarithm of the side required.*

Bear in mind that the sine of the *angle of the traverse* is the co-ordinate "Base"; and the sine of its complement, the co-ordinate "Per." (or "Perpendicular").

The sine of 90° being equal radius—the angles treated being all right angles—we have

One proof of Ex. 1. (giving the "Base")

As Rad.....	=	10·0000000
: log. of 666	=	2·8234742
:: sine ∠ 33° 42'.....	=	9·7441712
: log. of 369·25	=	2·5676454

Also one proof of Ex. 2. (giving the "Base").

As Rad.....	=	10·0000000
: log. of 666	=	2·8234742
:: sine ∠ 56° 18'.....	=	9·9200994
: log. of 554·08.....	=	2·7435736

Proofs of Ex. 3.

As Rad..... = 10·0000000

: log. of 745 ..... = 2·8721563
:: sine ∠ 20° 39′ ..... = 9·5473542

: log. of 262·73 ..... = 2·4195105

and As Rad..... = 10·0000000

: log. of 745 ..... = 2·8721563
:: sine ∠ 69° 21′..... = 9·9711608

: log. of 697·13..... = 2·8433171

Proofs of Ex. 4.

As Rad. ..... = 10·0000000

: log. of 1789..... = 3·2526103
:: sine ∠ 76° 45′ ..... = 9·9882821

: log. of 1741·37. ..... = 3·2408924

and As Rad..... = 10·0000000

: log. of 1789..... = 3·2526103
:: sine ∠ 13° 15′..... = 9·3602154

: log of 410·04 ..... = 2·6128257

These proofs shew the construction of the Tables, as well as supplying conclusive evidence of their accuracy, and of the accuracy of the method employed in the operation of extracting the co-ordinates for the different angles, and length of the lines.

There is nothing new in the proposal to apply these principles to surveying. They were, so long ago as A. D. 1635, applied by a Mr Norwood to lines and angles taken with the circumferentor over the public road from York to London, and the difference of latitude of those two cities determined by him, very nearly, from the traverses; and proposals have been made to apply the principles to the planning of large estates; but, so far as the author knows, there have been no

other Tables so far issued, so well calculated as these are to render the application of these principles to surveying both easy and general,—computed as these are to a degree of minuteness sufficient for all practical purposes of correct surveying, and their application duly explained in the accompanying letter-press.

There is no reason why these principles should not be applied extensively to mining surveying; for in large and overlying mining operations there are cases continually arising where it is required to sink from one vein of mineral to another, for ventilation or some other purpose; also to drive from one part of the workings in some mine or colliery across the measures to another; and also when driving in both directions it is highly important that the points given to the drivages should be correct; and sometimes it is required to drift at a more or less steep pitch from one measure to another; and in such operations, when the work proceeds in both directions at the same time, the question of the cost, as well as the matter of convenience, depends greatly upon good surveying and correct points; and it is such cases as these that really put the skill of the surveyor to the test, and they are also those cases in which the application of the principle of traversing is found to yield the most satisfactory results. But cases arise also where it is desirable to ascertain if the boundary has been reached, at some point very remote from the Pit, or level mouth; and sometimes it will require a series of lines of somewhere between 60 and 100 (perhaps more) to reach the supposed position of the boundary: then the survey should be taken with great care, and the application of Traversing should be adopted in such a case, as being much more conducive to accuracy than plotting can be from the same data.

It will likewise occur frequently that in a long underground survey there will occasionally be a prominent turn in the general bearing of the workings; perhaps the general bearing so far has been nearly westward, and at a particular part the direction alters, and the bearings are somewhere to northward. It is very desirable that the point where the change of direction occurs should be very carefully marked down from the traverses

first, and also the terminal point; the plotting should then be proceeded with, and the plan so made should be brought as near as possible at those corresponding parts to the points marked from the traversing computation; and where a little difference is found to have accrued, preference should be given to the traverse points (always bearing in mind that care should be observed to ensure accuracy in taking out the co-ordinates).

If it is suggested that this double operation is unnecessary, and that plotting is sufficient without traversing, we can confidently assert that bad and loose surveying is exceedingly expensive; and that there is no system so conducive to true economy as accuracy, and this cannot be attained without due measures being adopted to ensure it.

The chief utility of the Traverse Tables in surface surveying is the facilities they afford for reducing the principal lines across an estate to one pair of rectangular co-ordinates, and thus increase accuracy.

Although it is still the practice with many surveyors, in making a survey of a property, to make a circuit of the boundary by taking a great number of short lines according to the bends, or outline of the limits of the property,—making these short lines the ground-work of the survey from which to construct the map,—and especially where there is but little more than the boundary to lay down; but it is about the worst system that can be followed, and often results in the production of a Plan not worth the labour expended upon it.

The salient angles in the boundary of the property to be surveyed should first be selected by the surveyor, in sufficient number to enable him to devise such a system of main base-lines and triangles across the property as shall enable him to fix all those points, as well as a sufficient number of objects within the boundary on his Plan, with absolute certainty, by Traversing, or Trigonometry, or both combined, as circumstances require: the intervening lengths of the boundary should then be surveyed by a combination of straight lines and triangles, according to the conformation of the boundary line; and in all cases running the straight lines *where practicable* from one salient point to another, and filling in where neces-

sary with diverging lines to meet bends, and which divergence may be measured as a check with a sextant. In this way, if errors have been committed at any point they are almost sure of being detected, and their locality known; and if they arise between some two of the points selected, they cannot affect the accuracy of the next section; and all the internal objects will be easily taken, in connection with the different internal stations of the triangulation.

As scarcely any two estates are of similar outline, or are affected by similar conformations, so the same system of lines will seldom be found perfectly applicable to any two surveys, and hence the judgment and experience of the surveyor must in each case be relied on to guide him, in the selection of that system which will involve the least amount of labour combined with the greatest amount of attainable accuracy.

Where the estate is tolerably level the selection of these lines, and their measurement, do not present much difficulty; but where the country is mountainous, and steep escarpments have to be crossed and measured it is different, and careful means have to be then adopted to ensure accuracy. Where it appears to be indispensably necessary to have a line, either as a principal, or as a check-line, up a steep and rugged rise, it will generally be found more accurate and preferable to obtain the true length of the line by the application of trigonometry; and which will probably be best accomplished by selecting two stations in the plain, one of which shall be the end of the line to be measured (or even an intermediate point in it, if it is thought to answer the purpose better than the end), and between which and the other station in the plain the ground must be favourable for *correct chaining*,—each visible from the other, and from another station on the top of the hill, which may be the other end of, or an intermediate position in, the line to be measured, and to be selected on favourable ground, from which correct chaining may be continued. The three angles of this triangle should be correctly taken with an accurate instrument, and their sum should equal 180°; and the line in the plain to be measured should be gone over carefully twice, so that the first result may be checked. Then,

by applying the rule of trigonometry previously given in this chapter, the correct horizontal length of the ascending line can be easily determined; and this length should be substituted for the length found by chaining, as being more correct, (even though the horizontal measure may have been procured as near as practicable), and therefore entitled to the preference. If this is a line forming one of a series, for the purpose of determining the positions of the *salient points of the boundary only*, the *chaining* of it will be unnecessary.

When it is thus determined to have a few triangles over the property, to determine the position of the salient points, from which to form the ground-work of the Plan, one base-line should be measured on the most favourable ground obtainable near one side of the property; this should be the "base of computation," on which all the calculations of the Triangulation shall be made; and on the opposite side of the

TRAVERSING COMPUTATION. No. 1.

No. of the line.	Quadrant where found.	Traverse Angle.	Designation of Co-ordinates.		Length in Links.	Perpendicular.		Base.		Remarks.
						Northing.	Southing.	Easting.	Westing.	
		o ′								
1	1st	78·26	N.	E.	208	41·71	...	203·78	...	
2	2nd	76·42	S.	E.	354	...	81·43	344·50	...	
3	1st	3·46	N.	E.	246	245·47	...	16·15	...	
4	4th	5·34	N.	W.	208	207·02	...	...	20·17	
5	do.	11·48	N.	W.	349	341·62	...	...	71·37	
6	do.	15·00	N.	W.	540	521·60	...	...	139·76	
7	do.	81· 9	N.	W.	240	36·92	...	...	237·14	
8	3rd	85·30	S.	W.	320	...	25·10	...	319·01	
9	4th	61·33	N.	W.	528	251·53	...	...	464·22	
10	1st	3·00	N.	E.	340	339·53	...	17·79	...	
					Totals are =	1985·40	106·53	582·22	1251·67	
					Subtract	106·53			582·22	
					Nett results	1878·87 = Northing.			669·45 = Westing.	

property the best line possible for correct measurement should be chained, as a check upon the trigonometrical computation. This will be called the "base of verification," and if the angles

---

The following will exhibit the operation of taking out the above co-ordinates in succession.

(1) $78^{\circ}\cdot26'$ and 208

Dist.	Per.	Base.
200 =	40·11 —	195·94
8 =	1·60 —	7·84
208 =	41·71 —	203·78

(2) $76^{\circ}\cdot42'$ and 354

Dist.	Per.	Base.
300 =	69·01 —	291·95
50 =	11·50 —	48·66
4 =	·92 —	3·89
354 =	81·43 —	344·50

(3) $3^{\circ}\cdot46'$ and 246

Dist.	Per.	Base.
200 =	199·57 —	13·13
40 =	39·91 —	2·63
6 =	5·99 —	·39
246 =	245·47 —	16·15

(4) $5^{\circ}\cdot34'$ and 208

Dist.	Per.	Base.
200 =	199·06 —	19·40
8 =	7·96 —	·77
208 =	207·02 —	20·17

(5) $11^{\circ}\cdot48'$ and 349

Dist.	Per.	Base.
300 =	293·66 —	61·35
40 =	39·15 —	8·18
9 =	8·81 —	1·84
349 =	341·62 —	71·37

(6) 15° and 540

Dist.	Per.	Base.
500 =	482·96 —	129·41
40 =	38·64 —	10·35
540 =	521·60 —	139·76

(7) $81^{\circ}\cdot9'$ and 240

Dist.	Per.	Base.
200 =	30·77 —	197·62
40 =	6·15 —	39·52
240 =	36·92 —	237·14

(8) $85^{\circ}\cdot30'$ and 320

Dist.	Per.	Base.
300 =	23·53 —	299·07
20 =	1·57 —	19·94
320 =	25·10 —	319·01

(9) $61^{\circ}\cdot33'$ and 528

Dist.	Per.	Base.
500 =	238·19 —	439·61
20 =	9·53 —	17·58
8 =	3·81 —	7·03
528 =	251·53 —	464·22

(10) 3° and 340

Dist.	Per.	Base.
300 =	299·59 —	15·70
40 =	39·94 —	2·09
340 =	339·53 —	17·79

have been taken and the sides calculated, each correctly, this last measured line should not differ from the computed length more than from 2 to 3 links. This satisfactory result being obtained (and with instruments of the best construction for taking the angles a nearer agreement is quite possible, and generally considered essential), the points so determined will form an excellent ground-work for the making of a thoroughly reliable map of the property; and the labour expended in obtaining it will be well repaid, by the confidence with which the Plan may subsequently be referred to at all times; and especially should any question as to infringement of boundary, in the working of the minerals of the property, or a committal of trespass from an adjoining property, at any time arise.

As shewing the application of Traversing to a series of underground lines of a survey, we will now proceed to take the first 10 lines of the preceding example of a Field-book, in which *A* (see the plotted Plan of same), the starting point, may be supposed to represent a Pit or Level Mouth; and *B* to be the "face," and end of the 10th line. *C* may also be considered as the face of a branch part of the same workings; and if we suppose it to be required to drive from *C* to *B*, by having a point given at *C*, we shall be able by the Tables to discover the true distance from *C* to *B*, and the point to be given at *C* to drive into the "face" at *B*.

The nett results of the foregoing traversing operations is a Northing of 1878·87 links, and a Westing of 669·45 links; and if the process as before directed be performed, the terminal point of the (10) line can be exactly described from the above co-ordinates as here found and expressed.

We may now proceed from the two lines here found of the triangle, with the included right angle, to determine the other line and the two other angles, and thus complete the triangle; the rule for which is the following: Having two sides and the included angle,

RULE:—*When the angle included is a right angle, add the radius to the logarithm of the less side, and from the sum subtract the logarithm of the greater side, or add its arith.*

mplement: the remainder, or sum, will be the tangent of he angle opposed to the less side.

Then, taking the foregoing sides of the triangle, we have

ad. + Log. of 669·45 = 12·8257181

rith. Comp. Log. 1878·87 = 6·7261032

9·5518213 = Tan. 19° 37′ nearly.

Therefore 90° − 19° 37′ = 70° 23′ is = the third angle of the riangle.

By applying Euclid I, Prop. 47, we shall ascertain the ngth of the third side: using logarithms, we have

Log. 1878·87 = 3·2738968

2

6·5477936 = 35301533 = 1878·87².

Log. 669·45 = 2·8257181

2

5·6514362 = 448163·2 = 669·45².

nd the sum of the squares are thus = 3978316·5

Then, Log. 3978316·5 = 6·5996993

÷ by 2 = 3·2998496 = 1994·57 = √3978316·5.

= the side *opposite the right angle.*

We may prove this result by finding the number 1994·57 om the Tables: taking 19° 36′ as being the next nearest umber in the minute column we have,

	Per.	Base.	Numbers.
∠ 19° 36′, and the coordinates	1878·87	669·45	
in column of thousands take	942·06	335·45	= 1000
remainder	936·81	334·00	
„ „ of 900 take	847·85	301·91	= 900
remainder	88·96	32·09	
„ „ of 900 take	84·78	30·19	= 90
remainder	4·18	1·90	
„ „ of 400 take	3·76	1·34	= 4
„ „ of 500 approximately	·42	·56	= ·5
			1994·5

2—5

These numbers from the Tables being successively subtracted from the preceding remainder, exhaust the co-ordinates; and adding up the successive corresponding numbers, we have 1994·5.

This last operation proves the correctness of the mode of working, and also the finding the side by Euclid I, Prop. 47 for although the last figure ·5 is not found strictly correct, yet as the tangent of the angle lay between 19° 36′ and 19° 37 (nearer the latter than the former), and the co-ordinates here taken out stand on the line for 19° 36′, the agreement is so near that for all practical purposes the difference may be disregarded.

It may sometimes be necessary to find the third side, and the two other angles, so that the position of the third line may be correctly laid out on the surface from one of the termini (which may perhaps be the center of a Pit or the Mouth of a Level) to the other, and the angle set out for finding the position of the other terminal point corresponding with that underground, either by chaining along the line laid out to the angle given, or by the application of trigonometry, or a combination of both: this method is much more correct than that of attempting to repeat on the surface all the lines taken underground from one terminal point to the other. Where an important work, such as the sinking of a Pit or some other matter is to be proceeded with, upon the data arrived at by such methods as these, care and precision, with the aid of good instruments, should yield perfectly satisfactory results.

It will here be proper to remark that the lesser angle, whose tangent is found by the foregoing trigonometrical computation, is not *necessarily* the "traversing" angle, by which to ascertain the length of the third side, as in this example; for "the greater side of a triangle is subtended by the greater angle," *but the traversing angle is always subtended by the co-ordinate* "Base": this will be either the greater or lesser co-ordinate according to the nature of the lines operated on. In this example the co-ordinate "Base" is the lesser, and therefore subtended by the lesser angle; and as this trigonometrical operation is to find the lesser angle, it in *this case*

finds the *traversing angle.* But supposing 1878·87 to have been the co-ordinate "Base", and 669·45 to have been the co-ordinate "Per.", then in that case 70° 23′ would have been

TRAVERSING COMPUTATION. No. 2.

No. of the line.	Quadrant where found.	Traverse Angle.	Designation of Co-ordinates.		Length in Links.	Latitude.		Departure.		Remarks.
						Northing.	Southing.	Easting.	Westing.	
		° ′								
1	1st	78·26	N.	E.	208	41·71	...	203·78	...	
2	2nd	76·42	S.	E.	78	...	17·94	75·90	...	
11	4th	56·42	N.	W.	246	135·05	...	...	205·60	
12	4th	64·50	N.	W.	332	141·18	...	...	300·48	
13	3rd	84·36	S.	W.	450	...	42·34	...	448·00	
14	3rd	74·30	S.	W.	320	...	85·51	...	308·36	
15	Par^{l}.	90·00	...	W.	248	...	...	...	248·00	
16	4th	10·51	N.	W.	675	662·93	...	...	127·06	
17	1st	7·54	N.	E.	436	431·85	...	59·92	...	
18	1st	12·15	N.	E.	94	91·86	...	19·95	...	
19	1st	7·44	N.	E.	216	214·04	...	29·07	...	
						1718·62	145·79	388·62	1637·50	
Subtract^{n}. lesser from greater						145·79			388·62	
Nett result						1572·83	and		1248·88	

COMPUTATION. No. 3.

20	1st	62·9½	N.	E.	655·3	306·04	...	579·43	...	
Add Northing						1878·87	Subt. Easting		669·45	

the angle *on whose line in the Tables* should have been sought the length of the third line; and not on that of its complement 19° 37′: this should be carefully remembered in these operations. *It is perfectly* true that the "line" in the Tables of an

angle and its complement is always *the same*, but the *designation* of the two co-ordinates are in one case the *reverse* of those of the other.

The preceding traversing operation No. 1, embraces the lines of the plotted example of a survey at page 30 from *A* to *B*, lines 1 to 10; the No. 2 embraces the left-hand series of those lines from *A* to *C*, and diverges from the right-hand series at (2) 78.

On comparing the No. 2 with No. 1 computation, it will be seen that the No. 1 line is identical in both, being in fact the same line; No. 2 line of No. 2 computation is so much of the No. 2 line in the No. 1 computation as lies between the commencement of the line and the point of branching off, viz. at 78. From this point they are quite a distinct series of lines. No. 15 line goes due west, and it has therefore no pair of co-ordinates, but the *whole length* of the line is placed *in the column "Westing."*

The nett results will be found to differ from the results of No. 1 operation in having a less Northing, and a greater Westing; and a little reflection will shew that the co-ordinates of the "point or angle" to be given at *C*, to guide a drivage to *B*, will be a Northing and an Easting; consequently it will be in the first quadrant.

No. 3 computation, line 20, supplies the data to make the results of No. 2 equal to those of No. 1, arriving in fact at the same point; and a comparison will shew that the Northing in No. 1 is 306·04 more than in No. 2, and that the Westing in No. 1 is less than in No. 2 by 579·43; and we must reduce the No. 2 Westing to that extent, by having an Easting co-ordinate; therefore a Northing and an Easting: from these data we must now decide the angle and the distance, according to the method before given: viz.

Rad. + Log. 306·04 = 12·4857782
Log. 579·43 = 2·7630010
9·7227772 = Tan. ∠ 27° 50¼.

Therefore the angle opposite the co-ordinate Base is

$90^{\circ} - 27^{\circ}\,50\frac{1}{2}' = 62^{\circ}\,9\frac{1}{2}'$; and taking this $\angle$ and the co-ordinates as follows.

		Per.	Base.	Numbers.
		306·04	579·43	
and finding		280·22	530·54	= 600
	rem.	25·82	48·89	
„ „		23·35	44·21	= 50
	rem.	2·47	4·68	
„ „		2·33	4·42	= 5
	rem.	·14	·26	
„ „		·14	·26	= ·3

we thus find the length of line No. 20 equal to 655·3 links.

We might have arrived at the same result if we had taken the whole of the lines around from *B* to *C*, and have combined them in one computation, omitting No. 1 line and the first 78 links of No. 2; that is, taking No. 2 line as 276 links instead of 354: in that case however either the right or left-hand series of lines would have *a different designation*, accordingly as the survey was taken from *B* to *C*, or from *C* to *B*; if the former, the *right-hand* series would have opposite designations, and if the latter, the *left-hand* series would have the opposite designations. This operation may easily be performed as an example for practice.

Having gone thus fully into the working of underground traverses, and there being really no difference in the mode of application of these principles to any lines either on the surface, or otherwise, there will now be no difficulty in applying them to any series or combination of lines whatsoever to which they are applicable. It is unnecessary therefore to pursue this part of the subject any further.

CHAPTER VIII.

AN IMPROVED DIAL AND PROTRACTOR.

For the adoption of the true meridian as the working base-line of the Survey and Plan, it is necessary to have an instrument suited to such method of working; for the practice of the process of computing it from the "declination", through all the varied angles of each successive survey, and thereby reducing the several angles to their relation to the true meridian, would be a matter of great labour, and its practical difficulty would, as a rule, prevent its adoption; and the practice of a more correct process thus requires an improved instrument for the direct taking of the angles of a survey, in relation to the true meridian as a base-line or zero.

It would be easy enough, in the matter of a simple surface survey only, to represent upon the plan the true meridian; but in the matter of mining surveys where the Plans are being constantly added to over a long series of years, and where the magnetic needle is the medium (and doubtless the best) of adjustment for the instrument, it seems to be essential, to the adoption of the true meridian as the working base-line, that the instrument itself should contain the appliances and means for the necessary correction; while, at the same time, admitting of the same simple method of reading the angles as in the ordinary make of instruments.

To provide for this we have designed an improved circumferentor, by the use of which the correction is made without in any way complicating the method or operation of working the instrument, or of reading and entering the angles of the survey. This improvement consists of an adjustable vernier, working in the divided ring of the dial-box to which the needle is set, and on which the reading verniers move; and it reads on the inside of the ring, and downwards to the bottom plate of the dial-box: and a small portion of the initial part of

the fourth quadrant is divided on the said plate to half-degrees for this operation; and on this the vernier, which reads to minutes, is adjusted; so that its reading, reckoning from the ordinary zero or 360°, expresses the correct declination of the magnetic meridian for the time being. This adjusting vernier carries a small angle piece which works flush with the inside and top of the ring, and for which a small portion of the ring is sunk, by cutting away; and the divisions so cut away from the top of the ring are recut on the sunk part, so that the instrument may be used by the old methods when desirable or necessary: the small angle piece carries a line, in prolongation of the zero line of the adjusting vernier, on its side and top, and to this line the needle is always set instead of to the ordinary zero of the instrument.

The needle being set to this adjusting zero, the ordinary zero of the instrument will be in the *true meridian*, and all the readings of the survey will express the several angles which the successive lines make with that meridian.

If then the meridional lines laid upon the plan be those of the *true meridian*, the protractor must be laid upon those lines; and the "readings" are to be then taken, or marked off, just in the same manner as though the magnetic meridian was being worked from—there being in this respect no difference in the process; and all computations are thus rendered unnecessary.

It will be necessary to adjust this "declination" or adjusting vernier, either quarterly, half-yearly, or yearly, according to the necessities of each surveyor; but in general it would be sufficient to make the adjustment half-yearly. And the plan should have the dates of the general surveys, and a record of the amount of the declination to which the instrument is successively set, entered in tabular order regularly, so that at any future time the later surveys may be made precisely to accord and compare with those made at former periods.

The adjustment is easily effected by the use of a small key, by which the vernier can be moved either way at pleasure; but it is not liable to get out of order, and will not move except when acted on by the accompanying key.

For the purpose of applying this principle to surveying it is necessary to have the means at hand to correct the instrument periodically to the true meridian. This may entail some little labour and expense at the first, but surely the desirability of having first-class Plans will far outweigh any such consideration. Only those who have been much engaged in mining operations, and have observed the great expense very often attendant on bad surveying and bad Plans, as well as the frequent loss of no inconsiderable quantity of valuable mineral, will for a moment question the desirability of adopting good and correct methods of surveying,—unless indeed such persons are blinded by prejudice against the introduction of improvements, in this, as well as in other matters connected with mining.

The expense of procuring the improved instrument, or of having the improvement applied to an existing instrument, is indeed inconsiderable. For the application of the principle continuously upon any property it is desirable—though not *absolutely* necessary—to have two distinct points of observation, either *corresponding with* the true meridian, or making a *known* angle with it. This having been procured it only remains to take the instrument periodically to one of these points, and observe with the adjusted telescope the pole or other object at the other point: if they are *in* the true meridian, set the zero and telescope of the instrument to the said pole, or, if they make a *known* angle with the true meridian, set the verniers of the instrument to the said required angle, and turn the entire instrument round towards the pole or object until the telescope accords with it, while the verniers read the permanent variation of those points from the true meridian. Then observe if the needle and the adjusting vernier agree with each other; if they do not, take the key of the adjusting vernier and move it until it accords with the needle exactly, and the readjustment is complete. Care must be observed in performing this last operation to guard against any attraction of the needle from any cause, or with the correction of one error another will be committed; proper diligence will however ensure against this.

Now it is not absolutely necessary that the true meridian should be laid out upon the property, in order to practise this improved method of surveying, for we may take *any* line near the true meridian (so that it is distinctly understood), and adjust from that line periodically, in the same way as before mentioned, and so ensure the advantages derivable from a correction for magnetic variation: it is doubtless however preferable to have the line laid out either *in* or *from* the true meridian, so as to apply the principle more completely.

We give subjoined two methods for finding the true meridian at any place whose latitude and longitude are known, or are determined.

1st. By equal altitudes of the sun, or a fixed star.

The theodolite being fixed in a position selected as one of the points in the desired line, measure the horizontal angle from the said line to the sun or fixed star (whichever is used), when it is not near the highest or lowest point of its apparent daily course, and take also the altitude, adjusting the intersection of the hairs of the telescope to it, in some marked and definite manner. Leave the limb clamped and let the instrument remain quite undisturbed until the sun or star is approaching the same altitude at the other side of its apparent circular course. Then, without moving the body of the instrument, unclamp the limb, and direct again the telescope towards the same object, and follow it with the aid of the tangent screw until the cross hairs correspond precisely as before with the same relative position upon the disc of the object, as in the first observation: this being done, read off the horizontal measure of the angle between the assumed line and the new direction of the observed object; the mean between the two horizontal angles will define the position of the true meridian, *if a star has been observed.*

If the *sun* has been observed a correction is required in consequence of the sun's change of declination. When that declination changes towards the north the approximate direction of the meridian as found by the foregoing method is too far to the right; if declination changes towards the south it is too far to the left.

The required correction is found by the following formula:—$\frac{\text{change of sun's declination}}{2} \times \text{sec. latitude} \times \text{cosec.} \frac{1}{2}$ angular motion of the sun between the observations.

Example. Given:—Date of observation (say 26 July); sun's declination changing towards the south at the rate of 13′ per day, or 32″·5 per hour; time between the observations, say 6 hours, change of declination for 6 hours 3′ 15″; angular motion of the sun between the observations, say 80°; latitude of place of observation, say 51° 34′ N.

Then the correction becomes

$$\text{Log.} \frac{3' 15''}{2} = 97''{\cdot}5 = 1{\cdot}9890046$$
$$\text{„ sec. } \angle 51°34' = 10{\cdot}2064865$$
$$\text{„ cosec } \angle 40° = 10{\cdot}1919325$$
$$\text{„ } 244'' = 2{\cdot}3874236$$

therefore the approximate direction as found by the observation is too far to the *left* by 244″, or 4′ 4″,

In the preceding process it must be observed that the mean of the two horizontal angles is their half-sum when they are at the same side of the station line, but their half-difference when they are at opposite sides of the said line.

2ndly. Where Greenwich mean time is given or obtainable, by the aid of the telegraph, procure the exact Greenwich time on some convenient day, and with the "equation of time" change that mean time into true apparent solar time: then take the longitude of the place of observation, and add for each degree of difference in west longitude 4 minutes of time, and for each minute of longitude 4 seconds of time; if the observation is in longitude east of Greenwich the same has to be subtracted instead of added.

Then these differences for longitude having been added to, or subtracted from the Greenwich apparent solar time, gives the apparent solar time at the place of observation, and at 12 of that time the sun is due south.

A chromatic object-glass for the telescope is necessary in making these observations.

The small round legs of the mining dial or circumferentor are not sufficiently strong for out-door work in windy weather, when the telescope is being used; for the action of a slight wind will often be sufficient to cause the needle to be unsteady. There seems to be no practicable remedy for this but to have a strong tripod-stand for use in out-door surveying; and while this entails the expense of two sets of legs for the instrument, the advantage gained is often much more than sufficient to compensate for the extra cost. The tripod-stand cannot be used with advantage underground, in many places, for it is too heavy and unsuitable; while it is by far the best stand for surface operations.

Improved Protractor.

We have also designed an Improved Protractor, in the using of which the successive lines of the survey are run off at once from the instrument to their positions upon the Plan, instead of making punctures in the paper, with pencil marks and numbers to distinguish one angle from the other; the pricking of the paper is also thus avoided.

The instrument is made by lengthening out the central bar that carries the verniers, to about 3 inches each way beyond the outer side of the divided circle, and at each end of this bar there is a transverse bar: and on the ends of these transverse bars and reaching from one to the other, are fixed two ebony or metal bars—one on each side—sufficiently distant apart for the inner edge to just work clear of the divided circle. The ends of the central bar each carry a small glass with a + cut, so that those two and the central + are in exact alignment, and form the zero of the instrument. Each side of the frame is exactly parallel with this zero line.

The outer side of the divided circle has a projecting shoulder cut on it, and is provided with a clamp, and adjusting tangent screw, as in the Theodolite.

In plotting a survey from this Protractor it is first laid

upon the meridional line in the most convenient position, and each line of the survey is then laid down in succession as taken from the instrument, either with the large set-square, or parallel ruler, and at once laid down in its proper position; and thus the work of first marking off and numbering the readings is rendered unnecessary.

With the large set-squares either one side or the other of this frame will be sure to be convenient for plotting from.

These instruments can be procured from Messrs Troughton and Simms the eminent Opticians, who have made them from the designs of the author.

CHAPTER IX.

PLOTTING THE SURVEY, ETC.

If the directions respecting the proper seasoning of the paper, laying down the meridional and transverse lines, &c., have been complied with, and the survey made and duly entered in the field-book, the plotting operation will now be proceeded with.

Unless the position of the boundary, and other objects on the surface, can be so far imagined that the site of the pit, or level, can be with confidence fixed for some particular point on the paper (this can frequently be done from some old plan, where such is in existence), the surface survey should be carefully laid down first; and the position of the pit or level having been marked, the underground workings can then be taken in succession.

Taking the underground survey, and the position of the starting point being known or fixed upon, the first thing will be to fix upon an intersection of base-lines from which conveniently to take, or mark off the compass-readings correctly on the paper with the aid of the Protractor.

To produce satisfactory results the surveyor should be possessed of instruments of the best kind, and should then

take care of them. Good instruments once possessed and taken care of will last a lifetime, and will always have the confidence of the owner; but even the best tools, if roughly and carelessly used, cannot be expected to ensure correct results; and badly made instruments can never be reasonably supposed to do so: and the surveyor may rest assured that should his plans prove to be incorrect, the faults will never be attributed to his tools, but to his own want of skill, for he will be expected, or supposed, to have correct tools to work with.

A good protractor is a very essential thing, and those with double folding arms with verniers divided to minutes (when of the best make) are, next to the improved instrument spoken of in the preceding chapter, the best; this instrument having been correctly fixed on the meridian line, the center coinciding with one of the intersections, the two readings of each line should be made to coincide with the verniers, with the aid of a magnifying glass, and both points marked on the paper with a small pencil circle around the punctures, and with the number of the line to which they refer, or run off at once to their position, as the case may be. This having been done with the whole of the lines (if with a folding arm protractor), or of as many of them as can conveniently be marked off from that part of the paper, the readings should then be taken backwards in succession as a check, to see if each pair has been correctly marked off: this being done the protractor will now be removed, and the laying down the lines proceeded with.

For running off the lines either from the improved instrument, or from their markings as before mentioned to the position they are to occupy on the Plan, the best instruments are a pair of large pear-tree angles or set-squares: these will be found to be far preferable to a parallel ruler, or even to one set-square and a straight-edge; for the large set-square has a much broader bearing on the paper than a straight-edge, and is much steadier and less liable to those small lateral movements which will frequently be found to occur with the straight-edge (unless it is a large steel edge, and then it is too

large to be handy for this operation), when sliding in close contact the one over the other, to the position for the lines.

It will be found conducive to accuracy to mark off no more compass readings in any one place on the paper than can easily be run off to their position with one (except in occasional instances) movement of the set-squares; for it will be better to fix the protractor in a new position, and mark off the readings nearly on the part of the paper the lines are to occupy, than to mark off all in one place, and be under the necessity of running them off across a considerable breadth of paper, to their several positions; and with the meridional and transverse lines before recommended, the protractor can be put at any intersection of those lines desirable.

The first line should now be marked in its position by placing the side of the set-square to the two angle-points marked 1 (and a check upon this operation will be afforded by running the eye along the side of the set-square, and observing if it cuts the intersection of the meridional and transverse lines), then placing the other set-square to that side of the former which will the most readily permit the proper side of it *to come upon the starting point* run the line off to its position: a faint pencil mark should now be drawn along the edge of the set-square through it with a hard pencil, so cut that it shall have a thin wedge-like edge, and a flat side to slide against the set-square; and having drawn a line sufficiently long to embrace the distance to be marked off, run the set-square back again to the points to see if it still remains parallel with them; this being proved, next take the compass or dividers with the adjusting leg and the diagonal divided scale, and set the legs to the length required; or if the line be too long to be marked off at once in this manner a portion of the length may be marked off with a scale, and the remainder, including the part less than 100, taken in the compass and added to the former part; a small puncture should be made to indicate the end of the line, and it should be distinguished by a small pencil circle and numbered; also remember to put the number at the *beginning* of the line, as shewn in, and to correspond with, the field-book; the next and

succeeding lines should then be operated on in the same way, until they are all marked off in their respective positions. In progressing forward it will frequently be found that the next line to be put on runs almost at right angles to that last plotted, and except the workings of the mine are thoroughly well known to the surveyor he will be at a loss to know whether it should be a turn to the right or left hand, if he has not remembered to indicate the turn in the field-book; and for this reason the practice should never be omitted, but by turning to the field-book the mark should at once indicate which way to draw the line, whether to the right or left hand; and so on of all the other turns that are capable of misleading without a distinct mark for guidance.

Having laid on all the lines, and being assured of the correct lengths, etc., the different objects and particulars entered to each line in succession should now be placed upon the plan, as indicated by the entries in the field-book.

When we come to a point where the survey has subsequently been continued in another direction, as for instance at 78 ② of the example of a mining survey before given, the length 78 should be marked with the compasses from the diagonal scale, and the "ribs" sketched with the pencil on the proper side, to indicate the position of the commencement of the subsequent work; but where stall roads, faults, commencement of gobs, ribs, or other things have to be indicated it will be sufficiently accurate to mark them off with a pencil, from a long scale laid upon the line in a correct position for so doing, or with a small set scale where necessary. The matter to which these lengths refer should be marked down to each line in succession (after all the lines themselves have been laid down), as the work of filling up proceeds, so that there may be no error from memory in trying to remember subsequently to what the marks refer.

In this way should all the workings of a colliery, or other mine—with the exception of stall-points—be marked down in succession; and as each page of the field-book is completed a mark should be made upon it distinctly, to shew that it is done with.

In reference to the points of stalls, it will be unnecessary to lay down these points in the same manner as those of the important headings, and other parts of the workings. The handiest way of laying down the points of stall roads is to take the small protractor which usually accompanies the other drawing instruments, and laying it properly on the meridional line most conveniently situate, and at one of the intersections, mark off the point with the pencil, and at once with the parallel ruler run off the line to its proper position, and lay down the stall to which it refers; and so on of the others in succession. This will be sufficiently accurate for these things, and they will be pricked off and laid down at once in the operation of laying down the details, instead of mixing them up with the points of the headings and other more important parts of the survey.

If the mine "pitches" too much to make the correction to reduce the measure to "horizontal" as the work of surveying proceeds, care should be observed to make the reduction before the plotting is proceeded with. Where the pitch is general, one taking of the angle of elevation or depression will mostly be sufficient; but if the pitch varies, it will be necessary to observe the angle of elevation or depression more often, and to enter each distinctly: if it is considerable it will be advisable to reduce the lengths of the whole lines, and of any intermediate particular object by the Traverse Tables, for those tables are as applicable to the reduction of hypo. to base, as to the working of traverses on the flat. But here it must be borne in mind, that the horizontal measure will *invariably* be represented by the figures as found in the column "latitude" or "perpendicular," and the other column will shew the vertical rise or fall in the length of the line: in this application of the tables they form a ready medium for correcting the different rises in mines that pitch much, and by an expeditious and correct operation to facilitate the elimination of the true horizontal measure. And where the pitch is considerable, 10° or upwards, the horizontal measure decreases rapidly, and renders it requisite to observe the more care in obtaining the angle of altitude.

While the correct laying down of mining surveys is not difficult to those who go about it with care and diligence, and with a genuine intention to ensure accuracy, it will seldom occur that carelessness or inattention, or a despising of those small niceties which are essential to ensure precision in working, will result in anything but annoying disappointment.

The whole of the workings having been put upon the plan, together with all the details of which note has been made in the field-book, the matter of "inking in" will be ready to be proceeded with. Where two or more veins of mineral are worked one over the other, and are placed upon the same plan, it will be necessary to distinguish one from the other in the colours assigned to the several separate workings, according as fancy or taste may decide, so that each may easily be recognized, with their several connections. Some use the brush in distinguishing the veins one from the other, using black to mark all the workings in, but painting the spaces of each between the lines with a distinguishing colour: of course, these details are very much matter of taste or opinion, and are not of such importance as those principles upon which *accuracy* depends; but we hold that, so far as possible, it is better to dispense with the brush, and use the colours only with the drawing pen; and we consider that a mining plan will generally look neater and better managed in this way than if the colours are put on with the brush, over all the exhausted space. With a surface plan which is finished at once the colouring, shading, etc. may be put on with the brush, and will if done well look well; but with mining plans which are constantly being *added to* it is different, for in this case if the shades as laid on with the brush are not precisely alike they do not look well; and if the colours selected are not simple colours the difficulty of exactly matching them is increased, therefore we think that as much as possible the brush should be dispensed with on a mining plan.

It is very easy in competent colouring hands to make inaccurate plans *look* well, and it is easy to deceive the inexperienced into saying much in praise of a plan so finished, and of the person who has finished it; but no amount of colour

will make an *accurate* plan: and while every surveyor should seek to finish his work neatly his chief care should be to be accurate, and this can only be attained by constant attention to, and practice of, those essential principles upon which accuracy depends.

The manner of laying down the surface lines, and the details of the surface survey, does not essentially differ from that already indicated for the underground survey. In general the surface lines will be much longer and less numerous than the underground lines, and their accuracy will admit of frequent proof. If the groundwork of a survey has been formed by a series of triangles and long base lines in the way indicated in Chapter XI., the laying down the details and the filling in the shorter lines will be comparatively easy; and by a proper disposition of those lines to easily embrace the fences etc., and distinct memoranda in the field-book shewing where they abut on the main base lines, their accuracy, and the accuracy of the plotting of the main lines, will be constantly and reciprocally checked.

The finished plan will of course bear the descriptive title of the property; the name by which it is distinguished; together with the parish and county in which it is situate, and the name of the owner; also on the different boundaries the names of the owners of the adjoining properties. The scale to which it is made will be indicated, and also the detailed area of the property where necessary, and the total area. It will also bear the names of any particular farms, houses, brooks, rivers, woods, faults, or other objects contained within the property.

If the paper has been divided into 10 acre squares as before indicated these will generally assist in the computation of the area: if the whole squares are taken separately, and the parts separately, and the latter added to the former, the aggregate will be the total area. It will however be well to take also another method of computation, that of computing the property as a whole, without reference to the squares; and by comparing one result with the other a check will be obtained upon each computation, and the result obtained will

be entitled to greater confidence. The area will of course be temporarily divided for computation into trapeziums, triangles, etc. principally, and the rules of practical geometry applied to compute the area of those and other figures necessarily entering into the division.

If the meridional lines upon the plan are those of the True Meridian there should be a columnar table on one margin of the plan, in which should be successively entered the date of the last general survey, and also the amount of "declination" to which the instrument was adjusted for the survey; this will then afford a systematic view of the correction continuously applied, for reducing the angular readings to the True Meridian.

It will be found very useful to have a sheet of good tracing paper or tracing cloth, divided into one acre squares (drawn to the same scale as the plan with which it is to be used), in black lines, and each of these squares bisected in both directions with ink of another colour in faint lines, which subdivisions will consequently be each equal $\frac{1}{4}$ acre. If it is then necessary to see approximately the area of ground exhausted of any particular vein of mineral, it will be only necessary to lay this sheet of divided paper on the exhausted space represented on the plan; and by counting the whole acres, and counting and averaging the $\frac{1}{4}$ acres (which can be done by a practised eye very nearly), and adding these together, the area will be obtained to very near the truth, without using pencil lines about or drawing figures upon the plan. And by doing this at the end of each year, and comparing the area of ground exhausted with the coal or other mineral obtained from it, it will be seen at once whether the vein is producing the quantity of mineral which under the concurrent circumstances it ought to do. The side of a square whose area is equal one acre measures 316·228 links.

As examples of the quantities we have proved different veins of coal to produce per acre, for each 1 foot of thickness of the veins, we beg to refer the reader to what is said on that subject in Chapter XII.

CHAPTER X.

THE BUSINESS AND APPLICATION OF SURVEYING.

THE work and business of a surveyor enters largely into mining operations, and particularly into coal mining, and it may very fairly be said that the extent to which good surveying is applied in mining, goes in some degree to indicate the advance made towards a perfect system of management; for although it can never take the place of, or supply the default of, discipline and good scientific knowledge, yet the application of scientific knowledge will proceed, in no small degree, through the channel of good surveying.

Given: A mineral property to be worked, and the direction in which the measures dip being known, it will be of the first importance to know the figure of the property under consideration, so that the position for the "winning" may be determined upon, in order that it may be so situate as to facilitate the economical and convenient raising and draining of the minerals, as well as their despatch to market; and thus a correct Map will be essentially necessary, so that the plan of working may be determined upon. It is still however often the practice to allow the colliery or other mine to form itself, as it were; there being no prearranged plan of development, but simply leaving the different principal headings to follow what appears to the workmen the most natural course. This plan however generally, or rather *invariably* leads, sooner or later, to a complication of workings ill adapted to ensure either the most perfect ventilation of the mines, or the convenient and economical carriage of the minerals to the bank.

If it is a winning by means of a pit, and it is in contemplation to raise a large daily quantity, the laying out of the pit bottom will be a matter that should be well considered; for as this part of the mine will have to pass the whole daily quantity of mineral raised, economy is sometimes considerably affected by the way in which it is laid out: and the most perfect ar-

rangement for passing the full wagons on to the carriages, as well as the empties off for entering the workings, will be found to be worth all the thought that can be bestowed upon it, so as to ensure convenience and despatch. Where the empties are conducted away by a separate road, which has just sufficient fall to keep them moving on to where they are taken off by the horses, or other hauling power, the road will require a fall of from an half-inch to an inch per yard, according to the state the trams are kept in for easy running.

Engine drawing planes on the levels, self-acting incline planes to the rise, and engine drifts to the dip, are now being more generally used than formerly, to cheapen the cost of haulage by reducing the number of horses, as well as at the same time to keep the air more pure and cool than it can be where so large a number of horses, as some collieries would otherwise require, are passing through all the workings continually; and the correct and well-considered laying out of these works and their "banks" will have a considerable effect upon the subsequent cost of working them; for if they are not (except in regular and intentional curves) practically straight, the wear and tear and consequent cost of the wire ropes are very much increased; so that it becomes a matter of great practical importance to get the engine and incline planes in perfect alignment, thereby to ensure that whenever the ropes are by the strain lifted off the rollers they shall again fall back into their correct position, to prevent chafing and cutting against the ground, and surfaces that are not rolling: and if the supervision of the opening of this work is given into the hands of the surveyor, he should take particular care that it is thoroughly done.

There is again the work of opening the headings so that they may be as near as is practicable parallel with each other, when the best point for them has been determined upon; for few things look worse on a mining plan, or prove more objectionable in the practical working of mines, than having all the headings going at random, some to the left hand and some to the right, some giving the stall roads 40 yards to go, and others giving 140 yards before they reach their end; but if they are

driven parallel the coal can be worked much better, and more systematically, and as a natural consequence cheaper and cleaner. And while we know that it rests with the management as to whether such a system is allowed to obtain, and that it cannot well exist where there is a systematic plan of having "points" put on all the headings (and the workmen made to keep them), yet there is very frequently much less care bestowed on this matter than there should be, even with those who will at once admit the necessity and desirability of the principle.

It is sometimes the practice to have points put upon all the stalls where "long-work" is not adopted, as well as upon the headings, and in some veins there is no expenditure of labour that returns a more ample interest than does this; for it is of the first importance to keep the pillars their proper thickness while the roads are going in, to prevent their being reduced, and often as a consequence destroyed, by being "robbed" and made too weak to sustain the top—occasioned by crooked driving; and not only do the pillars thus get crushed and rendered partly, and occasionally wholly worthless, but heavy falls are often thereby occasioned, and sudden outbursts of explosive gas rendered more frequent, which would have exuded more gradually, but for the fall, and the ordinary currents of air would have been able the more effectually to dilute it, and render it less dangerous than is possible when it comes off in large quantities suddenly. Where long-work is adopted, there is not so much necessity for points on the stalls, as there is a much better chance of keeping the roads nearly parallel, when they are open one to the other along the face.

In the making of quarterly or other periodical surveys, it is of importance to have a distinct knowledge as to the position at which to begin. Where it is possible to mark each survey, by placing a *D* or any other mark determined on upon the rib or roof, there is not much difficulty in the matter; but it is not often that the positions can thus be easily determined, and then the surveyor has to fall back upon his knowledge of the relative position of some heading or stall parting, or other

object, and trace out his last terminal position from that. Where there is not much changing of the workmen the name of the man who was working the last road in a panel of work taken, might be entered in the proper position in the book, and the chainage of this parting "cross" being taken it will generally be a good mark from which to define the position at which a former survey terminated, and from which to continue the work of surveying at a subsequent period: though this is, generally speaking, a very correct way of proceeding, yet at times there is a possibility of the surveyor being misled by having the wrong road pointed out as that for which enquiry is being made; and hence constant vigilance will be essentially necessary to ensure against error in this respect. Sometimes it is necessary to measure a level or other heading from some distinct turn, or other conspicuous object; and the system adopted, and regularity with which a surveyor is able to select these points and mark them in his book with clearness for subsequent reference, will greatly influence the time that he will be occupied in going around a large mine to take the new work opened; while an uncertainty in having positions to start from that are but ill defined in the field-book, will often lead to error by the operator taking a wrong point of departure, instead of spending the requisite time to ascertain the correct: hence nothing will contribute more to accuracy than a thoroughly clear and careful method of keeping the field-book, and of entering in a uniform manner the different matter which pertains to the survey made, and whatever may forward the work of continuing the survey at a *subsequent period.*

To facilitate the work of periodical surveys, we would strongly recommend the surveyor to adopt some particular *route* through the workings, and to keep up that route at all his surveys. Also, before going about the survey of a mine or colliery at which he has been before, to sit down and go over all the principal points of his last survey,—making notes in succession upon the different points from which he is about to continue the work of former surveys; these notes being entered in succession in a condensed form on the first page allotted for the new survey, will be all under his eye, and he will

see them all at a glance when proceeding to the operation of surveying, instead of having to search through the whole of the entries made on the last occasion, at each different point of the work. Much time is thus saved in the underground operations, and this system has the additional advantage of bringing before the mind's eye the whole of the workings, and may perhaps recall to mind several matters of importance which it is advisable to note closely, and which, but for it, would probably have been overlooked. It also induces a correct habit in the matter of making entries in the field-book, and of so placing the particulars that they shall be uniform for extracting the notes when required on the next occasion.

The matter of moving points and setting out the gradients of drivages has been treated of in another part of this work; therefore it is unnecessary to go further into that part of the subject in this place. The learner will have no difficulty in ascertaining the point to be given to a drivage, if the line to be followed be first laid down in position on the plan, and next with the parallel ruler or other instrument it be run off to an intersection of the meridional and transverse lines; after which, placing the protractor in its proper position, see what is the angle made by the line of the proposed drivage, and making a note of the same in the field-book, give that angle with the instrument, or dial, to the proper place underground.

In laying out the siding communication, and railways, to the tips or screens of an extensive colliery, or for Iron Works or other operations of large extent, there is need of great care and discernment, and few things will more effectually test the skill of the surveyor, than the designing and planning of these things—indeed it may be almost considered as an entirely distinct matter from the ability to make an ordinary survey and plan; for the latter is, more simply, the making a plan of things, as they already exist, while the former is the *designing* the means of communication for an extent of operations which demand convenience of arrangement with facilities for despatch, in all its details, and this will call for the exercise of sound engineering skill; and upon the successful manner in which these are laid out to meet the peculiarities of the traffic to be

accommodated, and provided for, will depend the amount of engine or other power that will be required to move about, and to place the same; and it is not too much to say that a bad arrangement of roads will speedily involve the employment of an extra engine for shunting, with all its attendant expense, besides perpetuating a continuous existence of more wear and tear, upon both roads and trucks: therefore, the accomplishment of this part of the surveyor's or engineer's work will demand his best energies, for the successful accommodation of the traffic of large works.

It is of great importance to arrange the gradients, wherever it is practicable, so that the wagons shall pass under and away from the colliery screens by their own gravity, giving just sufficient fall to the road to overcome the friction of the rolling surfaces, and thus avoid the necessity of having horses always in attendance: and while in many places the natural conformation of the ground is such that this can be accomplished without the least difficulty, there are others which require to be carefully thought out, to properly accommodate the requirements of the works. And as the rails of the sidings about works are seldom very clean, consequent upon the nature of the traffic to which they are subject, it will not be advisable to count upon flatter gradients than about 1 in 100 for the wagons to run alone, and if a little more fall can be given so much the better; for while a gradient of 1 in 100 will allow for about 22·4 lb. per ton for friction, and should under good conditions be much more than sufficient, yet if wagons and roads are not kept in good running order there will not be any considerable superfluous margin.

In Iron Works it is often impossible to arrange the roads with falling gradients in either direction, to in any appreciable degree facilitate some portions of the traffic; and occasionally the nature of the traffic less requires it than at collieries; but still in such instances there is always much to be considered in the disposition of the roads and partings, to provide for that convenient despatch which is essentially necessary, where so much *is being done* constantly and unremittingly, night

and day; and for which no further rule can be given than that each particular case must be considered on its own merits, always bearing in mind the quantity and kind of traffic to be provided for, together with the space at hand that can be assigned for its accommodation: and wherever an advantage is to be gained by the adoption of some particular gradient, and there are no insuperable difficulties in the way of its being carried out, such details should always have due consideration.

The practice of levelling for mining purposes does not much differ from that of taking levels for other works, further than this, that when it has to be done underground it is accomplished under very considerable disadvantages; and great care is necessary in throwing light into the telescope, so as to be able to see the cross-hairs, and to get a steady light, yet only what will be just sufficient for the purpose; and also to hold the light as much as possible in the alignment of the axis of the telescope, or else the cross-hairs will appear very unsteady, and the vision of them will frequently be flickering and uncertain to the eye. A good steady light will also be necessary for the assistant who holds the staff, so that the figures may be seen with ease and certainty. There is often great difficulty in securing anything like a good B. M. (bench mark) underground, in consequence of the movements of the ground, but the inconvenience arising from this is generally much less than in important surface works.

The business of surveying as applied to other operations than that of mining etc., has been so frequently and ably treated of before by others, that those who seek specific information on such branches may safely be referred to those works for the information they are in need of.

In the succeeding chapter will be found a more full explanation and illustration of the application of Triangulation to a considerable surface survey; and as the value of a Map depends upon its accuracy, and in mountainous districts the operation of chaining is rendered much more difficult and less accurate, by reason of the uneven nature of the ground, it *seems to be most* desirable that the principal groundwork of

every important survey should be formed by the application of those principles, therein explained and applied.

CHAPTER XI.

ON TRIANGULATION, ETC.

We will now proceed to give an example of the application of Trigonometry to a surface survey, shewing how a property of a certain figure may be divided for Triangulation, and computed through the whole series of lines. This example is not from any actual survey, but is given as an instance of the application of the principles enunciated in the foregoing chapters of this work.

The superiority of these principles—if accuracy is considered to be at all desirable—cannot be for a moment doubted, and the slightly increased amount of labour, if indeed there is any increase of labour, is abundantly compensated by the increased value of a thoroughly reliable Plan on which to lay out the workings, and guide them for the proper exhaustion of the minerals throughout the property to the boundaries, and the reservation of proper barriers to ensure against flooding and other mischiefs.

In the example here given, Plate 3, line *a* of No. 1 triangle is that supposed to be measured very accurately, for computing the whole of the lines of the Triangulation; and this line, called the "Base of computation," is here represented to be 2564 links. The process of computation is carried on, first from line *a* to line *j*, embracing *b*, *c*, *d*, *e*, *f*, *g*, *h*, and *i*; then from line *a* to line *k*, embracing *q*, *p*, *o*, *e*, *n*, *m*, *l*, *i*, and *k*; thus the lines *e*, and *i*, come into each of the series of computations, and will each form a check upon both series, one of the other; and if these lines come the same in each (as they ought to do) it is so far satisfactory to the operator. Then, selecting one of *the lines*—say, for instance, *k*— as a "Base of verifica-

tion," it should be measured on the ground with the chain, and checked with extreme care, to ascertain if it corresponds with the computed length: if it comes within ·5, or 1 link of the computed length, it may be looked upon as being very satisfactory.

Care should be taken to avoid as much as possible the adoption of angles greater than 90°, as they are neither so convenient, nor so easy of computation: it should be also carefully observed that the sum of the angles of each triangle equals 180°; and that the sum of all the central angles of each closed polygon (at *A* and *B* for instance) equals 360°.

An instrument, theodolite or circumferentor, of the best make, and in perfect adjustment, will be requisite for taking these angles; and having carefully levelled the instrument the surveyor should proceed to take the angles, and enter them in a sketch, made for the purpose, of the several triangles in their proper relative positions. In some states of the weather the refraction of light will have a very perceptible influence upon the operation of taking the angles, and this should be carefully noted, and errors as far as is possible guarded against: for instance, if there are passing clouds, and *one* observation (or one of the readings for determining the angle) be taken while the sun is obscured and the other *after* the cloud has passed, there will often be a perceptible difference (dependent upon the state of the atmosphere) in the measure of that angle, compared with the measurement when both observations have been taken either in sunshine or in shade. Therefore it is well and proper to bear this in mind, and to check the readings of each angle by a double operation, before the instrument is removed from the position or station.

At *A*, and *B*, the whole of the angles at the center of each polygon can be taken and checked at one fixing of the instrument.

The trigonometrical Rule by which these computations are made, is that given before:—viz. *Add the logarithm of the given side to the sine of the angle opposite to the side required, and from the sum subtract the sine of the angle opposite to the given side; the remainder will be the logarithm*

of the side required: or, instead of subtracting the sine of the angle opposite to the given side add its co-secant, and the sum will be the logarithm of the side required.

Then, the given side a being 2564 links, we have the following computations.

To find side b.

As sine of $\angle 82^\circ 33'$	$= 9{\cdot}9963183$
: log. side $a = 2564$	$= 3{\cdot}4089180$
:: sine of $\angle 40^\circ 30'$	$= 9{\cdot}8125444$
	$13{\cdot}2214624$
: log. side $b = 1679{\cdot}4$	$= 3{\cdot}2251441$

To find side c.

As sine of $\angle 46^\circ 21'$	$= 9{\cdot}8594804$
: log. side $b = 1679{\cdot}4$	$= 3{\cdot}2251441$
:: sine of $\angle 75^\circ 34'$	$= 9{\cdot}9860720$
	$13{\cdot}2112161$
: log. side $c = 2247{\cdot}7$	$= 3{\cdot}3517357$

To find side d.

As sine of $\angle 75^\circ 34'$	$= 9{\cdot}9860720$
: log. side $c = 2247{\cdot}7$	$= 3{\cdot}3517357$
:: sine of $\angle 58^\circ 5'$	$= 9{\cdot}9288145$
	$13{\cdot}2805502$
: log. side $d = 1970{\cdot}1$	$= 3{\cdot}2944782$

To find side e.

As sine of $\angle 38^\circ 21'$	$= 9{\cdot}7927163$
: log. side $d = 1970{\cdot}1$	$= 3{\cdot}2944782$
:: sine of $\angle 76^\circ 29'$	$= 9{\cdot}9878012$
	$13{\cdot}2822794$
: log. side $e = 3087{\cdot}2$	$= 3{\cdot}4895631$

To find side *f*.

As sine of ∠ 38° 21′	= 9·7927163
: log. side *d* = 1970·1	= 3·2944782
:: sine of ∠ 65° 10′	= 9·9578626
	13·2523408
: log. side *f* = 2881·5	= 3·4596245

To find side *g*.

As sine of ∠ 51° 41′	= 9·8946461
: log. side *f* = 2881·5	= 3·4596245
:: sine of ∠ 68° 35′	= 9·9689262
	13·4285507
: log. side *g* = 3419·	= 3·5339046

To find side *h*.

As sine of ∠ 68° 35′	= 9·9689262
: log. side *g* = 3419·	= 3·5339046
:: sine of ∠ 59° 44′	= 9·9363574
	13·4702620
: log. side *h* = 3172·	= 3·5013358

To find side *i*.

As sine of ∠ 48° 7′	= 9·8718681
: log. side *h* = 3172·	= 3·5013358
:: sine of ∠ 75° 9′	= 9·9852468
	13·4865826
: log. side *i* = 4118·2	= 3·6147145

To find side *j*.

As sine of ∠ 75° 9′	= 9·9852468
: log. side i = 4118·2	= 3·6147145
:: sine of ∠ 56° 44′	= 9·9222721
	13·5369866
: log. side j = 3562·4	= 3·5517398

To find side *q*.

As sine of ∠ 40° 30′	= 9·8125444
: log. side b = 1679·4	= 3·2251441
:: sine of ∠ 56° 57′	= 9·9233450
	13·1484891
: log. side q = 2167·4	= 3·3359447

To find side *p*.

As sine of ∠ 46° 6′	= 9·8576648
: log. side q = 2167·4	= 3·3359447
:: sine of ∠ 75° 20′	= 9·9856129
	13·3215576
: log. side p = 2910	= 3·4638928

To find side *o*.

As sine of ∠ 75° 20′	= 9·9856129
: log. side p = 2910	= 3·4638928
:: sine of ∠ 58° 34′	= 9·9310750
	13·3949678
: log. side o = 2566·6	= 3·4093549

To find side *n*.

As sine of ∠ 68° 8′	= 9·9675728
: log. side *e* = 3087·2	= 3·4895723
:: sine of ∠ 61° 23′	= 9·9434172
	13·4329895
: log. side *n* = 2920·2	= 3·4654167

To find side *m*.

As sine of ∠ 46° 7′	= 9·8577863
: log. side *n* = 2920·2	= 3·4654167
:: sine of ∠ 86° 15′	= 9·9990691
	13·4644858
: log. side *m* = 4042·9	= 3·6066995

To find side *l*.

As sine of ∠ 86° 15′	= 9·9990691
: log. side *m* = 4042·9	= 3·6066995
:: sine of ∠ 47° 38′	= 9·8685548
	13·4752543
: log. side *l* = 2993·5	= 3·4761852

To find side *k*.

As sine of ∠ 44° 46′	= 9·8477091
: log. side *l* = 2993·5	= 3·4761852
:: sine of ∠ 59° 36′	= 9·9357660
	13·4119512
: log. side *k* = 3666·4	= 3·5642421

To find side *i* by this series.

As sine of ∠ 44° 46′	= 9·8477091
: log. side k = 2993·5	= 3·4761852
:: sine of ∠ 75° 38′	= 9·9862017
	13·4623869
: log. side i = 4118	= 3·6146778

being ·2 difference between the first and second computation to find the side *i*; this is satisfactory.

If it should be required to ascertain what the respective outer angles of No. 9 triangle *should* be, so as to close the polygon composed of triangles 3, 4, 5, 9, 8, and 7, and the length of the line k between the two abutting triangles 5 and 8, we must then apply the following rule. Having two sides and the angle between them; to find the two other angles and the third side. **Rule:—**

If the angle included be oblique, add the logarithm of the difference of the given sides to the tangent of half the sum of the unknown angles, and from the sum subtract the logarithm of the sum of the given sides, or add its complement; the remainder or sum will be the tangent of half their difference.

Applying this rule, we have the two given sides = 4118·3 and 2993·5; and 2993·5 + 4118·3 = 7111·8 = the sum; and 2993·5 − 4118·3 = 1124·8 = their difference.

Also sum of unknown angles = 180° − 59° 36′ = 120° 24′; and 120° 24′ ÷ 2 = 60° 12′ = the half sum.

Then, Log. diff. 1124·8 =	3·0510367
Log. Tangent 60° 12′ =	10·2420687
	13·2931054
Sub. Log. sum = 7111·8 =	3·8519795
Log. Tangent 15° 26′ =	9·4411259.

Therefore the angles will be, 1st, 60° 12′ + 15° 26′ = 75°.

35′; and 2nd. 60° 12′ − 15° 26′ = 44 46′; and the side *k* will then be computed by the rule given for the other sides.

The diagram of lines of which the foregoing is the computation forms a complete foundation or groundwork on which to proceed to fill up all the details of the estate to which it may refer. Good firm stakes, or some other reliable marks, should clearly distinguish the positions of all the stations, and then poles can be set up for measuring those lines or combining short diverging lines with them, as circumstances may require, in order to take in all the requisite boundaries, fences, brooks, houses, or other matter; and, if found necessary, portions only of some of the lines can be measured from one or other of the ends if complete information for plotting can thus be obtained, and so that the correct particulars are entered in the field-book. In this way awkward and rugged parts of lines, which, with another system, would have to be measured entire to complete the information requisite to plot the work, may be occasionally omitted, without in any manner impairing the accuracy of the Plan: and no error could be continued beyond the triangle in which it arises, and could scarcely arise (with ordinary diligence) without being detected.

The selection of the secondary lines for filling up, and their directions, depend entirely upon the judgment of the surveyor being brought to bear upon the peculiarities and requirements of each particular case, and for which scarcely any two instances will be found requiring the same treatment and division: therefore the better and quicker the judgment exercised in their selection, the more accurate and less laboriously attained will be the result.

The application of these principles is often of great importance also in foreign countries, in the procuring information respecting, and the development of, their mineral resources, and for acquiring a fairly accurate idea of the stratification, correct average line of dip, direction of principal faults, and other information so necessary to guard against error in taking up concessions, and developing the mineral riches of comparatively unknown countries. For while in England,

generally speaking, the boundaries of our deposits of coal &c., are pretty well known, in new and undeveloped countries much information has to be gathered.

The object then to be attained, is to procure the data from which to lay down a connected relative view of different and distant points; for while, often, a consideration of the peculiarities and evidences of any one small district, taken alone, will be found to contribute but little to a general knowledge of the surrounding country, and will often indeed be found, when read *by themselves*, to be completely contradictory of the *general* evidences found elsewhere, they will—when read in the light of the *combined* information to be gathered throughout the area under enquiry, and combined also with a consideration of the relative positions of those places, the character, pitch, and strike of the strata as a whole, line of faults, evidences afforded by denudations of the strata, either in large valleys or deep ravines, together with the fossils to be found in the area being examined—enable the intelligent enquirer to form a tolerably accurate idea as to the capabilities of the district under consideration to yield any of those minerals which have been so much a source of wealth and greatness to the countries possessed of them, and of which he may be in search.

In getting up a Plan of such a district as is here supposed, the application of the science of Trigonometry is generally the only practicable mode of doing so; and at the same time it provides a groundwork for the filling in any details in reference to any particular part deemed desirable, either at that or at any subsequent period.

The rules here given are those most generally employed, in such computations as are here indicated; but there are others which have to be adopted occasionally, under peculiar circumstances, instead of these, and which will be found given in treatises on Trigonometry. Also, when the lines under consideration are so large that the curvature of the earth has an appreciable effect upon them, Spherical Trigonometry must be employed, intead of Plane Trigonometry.

While the peculiar evidences of *large* districts must thus

be sought, if coal, stratified deposits of iron ore, and some other minerals, are being sought after, there are some deposits, and amongst them the *casual* deposits of iron ore, which do not become influenced so much by the general features of large districts, but their evidences are rather to be sought for in a more confined area. Occasionally an unpromising looking outcrop will be found to lead to a very valuable deposit of rich iron ore beneath; while a very considerable area on the slope of a hill may be reddened by the descent of the rain-waters, whose solvent action upon a *slightly* disseminated sprinkling of ore in the strata of the brow of the hill will have brought about a gradual change of colour, and which may lead some persons to fancy that a very valuable deposit of rich iron ore is near at hand. Springs of water holding iron in solution will often give a colour to the surface over which it flows, and which, if taken as indicative of what may be found in the immediate substrata, will be eminently calculated to mislead. We have taken crusts of brown oxyd of iron, upwards of two inches thick, from the face of a bank over which has flowed a stream of water that has contained iron in solution, and which iron was, most probably, originally taken up from decomposing iron pyrites in the strata through which the water had flowed, as that mineral was known to exist near in considerable quantities: and this crust could not have been, from the peculiar nature of the position, many years in forming. Sometimes the material of which houses are constructed (if stone has been employed) will give a clue to deposits in the neighbourhood, by the occasional appearance of a stray lump of ore amongst the building material, especially where, as in primitive countries, the people gather and use the loose material they find lying in their fields, rather than raise it in a quarry. Sometimes the outcrop of a deposit of mineral may be discovered in going along over a country after a very heavy rain, such as falls in southern countries, which has washed the surface of all the loose débris, and left the native strata quite clean and bare—it being, in fact, nature's performance of that operation of "scouring," which is still carried out artificially, occasionally, in many countries, to discover the outcrops of metallic deposits

and other minerals of value. Deep ravines, and the beds of brooks when dry, will also often yield unerring evidence of the presence, or otherwise, of certain metalliferous deposits; as will also the examination of the localities of disruptions, and dislocations of the strata, and also by following the line of contact of rocks which lie unconformably one upon another.

In examining any new country and seeking therein evidence of mineral deposits, these, and many other such-like circumstances, will be made use of by the experienced observer, in endeavouring to ascertain the prospects of success (setting aside for the moment the questions of labour, transit, climate, &c.) of any mining enterprise with which he may be connected and have an interest in establishing upon a profitable basis, and with which the business of surveying must become more or less intimately connected.

CHAPTER XII.

ON THE VALUATION OF MINING PROPERTIES.

As the raising of minerals, and converting them to profitable use, is one of the businesses of life, and not one of its luxuries, except perhaps to an exceptional few, whose luxuries in it consist less of profits derived from the legitimate working of mineral properties than of profits made out of the unwary, by letting them into worthless things at a very high figure under specious colours, and from which no profit perhaps ever has been, nor is ever likely to be made—those who place their capital in mining enterprises do so in the legitimate hope and expectation of reaping a proper return for its employment. There are things in which money is embarked or spent, and in which, if the expectation of profit is not very great, the liability to risk and accident and loss is at least very small; but mining is much too serious a matter to embark in simply

from a love of the adventurous, and therefore those who take, or buy mining property, to work it legitimately, and who place their capital in it, have a right to look for an ample return upon their investment.

Whether the question of the manner of deposition of our splendid deposits of minerals, and especially of coal, will ever be decided to the satisfaction of every enquiring mind is extremely doubtful; nor does the value of the possession depend upon the decision of any such abstract question. The fact of its value is unquestioned, and those countries which possess it in greatest abundance, and also the means for its development, are found, taken at large, to be the most advanced in wealth, and prosperity, and high civilization. It is true that we do not always find an advanced state of civilization amongst the workers in our collieries and mines. The miners are a race of men whom some may judge to be somewhat repulsive and uncivilized, simply from the black appearance the coal-dust, or the red skin that the hematite mine and other accompaniments of mining, give them—adhering to the strong and able frame in consequence of the streams of perspiration that pour out through all the pores of the whole body in the laborious work of mining. Such a judgment would however be very inaccurate, and would, as a rule, convey a most uncharitable idea of the miner. That he is impulsive, and often careless of his own life and that of his fellows, we have frequent evidence of in the melancholy testimony borne to the causes which lead, or have led, to the too frequent recurrence of the sad loss of life in collieries and other mines: but it is by no means just to lay all the blame upon the miner when an accident happens, and come at once to the conclusion that it has necessarily originated in his carelessness or foolishness. Other causes, over which he has no control, and for which he is in no way responsible, but by which he is placed in imminent peril, are often operating to accelerate and bring about destruction to life and property; and some of these it is within the range of possibility to prevent, and some are events which it is to be feared no ordinary forethought could have fully averted.

Placed thus in the midst of daily danger, and labouring in the monotonous toil of the mine, it is not to be wondered at if the miner is sometimes found to be heedless and callous; but such is not the case universally, for there will be found amongst miners men of noble impulse and generosity, and some who take a greater notice of the mineral they raise than that merely involved in the raising and filling it into the trams. There are those who are fond of collecting specimens of some of those beautiful fern fronds, and other fossiliferous impressions so frequently to be found in some strata in and about the minerals, which evince an enquiring and teachable mind; and they have also (some of them) formed some opinions of their own respecting the manner of deposition of the veins, &c. they labour in. These, and similar evidences, tend to shew that if the miner is not so highly civilized as he should be, the fault is frequently less his own than of the concurrent surrounding circumstances of his position, and perhaps also of those who are by their opportunities and education placed by Providence in a position that enables them, if they would, to assist in the work of improving his mental condition.

The many works of practical benevolence and love which the miner is found assisting in, and in some instances to initiate, shew that he has a heart as warm and generous as others more generally recognized; and if his heart is warmly appealed to in the matters of religion, purity, prudence, and charity, it will not infrequently be as warmly responded to. Therefore we would submit that if the miner is not in all things what it would be desirable to have him to be, he is not at the same time what he is capable of being made; and those with superior endowments and positions may at all times do much towards raising him to that standard, to which it is very frequently said the "safe" miner should conform.

It is occasionally said that as men grow in intelligence they dislike the mine, and that the possession of one is inconsistent with the performance of labour in the other: but to apply such judgment as a principle, simply because isolated instances may have arisen in confirmation of such an idea, would be manifestly unfair. And can it be for a moment supposed that

an All-wise Providence has so placed these great blessings and comforts—as our mineral riches are admitted to be—in a position from which they can be brought only by the prevalence of the most ignorant and degraded class of labour? and that its removal can only be properly secured by the existence of that state of being which is utterly repugnant to, and inconsistent with, those higher attainments of our nature to which, in other works of the same All-wise Providence, we are constantly called? Surely this cannot be, and we should be guilty of great indiscretion if we were to suppose that it is not possible to secure these great blessings, and accessions to our comforts, at a less cost than the perpetual existence of a maxima of vice and irreligion.

Doubtless there will always be enough, and too much, of these in our world while the present course of things continues; but at the same time there is no reason why a general advancement in intelligence should not be striven after, for the benefit of each generation as it arises; for the more men grow in intelligence, the less will they become a prey to designing and professional agitators, and the more will the connection between labour and capital be improved. Men will see that it is to the advantage of themselves and of their employers that their labour should be performed with the greatest care, and to secure the best results; and that if capital cannot be equally well remunerated in mining enterprises with labour, it will not continue to be so employed, but will seek new fields of enterprise for its employment.

Thus we submit that this question of the state of intelligence of the labour employed has no slight influence upon the value of mineral properties; for it is well known that where there are steady, and contentedly settled men, with which to carry on mining operations, there is a great advantage in comparison of that where men are unsettled and roving, and consequently less easily controlled and disciplined, and less amenable to reason.

When mining property comes into the market for sale, its real value is a matter not always easily determined. Foreign enterprises are occasionally offered to speculators and capi-

talists, and often consist of concessions held from foreign governments; these concessions we have known in some instances to have been both numerous, and widely dispersed; and instead of a large number of concessions being a source of strength to foreign mining it is much more frequently its weakness, for it is mostly made compulsory upon the holders that a certain amount of work shall be performed at each concession yearly, or the right to hold is endangered, and may be forfeited: and thus are many companies led into attempting too great a series of operations at the first, which, in new countries, and with untrained labour, often involve so heavy an expenditure that not a few collapse under the burden; while if attention had been confined to some two of the most promising and conveniently situate until they were fairly developed and made productive, much less preliminary cost would have been incurred, much capital saved, and the other concessions could then be gradually attended to and developed in a manner most conducive to the permanent success of the entire undertaking; and much fewer companies would then be brought to ruin.

If mining properties in foreign countries are much scattered there is much attendant expense in opening up and maintaining roads, or channels of communication and transit for the minerals; for, most likely, there will often be but few native roads that can be made available in any but detached parts; and where this is so, and native labour is used, though it may be available in sufficient abundance it may still be unacquainted with the class of work to be performed, and thus, while the labour is nominally cheap, it may in reality be very much dearer than a higher paid class of labour in other countries; and, as a consequence, the results of carrying on work in foreign countries seldom realize the expectations raised on the basis of cheap labour. These things will be elements in the calculation, in seeking to form an estimate of the value of foreign mining or other properties for the profitable employment of capital, and great care will be needful in making such valuations: for while doubtless there are many rich properties awaiting the application of capital, to yield a

most remunerative return, there are others from which little can be properly expected.

The same may be said of properties in our own country, coming into the market; for while there are some properties which are thoroughly legitimate and sound, and offer a good security for the investment of capital, there are some occasionally offered which, if they ever have paid a return on capital, have now pretty well ceased to have any prospects of doing so any more; in fact the owners may wish to sell them in consequence of their being of no value to hold. It is, however, certain, that such transactions are not confined to mining, for in many other ways we find the same principle acted on; and if a person with his eyes open buys a worthless thing he has himself principally to blame, if he did not take due precaution to ascertain by the best available means whether it was of the value represented to him.

While coal veins, and other stratified deposits, admit of the application of general estimates of acreage yields of unworked ground, and with the cost at which the mineral can be produced and sold supply general information for computation, casual deposits cannot often have such principles wholly applied to them; for they are in some cases very variable in their features, and so irregular in the quantities yielded by similar areas, that it is but the merest guess-work to assign any quantity as a probable yield.

Doubtless, in some of the hematite iron ore deposits, the further we follow them down the greater we may find their bulk to be, and probably their richness also; but the manner of working imposed by the nature of the deposit, and the precautions necessary to ensure against flooding, will be certain, in these deposits, to affect their value in the course of time; and what will be a good system for one deposit in one country, may in another country, and with precisely similar surroundings of stratification etc., be quite inapplicable: for if we suppose the case of a hematite deposit, very rich in itself, but situate where the Lancashire practice of working downward would be inapplicable in consequence of semi-tropical or violent rains prevailing at times—an instance of which we

have known, and have been connected with, and directing, in Portugal—some other mode of working must be adopted, so as to keep the surface intact; for were it in such cases to be broken by the subsidence brought about by working downward from the surface, the immense rains which in a very short time occasionally convert the surface of the ground into one wide sheet of water, would then quickly bring about the destruction of the mine, not alone by flooding the lower workings, but by carrying down into the workings such great quantities of the small refuse and sand overlying the district, that it would become a matter of *reopening* the mine to get at the former workings again. Of course, when the deposit being worked is situate on a hill, where good natural drainage can be arranged, such inconvenience from this cause does not arise, or is easily provided for. Under the circumstances we have mentioned, the only feasible plan seems to be that of going sufficiently deep to commence operations, and then to work upwards towards the surface, filling in the excavated space with rough material sent down into the mine; and always leaving a sufficient thickness untouched, to ensure an unbroken crust to keep out the flood waters.

These and similar circumstances will all go to tell upon the value of mineral undertakings, of the different kinds to which they respectively apply; so that the correct estimation of the value of a mineral property is often a complicated question, involving several matters which require special consideration,—and can only be duly arrived at by the examination of each property, not only upon general principles, but also with regard to the special features of the nature of the deposit; country in which situate; facilities for transit; abundance of labour; cost of establishing, developing, and conducting the operations; market for produce at a profitable price; and other matters of a relative nature which will suggest themselves to a competent valuer, who may have to entertain the question of the valuation of such properties.

We have found that veins of coal of thicknesses varying from 2 ft. 6 in. to 5 ft. have yielded the following different numbers of tons per foot of thickness per acre: viz. 1100,

1090, 920, 1300, and 1000 tons, statute weight—taking the exhausted ground as measurement; and these numbers will probably be found to be about what it is possible to realize in practice generally, though some of the quantities may be considered to be very low; but several causes go to influence the total quantity to be obtained from any particular vein,—not only the varying specific gravity of coals, but the strength or firmness of the veins, the nature of the superincumbent strata, mode of working, and also, in no slight degree, the system of management.

As being amongst the prominent questions that would have to be entertained and considered, in valuing any colliery that may be offered for sale, are some or most of the following.

1st. The area and compactness of the property, provisions and clauses of lease:—are they reasonably favourable to the Lessee, and what is the royalty reserved, dead rent, average clause, power of assignment, of removal of plant at expiration or other determination of lease etc. etc. etc.?

2nd. What is its relative position in regard to other properties being worked?

3rd. What is its relative position for market purposes for produce; to what markets can its produce be sent; and has it good railway, or other sufficient service?

4th. What are the general known features of the strata in respect of Faults, Springs, Swamps, old Workings (if any) etc., and how situate?

5th. Are any of the veins of mineral—coal or iron—in the same property, that can be worked to the detriment of that whose value is sought, demised to *other* lessees?

6th. Quantity and quality of coal unworked, and its accessibility from Pit, or Level; and will the coal last out the term of the lease, and cover the dead rent to the end?

7th. What is the price at which the coal can be delivered at "bank" in ordinary times, all working charges paid; and what are the royalties, wayleaves, and other charges binding on same?

8th. What profit per ton will this cost admit of in ordinary

states of the market; and what quantity is the colliery capable of producing per diem?

9th. Does the vein of coal give off much explosive gas; is the "top" good; and does it require much timber?

10th. Is there a good sound system of ventilation in operation, with sufficient air, and shafts etc. for same?

11th. How many years will the royalty last to *give profit?*

12th. Is the colliery well provided with machinery, plant etc., requisite for raising and despatching the coal; and are good plans of all the *old* workings obtainable?

13th. Are the boundaries infringed upon at any point; and do any liabilities attach to the property other than those usual and ordinary?

14th. What facilities of access to other veins, or royalties, does the possession of the present field and vein, or veins, give; and what is their money value to an incoming tenant or purchaser?

15th. What convenience, and area of spoil ground, is there for tipping rubbish etc. from the colliery?

16th. Do the minerals underlie any town, village, reservoir or accumulation of water, or any other notable place or thing, which would render the working of the coal liable to, or for, any damages, or actions at law, more than ordinary?

17th. Then:—Under all the circumstances what net profit per annum will the colliery produce, and for how many years, at a certain estimated output per annum?

An amount should be allowed off the profit for an insurance or compensation fund (in case of accident), and the income should provide a sufficient amount, after that deduction, to give a good interest on capital laid out, as well as to provide for the recouping of capital, before the colliery becomes exhausted.

The annual value etc. having been thus obtained, and any other matter observed necessary being duly considered, the present value will have to be worked out by the ordinary rules for money computations of this nature, and the result shewn in a proper tabulated form.

We will conclude by giving a few examples of the valuation of the freehold interest in mineral property; and also of a reserved rent-charge: and these will also, to a considerable extent, illustrate the principle to be followed in estimating the value of a terminable income, annuity, or other interest, arising from a colliery, or other property generally.

Reserved Rent Charge.

Example 1.

A person is entitled to an annual rent-charge of £140 upon a property, for a remaining term of 17 years; and it is required to clear the property of this charge:—the proprietor is willing to accept an immediate equivalent, and to allow interest at the rate of 3½ per cent. per annum. To what amount does he become immediately entitled?

To solve this, we require to find the value of an immediate annuity of £1 per annum, at that rate of interest; this is found by Smart's Tables to be £12·65132, and if we multiply this amount into the rent-charge we have 12·65132 × 140 = £1771·184 for the value of the immediate equivalent.

We may also work out the same result by Thoman's Tables —using logarithms.

Thus, taking same term and rate,

Comp. log. a^n = 1·1021358
Log. 140 = 2·1461280

Log. 1771·184 = 3·2482638 = the same amount as that above given, or £1771. 3*s.* 8*d.*

A little consideration will suffice to shew that these formulæ will apply to other questions of money interests. For instance, the computations will apply if the question is:—What is the present value of an immediate annuity for 17 years, in any property, if it is required to make an interest of 3½ per cent. per annum? for a person who is liable to pay an annual rent-charge, if he rids himself of the liability

by paying down a certain sum, does, in effect, purchase to himself an annuity equal in amount to the rent-charge he was before paying. Other applications of the same principle will readily suggest themselves to the enquiring mind.

If the result of the computation be first obtained, while treating the annuity as being one single yearly payment, though it be, in fact, really divided into quarterly payments, or half-yearly payments, we may find the increased value under the latter circumstances very simply by Thoman's Tables.

Example 2.

Question. A property yields a yearly rent of £860: what is it worth as a perpetuity when the rent is paid yearly; also when paid half-yearly; and when paid quarterly? Interest at the rate of 7½ per cent. per annum.

1st. When paid yearly.

Comp. log. a^n	= 1·1249387
Log. 860	= 2·9344985
Log. £11,466·66	= 4·0594372 = the Value.

2ndly. When paid half-yearly.

Log. of 1st value = 11,466·66	= 4·0594372
+ Q_2 equivalent	= 0·0080676
Log. £11,681·664	= 4·0675048 = the Value.

To prove the second computation, it is sufficient to shew that the 1st value is increased by an amount = to the value of a perpetuity of ½ year's interest on ½ the annuity, at 7½ per cent. as before; viz. £16·125.

Then	Comp. log. a^n	= 1·1249387
	Log. 16·125	= 1·2074997
	Log. £215	= 2·3324384 = the Value; being

the amount by which the 1st value is increased in the 2nd computation: viz. 11,466·66 + 215 = £11,681·66.

3rdly. What is the value when the annuity is paid quarterly, the same rate of interest being allowed?

Log. of 1st value = 4·0594372
+ Q_4 equivalent = ·0121951
Log. £11,793·216 = 4·0716323 = the Value; being the value when the annuity is paid quarterly.

To prove the 3rd computation the proceeding is more intricate; but it may be shewn that the 1st value, £11,466·66, is increased by the perpetuity of the following amounts, viz.:

1st. ¾ interest on 1 quarter of the annuity
= £12·09375 = in value £161·249

2nd. ½ interest on 1 quarter of the annuity
= £8·0625 = in value £107·50

3rd. ¼ interest on 1 quarter of the annuity
= 4·03125 = in value £53·73

and by the compound interest on the quarter's interest on the quarter's interest on the quarters of the annuity = £4·07

Then, Amount of Value when paid yearly = £11,466·660
Total Value as per 3rd computation = £11,793·216

Example 3.

The Valuation of Freehold Property with Minerals immediately productive.

What is the Value of an Estate of 400 acres, the minerals of which are just beginning to be worked, the fair estimated output per annum of coal being 120,000 tons (=400 tons per day for 300 days) at a royalty of, say, 10*d.* per ton; and the estimated duration of the same being 80 years? This would produce an annuity of £5000 for 80 years. The surface is being let, as farm land and rough pasturage, at £250 a year. Interest on capital to be allowed at 8 per cent. per annum; and capital to be recouped at 3½ per cent. per annum; interest on purchase money of surface being at the rate of 4 per cent. per annum, and in perpetuity.

Then, the surface will thus be worth 25 years' purchase, or a total derived thus: $250 \times 25 = 6{,}250$ £6,250. 0

The annuity of £5000 for 80 years, at 8 per cent. annum, and to recoup at 3½ per cent. per annum, is worth in present money the sum total of £60,690. 15. 0

Total Value £66,940. 15. 0

The formula by which the second value is derived is that given by Thoman in his treatise, and is as follows:

$$V = \frac{a}{t' + \frac{a^n}{r^n}},$$

in which V is the value; a the annuity; t' the rate per cent. to be made on purchase money; a^n the annuity which £1 will purchase for that term, and at rate of recoupment; and r^n the amount of £1 at the end of the term, and at the same rate.

Then applying this formula to the foregoing case we have the following values:

	Logarithms.	Nat. Numbers.
Log. a^n	$= 8{\cdot}5726961$	
Log. r^{-n}	$= 1{\cdot}1952280$	
$a^n r^{-n}$	$= 7{\cdot}3774681 =$	. . . . . $0{\cdot}0023845$
		$+ t' = 0{\cdot}08$
Log. $t' + \frac{a^n}{r^n}$	$= 8{\cdot}9158475 =$	. . . . . $= 0{\cdot}0823845$
Log. a	$= 5{,}000 = 3{\cdot}6989700$	
Log. of V	$= 4{\cdot}7831225 =$	£60,690·75, or £60,690. 15*s.* 0*d.*

= purchase money of the annuity.

We may check the above computation by working out the question by the rules given by Hardy as in Inwood's Tables at page 179.

1st. by Smart's Tab. 3, $(a)^{80} = 419{\cdot}30678$

5000

Product $= 2096533{\cdot}9$

2nd. $(a)^{80} = 419{\cdot}30678$
$\times t' = \quad {\cdot}08$
Product $= 33{\cdot}5445424$
$+ \ 1$
Sum $= 34{\cdot}5445424$

3rd.

$$\frac{2096533{\cdot}9}{34{\cdot}5445424} = £60{,}690{\cdot}75 = V \text{ the value as before.}$$

Then, the interest on this value at 8 per cent. per annum will amount to.....4th. ..... 4855·26
giving for amortisement at $3\frac{1}{2}\%$ $(=s)$ 144·74
Total annuity £5,000·00

And to prove the sufficiency of the amortisement we have, by following the same rule,—

5th. Smart's Tab. 1.
$r^{80} = 15{\cdot}67573$
$- \ 1{\cdot}$
Diff. $= 14{\cdot}67573$

6th. Log. $14{\cdot}67573 = 1{\cdot}1666016$
Log. $s = 144{\cdot}74 = 2{\cdot}1605886$
C^t Log. rate $\cdot 035 = 11{\cdot}4559320$
Log. $60{,}690{\cdot}71 = 4{\cdot}7831222$ = the capital recouped

at the end of the term of 80 years.

The foregoing estimate of quantity of coal would require a total thickness of 25 ft. or thereabouts, over the whole area of the property.

Example 4.

Freehold Property with Minerals, being partly immediately productive, and partly deferred, and comprising the following lots, viz.:

Lot A. Surface rental of 350 acres, equal to a perpetuity, and let at a yearly sum of £145, net.

Lot B. The upper veins of Coal producing 200 tons per day, or 60,000 tons per annum, let at 9*d.* per ton royalty; and calculated to yield this quantity for a further term of 18 years.

Lot C. The lower veins of Coal which from their favourable position are likely to be productive in 15 years, and then to yield an output of 300 tons per day, or 90,000 tons per annum, for a term of 65 years, and to let at 1*s.* per ton royalty.

Lot D. Freehold groundrents from houses built, amounting to £200 per annum, for 75 years unexpired term of the leases.

Lot E. Royalties or wayleaves yielding, at 1*d.* per ton, £80 per annum; and estimated so to continue for a further term of 12 years.

Then supposing interest to be allowed on the several lots as follows, viz:—

Lot A. 4 per cent. per annum as a perpetuity,
Lot B. 8 per cent. per an. on Capital, and to recoup at 3½ %,
Lot C. 10 „ „ „ „ „ „ 3 %,
Lot D. 7 „ „ „ „ „ „ 3½ %,
Lot E. 10 „ „ „ „ „ „ 3 %,

the following will be the values: the same notation and rules being applied as in Example 3.

The Value of Lot A will then be $145 \times 25 = £3{,}625.\ 0s.\ 0d.$

Lot B. Annuity for 18 years £2,250.
Interest on Capital 8 per cent.
Interest to recoup 3½ per cent.

	Logarithms.	Nat. Numbers.
Log. a^{18}	$= 8{\cdot}8797657$	
Log. r^{18}	$= 0{\cdot}2689262$	
Log. $a^{18}r^{-18}$	$= 8{\cdot}6108395 =$	$\ldots\ldots\ldots\ldots 0{\cdot}0408168$
		$+t' = 0{\cdot}08$
Log. $t' + \frac{a^{18}}{r^{18}}$	$= 9{\cdot}0821269 =$	$\ldots\ldots\ldots\ldots 0{\cdot}1208168$
Log. 2,250	$= 3{\cdot}3521825$	
Log. of Value	$= 4{\cdot}2700556 =$	£18.623'26.

Checking by Hardy's rules as in Ex. 3,

1st. Smart's Tab. 3, $(a)^{18} =$ 24·49969
2,250
Product = 55124·3025

2nd. $(a)^{18} =$ 24·49969
$\times t' =$ ·08
Prod. = 1·9599752
+ 1·
Sum = 2·9599752

3rd. $\frac{55124 \cdot 3025}{2 \cdot 9599752} = 18{,}623 \cdot 23 =$ Value.

4th. Int. on Value at 8 % = 1489·8584
Amort. to recoup 3½ % = 760·1416
The annuity = £2,250·0000

5th. Smart's Tab. 1. $r^{18} = 1 \cdot 85749$
$- 1 \cdot$
Diff. = 0·85749

Then 6th. Log. ·85749 = 9·9332291
Log. 760·1416 = 2·8808944
C^t Log. ·035 = 11·4559320
Log. 18,623·25 = 4·2700555 = the capital r

produced.

Lot C. The annuity for 65 years equals £4,500.
Interest on Capital = 10 per cent.
Interest to recoup = 3 per cent.
Period the annuity is deferred = 15 years.

	Logarithms.	
	$=8\cdot5458736$	
	$=0\cdot8344196$	Nat. Numbers.
	$7\cdot7114540=$	$\ldots\ldots\ldots\ldots\ldots\ldots 0\cdot0051458$
		$+t'=0\cdot10$
$t'+\frac{a^{65}}{r^{65}}$	$=9\cdot0217900=$	$\ldots\ldots\ldots$Sum$=\cdot1051458$
$4{,}500$	$=3\cdot6532125$	
Log. of V	$=4\cdot6314225=$	Value, treated as "immediate," $=$ £42,797·9.

Checked by Hardy's rules,

1st. Smart's Tab. 3, $(a)^{65}=194\cdot3328$

$4{,}500$

Product $=874497\cdot60$.

2nd. $(a)^{65}=194\cdot3328$

$\times t'=\quad\cdot10$

Prod. $=19\cdot43328$

$+\quad 1\cdot$

Sum $=20\cdot43328$

3rd. $\frac{874497\cdot6}{20\cdot433280}=42{,}797\cdot71=$ Value, as "immediate."

4th. Int. on Value at $10\frac{8}{8}=4279\cdot771$

Amort. to recoup at $3\frac{8}{8}=\quad 220\cdot229$

Total annuity £4,500·000

5th. Smart's Tab. 1. $r^{65}=6\cdot830$

$-\quad 1\cdot$

Diff. $=5\cdot830$

6th. Log. 5·83 = 0·7656686
Log. 220·229 = 2·3428746
C^t Log. ·03 = 11·5228787
Log. 42,797·85 = 4·6314219 = the capital rep

duced.

But as this annuity is deferred for 15 years (the fi payment coming due in the 16th year) the above value has be discounted for that term; and supposing that 8 per ce per annum discount is allowed for it we have to proceed follows. The interest at 8 per cent. per annum on £42,79 is £3,423·832.

Then (by Thoman's) Log. 3,423·832 = 3·5345164
÷ by Log. a^{15} = 9·0675527
Log. 29,374· = 4·4669637

∴ 42,797·9 − 29,374 = £13,423·9 = the value of the deferr annuity of Lot C treated on the terms indicated.

Lot D. The annuity for 75 years = £200.
Interest on Capital = 7 per cent.
Interest to recoup = 3½ per cent.

Logarithms.

Log. a^{75} = 8·5782860
Log. r^{75} = 1·1205262 Nat. Numbers.
Log. $a^{75}r^{-75}$ = 7·4577598 = ·0028692
$+t' = \cdot 07$
Log. $t' + \frac{a^{75}}{r^{75}}$ = 8·8625440 = Sum = ·0728692
Log. 200 = 2·3010300
Log. V = 3·4384860 = £2,744·64 = Value.

By Hardy's rules,

1st. $(a)^{75}$ = 348·53001
200
Product = 69706·002

2nd. $(a)^{75} = 348{\cdot}53001$
$\times t' = \quad {\cdot}07$
Prod. $= 24{\cdot}3971$
$+ \quad 1{\cdot}$
Sum $= 25{\cdot}3971$

3rd. $\frac{69{,}706{\cdot}002}{25{\cdot}3971} = £2{,}744{\cdot}64 =$ Value as above.

4th. Then Int. on Value at $7\frac{8}{8} = 192{\cdot}1248$
Amort. to recoup at $3\frac{1}{2}\frac{8}{8} = \quad 7{\cdot}8752$
Total annuity $= £200{\cdot}0000$

5th. $r^{75} = 13{\cdot}19855$
$- \quad 1{\cdot}$
Diff. $= 12{\cdot}19855$

6th. Log. $12{\cdot}19855 = 1{\cdot}0863082$
Log. $\quad 7{\cdot}8752 = 0{\cdot}8962616$
C^t Log. $\quad {\cdot}035 = 11{\cdot}4559320$.
Log. $2{,}744{\cdot}74 = 3{\cdot}4385018 =$ the capital reproduced at the end of 75 years.

Lot E. The annuity for 12 years equals £80.
Interest on Capital = 10 per cent.
Interest to recoup = 3 per cent.

Logarithms.

Log. $a^{12} = 9{\cdot}0020022$
Log. $r^{-12} = 0{\cdot}1540467$ Nat. Numbers.
Log. $a^{12}r^{-12} = 8{\cdot}8479555 =$ ..... $= {\cdot}070462$
$+t' = {\cdot}10$
Log. $t' + \frac{a^{12}}{r^{12}} = 9{\cdot}2316273 =$ ..... Sum $= {\cdot}170462$
Log. $80 = 1{\cdot}9030900$
Log. $V = 2{\cdot}6714627 = £469{\cdot}313$ the Value.

Check by Hardy's rules.

1st.

$(a)^{12} = 14{\cdot}192$
$\times \quad 80$
Product $= 1135{\cdot}36$

2nd.

$(a)^{12} = 14{\cdot}192$
$\times t' = \quad {\cdot}10$
Prod. $= 1{\cdot}4192$
$+ 1{\cdot}$
Sum $= 2{\cdot}4192$

3rd. $\frac{1135{\cdot}36}{2{\cdot}4192} = £469{\cdot}313 =$ Value as above.

Then 4th. Interest on Value at 10 % $= 46{\cdot}9312$
Amort. to recoup at 3 % $= 33{\cdot}0688$
Total annuity $= £80{\cdot}0000$

5th.

$r^{12} = 1{\cdot}4258$
$- 1{\cdot}$
Diff. $= {\cdot}4258$

6th. Log. ·4258 = 9·62292057
Log. 33·0688 = 1·5194185
C^n Log. ·03 = 11·5228787
Log. 469·35 = 2·6715029 = the capital reproduced
he end of the term.

SUMMARY OF VALUES.

	£	s.	d.
The Value of Lot A =	3,625	0	0
" Value of Lot B =	18,623	5	2
" Value of Lot C =	13,423	18	0
" Value of Lot D =	2,744	12	9
" Value of Lot E =	469	6	3
Total Value =	38,886	2	2

at

CHAPTER XIII.

THE TRAVERSE TABLES.

(DESCRIBED IN CHAPTER VII, PAGES 21—37.)

0 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 5
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.
0	100·00	0·00	200·00	0·00	300·00	0·00	400·00	0·00	500·0
3	99·99	0·08	199·99	0·17	299·99	0·26	399·99	0·35	499·9
6	99·99	0·17	199·99	0·35	299·99	0·52	399·99	0·70	499·9
9	99·99	0·26	199·99	0·52	299·99	0·78	399·99	1·05	499·9
12	99·99	0·35	199·99	0·70	299·99	1·04	399·99	1·39	499·9
15	99·99	0·44	199·99	0·87	299·99	1·30	399·99	1·74	499·9
18	99·99	0·52	199·99	1·04	299·99	1·57	399·99	2·09	499·9
21	99·99	0·61	199·99	1·21	299·99	1·83	399·99	2·44	499·9
24	99·99	0·70	199·99	1·39	299·99	2·09	399·98	2·79	499·9
27	99·99	0·78	199·99	1·56	299·99	2·35	399·98	3·14	499·9
30	99·99	0·87	199·99	1·74	299·98	2·61	399·98	3·49	499·9
33	99·99	0·96	199·99	1·91	299·98	2·87	399·98	3·84	499·9
36	99·99	1·05	199·99	2·09	299·98	3·14	399·97	4·18	499·9
39	99·99	1·13	199·98	2·26	299·98	3·40	399·97	4·53	499·9
42	99·99	1·22	199·98	2·44	299·97	3·66	399·96	4·88	499·9
45	99·99	1·31	199·98	2·61	299·97	3·92	399·96	5·23	499·9
48	99·99	1·39	199·98	2·79	299·96	4·18	399·95	5·58	499·9
51	99·99	1·48	199·97	2·96	299·96	4·44	399·95	5·93	499·9
54	99·98	1·57	199·97	3·14	299·96	4·71	399·94	6·28	499·9
57	99·98	1·66	199·97	3·31	299·95	4·97	399·94	6·63	499·9
60	99·98	1·74	199·97	3·49	299·95	5·23	399·94	6·98	499·9
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 5

89 Deg.

0 Deg.

	Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
00	700·00	0·00	800·00	0·00	900·00	0·00	1000·00	0·00	60
52	699·99	0·61	799·99	0·69	899·99	0·78	999·99	0·87	57
04	699·99	1·22	799·99	1·39	899·99	1·57	999·99	1·74	54
56	699·99	1·83	799·99	2·09	899·99	2·35	999·99	2·62	51
09	699·99	2·44	799·99	2·79	899·99	3·14	999·99	3·49	48
61	699·99	3·05	799·99	3·49	899·99	3·92	999·99	4·36	45
14	699·99	3·66	799·98	4·19	899·98	4·71	999·98	5·24	42
66	699·98	4·27	799·98	4·89	899·98	5·49	999·98	6·11	39
18	699·98	4·88	799·98	5·58	899·97	6·28	999·97	6·98	36
70	699·97	5·49	799·97	6·28	899·97	7·06	999·96	7·85	33
23	699·97	6·10	799·97	6·98	899·96	7·85	999·96	8·72	30
75	699·96	6·71	799·96	7·68	899·95	8·63	999·95	9·60	27
28	699·96	7·33	799·95	8·38	899·95	9·42	999·94	10·47	24
80	699·95	7·94	799·94	9·07	899·94	10·21	999·93	11·34	21
33	699·94	8·55	799·94	9·77	899·93	11·00	999·92	12·22	18
85	699·94	9·16	799·93	10·47	899·92	11·78	999·91	13·09	15
37	699·93	9·77	799·92	11·17	899·91	12·57	999·90	13·96	12
90	699·92	10·38	799·91	11·87	899·90	13·35	999·89	14·83	9
42	699·91	10·99	799·90	12·57	899·89	14·14	999·87	15·71	6
95	699·90	11·61	799·89	13·26	899·87	14·92	999·86	16·58	3
47	699·89	12·22	799·87	13·96	899·86	15·71	999·84	17·45	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

89 Deg.

1 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	99·98	1·74	199·97	3·49	299·95	5·23	399·94	6·98	499·92	8·72	60
3	99·98	1·83	199·96	3·66	299·95	5·49	399·93	7·33	499·91	9·16	57
6	99·98	1·92	199·96	3·84	299·94	5·76	399·92	7·67	499·91	9·60	54
9	99·98	2·01	199·96	4·01	299·94	6·02	399·92	8·02	499·90	10·03	51
12	99·97	2·09	199·95	4·18	299·93	6·28	399·91	8·37	499·89	10·47	48
15	99·97	2·18	199·95	4·35	299·93	6·54	399·90	8·72	499·88	10·90	45
18	99·97	2·27	199·95	4·53	299·92	6·80	399·89	9·07	499·87	11·34	42
21	99·97	2·35	199·94	4·70	299·91	7·06	399·88	9·42	499·86	11·77	39
24	99·97	2·44	199·94	4·88	299·91	7·33	399·88	9·77	499·85	12·21	36
27	99·96	2·53	199·93	5·05	299·90	7·59	399·87	10·12	499·84	12·64	33
30	99·96	2·62	199·93	5·23	299·90	7·85	399·86	10·47	499·83	13·08	30
33	99·96	2·70	199·92	5·40	299·89	8·11	399·85	10·82	499·82	13·52	27
36	99·96	2·79	199·92	5·58	299·88	8·37	399·84	11·17	499·80	13·96	24
39	99·96	2·88	199·91	5·75	299·87	8·63	399·83	11·52	499·79	14·39	21
42	99·95	2·97	199·91	5·93	299·86	8·89	399·82	11·86	499·78	14·83	18
45	99·95	3·05	199·90	6·10	299·86	9·15	399·81	12·21	499·76	15·26	15
48	99·95	3·14	199·90	6·28	299·85	9·42	399·80	12·56	499·75	15·70	12
51	99·95	3·23	199·89	6·45	299·84	9·68	399·79	12·91	499·74	16·13	9
54	99·94	3·31	199·89	6·63	299·83	9·94	399·78	13·26	499·72	16·57	6
57	99·94	3·40	199·88	6·80	299·82	10·20	399·76	13·61	499·71	17·01	3
60	99·94	3·49	199·87	6·98	299·81	10·47	399·75	13·96	499·69	17·45	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

88 Deg.

1 Deg.

Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
9·90	10·47	699·89	12·22	799·87	13·96	899·86	15·71	999·84	17·45	60
9·90	10·99	699·88	12·83	799·86	14·65	899·85	16·49	999·83	18·32	57
9·89	11·51	699·87	13·44	799·85	15·35	899·83	17·27	999·81	19·19	54
9·88	12·03	699·86	14·05	799·84	16·05	899·81	18·05	999·80	20·06	51
9·86	12·56	699·84	14·66	799·82	16·75	899·80	18·84	999·78	20·94	48
9·85	13·08	699·83	15·27	799·81	17·45	899·78	19·62	999·76	21·81	45
9·84	13·61	699·82	15·88	799·79	18·15	899·76	20·41	999·74	22·68	42
9·83	14·13	699·80	16·49	799·78	18·85	899·75	21·20	999·72	23·55	39
9·82	14·65	699·79	17·10	799·76	19·54	899·73	21·99	999·70	24·43	36
9·81	15·17	699·77	17·71	799·74	20·24	899·71	22·77	999·68	25·30	33
9·79	15·70	699·76	18·32	799·72	20·94	899·69	23·56	999·66	26·17	30
9·78	16·22	699·74	18·93	799·71	21·64	899·67	24·34	999·63	27·04	27
9·76	16·75	699·72	19·54	799·69	22·33	899·65	25·12	999·61	27·92	24
9·75	17·27	699·70	20·15	799·67	23·03	899·62	25·91	999·58	28·79	21
9·73	17·80	699·69	20·76	799·64	23·73	899·60	26·70	999·56	29·66	18
9·72	18·32	699·67	21·37	799·62	24·42	899·57	27·48	999·53	30·53	15
9·70	18·84	699·65	21·98	799·60	25·12	899·55	28·27	999·50	31·41	12
9·68	19·36	699·63	22·59	799·58	25·82	899·53	29·05	999·48	32·28	9
9·67	19·89	699·61	23·20	799·56	26·52	899·50	29·84	999·45	33·15	6
9·65	20·41	699·59	23·81	799·54	27·22	899·48	30·62	999·42	34·02	3
9·63	20·94	699·57	24·42	799·51	27·92	899·45	31·41	999·39	34·90	0
Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

88 Deg.

2 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	99·94	3·49	199·87	6·98	299·81	10·47	399·75	13·96	499·69	17·45	60
3	99·93	3·58	199·87	7·15	299·80	10·73	399·74	14·31	499·68	17·88	57
6	99·93	3·66	199·86	7·33	299·80	10·99	399·73	14·65	499·66	18·32	54
9	99·93	3·75	199·86	7·50	299·79	11·25	399·72	15·00	499·65	18·75	51
12	99·92	3·84	199·85	7·67	299·78	11·51	399·70	15·35	499·63	19·19	48
15	99·92	3·93	199·84	7·84	299·77	11·77	399·69	15·70	499·61	19·62	45
18	99·92	4·01	199·84	8·02	299·76	12·03	399·67	16·05	499·60	20·06	42
21	99·91	4·10	199·83	8·19	299·75	12·29	399·66	16·40	499·58	20·49	39
24	99·91	4·19	199·82	8·37	299·73	12·56	399·65	16·75	499·56	20·93	36
27	99·91	4·27	199·81	8·54	299·72	12·82	399·63	17·10	499·54	21·36	33
30	99·90	4·36	199·81	8·72	299·71	13·08	399·62	17·44	499·52	21·80	30
33	99·90	4·45	199·80	8·89	299·70	13·34	399·60	17·79	499·50	22·24	27
36	99·89	4·54	199·79	9·07	299·69	13·60	399·59	18·14	499·48	22·68	24
39	99·89	4·62	199·78	9·24	299·68	13·86	399·57	18·49	499·46	23·11	21
42	99·89	4·71	199·78	9·42	299·66	14·13	399·55	18·84	499·44	23·55	18
45	99·88	4·80	199·77	9·59	299·65	14·39	399·54	19·19	499·42	23·98	15
48	99·88	4·88	199·76	9·77	299·64	14·65	399·52	19·54	499·40	24·42	12
51	99·87	4·97	199·75	9·94	299·63	14·91	399·50	19·89	499·38	24·85	9
54	99·87	5·06	199·74	10·11	299·61	15·17	399·49	20·23	499·36	25·29	6
57	99·86	5·15	199·73	10·28	299·60	15·43	399·47	20·58	499·33	25·72	3
60	99·86	5·23	199·72	10·46	299·59	15·70	399·45	20·93	499·31	26·16	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

87 Deg.

2 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	599·63	20·94	699·57	24·42	799·51	27·92	899·45	31·41	999·39	34·90	60
3	599·61	21·46	699·55	25·03	799·49	28·62	899·42	32·19	999·36	35·77	57
6	599·60	21·98	699·53	25·65	799·46	29·31	899·39	32·98	999·33	36·64	54
9	599·58	22·50	699·50	26·26	799·44	30·01	899·36	33·76	999·30	37·51	51
12	599·56	23·03	699·48	26·87	799·41	30·71	899·33	34·54	999·26	38·39	48
15	599·54	23·55	699·46	27·48	799·38	31·41	899·30	35·32	999·23	39·26	45
18	599·52	24·07	699·43	28·09	799·35	32·10	899·27	36·11	999·19	40·13	42
21	599·49	24·59	699·41	28·70	799·32	32·80	899·24	36·89	999·16	41·00	39
24	599·47	25·12	699·38	29·31	799·30	33·50	899·21	37·68	999·13	41·87	36
27	599·45	25·64	699·36	29·92	799·27	34·20	899·17	38·46	999·09	42·75	33
30	599·43	26·17	699·33	30·53	799·24	34·89	899·14	39·25	999·05	43·62	30
33	599·40	26·69	699·30	31·14	799·21	35·59	899·10	40·03	999·01	44·49	27
36	599·38	27·21	699·28	31·75	799·17	36·29	899·07	40·82	998·97	45·36	24
39	599·36	27·74	699·25	32·36	799·14	36·99	899·03	41·60	998·93	46 23	21
42	599·33	28·26	699·22	32·97	799·11	37·68	899·00	42·39	998·89	47·11	18
45	599·31	28·78	699·19	33·58	799·08	38·38	898·96	43·17	998·84	47·98	15
48	599·28	29·31	699·16	34·19	799·04	39·08	898·92	43·96	998·80	48·85	12
51	599·26	29·83	699·13	34·80	799·01	39·78	898·88	44·74	998·76	49·72	9
54	599·23	30·35	699·10	35·41	798·97	40·47	898·84	45·53	998·72	50·59	6
57	599·20	30·88	699·07	36·02	798·94	41·17	898·80	46·31	998·67	51·46	3
60	599·18	31·40	699·04	36·63	798·90	41·86	898·76	47·10	998·63	52·34	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

87 Deg.

3 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	99·86	5·23	199·72	10·46	299·59	15·70	399·45	20·93	499·31	26·16	60
3	99·86	5·32	199·71	10·63	299·57	15·96	399·43	21·28	499·29	26·59	57
6	59·85	5·41	199·71	10·81	299·56	16·22	399·41	21·63	499·26	27·03	54
9	99·85	5·49	199·70	10·98	299·55	16·48	399·39	21·98	499·24	27·47	51
12	99·84	5·58	199·69	11·16	299·53	16·74	399·37	22·32	499·22	27·91	48
15	99·84	5·67	199·68	11·33	299·52	17·00	399·35	22·67	499·19	28·34	45
18	99·83	5·76	199·67	11·51	299·50	17·27	399·33	23·02	499·17	28·78	42
21	99·83	5·84	199·66	11·68	299·49	17·53	399·31	23·37	499·14	29·21	39
24	99·82	5·93	199·65	11·86	299·47	17·79	399·29	23·72	499·12	29·65	36
27	99·82	6·02	199·64	12·03	299·45	18·05	399·27	24·07	499·09	30·08	33
30	99·81	6·10	199·63	12·21	299·44	18·31	399·25	24·41	499·06	30·52	30
33	99·81	6·19	199·61	12·38	299·42	18·57	399·23	24·76	499·04	30·95	27
36	99·80	6·28	199·60	12·55	299·41	18·83	399·21	25·11	499·01	31·39	24
39	99·80	6·36	199·59	12·72	299·39	19·09	399·19	25·46	498·98	31·82	21
42	99·79	6·45	199·58	12·90	299·37	19·35	399·16	25·81	498·96	32·26	18
45	99·78	6·54	199·57	13·07	299·36	19·61	399·14	26·16	498·93	32·69	15
48	99·78	6·63	199·56	13·25	299·34	19·88	399·12	26·51	498·90	33·13	12
51	99·77	6·71	199·55	13·42	299·32	20·14	399·09	26·86	498·87	33·56	9
54	99·77	6·80	199·54	13·60	299·30	20·40	399·07	27·20	498·84	34·00	6
57	99·76	6·89	199·52	13·77	299·29	20·66	399·05	27·55	498·81	34·43	3
60	99·75	6·97	199·51	13·95	299·27	20·92	399·02	27·90	498·78	34·87	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

86 Deg.

3 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	599·18	31·40	699·04	36·63	798·90	41·86	898·76	47·10	998·63	52·34	60
3	599·15	31·92	699·01	37·24	798·86	42·56	898·72	47·88	998·58	53·21	57
6	599·12	32·44	698·97	37·85	798·83	43·26	898·68	48·67	998·54	54·08	54
9	599·09	32·96	698·94	38·46	798·79	43·06	898·64	49·45	998·49	54·95	51
12	599·06	33·49	698·91	39·07	798·75	44·65	898·60	50·24	998·44	55·82	48
15	599·03	34·01	698·87	39·68	798·71	45·35	898·55	51·02	998·39	56·69	45
18	599·00	34·54	698·84	40·29	798·67	46·05	898·51	51·80	998·34	57·56	42
21	598·97	35·06	698·80	40·90	798·63	46·75	898·46	52·58	998·29	58·43	39
24	598·94	35·58	698·76	41·51	798·59	47·44	898·41	53·37	998·24	59·31	36
27	598·91	36·10	698·73	42·12	798·55	48·14	898·37	54·15	998·18	60·18	33
30	598·88	36·63	698·69	42·73	798·51	48·84	898·32	54·94	998·13	61·05	30
33	598·85	37·15	698·65	43·34	798·46	49·54	898·27	55·72	998·08	61·92	27
36	598·81	37·67	698·62	43·95	798·42	50·23	898·22	56·51	998·02	62·79	24
39	598·78	38·19	698·58	44·56	798·38	50·93	898·17	57·29	997·97	63·66	21
42	598·75	38·72	698·54	45·17	798·33	51·62	898·12	58·08	997·91	64·53	18
45	598·71	39·24	698·50	45·78	798·28	52·32	898·07	58·86	997·86	65·40	15
48	598·68	39·76	698·46	46·39	798·24	53·01	898·02	59·64	997·80	66·27	12
51	598·64	40·28	698·42	47·00	798·19	53·71	897·97	60·42	997·74	67·14	9
54	598·61	40·81	698·38	47·61	798·15	54·41	897·92	61·21	997·68	68·01	6
57	598·57	41·33	698·33	48·22	798·10	55·11	897·86	61·99	997·62	68·88	3
60	598·54	41·85	698·29	48·83	798·05	55·80	897·81	62·78	997·56	69·75	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

86 Deg.

4 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dis
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.
	Per	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.
0	99·75	6·97	199·51	13·95	299·27	20·92	399·02	27·90	498·7
3	99·75	7·06	199·50	14·12	299·25	21·18	399·00	28·25	498·7
6	99·74	7·15	199·49	14·30	299·23	21·45	398·97	28·60	498·7
9	99·74	7·24	199·47	14·47	299·21	21·71	398·95	28·95	498·6
12	99·73	7·32	199·46	14·64	299·19	21·97	398·92	29·30	498·6
15	99·72	7·41	199·45	14·81	299·17	22·23	398·90	29·65	498·6
18	99·72	7·50	199·43	14·99	299·15	22·49	398·87	29·99	498·5
21	99·71	7·58	199·42	15·17	299·13	22·75	398·85	30·34	498·5
24	99·70	7·67	199·41	15·34	299·11	23·01	398·82	30·68	498·5
27	99·70	7·76	199·39	15·51	299·09	23·27	398·79	31·03	498·4
30	99·69	7·85	199·38	15·69	299·07	23·53	398·76	31·38	498·4
33	99·68	7·93	199·37	15·86	299·05	23·79	398·74	31·73	498·4
36	99·68	8·02	199·35	16·03	299·03	24·06	398·71	32·08	498·3
39	99·67	8·11	199·34	16·20	299·01	24·32	398·68	32·43	498·3
42	99·66	8·19	199·33	16·38	298·99	24·58	398·65	32·77	498·3
45	99·65	8·28	199·31	16·55	298·97	24·84	398·62	33·12	498·2
48	99·65	8·37	199·30	16·73	298·95	25·10	398·60	33·47	498·2
51	99·64	8·45	199·28	16·90	298·92	25·36	398·57	33·82	498·2
54	99·63	8·54	199·27	17·08	298·90	25·62	398·54	34·16	498·1
57	99·63	8·63	199·25	17·25	298·88	25·88	398·51	34·51	498·1
60	99·62	8·71	199·24	17·43	298·86	26·14	398·48	34·86	498·1
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dis

85 Deg.

4 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	598·54	41·85	698·29	48·83	798·05	55·80	897·81	62·78	997·56	69·75	60
3	598·50	42·37	698·25	49·44	798·00	56·50	897·75	63·56	997·50	70·63	57
6	598·46	42·90	698·21	50·05	797·95	57·19	897·70	64·34	997·44	71·50	54
9	598·42	43·42	698·16	50·66	797·90	57·89	897·64	65·12	997·37	72·37	51
12	598·39	43·94	698·12	51·27	797·85	58·59	897·58	65·91	997·31	73·24	48
15	598·35	44·46	698·07	52·88	797·80	59·29	897·53	66·69	997·25	74·11	45
18	598·31	44·98	698·03	52·49	797·75	59·98	897·47	67·47	997·18	74·98	42
21	598·27	45·50	697·98	53·10	797·69	60·68	897·41	68·25	997·12	75·85	39
24	598·23	46·03	697·94	53·70	797·64	61·37	897·35	69·04	997·05	76·72	36
27	598·19	46·55	697·89	54·31	797·59	62·07	897·29	70·82	996·98	77·59	33
30	598·15	47·07	697·84	54·92	797·53	62·77	897·23	70·61	996·92	78·46	30
33	598·11	47·60	697·79	55·33	797·48	63·47	897·16	71·39	996·85	79·33	27
36	598·06	48·12	697·74	56·14	797·42	64·16	897·10	72·18	996·78	80·20	24
39	598·02	48·64	697·70	56·75	797·36	64·86	897·04	72·96	996·71	81·07	21
42	597·98	49·16	697·65	57·35	797·31	65·55	896·97	73·75	996·64	81·94	18
45	597·94	49·68	697·59	57·96	797·25	66·25	896·91	74·53	996·56	82·81	15
48	597·89	50·20	697·54	58·57	797·19	66·94	896·84	75·31	996·49	83·68	12
51	597·85	50·72	697·49	59·18	797·13	67·64	896·78	76·09	996·42	84·55	9
54	597·80	51·25	697·44	59·79	797·07	68·33	896·71	76·87	996·34	85·42	6
57	597·76	51·77	697·39	60·40	797·01	69·03	896·64	77·65	996·27	86·29	3
60	597·72	52·29	697·33	61·01	796·95	69·72	896·58	78·44	996·19	87·15	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

85 Deg.

5 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	99·62	8·71	199·24	17·43	298·86	26·14	398·48	34·86	498·10	43·58	60
3	99·61	8·80	199·22	17·60	298·83	26·40	398·45	35·21	498·06	44·01	57
6	99·60	8·89	199·21	17·78	298·81	26·66	398·41	35·56	498·02	44·45	54
9	99·60	8·98	199·19	17·95	298·79	26·92	398·38	35·91	497·98	44·88	51
12	99·59	9·06	199·18	18·12	298·76	27·19	398·35	36·25	497·94	45·31	48
15	99·58	9·15	199·16	18·29	298·74	27·45	398·32	36·60	497·90	45·74	45
18	99·57	9·24	199·14	18·47	298·72	27·71	398·29	36·95	497·86	46·18	42
21	99·56	9·32	199·13	18·64	298·69	27·97	398·26	37·30	497·82	46·61	39
24	99·55	9·41	199·11	18·82	298·67	28·23	398·22	37·64	497·78	47·05	36
27	99·55	9·50	199·09	18·99	298·64	28·49	398·19	37·99	497·74	47·48	33
30	99·54	9·58	199·08	19·17	298·62	28·75	398·16	38·34	497·70	47·92	30
33	99·53	9·67	199·06	19·34	298·59	29·01	398·12	38·69	497·66	48·35	27
36	99·52	9·76	199·04	19·52	298·57	29·27	398·09	39·03	497·61	48·79	24
39	99·51	9·84	199·03	19·69	298·54	29·53	398·06	39·38	497·57	49·22	21
42	99·50	9·93	199·01	19·86	298·52	29·79	398·02	39·73	497·53	49·66	18
45	99·50	10·02	198·99	20·03	298·49	30·05	397·99	40·08	497·48	50·09	15
48	99·49	10·10	198·97	20·21	298·46	30·31	397·95	40·42	497·44	50·53	12
51	99·48	10·19	198·96	20·38	298·44	30·57	397·92	40·77	497·40	50·96	9
54	99·47	10·28	198·94	20·55	298·41	30·83	397·88	41·12	497·35	51·40	6
57	99·46	10·36	198·92	20·72	298·38	31·09	397·84	41·47	497·31	51·83	3
60	99·45	10·45	198·90	20·90	298·36	31·36	397·81	41·81	497·26	52·26	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

84 Deg.

5 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	597·72	52·29	697·33	61·01	796·95	69·72	896·58	78·44	996·19	87·15	60
3	597·67	52·81	697·28	61·62	796·89	70·42	896·51	79·22	996·11	88·02	57
6	597·62	53·33	697·23	62·22	796·83	71·11	896·44	80·01	996·04	88·89	54
9	597·58	53·85	697·17	62·83	796·77	71·81	896·37	80·79	995·96	89·76	51
12	597·53	54·38	697·12	63·44	796·70	72·50	896·30	81·57	995·88	90·63	48
15	597·48	55·90	697·06	64·05	796·64	73·20	896·22	82·35	995·80	91·50	45
18	597·43	55·42	697·00	64·66	796·58	73·89	896·15	83·13	995·72	92·37	42
21	597·39	55·94	696·95	65·27	796·51	74·59	896·08	83·91	995·64	93·24	39
24	597·33	56·46	696·89	65·87	796·45	75·28	896·01	84·70	995·56	94·11	36
27	597·29	56·98	696·83	66·48	796·38	75·98	895·93	85·48	995·48	94·98	33
30	597·24	57·51	696·78	67·09	796·32	76·68	895·86	86·26	995·39	95·84	30
33	597·19	58·03	696·72	67·70	796·25	77·38	895·78	87·04	995·31	96·71	27
36	597·13	58·55	696·66	68·31	796·18	78·07	895·70	87·82	995·23	97·58	24
39	597·08	59·07	696·60	68·92	796·11	78·77	895·63	88·60	995·14	98·45	21
42	597·03	59·59	696·54	69·52	796·04	79·46	895·55	89·38	995·05	99·32	18
45	596·98	60·11	696·48	70·13	795·97	80·15	895·47	90·16	994·97	100·19	15
48	596·93	60·63	696·42	70·74	795·90	80·84	895·39	90·95	994·88	101·05	12
51	596·87	61·15	696·35	71·35	795·83	81·54	895·31	91·73	994·79	101·92	9
54	596·82	61·67	696·29	71·95	795·76	82·23	895·23	92·51	994·70	102·79	6
57	596·77	62·19	696·23	72·56	795·69	82·93	895·15	93·29	994·61	103·66	3
60	596·71	62·71	696·16	73·17	795·62	83·62	895·07	94·07	994·52	104·53	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

84 Deg.

6 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist.
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.
0	99·45	10·45	198·90	20·90	298·36	31·36	397·81	41·81	497·26
3	99·44	10·54	198·88	21·07	298·33	31·62	397·77	42·16	497·21
6	99·43	10·62	198·87	21·25	298·30	31·88	397·73	42·50	497·17
9	99·42	10·71	198·85	21·42	298·27	32·14	397·70	42·85	497·12
12	99·41	10·80	198·83	21·60	298·24	32·40	397·66	43·20	497·07
15	99·40	10·89	198·81	21·77	298·21	32·66	397·62	43·55	497·03
18	99·39	10·97	198·79	21·95	298·19	32·92	397·58	43·89	496·98
21	99·38	11·06	198·77	22·12	298·16	33·18	397·54	44·24	496·93
24	99·37	11·15	198·75	22·29	298·13	33·44	397·51	44·59	496·88
27	99·36	11·23	198·73	22·46	298·10	33·70	397·47	44·94	496·83
30	99·35	11·32	198·71	22·64	298·07	33·96	397·43	45·28	496·78
33	99·34	11·41	198·69	22·81	298·04	34·22	397·39	45·63	496·73
36	99·33	11·49	198·67	22·98	298·01	34·48	397·35	45·97	496·68
39	99·32	11·58	198·65	23·15	297·98	34·74	397·31	46·32	496·63
42	99·31	11·67	198·63	23·33	297·95	35·00	397·27	46·67	496·58
45	99·30	11·75	198·61	23·50	297·92	35·26	397·23	47·02	496·53
48	99·29	11·84	198·59	23·68	297·89	35·52	397·18	47·36	496·48
51	99·28	11·93	198·57	23·85	297·86	35·78	397·14	47·71	496·43
54	99·27	12·01	198·55	24·03	297·83	36·04	397·10	48·05	496·38
57	99·26	12·10	198·53	24·20	297·79	36·30	397·06	48·40	496·33
60	99·25	12·19	198·51	24·38	297·76	36·56	397·02	48·75	496·27
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist.

83 Deg.

6 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	596·71	62·71	696·16	73·17	795·62	83·62	895·07	94·07	994·52	104·53	60
3	596·66	63·23	696·10	73·78	795·54	84·31	894·99	94·85	994·43	105·39	57
6	596·60	63·76	696·04	74·38	795·47	85·01	894·90	95·63	994·34	106·26	54
9	596·55	64·28	695·97	74·99	795·39	85·70	894·82	96·41	994·24	107·13	51
12	596·49	64·80	695·90	75·60	795·32	86·40	894·74	97·20	994·15	108·00	48
15	596·43	65·32	695·84	76·21	795·24	87·09	894·65	97·98	994·05	108·87	45
18	596·37	65·84	695·77	76·81	795·17	87·79	894·56	98·76	993·96	109·73	42
21	596·32	66·36	695·70	77·42	795·09	88·48	894·48	99·54	993·86	110·60	39
24	596·26	66·88	695·64	78·03	795·01	89·17	894·39	100·32	993·77	111·47	36
27	596·20	67·40	695·57	78·64	794·93	89·86	894·30	101·10	993·67	112·33	33
30	596·14	67·92	695·50	79·24	794·86	90·56	894·21	101·88	993·57	113·20	30
33	596·08	68·44	695·43	79·85	794·77	91·25	894·12	102·66	993·47	114·07	27
36	596·02	68·96	695·36	80·46	794·69	91·95	894·03	103·44	993·37	114·94	24
39	595·96	69·48	695·29	81·07	794·61	92·65	893·94	104·22	993·27	115·80	21
42	595·90	70·00	695·22	81·67	794·53	93·34	893·85	105·00	993·17	116·67	18
45	595·84	70·52	695·14	82·28	794·45	94·03	893·76	105·78	993·07	117·54	15
48	595·78	71·04	695·07	82·88	794·37	94·72	893·67	106·56	992·96	118·40	12
51	595·72	71·56	695·00	83·49	794·29	95·42	893·57	107·34	992·86	119·27	9
54	595·65	72·08	694·93	84·10	794·20	96·11	893·48	108·12	992·76	120·13	6
57	595·59	72·60	694·85	84·71	794·12	96·80	893·38	108·90	992·65	121·00	3
60	595·53	73·12	694·78	85·31	794·03	97·50	893·29	109·68	992·54	121·87	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

83 Deg.

7 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base	
0	99·25	12·19	198·51	24·38	297·76	36·56	397·02	48·75	496·27	60·93	60
3	99·24	12·27	198·49	24·55	297·73	36·82	396·97	49·10	496·22	61·37	57
6	99·23	12·36	198·46	24·72	297·70	37·08	396·93	49·44	496·17	61·80	54
9	99·22	12·45	198·44	24·90	297·67	37·34	396·89	49·79	496·11	62·23	51
12	99·21	12·53	198·42	25·07	297·63	37·60	396·84	50·13	496·06	62·67	48
15	99·20	12·62	198·40	25·24	297·60	37·86	396·80	50·48	496·00	63·10	45
18	99·19	12·71	198·38	25·42	297·57	38·12	396·76	50·83	495·95	63·53	42
21	99·18	12·79	198·36	25·59	297·53	38·38	396·71	51·17	495·89	63·97	39
24	99·17	12·88	198·33	25·76	297·50	38·64	396·67	51·52	495·83	64·40	36
27	99·15	12·97	198·31	25·93	297·47	38·90	396·62	51·87	495·78	64·83	33
30	99·13	13·05	198·28	26·11	297·43	39·16	396·58	52·21	495·72	65·26	30
33	99·12	13·14	198·26	26·28	297·40	39·42	396·53	52·56	495·66	65·70	27
36	99·11	13·22	198·24	26·45	297·36	39·68	396·48	52·90	495·61	66·13	24
39	99·10	13·31	198·22	26·63	297·33	39·94	396·44	53·25	495·55	66·56	21
42	99·09	13·40	198·20	26·80	297·29	40·20	396·39	53·60	495·49	66·99	18
45	99·07	13·48	198·17	26·97	297·26	40·46	396·35	53·94	495·43	67·42	15
48	99·06	13·57	198·15	27·14	297·22	40·72	396·30	54·29	495·37	67·86	12
51	99·05	13·66	198·12	27·32	297·19	40·98	396·25	54·63	495·31	68·29	9
54	99·04	13·74	198·10	27·49	297·15	41·23	396·20	54·98	495·25	68·72	6
57	99·03	13·83	198·08	27·66	297·12	41·49	396·15	55·32	495·19	69·15	3
60	99·02	13·92	198·05	27·84	297·08	41·75	396·11	55·67	495·13	69·59	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

82 Deg.

7 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	595·53	73·12	694·78	85·31	794·03	97·50	893·29	109·68	992·54	121·87	60
3	595·46	73·64	694·71	85·92	793·95	98·19	893·19	110·46	992·44	122·73	57
6	595·40	74·16	694·63	86·52	793·86	98·88	893·10	111·24	992·33	123·60	54
9	595·33	74·68	694·55	87·13	793·78	99·57	893·00	112·02	992·22	124·47	51
12	595·27	75·20	694·48	87·73	793·69	100·27	892·90	112·80	992·11	125·33	48
15	595·20	75·72	694·40	88·34	793·60	100·96	892·80	113·58	992·00	126·20	45
18	595·13	76·24	694·32	88·94	793·51	101·65	892·70	114·36	991·89	127·06	42
21	595·07	76·76	694·25	89·55	793·42	102·34	892·60	115·14	991·78	127·93	39
24	595·00	77·28	694·17	90·16	793·33	103·04	892·50	115·92	991·67	128·79	36
27	594·93	77·80	694·09	90·76	793·24	103·73	892·40	116·69	991·56	129·66	33
30	594·86	78·32	694·01	91·37	793·15	104·42	892·30	117·47	991·44	130·52	30
33	594·80	78·83	693·93	91·97	793·06	105·11	892·20	118·25	991·33	131·39	27
36	594·73	79·35	693·85	92·58	792·97	105·80	892·09	119·03	991·21	132·26	24
39	594·66	79·87	693·77	93·19	792·88	106·50	891·99	119·81	991·10	133·12	21
42	594·59	80·39	693·69	93·79	792·78	107·19	891·88	120·59	990·98	133·98	18
45	594·52	80·91	693·60	94·40	792·69	107·88	891·78	121·36	990·86	134·85	15
48	594·45	81·43	693·52	95·00	792·60	108·57	891·67	122·14	990·75	135·71	12
51	594·38	81·95	693·44	95·60	792·50	109·26	891·56	122·92	990·63	136·58	9
54	594·30	82·47	693·35	96·21	792·41	109·95	891·46	123·70	990·51	137·44	6
57	594·23	82·99	693·27	96·82	792·31	110·65	891·35	124·48	990·39	138·31	3
60	594·16	83·50	693·18	97·42	792·21	111·34	891·24	125·26	990·27	139·17	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

82 Deg.

8 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	99·02	13·92	198·05	27·84	297·08	41·75	396·11	55·67	495·13	69·59	60
3	99·01	14·00	198·03	28·01	297·04	42·01	396·06	56·02	495·07	70·02	57
6	99·00	14·09	198·00	28·18	297·01	42·27	396·01	56·36	495·01	70·45	54
9	98·99	14·18	197·98	28·36	296·97	42·53	395·96	56·71	494·95	70·88	51
12	98·98	14·26	197·95	28·53	296·93	42·79	395·91	57·05	494·89	71·31	48
15	98·96	14·35	197·93	28·70	296·89	43·05	395·86	57·40	494·82	71·75	45
18	98·95	14·43	197·90	28·87	296·86	43·31	395·81	57·74	494·76	72·18	42
21	98·94	14·52	197·88	29·05	296·82	43·57	395·76	58·09	494·70	72·61	39
24	98·93	14·61	197·85	29·22	296·78	43·83	395·71	58·44	494·63	73·04	36
27	98·91	14·69	197·83	29·39	296·74	44·08	395·66	58·78	494·57	73·47	33
30	98·90	14·78	197·80	29·57	296·70	44·34	395·61	59·12	494·51	73·90	30
33	98·89	14·87	197·78	29·74	296·66	44·60	395·55	59·47	494·44	74·34	27
36	98·87	14·95	197·75	29·91	296·63	44·86	395·50	59·81	494·38	74·77	24
39	98·86	15·04	197·72	30·08	296·59	45·12	395·45	60·16	494·31	75·20	21
42	98·85	15·13	197·70	30·25	296·55	45·38	395·40	60·51	494·25	75·63	18
45	98·84	15·21	197·67	30·43	296·51	45·64	395·34	60·85	494·18	76·06	15
48	98·82	15·30	197·64	30·60	296·47	45·90	395·29	61·19	494·11	76·49	12
51	98·81	15·38	197·62	30·77	296·43	46·16	395·24	61·54	494·05	76·92	9
54	98·79	15·47	197·59	30·94	296·39	46·41	395·18	61·88	493·98	77·36	6
57	98·78	15·56	197·56	31·12	296·35	46·67	395·13	62·23	493·91	77·79	3
60	98·77	15·64	197·54	31·29	296·30	46·93	395·07	62·57	493·84	78·22	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

81 Deg.

8 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	594·16	83·50	693·18	97·42	792·21	111·34	891·24	125·26	990·27	139·17	60
3	594·09	84·02	693·10	98·03	792·11	112·03	891·13	126·03	990·14	140·04	57
6	594·01	84·54	693·01	98·63	792·02	112·72	891·02	126·81	990·02	140·90	54
9	593·94	85·06	692·93	99·24	791·92	113·41	890·91	127·59	989·90	141·76	51
12	593·86	85·58	692·84	99·84	791·82	114·10	890·80	128·37	989·77	142·63	48
15	593·79	86·09	692·75	100·44	791·72	114·79	890·69	129·14	989·65	143·49	45
18	593·71	86·61	692·67	101·05	791·62	115·48	890·57	129·92	989·52	144·36	42
21	593·64	87·13	692·58	101·65	791·52	116·17	890·46	130·70	989·40	145·22	39
24	593·56	87·65	692·49	102·26	791·42	116·86	890·34	131·47	989·27	146·08	36
27	593·48	88·17	692·40	102·86	791·31	117·56	890·23	132·25	989·14	146·94	33
30	593·41	88·69	692·31	103·47	791·21	118·25	890·11	133·03	989·01	147·81	30
33	593·33	89·20	692·22	104·07	791·11	118·94	890·00	133·80	988·88	148·67	27
36	593·25	89·72	692·13	104·67	791·00	119·63	889·88	134·58	988·75	149·53	24
39	593·17	90·24	692·04	105 28	790·90	120·32	889·76	135·36	988·62	150·40	21
42	593·09	90·76	691·95	105·88	790·80	121·01	889·64	136·13	988·49	151·26	18
45	593·02	91·27	691·85	106·48	790·69	121·70	889·52	136·91	988·36	152·12	15
48	592·94	91·79	691·76	107·09	790·58	122·39	889·41	137·69	988·23	152·98	12
51	592·86	92·31	691·66	107·69	790·47	123·08	889·28	138·46	988·09	153·85	9
54	592·77	92·83	691·57	108·30	790·37	123·77	889·16	139·24	987·96	154·71	6
57	592·69	93·34	691·47	108·90	790·26	124·46	889·04	140·01	987·82	155·57	3
60	592·61	93·86	691·38	109·50	790·15	125·15	888·92	140·79	987·69	156·43	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

81 Deg.

9 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	98·77	15·64	197·54	31·29	296·30	46·93	395·07	62·57	493·84	78·22	60
3	98·75	15·73	197·51	31·46	296·26	47·19	395·02	62·92	493·77	78·65	57
6	98·74	15·81	197·48	31·63	296·22	47·45	394·96	63·26	493·71	79·08	54
9	98·73	15·90	197·45	31·81	296·18	47·71	394·91	63·61	493·64	79·51	51
12	98·71	15·99	197·43	31·98	296·14	47·96	394·85	63·95	493·57	79·94	48
15	98·70	16·07	197·39	32·15	296·10	48·22	394·80	64·30	493·50	80·37	45
18	98·68	16·16	197·37	32·32	296·06	48·48	394·74	64·64	493·43	80·80	42
21	98·67	16·25	197·34	32·50	296·01	48·75	394·68	64·99	493·36	81·23	39
24	98·66	16·33	197·31	32·67	295·97	49·00	394·63	65·33	493·28	81·66	36
27	98·64	16·42	197·28	32·84	295·93	49·25	394·57	65·68	493·21	82·09	33
30	98·63	16·50	197·26	33·01	295·88	49·52	394·51	66·02	493·14	82·52	30
33	98·61	16·59	197·23	33·18	295·84	49·77	394·46	66·36	493·07	82·95	27
36	98·60	16·68	197·20	33·36	295·80	50·03	394·40	66·71	493·00	83·38	24
39	98·58	16·76	197·17	33·53	295·75	50·29	394·34	67·05	492·92	83·81	21
42	98·57	16·85	197·14	33·70	295·71	50·55	394·28	67·40	492·85	84·24	18
45	98·55	16·93	197·11	33·87	295·67	50·81	394·22	67·74	492·78	84·67	15
48	98·54	17·02	197·08	34·04	295·62	51·06	394·16	68·08	492·70	85·10	12
51	98·52	17·11	197·05	34·22	295·58	51·32	394·10	68·43	492·63	85·53	9
54	98·51	17·19	197·02	34·39	295·53	51·58	394·04	68·77	492·55	85·96	6
57	98·49	17·28	196·99	34·56	295·49	51·84	393·98	69·12	492·48	86·39	3
60	98·48	17·36	196·96	34·73	295·44	52·09	393·92	69·46	492·40	86·82	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

80 Deg.

9 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	592·61	93·86	691·38	109·50	790·15	125·15	888·92	140·79	987·69	156·43	60
3	592·53	94·38	691·28	110·11	790·04	125·84	888·80	141·57	987·55	157·30	57
6	592·45	94·89	691·19	110·71	789·93	126·53	888·67	142·34	987·41	158·16	54
9	592·37	95·41	691·09	111·31	789·82	127·21	888·55	143·12	987·27	159·02	51
12	592·28	95·93	690·99	111·92	789·71	127·90	888·42	143·80	987·14	159·88	48
15	592·20	96·45	690·90	112·52	789·60	128·59	888·30	144·67	987·00	160·74	45
18	592·11	96·96	690·80	113·12	789·48	129·28	888·17	145·44	986·85	161·60	42
21	592·03	97·48	690·70	113·72	789·37	129·97	888·04	146·22	986·71	162·46	39
24	591·94	97·99	690·60	114·33	789·26	130·66	887·91	147·00	986·57	163·32	36
27	591·86	98·51	690·50	114·93	789·14	131·35	887·79	147·77	986·43	164·19	33
30	591·77	99·03	690·40	115·53	789·03	132·04	887·66	148·54	986·28	165·05	30
33	591·68	99·54	690·30	116·14	788·91	132·73	887·53	149·32	986·14	165·91	27
36	591·60	100·06	690·20	116·74	788·80	133·41	887·40	150·09	986·00	166·77	24
39	591·51	100·58	690·09	117·34	788·68	134·10	887·27	150·87	985·85	167·63	21
42	591·42	101·09	689·99	117·94	788·56	134·79	887·13	151·64	985·70	168·49	18
45	591·33	101·61	689·89	118·54	788·44	135·48	887·00	152·41	985·55	169·35	15
48	591·24	102·12	689·79	119·15	788·32	136·17	886·86	153·19	985·41	170·21	12
51	591·15	102·64	689·68	119·75	788·21	136·85	886·73	153·96	985·26	171·07	9
54	591·06	103·16	689·58	120·35	788·09	137·54	886·60	154·74	985·11	171·93	6
57	590·97	103·67	689·47	120·95	787·97	138·23	886·46	155·51	984·96	172·79	3
60	590·88	104·19	689·36	121·55	787·84	138·92	886·33	156·28	984·81	173·65	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

80 Deg.

10 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	98·48	17·36	196·96	34·73	295·44	52·09	393·92	69·46	492·40	86·82	60
3	98·46	17·45	196·93	34·90	295·40	52·35	393·86	69·80	492·33	87·25	57
6	98·45	17·54	196·90	35·08	295·35	52·61	393·80	70·15	492·25	87·68	54
9	98·43	17·62	196·87	35·25	295·30	52·87	393·74	70·49	492·17	88·11	51
12	98·42	17·71	196·84	35·42	295·26	53·13	393·68	70·83	492·10	88·54	48
15	98·40	17·80	196·81	35·59	295·21	53·38	393 62	71·18	492·02	88·97	45
18	98·39	17·88	196·78	35·76	295·17	53·64	393·55	71·52	491·94	89·40	42
21	98·37	17·97	196·75	35·93	295·12	53·90	393·49	71·86	491·86	89·83	39
24	98·36	18·05	196·71	36·11	295·07	54·16	393·43	72·21	491·78	90·26	36
27	98·34	18·14	196·68	36·28	295·02	54·41	393·36	72·55	491·71	90·69	33
30	98·32	18·23	196·65	36·45	294·97	54·67	393·30	72·89	491·63	91·12	30
33	98·31	18·31	196·62	36·62	294·93	54·93	393·24	73·24	491·55	91·55	27
36	98·29	18·40	196·59	36·79	294·88	55·19	393·17	73·58	491·47	91·98	24
39	98·28	18·49	196·55	36·96	294·83	55·44	393·11	73·92	491·39	92·40	21
42	98·26	18·57	196·52	37·13	294·78	55·70	393·04	74·27	491·31	92·83	18
45	98·24	18·66	196·49	37·30	294·73	55·96	392·98	74·61	491·22	93·26	15
48	98·23	18·74	196·46	37·48	294·68	56·21	392·91	74·95	491·14	93·69	12
51	98·21	18·83	196·42	37·65	294·63	56·47	392·85	75·30	491·06	94·12	9
54	98·19	18·91	196·39	37·82	294·58	56·73	392·78	75·64	490·98	94·55	6
57	98·18	19·00	196·36	37·99	294·53	56·99	392·72	75·98	490·90	94·98	3
60	98·16	19·08	196·32	38·16	294·48	57·24	392·65	76·32	490·81	95·40	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Minutes.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

79 Deg.

10 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	590·88	104·19	689·36	121·55	787·84	138·92	886·33	156·28	984·81	173·65	60
3	590·79	104·70	689·26	122·15	787·72	139·60	886·19	157·06	984·65	174·51	57
6	590·70	105·22	689·15	122·76	787·60	140·29	886·05	157·83	984·50	175·37	54
9	590·61	105·73	689·04	123·36	787·48	140·98	885·91	158·60	984·35	176·22	51
12	590·52	106·25	688·94	123·96	787·36	141·67	885·78	159·38	984·19	177·08	48
15	590·42	106·76	688·83	124·56	787·23	142·35	885·64	160·15	984·04	177·94	45
18	590·33	107·28	688·72	125·16	787·11	143·04	885·50	160·92	983·88	178·80	42
21	590·23	107·79	688·61	125·76	786·98	143·73	885·35	161·69	983·73	179·66	39
24	590·14	108·31	688·50	126·36	786·86	144·41	885·21	162·47	983·57	180·52	36
27	590·04	108·83	688·39	126·96	786·73	145·10	885·07	163·24	983·41	181·38	33
30	589·95	109·34	688·28	127·56	786·60	145·79	884·93	164·01	983·25	182·23	30
33	589·85	109·86	688·17	128·16	786·48	146·47	884·79	164·78	983·09	183·09	27
36	589·76	110·37	688·05	128·76	786·35	147·16	884·64	165·56	982·94	183·95	24
39	589·66	110·89	687·94	129·36	786·22	147·85	884·50	166·33	982·77	184·81	21
42	589·56	111·40	687·83	129·96	786·09	148·53	884·35	167·10	982·61	185·67	18
45	589·47	111·91	687·71	130·56	785·96	149·22	884·21	167·87	982·45	186·52	15
48	589·37	112·43	687·60	131·17	785·83	149·90	884·06	168·64	982·29	187·38	12
51	589·27	112·94	687·48	131·77	785·70	150·59	883·91	169·41	982·12	188·24	9
54	589·17	113·46	687·37	132·37	785·57	151·28	883·76	170·19	981·96	189·09	6
57	589·07	113·97	687·25	132·97	785·43	151·96	883·61	170·96	981·79	189·95	3
60	588·97	114·48	687·14	133·57	785·30	152·65	883·46	171·73	981·62	190·81	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

79 Deg.

11 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	98·16	19·08	196·32	38·16	294·48	57·24	392·65	76·32	490·81	95·40	60
3	98·14	19·16	196·29	38·33	294·43	57·50	392·58	76·66	490·73	95·83	57
6	98·13	19·25	196·26	38·51	294·39	57·76	392·52	77·01	490·64	96·26	54
9	98·11	19·34	196·22	38·68	294·34	58·01	392·45	77·35	490·56	96·69	51
12	98·09	19·42	196·19	38·85	294·28	58·27	392·38	77·69	490·48	97·12	48
15	98·08	19·51	196·16	39·02	294·23	58·53	392·31	78·04	490·39	97·54	45
18	98·06	19·59	196·12	39·19	294·18	58·78	392·24	78·38	490·31	97·97	42
21	98·04	19·68	196·09	39·36	294·13	59·04	392·18	78·72	490·22	98·40	39
24	98·02	19·76	196·05	39·53	294·08	59·30	392·11	79·06	490·13	98·83	36
27	98·00	19·85	196·02	39·70	294·03	59·55	392·04	79·40	490·05	99·26	33
30	97·99	19·94	195·98	39·88	293·98	59·81	391·97	79·75	489·96	99·68	30
33	97·97	20·02	195·95	40·05	293·92	60·06	391·90	80·09	489·87	100·11	27
36	97·95	20·11	195·91	40·22	293·87	60·32	391·83	80·43	489·79	100·54	24
39	97·94	20·19	195·88	40·39	293·82	60·58	391·76	80·77	489·70	100·96	21
42	97·92	20·28	195·84	40·56	293·77	60·84	391·69	81·11	489·61	101·39	18
45	97·90	20·36	195·81	40·73	293·71	61·09	391·62	81·45	489·52	101·82	15
48	97·89	20·45	195·77	40·90	293·66	61·35	391·54	81·80	489·43	102·25	12
51	97·87	20·53	195·74	41·07	293·61	61·61	391·47	82·14	489·34	102·68	9
54	97·85	20·62	195·70	41·24	293·55	61·86	391·40	82·48	489·25	103·10	6
57	97·83	20·71	195·66	41·14	293·50	62·12	391·33	82·82	489·16	103·53	3
60	97·81	20·79	195·63	41·58	293·44	62·37	391·26	83·16	489·07	103·95	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Minutes.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

78 Deg.

11 Deg.

Minutes.	Dist. 600. Lat. Per.	Dist. 600. Dep. Base.	Dist. 700. Lat. Per.	Dist. 700. Dep. Base.	Dist. 800. Lat. Per.	Dist. 800. Dep. Base.	Dist. 900. Lat. Per.	Dist. 900. Dep. Base.	Dist. 1000. Lat. Per.	Dist. 1000. Dep. Base.	
0	588·97	114·48	687·14	133·57	785·30	152·65	883·46	171·73	981·62	190·81	60
3	588·87	115·00	687·02	134·17	785·17	153·33	883·31	172·50	981·46	191·66	57
6	588·77	115·51	686·90	134·76	785·03	154·08	883·16	173·27	981·29	192·52	54
9	588·67	116·03	686·79	135·36	784·90	154·70	883·01	174·04	981·12	193·38	51
12	588·57	116·54	686·67	135·96	784·76	155·40	882·86	174·81	980·95	194·23	48
15	583·47	117·05	686·55	136·56	784·63	156·09	882·71	175·58	980·78	195·09	45
18	588·37	117·57	686·43	137·16	784·49	156·76	882·55	176·35	980·61	195·95	42
21	588·27	118·08	686·31	137·76	784·35	157·44	882·40	177·12	980·44	196·80	39
24	588·16	118·59	686·19	138·36	784·22	158·13	882·24	177·89	980·27	197·66	36
27	588·06	119·11	686·07	138·96	784·08	158·81	882·09	178·66	980·10	198·51	33
30	587·95	119·62	685·95	139·56	783·94	159·49	881·93	179·42	979·92	199·37	30
33	587·85	120·13	685·82	140·16	783·80	160·18	881·77	180·19	979·75	200·22	27
36	587·74	120·65	685·70	140·75	783·66	160·86	881·62	180·97	979·57	201·08	24
39	587·64	121·16	685·58	141·35	783·52	161·55	881·46	181·74	979·40	201·93	21
42	587·53	121·67	685·45	141·95	783·38	162·23	881·30	182·51	979·22	202·79	18
45	587·42	122·18	685·33	142·55	783·23	162·91	881·14	183·28	979·04	203·64	15
48	587·32	122·70	685·21	143·15	783·09	163·60	880·98	184·05	978·86	204·49	12
51	587·21	123·21	685·08	143·74	782·95	164·28	880·82	184·82	978·69	205·35	9
54	587·10	123·72	684·95	144·34	782·81	164·96	880·66	185·58	978·51	206·20	6
57	587·00	124·23	684·83	144·94	782·66	165·65	880·49	186·35	978·33	207·06	3
60	586·89	124·75	684·70	145·54	782·52	166·33	880·33	187·12	978·15	207·91	0
	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Minutes.
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

78 Deg.

12 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	97·81	20·79	195·63	41·58	293·44	62·37	391·26	83·16	489·07	103·95	60
3	97·80	20·88	195·59	41·76	293·39	62·63	391·18	83·51	488·98	104·38	57
6	97·78	20·96	195·56	41·92	293·33	62·87	391·11	83·85	488·89	104·81	54
9	97·76	21·05	195·52	42·10	293·28	63·14	391·04	84·19	488·80	105·24	51
12	97·74	21·13	195·48	42·27	293·22	63·40	390·96	84·53	488·71	105·66	48
15	97·72	21·22	195·44	42·44	293·17	63·66	390·89	84·87	488·61	106·09	45
18	97·70	21·30	195·41	42·61	293·11	63·91	390·82	85·21	488·52	106·51	42
21	97·68	21·39	195·37	42·78	293·06	64·17	390·74	85·55	488·43	106·94	39
24	97·67	21·47	195·33	42·95	293·00	64·42	390·67	85·89	488·33	107·37	36
27	97·65	21·56	195·30	43·12	292·94	64·68	390·59	86·24	488·24	107·79	33
30	97·63	21·64	195·26	43·29	292·89	64·93	390·52	86·58	488·15	108·22	30
33	97·61	21·73	195·22	43·46	292·83	65·19	390·44	86·92	488·05	108·64	27
36	97·59	21·81	195·18	43·63	292·77	65·44	390·37	87·26	487·96	109·07	24
39	97·57	21·90	195·14	43·80	292·72	65·70	390·29	87·60	487·86	109·50	21
42	97·55	21·98	195·11	43·97	292·66	65·95	390·21	87·94	487·77	109·93	18
45	97·53	22·07	195·07	44·14	292·60	66·21	390·14	88·28	487·67	110·35	15
48	97·51	22·15	195·03	44·31	292·54	66·47	390·06	88·62	487·57	110·77	12
51	97·49	22·24	194·99	44·48	292·49	66·72	389·98	88·96	487·48	111·20	9
54	97·48	22·33	194·95	44·65	292·43	66·98	389·90	89·30	487·38	111·62	6
57	97·46	22·41	194·91	44·82	292·37	67·23	389·83	89·64	487·28	112·15	3
60	97·44	22·49	194·87	44·99	292·31	67·49	389·75	89·98	487·18	112·47	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

77 Deg.

12 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	586·89	124·75	684·70	145·54	782·52	166·33	880·33	187·12	978·15	207·91	60
3	586·78	125·26	684·57	146·13	782·37	167·01	880·17	187·89	977·96	208·76	57
6	586·67	125·77	684·45	146·73	782·22	167·69	880·00	188·66	977·78	209·62	54
9	586·56	126·28	684·32	147·33	782·08	168·38	879·84	189·42	977·60	210·47	51
12	586·45	126·79	684·19	147·93	781·93	169·06	879·67	190·19	977·41	211·32	48
15	586·34	127·31	684·06	148·52	781·78	169·74	879·51	190·96	977·23	212·18	45
18	586·23	127·82	683·93	149·12	781·63	170·42	879·34	191·73	977·04	213·03	42
21	586·11	128·33	683·80	149·72	781·48	171·10	879·17	192·49	976·86	213·88	39
24	586·00	128·84	683·67	150·31	781·33	171·79	879·00	193·26	976·67	214·73	36
27	585·89	129·35	683·54	150·91	781·18	172·47	878·84	194·03	976·48	215·59	33
30	585·78	129·86	683·41	151·51	781·03	173·15	878·67	194·79	976·29	216·44	30
33	585·66	130·37	683·27	152·10	780·88	173·83	878·50	195·56	976·10	217·29	27
36	585·55	130·88	683·14	152·70	780·73	174·51	878·32	196·33	975·91	218·14	24
39	585·43	131·40	683·01	153·30	780·58	175·19	878·15	197·09	975·72	218·99	21
42	585·32	131·91	682·87	153·89	780·43	175·88	877·98	197·86	975·53	219·85	18
45	585·20	132·42	682·74	154·49	780·27	176·56	877·81	198·63	975·34	220·70	15
48	585·09	132·93	682·60	155·08	780·12	177·24	877·63	199·39	975·15	221·55	12
51	584·97	133·44	682·47	155·68	779·96	177·92	877·46	200·16	974·95	222·40	9
54	584·86	133·95	682·33	156·27	779·81	178·60	877·28	200·92	974·76	223·25	6
57	584·74	134·46	682·19	156·87	779·65	179·28	877·11	201·70	974·56	224·11	3
60	584·62	134·97	682·06	157·46	779·49	179·96	876·93	202·45	974·37	224·95	0
	Base.	Per.	Base.	Per	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

77 Deg.

13 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	97·44	22·49	194·87	44·99	292·31	67·49	389·75	89·98	487·18	112·47	60
3	97·42	22·58	194·83	45·16	292·25	67·74	389·67	90·32	487·09	112·90	57
6	97·40	22·66	194·79	45·33	292·19	67·99	389·59	90·66	486·99	113·32	54
9	97·38	22·75	194·75	45·50	292·13	68·25	389·51	91·00	486·89	113·75	51
12	97·36	22·83	194·71	45·67	292·07	68·51	389·43	91·34	486·79	114·17	48
15	97·34	22·92	194·67	45·84	292·01	68·76	389·35	91·68	486·69	114·60	45
18	97·32	23·00	194·63	46·01	291·95	69·01	389·27	92·02	486·59	115·02	42
21	97·30	23·09	194·59	46·18	291·89	69·27	389·19	92·36	486·49	115·45	39
24	97·28	23·17	194·55	46·35	291·83	69·52	389·11	92·70	486·39	115·87	36
27	97·26	23·26	194·51	46·52	291·77	69·78	389·03	93·04	486·29	116·30	33
30	97·24	23·34	194·47	46·69	291·71	70·03	388·95	93·38	486·18	116·72	30
33	97·22	23·43	194·43	46·86	291·65	70·29	388·86	93·72	486·08	117·15	27
36	97·20	23·51	194·39	47·03	291·59	70·54	388·78	94·06	485·98	117·57	24
39	97·18	23·60	194·35	47·20	291·52	70·80	388·70	94·40	485·88	117·99	21
42	97·15	23·68	194·31	47·37	291·46	71·05	388·62	94·74	485·77	118·42	18
45	97·13	23·77	194·27	47·54	291·40	71·31	388·54	95·07	485·67	118·84	15
48	97·11	23·85	194·23	47·71	291·34	71·56	388·45	95·41	485·57	119·27	12
51	97·09	23·94	194·18	47·88	291·28	71·81	388·37	95·75	485·46	119·69	9
54	97·07	24·02	194·14	48·05	291·21	72·07	388·29	96·09	485·36	120·11	6
57	97·05	24·11	194·10	48·22	291·15	72·32	388·20	96·43	485·25	120·54	3
60	97·03	24·19	194·06	48·39	291·09	72·58	388·12	96·77	485·15	120·96	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

76 Deg.

13 Deg.

ist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
62	134·97	682·06	157·46	779·49	179·96	876·93	202·45	974·37	224·95	60
50	135·48	681·92	158·06	779·34	180·64	876·75	203·22	974·17	225·80	57
38	135·99	681·78	158·65	779·18	181·32	876·58	203·99	973·97	226·65	54
26	136·50	681·64	159·25	779·02	182·00	876·40	204·75	973·78	227·50	51
15	137·01	681·50	159·85	778·86	182·68	876·22	205·51	973·58	228·35	48
03	137·52	681·36	160·44	778·70	183·36	876·04	206·28	973·38	229·20	45
91	138·03	681·22	161·03	778·54	184·04	875·86	207·04	973·18	230·05	42
78	138·54	681·08	161·63	778·38	184·72	875·68	207·81	972·98	230·90	39
66	139·05	680·94	162·22	778·22	185·40	875·50	208·57	972·77	231·75	36
54	139·56	680·80	162·82	778·06	186·08	875·31	209·34	972·57	232·60	33
42	140·07	680·66	163·41	777·89	186·76	875·13	210·10	972·37	233·45	30
30	140·57	680·51	164·00	777·73	187·44	874·95	210·86	972·16	234·29	27
17	141·08	680·37	164·60	777·57	188·11	874·76	211·62	971·96	235·14	24
05	141·59	680·23	165·19	777·40	188·79	874·57	212·39	971·75	235·99	21
93	142·10	680·08	165·79	777·24	189·47	874·39	213·15	971·55	236·84	18
80	142·61	679·94	166·38	777·07	190·15	874·21	213·92	971·34	237·69	15
68	143·12	679·80	166·97	776·91	190·83	874·02	214·68	971·13	238·53	12
55	143·63	679·65	167·57	776·74	191·50	873·83	215·44	970·92	239·38	9
43	144·14	679·50	168·16	776·57	192·18	873·64	216·20	970·72	240·23	6
30	144·64	679·35	168·75	776·40	192·86	873·46	216·97	970·51	241·07	3
18	145·15	679·21	169·34	776·23	193·54	873·27	217·73	970·30	241·92	0
.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
st. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

76 Deg.

14 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	97·03	24·19	194·06	48·39	291·09	72·58	388·12	96·77	485·15	120·96	60
3	97·01	24·28	194·02	48·55	291·02	72·83	388·03	97·11	485·04	121·38	57
6	96·99	24·36	193·97	48·72	290·96	73·08	387·95	97·44	484·94	121·81	54
9	96·96	24·45	193·93	48·89	290·90	73·34	387·86	97·78	484·83	122·23	51
12	96·94	24·53	193·89	49·06	290·83	73·59	387·78	98·12	484·72	122·65	48
15	96·92	24·62	193·84	49·23	290·77	73·85	387·69	98·46	484·61	123·08	45
18	96·90	24·70	193·80	49·40	290·70	74·10	387·60	98·80	484·51	123·50	42
21	96·88	24·78	193·76	49·57	290·64	74·35	387·52	99·14	484·40	123·92	39
24	96·86	24·87	193·72	49·74	290·57	74·61	387·43	99·48	484·29	124·34	36
27	96·84	24·95	193·67	49·91	290·51	74·86	387·34	99·81	484·18	124·77	33
30	96·81	25·04	193·63	50·08	290·44	75·11	387·26	100·15	484·07	125·19	30
33	96·79	25·12	193·58	50·25	290·38	75·37	387·17	100·49	483·96	125·61	27
36	96·77	25·21	193·54	50·42	290·31	75·62	387·08	100·83	483·85	126·03	24
39	96·75	25·29	193·50	50·58	290·25	75·87	386·99	101·16	483·74	126·46	21
42	96·73	25·37	193·45	50·75	290·18	76·13	386·91	101·50	483·63	126·88	18
45	96·70	25·46	193·41	50·92	290·11	76·38	386·82	101·84	483·52	127·30	15
48	96·68	25·54	193·36	51·09	290·05	76·63	386·73	102·18	483·41	127·72	12
51	96·66	25·63	193·32	51·26	289·98	76·89	386·64	102·51	483·30	128·14	9
54	96·64	25·71	193·27	51·43	289·91	77·14	386·55	102·85	483·19	128·57	6
57	96·62	25·80	193·23	51·60	289·84	77·39	386·46	103·19	483·07	128·99	3
60	96·59	25·88	193·18	51·76	289·78	77·65	386·37	103·53	482·96	129·41	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

75 Deg.

14 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	582·18	145·15	679·21	169·34	776·23	193·54	873·27	217·73	970·29	241·92	60
3	582·05	145·66	679·06	169·94	776·07	194·21	873·07	218·49	970·08	242·77	57
6	581·92	146·17	678·91	170·53	775·90	194·89	872·88	219·25	969·87	243·61	54
9	581·79	146·68	678·76	171·12	775·73	195·57	872·69	220·01	969·66	244·46	51
12	581·67	147·18	678·61	171·71	775·55	196·24	872·50	220·77	969·44	245·31	48
15	581·54	147·69	678·46	172·31	775·38	196·92	872·31	221·54	969·23	246·15	45
18	581·41	148·20	678·31	172·90	775·21	197·60	872·11	222·30	969·01	247·00	42
21	581·28	148·71	678·16	173·49	775·04	198·27	871·92	223·06	968·80	247·84	39
24	581·15	149·21	678·01	174·08	774·86	198·95	871·72	223·82	968·58	248·69	36
27	581·02	149·72	677·85	174·67	774·69	199·63	871·53	224·58	968·36	249·53	33
30	580·89	150·23	677·70	175·27	774·52	200·30	871·33	225·34	968·14	250·38	30
33	580·75	150·73	677·55	175·86	774·34	200·98	871·13	226·10	967·93	251·22	27
36	580·62	151·24	677·39	176·45	774·17	201·66	870·94	226·86	967·71	252·07	24
39	580·49	151·75	677·24	177·04	773·99	202·33	870·74	227·62	967·49	252·91	21
42	580·36	152·25	677·09	177·63	773·81	203·01	870·54	228·38	967·27	253·76	18
45	580·23	152·76	676·93	178·22	773·64	203·68	870·34	229·14	967·04	254·60	15
48	580·09	153·27	676·77	178·81	773·46	204·36	870·14	229·90	966·82	255·45	12
51	579·96	153·77	676·62	179·40	773·28	205·03	869·94	230·66	966·60	256·29	9
54	579·82	154·28	676·46	179·99	773·10	205·71	869·74	231·43	966·37	257·13	6
57	579·69	154·78	676·30	180·58	772·92	206·38	869·54	232·19	966·15	257·97	3
60	579·55	155·29	676·15	181·17	772·74	207·05	869·33	232·94	965·92	258·82	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

75 Deg.

15 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	96·59	25·88	193·18	51·76	289·78	77·65	386·37	103·53	482·96	129·41	60
3	96·57	25·97	193·14	51·93	289·71	77·90	386·28	103·86	482·85	129·83	57
6	96·55	26·05	193·09	52·10	289·64	78·15	386·19	104·20	482·74	130·25	54
9	96·52	26·13	193·05	52·27	289·57	78·40	386·10	104·54	482·62	130·67	51
12	96·50	26·22	193·00	52·44	289·50	78·66	386·01	104·87	482·51	131·09	48
15	96·48	26·30	192·96	52·61	289·44	78·91	385·91	105·21	482·40	131·52	45
18	96·45	26·39	192·91	52·78	289·37	79·16	385·82	105·55	482·28	131·94	42
21	96·43	26·47	192·86	52·94	289·30	79·41	385·73	105·87	482·16	132·36	39
24	96·41	26·55	192·82	53·11	289·23	79·67	385·64	106·22	482·05	132·78	36
27	96·39	26·64	192·77	53·28	289·16	79·92	385·55	106·56	481·93	133·20	33
30	96·36	26·72	192·73	53·45	289·09	80·17	385·45	106·89	481·81	133·62	30
33	96·34	26·81	192·68	53·62	289·02	80·42	385·36	107·23	481·70	134·04	27
36	96·32	26·89	192·63	53·78	288·95	80·67	385·26	107·57	481·58	134·46	24
39	96·29	26·98	192·58	53·95	288·88	80·93	385·17	107·90	481·46	134·88	21
42	96·27	27·06	192·54	54·12	288·81	81·18	385·08	108·24	481·34	135·30	18
45	96·24	27·14	192·49	54·29	288·73	81·43	384·98	108·58	481·23	135·72	15
48	96·22	27·23	192·44	54·46	288·66	81·68	384·89	108·91	481·11	136·14	12
51	96·20	27·31	192·40	54·62	288·59	81·94	384·79	109·25	480·99	136·56	9
54	96·17	27·39	192·35	54·79	288·52	82·19	384·70	109·58	480·87	136·98	6
57	96·15	27·48	192·30	54·96	288·45	82·44	384·60	109·92	480·75	137·40	3
60	96·13	27·56	192·25	55·13	288·38	82·69	384·50	110·25	480·63	137·82	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

74 Deg.

15 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	579·55	155·29	676·15	181·17	772·74	207·05	869·33	232·94	965·92	258·82	60
3	579·42	155·80	675·99	181·76	772·56	207·73	869·13	233·70	965·70	259·66	57
6	579·28	156·30	675·83	182·35	772·38	208·40	868·93	234·45	965·47	260·50	54
9	579·14	156·81	675·67	182·94	772·19	209·08	868·72	235·21	965·24	261·35	51
12	579·01	157·31	675·51	183·53	772·01	209·75	868·51	235·97	965·01	262·19	48
15	578·87	157·82	675·35	184·12	771·83	210·42	868·31	236·73	964·77	263·03	45
18	578·73	158·32	675·19	184·71	771·65	211·10	868·10	237·49	964·56	263·87	42
21	578·60	158·83	675·03	185·30	771·46	211·77	867·89	238·24	964·33	264·71	39
24	578·46	159·33	674·87	185·89	771·28	212·44	867·69	239·00	964·09	265·55	36
27	578·32	159·84	674·70	186·48	771·09	213·12	867·48	239·76	963·86	266·40	33
30	578·18	160·34	674·54	187·07	770·90	213·79	867·27	240·51	963·63	267·24	30
33	578·04	160·85	674·38	187·65	770·72	214·46	867·06	241·27	963·40	268·08	27
36	577·90	161·35	674·21	188·24	770·53	215·13	866·85	242·03	963·16	268·92	24
39	577·75	161·86	674·05	188·83	770·34	215·81	866·63	242·78	962·93	269·76	21
42	577·61	162·36	673·88	189·42	770·15	216·48	866·42	243·54	962·69	270·60	18
45	577·47	162·86	673·72	190·01	769·96	217·15	866·21	244·30	962·45	271·44	15
48	577·33	163·37	673·55	190·60	769·77	217·82	866·00	245·05	962·22	272·28	12
51	577·19	163·87	673·38	191·19	769·58	218·50	865·78	245·81	961·98	273·12	9
54	577·04	164·37	673·22	191·77	769·39	219·17	865·57	246·56	961·74	273·96	6
57	576·90	164·88	673·05	192·36	769·20	219·84	865·35	247·32	961·50	274·80	3
60	576·76	165·38	672·88	192·95	769·01	220·51	865·14	248·07	961·26	275·64	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

74 Deg.

16 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	96·13	27·56	192·25	55·13	288·38	82·69	384·50	110·25	480·63	137·82	60
3	96·10	27·65	192·20	55·29	288·30	82·94	384·41	110·59	480·51	138·24	57
6	96·08	27·73	192·15	55·46	288·23	83·19	384·31	110·92	480·39	138·66	54
9	96·05	27·81	192·11	55·63	288·16	83·44	384·21	111·26	480·27	139·08	51
12	96·03	27·90	192·06	55·80	288·09	83·72	384·12	111·60	480·15	139·49	48
15	96·00	27·98	192·01	55·97	288·01	83·97	384·02	111·93	480·03	139·91	45
18	95·98	28·07	191·96	56·13	287·94	84·20	383·92	112·27	479·90	140·33	42
21	95·95	28·15	191·91	56·30	287·87	84·45	383·82	112·60	479·78	140·75	39
24	95·93	28·23	191·86	56·47	287·79	84·70	383·73	112·94	479·66	141·17	36
27	95·91	28·32	191·81	56·63	287·72	84·95	383·63	113·27	479·53	141·59	33
30	95·88	28·40	191·76	56·80	287·65	85·20	383·53	113·61	479·41	142·01	30
33	95·86	28·48	191·71	56·97	287·57	85·45	383·43	113·94	479·28	142·43	27
36	95·83	28·57	191·66	57·14	287·50	85·71	383·33	114·27	479·16	142·84	24
39	95·81	28·65	191·61	57·30	287·42	85·96	383·23	114·61	479·03	143·26	21
42	95·78	28·74	191·56	57·47	287·35	86·21	383·13	114·94	478·91	143·68	18
45	95·76	28·82	191·51	57·64	287·27	86·46	383·03	115·28	478·78	144·10	15
48	95·73	28·90	191·46	57·81	287·20	86·71	382·93	115·61	478·66	144·51	12
51	95·71	28·99	191·41	57·97	287·12	86·96	382·83	115·95	478·53	144·93	9
54	95·68	29·07	191·36	58·14	287·04	87·21	382·72	116·28	478·40	145·35	6
57	95·65	29·15	191·31	58·31	286·97	87·46	382·62	116·62	478·28	145·77	3
60	95·63	29·24	191·26	58·47	286·89	87·71	382·52	116·95	478·15	146·18	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

73 Deg.

16 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	576·76	165·38	672·88	192·95	769·01	220·51	865·14	248·07	961·26	275·64	60
3	576·61	165·88	672·71	193·53	768·82	221·18	864·92	248·83	961·02	276·48	57
6	576·47	166·39	672·54	194·12	768·62	221·85	864·70	249·58	960·78	277·31	54
9	576·32	166·89	672·37	194·71	768·43	222·52	864·48	250·34	960·53	278·15	51
12	576·18	167·39	672·20	195·29	768·23	223·19	864·27	251·09	960·29	278·99	48
15	576·03	167·90	672·03	195·88	768·04	223·86	864·05	251·84	960·05	279·83	45
18	575·88	168·40	671·86	196·47	767·84	224·53	863·83	252·60	959·80	280·67	42
21	575·74	168·90	671·69	197·05	767·65	225·20	863·61	253·35	959·56	281·50	39
24	575·59	169·40	671·52	197·64	767·45	225·87	863·39	254·11	959·31	282·34	36
27	575·44	169·91	671·35	198·22	767·25	226·54	863·16	254·86	959·07	283·18	33
30	575·29	170·41	671·17	198·81	767·05	227·21	862·94	255·61	958·82	284·01	30
33	575·14	170·91	671·00	199·40	766·85	227·88	862·71	256·38	958·57	284·85	27
36	574·99	171·41	670·82	199·98	766·66	228·55	862·49	257·12	958·32	285·69	24
39	574·84	171·91	670·65	200·57	766·46	229·22	862·27	257·87	958·07	286·52	21
42	574·69	172·42	670·47	201·15	766·26	229·89	862·04	258·62	957·82	287·36	18
45	574·54	172·92	670·30	201·74	766·05	230·56	861·81	259·37	957·57	288·20	15
48	574·39	173·42	670·12	202·32	765·85	231·23	861·59	260·13	957·32	289·03	12
51	574·24	173·92	669·95	202·91	765·65	231·89	861·36	260·88	957·07	289·87	9
54	574·09	174·42	669·77	203·49	765·45	232·56	861·13	261·63	956·81	290·70	6
57	573·93	174·92	669·59	204·08	765·25	233·23	860·90	262·38	956·56	291·54	3
60	573·78	175·42	669·41	204·66	765·04	233·90	860·68	263·13	956·30	292·37	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

73 Deg.

17 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	95·63	29·24	191·26	58·47	286·89	87·71	382·52	116·95	478·15	146·18	60
3	95·60	29·32	191·21	58·64	286·81	87·96	382·42	117·28	478·02	146·60	57
6	95·58	29·40	191·16	58·81	286·74	88·21	382·32	117·62	477·89	147·02	54
9	95·55	29·49	191·11	58·97	286·66	88·46	382·21	117·95	477·77	147·44	51
12	95·53	29·57	191·05	59·14	286·58	88·71	382·11	118·28	477·64	147·85	48
15	95·50	29·65	191·00	59·31	286·50	88·96	382·01	118·62	477·54	148·27	45
18	95·47	29·74	190·95	59·47	286·43	89·21	381·90	118·95	477·38	148·69	42
21	95·45	29·82	190·90	59·64	286·35	89·46	381·80	119·28	477·25	149·10	39
24	95·42	29·90	190·85	59·81	286·27	89·71	381·70	119·62	477·12	149·52	36
27	95·40	29·99	190·80	59·97	286·19	89·96	381·59	119·95	476·99	149·94	33
30	95·37	30·07	190·74	60·14	286·11	90·21	381·49	120·28	476·86	150·35	30
33	95·34	30·15	190·69	60·31	286·03	90·46	381·38	120·62	476·73	150·77	27
36	95·32	30·24	190·64	60·47	285·96	90·71	381·27	120·95	476·59	151·18	24
39	95·29	30·32	190·58	60·64	285·88	90·96	381·17	121·28	476·46	151·60	21
42	95·26	30·40	190·53	60·81	285·80	91·21	381·06	121·61	476·33	152·02	18
45	95·24	30·49	190·48	60·97	285·72	91·46	380·96	121·94	476·20	152·43	15
48	95·21	30·57	190·43	61·14	285·64	91·71	380·85	122·27	476·06	152·85	12
51	95·18	30·65	190·37	61·30	285·56	91·96	380·74	122·61	475·93	153·26	9
54	95·16	30·73	190·32	61·47	285·48	92·21	380·64	122·94	475·80	153·68	6
57	95·13	30·82	190·26	61·64	285·40	92·45	380·53	123·27	475·66	154·09	3
60	95·10	30·90	190·21	61·80	285·32	92·70	380·42	123·61	475·53	154·51	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Minutes.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

72 Deg.

17 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	573·78	175·42	669·41	204·66	765·04	233·90	860·68	263·13	956·30	292·37	60
3	573·63	175·92	669·23	205·24	764·84	234·56	860·44	263·88	956·05	293·20	57
6	573·47	176·42	669·05	205·83	764·63	235·23	860·21	264·64	955·79	294·04	54
9	573·32	176·92	668·87	206·41	764·43	235·90	859·98	265·39	955·53	294·87	51
12	573·16	177·42	668·69	207·00	764·22	236·56	859·75	266·14	955·28	295·71	48
15	573·01	177·92	668·51	207·58	764·01	237·23	859·52	266·89	955·02	296·54	45
18	572·85	178·42	668·33	208·16	763·81	237·90	859·28	267·64	954·76	297·37	42
21	572·70	178·92	668·15	208·74	763·60	238·56	859·05	268·39	954·50	298·21	39
24	572·54	179·42	667·97	209·33	763·39	239·23	858·82	269·14	954·24	299·04	36
27	572·39	179·92	667·78	209·91	763·18	239·90	858·58	269·88	953·98	299·87	33
30	572·23	180·42	667·60	210·49	762·98	240·56	858·34	270·63	953·72	300·70	30
33	572·07	180·92	667·42	211·08	762·76	241·23	858·11	271·38	953·45	301·53	27
36	571·91	181·42	667·23	211·66	762·55	241·90	857·87	272·13	953·19	302·37	24
39	571·75	181·92	667·05	212·24	762·34	242·56	857·63	272·88	952·92	303·20	21
42	571·60	182·42	666·86	212·82	762·13	243·22	857·39	273·63	952·66	304·03	18
45	571·44	182·92	666·68	213·40	761·92	243·89	857·15	274·38	952·39	304·86	15
48	571·28	183·42	666·49	213·99	761·70	244·55	856·91	275·13	952·13	305·69	12
51	571·12	183·92	666·30	214·57	761·49	245·22	856·67	275·87	951·86	306·53	9
54	570·95	184·41	666·11	215·15	761·27	245·88	856·43	276·62	951·59	307·36	6
57	570·79	184·91	665·93	215·73	761·06	246·55	856·19	277·37	951·32	308·19	3
60	570·63	185·41	665·74	216·31	760·84	247·21	855·95	278·11	951·05	309·02	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

72 Deg.

18 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	95·10	30·90	190·21	61·80	285·32	92·71	380·42	123·61	475·53	154·51	60
3	95·08	30·98	190·16	61·97	285·23	92·95	380·31	123·94	475·39	154·92	57
6	95·05	31·07	190·10	62·13	285·15	93·20	380·21	124·27	475·26	155·34	54
9	95·02	31·15	190·05	62·30	285·07	93·45	380·10	124·60	475·12	155·75	51
12	95·00	31·23	189·99	62·47	284·99	93·70	379·99	124·93	474·98	156·17	48
15	94·97	31·32	189·94	62·63	284·91	93·95	379·88	125·26	474·85	156·58	45
18	94·94	31·40	189·88	62·80	284·83	94·20	379·77	125·60	474·71	156·99	42
21	94·91	31·48	189·83	62·96	284·74	94·44	379·66	125·93	474·57	157·41	39
24	94·88	31·56	189·77	63·13	284·66	94·69	379·55	126·26	474·44	157·82	36
27	94·86	31·65	189·72	63·29	284·58	94·94	379·44	126·59	474·30	158·24	33
30	94·83	31·73	189·66	63·46	284·50	95·19	379·33	126·92	474·16	158·65	30
33	94·80	31·81	189·61	63·63	284·41	95·44	379·22	127·25	474·02	159·07	27
36	94·78	31·89	189·55	63·79	284·33	95·69	379·11	127·58	473·88	159·48	24
39	94·75	31·98	189·50	63·96	284·25	95·94	378·99	127·91	473·74	159·89	21
42	94·72	32·06	189·44	64·12	284·16	96·18	378·88	128·24	473·60	160·31	18
45	94·69	32·14	189·38	64·29	284·08	96·43	378·77	128·58	473·46	160·72	15
48	94·66	32·23	189·33	64·45	283·99	96·68	378·66	128·91	473·32	161·13	12
51	94·64	32·31	189·27	64·62	283·91	96·93	378·55	129·24	473·18	161·54	9
54	94·61	32·39	189·22	64·78	283·82	97·17	378·43	129·57	473·04	161·96	6
57	94·58	32·47	189·16	64·95	283·74	97·42	378·32	129·90	472·90	162·37	3
60	94·55	32·56	189·10	65·11	283·65	97·67	378·21	130·23	472·76	162·78	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

71 Deg.

18 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	570·63	185·41	665·74	216·31	760·84	247·21	855·95	278·11	951·05	309·02	60
3	570·47	185·91	665·55	216·89	760·63	247·88	855·71	278·86	950·78	310·85	57
6	570·31	186·41	665·36	217·47	760·41	248·54	855·46	279·61	950·51	310·68	54
9	570·14	186·90	665·17	218·05	760·19	249·20	855·22	280·36	950·24	311·50	51
12	569·98	187·40	664·98	218·63	759·98	249·87	854·97	281·10	949·97	312·33	48
15	569·82	187·90	664·79	219·21	759·76	250·53	854·73	281·85	949·70	313·16	45
18	569·65	188·40	664·60	219·79	759·54	251·19	854·48	282·59	949·42	313·99	42
21	569·49	188·89	664·40	220·37	759·32	251·86	854·23	283·34	949·15	314·82	39
24	569·32	189·39	664·21	220·95	759·10	252·52	853·99	284·08	948·87	315·65	36
27	569·16	189·89	664·02	221·53	758·88	253·18	853·74	284·83	948·60	316·48	33
30	568·99	190·38	663·83	222·11	758·66	253·84	853·49	285·57	948·32	317·30	30
33	568·83	190·88	663·63	222·69	758·44	254·50	853·24	286·32	948·04	318·13	27
36	568·66	191·37	663·44	223·27	758·22	255·17	852·99	287·06	947·77	318·96	24
39	568·49	191·87	663·24	223·85	757·99	255·83	852·74	287·81	947·49	319·78	21
42	568·32	192·37	663·05	224·43	757·77	256·49	852·49	288·55	947·21	320·61	18
45	568·16	192·86	662·85	225·01	757·54	257·15	852·24	289·29	946·93	321·44	15
48	567·99	193·36	662·65	225·58	757·32	257·81	851·98	290·04	946·65	322·26	12
51	567·82	193·85	662·46	226·16	757·09	258·47	851·73	290·78	946·37	323·09	9
54	567·65	194·35	662·26	226·74	756·87	259·13	851·48	291·52	946·08	323·92	6
57	567·48	194·84	662·06	227·32	756·64	259·79	851·22	292·27	945·80	324·74	3
60	567·31	195·34	661·86	227·90	756·41	260·45	850·97	293·01	945·52	325·57	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

71 Deg.

19 Deg.

Minutes	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500	
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	D
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	B
0	94-85	32-5	189-70	65-1	284-55	97-6	379-40	130-2	474-26	162
3	94-82	32-6	189-65	65-2	284-47	97-8	379-29	130-4	474-12	162
6	94-79	32-7	189-59	65-4	284-38	98-0	379-18	130-8	473-97	163
9	94-76	32-8	189-53	65-6	284-29	98-2	379-06	131-0	473-82	163
12	94-73	32-9	189-47	65-8	284-21	98-4	378-94	131-2	473-68	164
15	94-70	33-0	189-41	66-0	284-12	98-6	378-83	131-4	473-53	164
18	94-67	33-1	189-35	66-2	284-03	98-8	378-71	131-6	473-39	165
21	94-64	33-2	189-29	66-4	283-94	99-0	378-59	131-8	473-24	165
24	94-61	33-3	189-23	66-6	283-85	99-2	378-47	132-0	473-09	166
27	94-58	33-4	189-17	66-8	283-76	99-4	378-35	132-2	472-94	166
30	94-55	33-5	189-11	67-0	283-67	99-6	378-23	132-4	472-79	167
33	94-52	33-6	189-05	67-2	283-57	99-8	378-11	132-6	472-64	167
36	94-49	33-7	188-99	67-4	283-48	100-0	377-98	132-8	472-49	168
39	94-46	33-8	188-93	67-6	283-39	100-2	377-86	133-0	472-33	168
42	94-43	33-9	188-87	67-8	283-29	100-4	377-74	133-2	472-18	169
45	94-40	34-0	188-81	68-0	283-20	100-6	377-61	133-4	472-02	169
48	94-37	34-1	188-75	68-2	283-10	100-8	377-48	133-6	471-86	170
51	94-34	34-2	188-68	68-4	283-00	101-0	377-35	133-8	471-70	170
54	94-31	34-3	188-62	68-6	282-90	101-2	377-22	134-0	471-54	171
57	94-28	34-4	188-56	68-8	282-80	101-4	377-09	134-2	471-38	171
60	94-24	34-5	188-49	69-0	282-70	101-6	376-95	134-4	471-22	172
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Pe
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	La
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500	

70 Deg.

19 Deg.

Minutes.	Dist. 600. Lat. Per.	Dist. 600. Dep. Base.	Dist. 700. Lat. Per.	Dist. 700. Dep. Base.	Dist. 800. Lat. Per.	Dist. 800. Dep. Base.	Dist. 900. Lat. Per.	Dist. 900. Dep. Base.	Dist. 1000. Lat. Per.	Dist. 1000. Dep. Base.	
0	567·31	195·34	661·86	227·90	756·41	260·45	850·97	293·01	945·52	325·57	60
3	567·14	195·83	661·66	228·47	756·19	261·11	850·71	293·75	945·23	326·39	57
6	566·97	196·33	661·46	229·05	755·96	261·77	850·45	294·49	944·95	327·22	54
9	566·80	196·83	661·26	229·63	755·73	262·43	850·20	295·24	944·66	328·04	51
12	566·62	197·32	661·06	230·21	755·50	263·09	849·94	295·98	944·38	328·87	48
15	566·45	197·81	660·86	230·78	755·27	263·75	849·68	296·72	944·09	329·69	45
18	566·28	198·31	660·66	231·36	755·04	264·41	849·42	297·46	943·80	330·51	42
21	566·11	198·80	660·46	231·94	754·81	265·07	849·16	298·20	943·51	331·34	39
24	565·93	199·30	660·25	232·51	754·58	265·73	848·90	298·94	943·22	332·16	36
27	565·76	199·79	660·05	233·09	754·34	266·39	848·64	299·69	942·93	332·98	33
30	565·58	200·28	659·85	233·66	754·11	267·04	848·38	300·43	942·64	333·80	30
33	565·41	200·78	659·64	234·24	753·88	267·70	848·11	301·17	942·35	334·63	27
36	565·23	201·27	659·44	234·81	753·64	268·36	847 85	301·91	942·06	335·45	24
39	565·06	201·76	659·23	235·39	753·41	269·02	847·59	302·65	941·76	336·27	21
42	564·88	202·26	659·03	235·97	753·17	269·67	847·32	303·39	941·47	337·09	18
45	564·70	202·75	658·82	236·54	752·94	270·33	847·06	304·13	941·17	337·91	15
48	564·53	203·24	658·62	237·11	752·70	270·99	846·79	304·86	940·88	338·74	12
51	564·35	203·73	658·41	237·69	752·47	271·65	846·53	305·60	940·58	339·56	9
54	564·17	204·23	658·20	238·26	752·23	272·30	846·26	306·34	940·29	340·38	6
57	563·99	204·72	657·99	238·84	751·99	272·96	845·99	307·08	939·99	341·20	3
60	563·81	205·21	657·78	239·41	751·75	273·61	845·72	307·82	939·69	342·02	0
	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Minutes.
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

70 Deg.

20 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	93·97	34·20	187·94	68·40	281·91	102·60	375·87	136·81	469·84	171·01	60
3	93·94	34·28	187·88	68·57	281·82	102·85	375·76	137·13	469·70	171·42	57
6	93·91	34·36	187·82	68·73	281·73	103·10	375·64	137·46	469·55	171·83	54
9	93·88	34·45	187·76	68·89	281·64	103·34	375·52	137·79	469·40	172·24	51
12	93·85	34·53	187·70	69·06	281·55	103·59	375·40	138·12	469·25	172·65	48
15	93·82	34·61	187·64	69·22	281·46	103·84	375·28	138·45	469·10	173·06	45
18	93·79	34·69	187·58	69·39	281·37	104·08	375·15	138·77	468·94	173·47	42
21	93·76	34·77	187·52	69·55	281·27	104·33	375·03	139·10	468·79	173·88	39
24	93·73	34·86	187·46	69·71	281·18	104·57	374·91	139·43	468·64	174·28	36
27	93·70	34·94	187·39	69·88	281·09	104·82	374·79	139·75	468·49	174·69	33
30	93·67	35·02	187·33	70·04	281·00	105·06	374·67	140·08	468·34	175·10	30
33	93·64	35·10	187·27	70·20	280·91	105·31	374·55	140·41	468·18	175·51	27
36	93·61	35·18	187·21	70·37	280·82	105·55	374·42	140·74	468·03	175·92	24
39	93·57	35·26	187·15	70·53	280·72	105·80	374·30	141·06	467·87	176·33	21
42	93·54	35·35	187·09	70·69	280·63	106·04	374·18	141·39	467·72	176·74	18
45	93·51	35·43	187·03	70·86	280·54	106·29	374·05	141·72	467·57	177·15	15
48	93·48	35·51	186·96	71·02	280·45	106·53	373·93	142·04	467·41	177·55	12
51	93·45	35·59	186·90	71·18	280·35	106·78	373·80	142·37	467·26	177·96	9
54	93·42	35·67	186·84	71·35	280·26	107·02	373·68	142·69	467·10	178·37	6
57	93·39	35·75	186·78	71·51	280·17	107·27	373·56	143·02	466·94	178·77	3
60	93·36	35·84	186·71	71·67	280·07	107·51	373·43	143·35	466·79	179·18	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

69 Deg.

20 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	563·81	205·21	657·78	239·41	751·75	273·61	845·72	307·82	939·69	342·02	60
3	563·63	205·70	657·57	239·99	751·51	274·27	845·45	308·55	939·39	342·84	57
6	563·45	206·19	657·36	240·56	751·27	274·93	845·19	309·29	939·09	343·66	54
9	563·28	206·69	657·15	241·13	751·03	275·58	844·92	310·03	938·79	344·48	51
12	563·10	207·18	656·94	241·71	750·79	276·24	844·64	310·77	938·49	345·30	48
15	562·91	207·67	656·73	242·28	750·55	276·89	844·37	311·50	938·19	346·12	45
18	562·73	208·16	656·52	242·85	750·31	277·55	844·10	312·24	937·89	346·93	42
21	562·55	208·65	656·31	243·43	750·07	278·20	843·83	312·98	937·59	347·75	39
24	562·37	209·14	656·10	244·00	749·83	278·86	843·55	313·71	937·28	348·57	36
27	562·18	209·63	655·88	244·57	749·58	279·51	843·28	314·45	936·98	349·39	33
30	562·00	210·12	655·67	245·14	749·34	280·16	843·00	315·19	936·67	350·21	30
33	561·82	210·61	655·45	245·72	749·09	280·82	842·73	315·92	936·37	351·02	27
36	561·64	211·10	655·24	246·29	748·85	281·47	842·45	316·66	936·06	351·84	24
39	561·45	211·59	655·02	246·86	748·60	282·13	842·17	317·39	935·75	352·66	21
42	561·26	212·08	654·81	247·43	748·35	282·78	841·90	318·13	935·44	353·47	18
45	561·08	212·57	654·59	248·00	748·11	283·43	841·62	318·86	935·13	354·29	15
48	560·89	213·06	654·38	248·57	747·86	284·08	841·34	319·60	934·82	355·11	12
51	560·71	213·55	654·16	249·14	747·61	284·74	841·06	320·33	934·51	355·92	9
54	560·52	214·04	653·94	249·72	747·36	285·39	840·78	321·06	934·20	356·74	6
57	560·33	214·53	653·72	250·29	747·11	286·04	840·50	321·80	933·89	357·55	3
60	560·15	215·02	653·50	250·86	746·86	286·69	840·22	322·53	933·58	358·37	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

69 Deg.

17 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	95·63	29·24	191·26	58·47	286·89	87·71	382·52	116·95	478·15	146·18	60
3	95·60	29·32	191·21	58·64	286·81	87·96	382·42	117·28	478·02	146·60	57
6	95·58	29·40	191·16	58·81	286·74	88·21	382·32	117·62	477·89	147·02	54
9	95·55	29·49	191·11	58·97	286·66	88·46	382·21	117·95	477·77	147·44	51
12	95·53	29·57	191·05	59·14	286·58	88·71	382·11	118·28	477·64	147·85	48
15	95·50	29·65	191·00	59·31	286·50	88·96	382·01	118·62	477·54	148·27	45
18	95·47	29·74	190·95	59·47	286·43	89·21	381·90	118·95	477·38	148·69	42
21	95·45	29·82	190·90	59·64	286·35	89·46	381·80	119·28	477·25	149·10	39
24	95·42	29·90	190·85	59·81	286·27	89·71	381·70	119·62	477·12	149·52	36
27	95·40	29·99	190·80	59·97	286·19	89·96	381·59	119·95	476·99	149·94	33
30	95·37	30·07	190·74	60·14	286·11	90·21	381·49	120·28	476·86	150·35	30
33	95·34	30·15	190·69	60·31	286·03	90·46	381·38	120·62	476·73	150·77	27
36	95·32	30·24	190·64	60·47	285·96	90·71	381·27	120·95	476·59	151·18	24
39	95·29	30·32	190·58	60·64	285·88	90·96	381·17	121·28	476·46	151·60	21
42	95·26	30·40	190·53	60·81	285·80	91·21	381·06	121·61	476·33	152·02	18
45	95·24	30·49	190·48	60·97	285·72	91·46	380·96	121·94	476·20	152·43	15
48	95·21	30·57	190·43	61·14	285·64	91·71	380·85	122·27	476·06	152·85	12
51	95·18	30·65	190·37	61·30	285·56	91·96	380·74	122·61	475·93	153·26	9
54	95·16	30·73	190·32	61·47	285·48	92·21	380·64	122·94	475·80	153·68	6
57	95·13	30·82	190·26	61·64	285·40	92·45	380·53	123·27	475·66	154·09	3
60	95·10	30·90	190·21	61·80	285·32	92·70	380·42	123·61	475·53	154·51	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

72 Deg.

21 Deg.

Minutes.	Dist. 600. Lat. Per.	Dist. 600. Dep. Base.	Dist. 700. Lat. Per.	Dist. 700. Dep. Base.	Dist. 800. Lat. Per.	Dist. 800. Dep. Base.	Dist. 900. Lat. Per.	Dist. 900. Dep. Base.	Dist. 1000. Lat. Per.	Dist. 1000. Dep. Base.	
0	560·14	215·02	653·50	250·85	746·86	286·69	840·22	322·53	933·58	358·37	60
3	559·96	215·50	653·28	251·42	746·61	287·34	839·94	323·26	933·26	359·18	57
6	559·77	215·99	653·06	251·99	746·36	287·99	839·66	323·99	932·95	359·99	54
9	559·58	216·48	652·84	252·56	746·11	288·64	839·38	324·72	932·64	360·81	51
12	559·39	216·97	652·62	253·13	745·86	289·29	839·09	325·46	932·32	361·62	48
15	559·20	217·46	652·40	253·70	745·61	289·94	838·81	326·19	932·01	362·44	45
18	559·01	217·95	652·18	254·27	745·35	290·60	838·52	326·92	931·69	363·25	42
21	558·82	218·44	651·96	254·84	745·10	291·25	838·24	327·65	931·37	364·06	39
24	558·63	218·92	651·73	255·41	744·84	291·90	837·95	328·38	931·05	364·87	36
27	558·44	219·41	651·51	255·98	744·59	292·55	837·66	329·11	930·73	365·69	33
30	558·24	219·90	651·29	256·55	744·33	293·20	837·37	329·85	930·41	366·50	30
33	558·05	220·39	651·07	257·12	744·08	293·85	837·08	330·58	930·09	367·31	27
36	557·86	220·87	650·84	257·68	743·82	294·50	836·79	331·31	929·77	368·12	24
39	557·67	221·36	650·62	258·25	743·56	295·15	836·50	332·04	929·45	368·93	21
42	557·47	221·84	650·39	258·82	743·30	295·79	836·21	332·77	929·13	369·74	18
45	557·28	222·33	650·17	259·39	743·04	296·44	835·92	333·50	928·81	370·55	15
48	557·09	222·82	649·94	259·95	742·78	297·09	835·63	334·23	928·48	371·36	12
51	556·90	223·31	649·71	260·52	742·52	297·74	835·34	334·96	928·16	372·17	9
54	556·70	223·79	649·48	261·09	742·26	298·39	835·05	335·68	927·83	372·98	6
57	556·50	224·28	649·25	261·66	742·00	299·04	834·75	336·41	927·51	373·79	3
60	556·30	224·76	649·02	262·22	741·74	299·68	834·46	337·14	927·18	374·60	0
	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Minutes.
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

68 Deg.

22 Deg.

Minutes	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	92·71	37·46	185·43	74·92	278·15	112·38	370·87	149·84	463·59	187·31	60
3	92·68	37·54	185·37	75·08	278·05	112·62	370·74	150·16	463·43	187·70	57
6	92·65	37·62	185·30	75·24	277·95	112·86	370·61	150·48	463·26	188·11	54
9	92·62	37·70	185·24	75·40	277·86	113·10	370·48	150·81	463·10	188·51	51
12	92·58	37·78	185·17	75·56	277·76	113·35	370·34	151·13	462·93	188·91	48
15	92·55	37·86	185·11	75·72	277·66	113·59	370·21	151·45	462·77	189·31	45
18	92·52	37·94	185·04	75·88	277·56	113·83	370·08	151·78	462·60	189·72	42
21	92·48	38·02	184·97	76·04	277·46	114·07	369·95	152·10	462·44	190·13	39
24	92·45	38·10	184·90	76·21	277·36	114·32	369·81	152·42	462·27	190·53	36
27	92·42	38·18	184·84	76·37	277·26	114·56	369·68	152·74	462·10	190·93	33
30	92·38	38·26	184·77	76·53	277·16	114·80	369·55	153·07	461·93	191·34	30
33	92·35	38·34	184·71	76·69	277·06	115·04	369·42	153·39	461·77	191·74	27
36	92·32	38·42	184·64	76·85	276·96	115·29	369·28	153·71	461·60	192·14	24
39	92·28	38·50	184·57	77·01	276·86	115·53	369·15	154·03	461·44	192·54	21
42	92·25	38·59	184·50	77·18	276·76	115·77	369·01	154·36	461·27	192·95	18
45	92·22	38·67	184·44	77·34	276·66	116·01	368·88	154·68	461·10	193·35	15
48	92·18	38·75	184·37	77·50	276·56	116·25	368·74	155·00	460·93	193·75	12
51	92·15	38·83	184·30	77·66	276·45	116·49	368·61	155·32	460·76	194·15	9
54	92·11	38·91	184·23	77·82	276·35	116·73	368·47	155·64	460·59	194·56	6
57	92·08	38·99	184·17	77·98	276·25	116·97	368·34	155·96	460·42	194·96	3
60	92·05	39·07	184·10	78·14	276·15	117·21	368·20	156·29	460·25	195·36	0
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Minutes.
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

67 Deg.

22 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.	
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.
0	556·30	224·76	649·02	262·22	741·74	299·68	834·46	337·14	927·18	374·60
3	556·11	225·24	648·79	262·79	741·48	300·33	834·17	337·87	926·85	375·41
6	555·91	225·73	648·56	263·35	741·22	300·97	833·87	338·60	926·52	376·22
9	555·72	226·21	648·33	263·92	740·96	301·62	833·58	339·33	926·19	377·03
12	555·52	226·70	648·10	264·48	740·69	302·27	833·28	340·05	925·86	377·84
15	555·32	227·18	647·87	265·05	740·43	302·92	832·99	340·78	925·53	378·64
18	555·12	227·67	647·64	265·61	740·16	303·56	832·69	341·51	925·20	379·45
21	554·92	228·15	647·41	266·18	739·90	304·21	832·39	342·24	924·87	380·26
24	554·72	228·64	647·18	266·74	739·63	304·85	832·09	342·96	924·54	381·07
27	554·52	229·12	646·95	267·31	739·37	305·50	831·79	343·69	924·21	381·88
30	554·32	229·61	646·71	267·87	739·10	306·14	831·49	344·41	923·87	382·68
33	554·12	230·09	646·48	268·44	738·83	306·79	831·19	345·14	923·54	383·48
36	553·92	230·57	646·24	269·00	738·56	307·43	830·89	345·86	923·20	384·28
39	553·72	231·06	646·01	269·57	738·30	308·08	830·59	346·59	922·87	385·09
42	553·52	231·54	645·77	270·13	738·08	308·72	830·28	347·31	922·53	385·90
45	553·32	232·03	645·54	270·70	737·76	309·37	829·98	348·04	922·20	386·70
48	553·11	232·51	645·30	271·26	737·49	310·01	829·67	348·76	921·86	387·51
51	552·91	233·00	645·06	271·82	737·22	310·66	829·37	349·49	921·52	388·31
54	552·71	233·47	644·82	272·38	736·94	311·30	829·06	350·21	921·18	389·12
57	552·51	233·95	644·59	272·94	736·67	311·94	828·76	350·93	920·84	389·92
60	552·30	234·43	644·35	273·51	736·40	312·58	828·45	351·65	920·50	390·73
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.	

67 Deg.

19 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	94·55	32·56	189·10	65·11	283·65	97·67	378·21	130·23	472·76	162·78	60
3	94·52	32·64	189·05	65·28	283·57	97·92	378·09	130·56	472·62	163·20	57
6	94·49	32·72	188·99	65·44	283·48	98·16	377·98	130·89	472·47	163·61	54
9	94·47	32·80	188·93	65·61	283·40	98·41	377·86	131·22	472·33	164·02	51
12	94·44	32·89	188·87	65·77	283·31	98·66	377·75	131·55	472·19	164·43	48
15	94·41	32·97	188·82	65·94	283·23	98·91	377·63	131·88	472·04	164·84	45
18	94·38	33·05	188·76	66·10	283·14	99·15	377·52	132·20	471·90	165·26	42
21	94·35	33·14	188·70	66·27	283·05	99·40	377·40	132·53	471·75	165·67	39
24	94·32	33·22	188·64	66·43	282·97	99·65	377·29	132·86	471·61	166·08	36
27	94·29	33·30	188·59	66·60	282·88	99·89	377·17	133·19	471·46	166·49	33
30	94·26	33·38	188·53	66·76	282·79	100·14	377·06	133·52	471·32	166·90	30
33	94·23	33·46	188·47	66·93	282·70	100·39	376·94	133·85	471·17	167·31	27
36	94·20	33·54	188·41	67·09	282·62	100·63	376·82	134·18	471·03	167·72	24
39	94·18	33·63	188·35	67·25	282·53	100·88	376·70	134·51	470·88	168·14	21
42	94·15	33·71	188·29	67·42	282·44	101·13	376·59	134·84	470·73	168·55	18
45	94·12	33·79	188·23	67·58	282·35	101·37	376·47	135·17	470·59	168·96	15
48	94·09	33·87	188·18	67·75	282·26	101·62	376·35	135·49	470·44	169·37	12
51	94·06	33·95	188·12	67·91	282·17	101·87	376·23	135·82	470·29	169·78	9
54	94·03	34·04	188·06	68·07	282·09	102·11	376·11	136·15	470·14	170·19	6
57	94·00	34·12	188·00	68·24	282·00	102·36	375·99	136·48	469·99	170·60	3
60	93·97	34·20	187·94	68·40	281·91	102·60	375·87	136·81	469·84	171·01	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

70 Deg.

19 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	567·31	195·34	661·86	227·90	756·41	260·45	850·97	293·01	945·52	325·57	60
3	567·14	195·83	661·66	228·47	756·19	261·11	850·71	293·75	945·23	326·39	57
6	566·97	196·33	661·46	229·05	755·96	261·77	850·45	294·49	944·95	327·22	54
9	566·80	196·83	661·26	229·63	755·73	262·43	850·20	295·24	944·66	328·04	51
2	566·62	197·32	661·06	230·21	755·50	263·09	849·94	295·98	944·38	328·87	48
5	566·45	197·81	660·86	230·78	755·27	263·75	849·68	296·72	944·09	329·69	45
8	566·28	198·31	660·66	231·36	755·04	264·41	849·42	297·46	943·80	330·51	42
1	566·11	198·80	660·46	231·94	754·81	265·07	849·16	298·20	943·51	331·34	39
4	565·93	199·30	660·25	232·51	754·58	265·73	848·90	298·94	943·22	332·16	36
7	565·76	199·79	660·05	233·09	754·34	266·39	848·64	299·69	942·93	332·98	33
0	565·58	200·28	659·85	233·66	754·11	267·04	848·38	300·43	942·64	333·80	30
3	565·41	200·78	659·64	234·24	753·88	267·70	848·11	301·17	942·35	334·63	27
6	565·23	201·27	659·44	234·81	753·64	268·36	847 85	301·91	942·06	335·45	24
9	565·06	201·76	659·23	235·39	753·41	269·02	847·59	302·65	941·76	336·27	21
2	564·88	202·26	659·03	235·97	753·17	269·67	847·32	303·39	941·47	337·09	18
5	564·70	202·75	658·82	236·54	752·94	270·33	847·06	304·13	941·17	337·91	15
8	564·53	203·24	658·62	237·11	752·70	270·99	846·79	304·86	940·88	338·74	12
1	564·35	203·73	658·41	237·69	752·47	271·65	846·53	305·60	940·58	339·56	9
4	564·17	204·23	658·20	238·26	752·23	272·30	846·26	306·34	940·29	340·38	6
7	563·99	204·72	657·99	238·84	751·99	272·96	845·99	307·08	939·99	341·20	3
0	563·81	205·21	657·78	239·41	751·75	273·61	845·72	307·82	939·69	342·02	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

70 Deg.

20 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	93·97	34·20	187·94	68·40	281·91	102·60	375·87	136·81	469·84	171·01	60
3	93·94	34·28	187·88	68·57	281·82	102·85	375·76	137·13	469·70	171·42	57
6	93·91	34·36	187·82	68·73	281·73	103·10	375·64	137·46	469·55	171·83	54
9	93·88	34·45	187·76	68·89	281·64	103·34	375·52	137·79	469·40	172·24	51
12	93·85	34·53	187·70	69·06	281·55	103·59	375·40	138·12	469·25	172·65	48
15	93·82	34·61	187·64	69·22	281·46	103·84	375·28	138·45	469·10	173·06	45
18	93·79	34·69	187·58	69·39	281·37	104·08	375·15	138·77	468·94	173·47	42
21	93·76	34·77	187·52	69·55	281·27	104·33	375·03	139·10	468·79	173·88	39
24	93·73	34·86	187·46	69·71	281·18	104·57	374·91	139·43	468·64	174·28	36
27	93·70	34·94	187·39	69·88	281·09	104·82	374·79	139·75	468·49	174·69	33
30	93·67	35·02	187·33	70·04	281·00	105·06	374·67	140·08	468·34	175·10	30
33	93·64	35·10	187·27	70·20	280·91	105·31	374·55	140·41	468·18	175·51	27
36	93·61	35·18	187·21	70·37	280·82	105·55	374·42	140·74	468·03	175·92	24
39	93·57	35·26	187·15	70·53	280·72	105·80	374·30	141·06	467·87	176·33	21
42	93·54	35·35	187·09	70·69	280·63	106·04	374·18	141·39	467·72	176·74	18
45	93·51	35·43	187·03	70·86	280·54	106·29	374·05	141·72	467·57	177·15	15
48	93·48	35·51	186·96	71·02	280·45	106·53	373·93	142·04	467·41	177·55	12
51	93·45	35·59	186·90	71·18	280·35	106·78	373·80	142·37	467·26	177·96	9
54	93·42	35·67	186·84	71·35	280·26	107·02	373·68	142·69	467·10	178·37	6
57	93·39	35·75	186·78	71·51	280·17	107·27	373·56	143·02	466·94	178·77	3
60	93·36	35·84	186·71	71·67	280·07	107·51	373·43	143·35	466·79	179·18	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

69 Deg.

20 Deg.

	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	563·81	205·21	657·78	239·41	751·75	273·61	845·72	307·82	939·69	342·02	60
3	563·63	205·70	657·57	239·99	751·51	274·27	845·45	308·55	939·39	342·84	57
6	563·45	206·19	657·36	240·56	751·27	274·93	845·19	309·29	939·09	343·66	54
9	563·28	206·69	657·15	241·13	751·03	275·58	844·92	310·03	938·79	344·48	51
2	563·10	207·18	656·94	241·71	750·79	276·24	844·64	310·77	938·49	345·30	48
5	562·91	207·67	656·73	242·28	750·55	276·89	844·37	311·50	938·19	346·12	45
8	562·73	208·16	656·52	242·85	750·31	277·55	844·10	312·24	937·89	346·93	42
1	562·55	208·65	656·31	243·43	750·07	278·20	843·83	312·98	937·59	347·75	39
4	562·37	209·14	656·10	244·00	749·83	278·86	843·55	313·71	937·28	348·57	36
7	562·18	209·63	655·88	244·57	749·58	279·51	843·28	314·45	936·98	349·39	33
0	562·00	210·12	655·67	245·14	749·34	280·16	843·00	315·19	936·67	350·21	30
3	561·82	210·61	655·45	245·72	749·09	280·82	842·73	315·92	936·37	351·02	27
6	561·64	211·10	655·24	246·29	748·85	281·47	842·45	316·66	936·06	351·84	24
9	561·45	211·59	655·02	246·86	748·60	282·13	842·17	317·39	935·75	352·66	21
2	561·26	212·08	654·81	247·43	748·35	282·78	841·90	318·13	935·44	353·47	18
5	561·08	212·57	654·59	248·00	748·11	283·43	841·62	318·86	935·13	354·29	15
8	560·89	213·06	654·38	248·57	747·86	284·08	841·34	319·60	934·82	355·11	12
1	560·71	213·55	654·16	249·14	747·61	284·74	841·06	320·33	934·51	355·92	9
4	560·52	214·04	653·94	249·72	747·36	285·39	840·78	321·06	934·20	356·74	6
7	560·33	214·53	653·72	250·29	747·11	286·04	840·50	321·80	933·89	357·55	3
0	560·15	215·02	653·50	250·86	746·86	286·69	840·22	322·53	933·58	358·37	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

69 Deg.

21 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	93·36	35·84	186·71	71·67	280·07	107·51	373·43	143·34	466·79	179·18	60
3	93·32	35·91	186·65	71·83	279·98	107·75	373·31	143·67	466·63	179·59	57
6	93·29	35·99	186·59	71·99	279·88	107·99	373·18	143·99	466·47	179·99	54
9	93·26	36·08	186·53	72·15	279·79	108·23	373·06	144·32	466·32	180·40	51
12	93·23	36·16	186·46	72·32	279·69	108·48	372·93	144·65	466·16	180·81	48
15	93·20	36·24	186·40	72·48	279·60	108·72	372·80	144·97	466·00	181·22	45
18	93·16	36·32	186·33	72·65	279·50	108·97	372·67	145·30	465·84	181·62	42
21	93·13	36·40	186·27	72·81	279·41	109·21	372·55	145·63	465·68	182·03	39
24	93·10	36·48	186·21	72·97	279·31	109·46	372·42	145·95	465·52	182·43	36
27	93·07	36·56	186·15	73·13	279·22	109·70	372·29	146·27	465·36	182·84	33
30	93·04	36·65	186·08	73·30	279·12	109·94	372·16	146·60	465·20	183·25	30
33	93·00	36·73	186·02	73·46	279·03	110·19	372·04	146·92	465·04	183·65	27
36	92·97	36·81	185·95	73·62	278·93	110·43	371·91	147·24	464·88	184·06	24
39	92·94	36·89	185·89	73·78	278·83	110·67	371·78	147·57	464·72	184·47	21
42	92·91	36·97	185·82	73·94	278·73	110·92	371·65	147·89	464·56	184·87	18
45	92·88	37·05	185·76	74·10	278·64	111·16	371·52	148·22	464·40	185·28	15
48	92·84	37·13	185·69	74·27	278·54	111·41	371·39	148·54	464·24	185·68	12
51	92·81	37·21	185·63	74·43	278·45	111·65	371·26	148·87	464·08	186·09	9
54	92·78	37·29	185·56	74·59	278·35	111·89	371·13	149·19	463·92	186·49	6
57	92·75	37·37	185·50	74·75	278·25	112·14	371·00	149·52	463·76	186·90	3
60	92·71	37·46	185·43	74·92	278·15	112·38	370·87	149·84	463·59	187·30	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

68 Deg.

21 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	560·14	215·02	653·50	250·85	746·86	286·69	840·22	322·53	933·58	358·37	60
3	559·96	215·50	653·28	251·42	746·61	287·34	839·94	323·26	933·26	359·18	57
6	559·77	215·99	653·06	251·99	746·36	287·99	839·66	323·99	932·95	359·99	54
9	559·58	216·48	652·84	252·56	746·11	288·64	839·38	324·72	932·64	360·81	51
2	559·39	216·97	652·62	253·13	745·86	289·29	839·09	325·46	932·32	361·62	48
5	559·20	217·46	652·40	253·70	745·61	289·94	838·81	326·19	932·01	362·44	45
8	559·01	217·95	652·18	254·27	745·35	290·60	838·52	326·92	931·69	363·25	42
1	558·82	218·44	651·96	254·84	745·10	291·25	838·24	327·65	931·37	364·06	39
4	558·63	218·92	651·73	255·41	744·84	291·90	837·95	328·38	931·05	364·87	36
7	558·44	219·41	651·51	255·98	744·59	292·55	837·66	329·11	930·73	365·69	33
10	558·24	219·90	651·29	256·55	744·33	293·20	837·37	329·85	930·41	366·50	30
3	558·05	220·39	651·07	257·12	744·08	293·85	837·08	330·58	930·09	367·31	27
6	557·86	220·87	650·84	257·68	743·82	294·50	836·79	331·31	929·77	368·12	24
9	557·67	221·36	650·62	258·25	743·56	295·15	836·50	332·04	929·45	368·93	21
2	557·47	221·84	650·39	258·82	743·30	295·79	836·21	332·77	929·13	369·74	18
5	557·28	222·33	650·17	259·39	743·04	296·44	835·92	333·50	928·81	370·55	15
8	557·09	222·82	649·94	259·95	742·78	297·09	835·63	334·23	928·48	371·36	12
1	556·90	223·31	649·71	260·52	742·52	297·74	835·34	334·96	928·16	372·17	9
4	556·70	223·79	649·48	261·09	742·26	298·39	835·05	335·68	927·83	372·98	6
7	556·50	224·28	649·25	261·66	742·00	299·04	834·75	336·41	927·51	373·79	3
0	556·30	224·76	649·02	262·22	741·74	299·68	834·46	337·14	927·18	374·60	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

68 Deg.

22 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	92·71	37·46	185·43	74·92	278·15	112·38	370·87	149·84	463·59	187·30	60
3	92·68	37·54	185·37	75·08	278·05	112·62	370·74	150·16	463·43	187·70	57
6	92·65	37·62	185·30	75·24	277·95	112·86	370·61	150·48	463·26	188·11	54
9	92·62	37·70	185·24	75·40	277·86	113·10	370·48	150·81	463·10	188·51	51
12	92·58	37·78	185·17	75·56	277·76	113·35	370·34	151·13	462·93	188·92	48
15	92·55	37·86	185·11	75·72	277·66	113·59	370·21	151·45	462·77	189·32	45
18	92·52	37·94	185·04	75·88	277·56	113·83	370·08	151·78	462·60	189·72	42
21	92·48	38·02	184·97	76·04	277·46	114·07	369·95	152·10	462·44	190·13	39
24	92·45	38·10	184·90	76·21	277·36	114·32	369·81	152·42	462·27	190·53	36
27	92·42	38·18	184·84	76·37	277·26	114·56	369·68	152·74	462·10	190·93	33
30	92·38	38·26	184·77	76·53	277·16	114·80	369·55	153·07	461·93	191·34	30
33	92·35	38·34	184·71	76·69	277·06	115·04	369·42	153·39	461·77	191·74	27
36	92·32	38·42	184·64	76·85	276·96	115·29	369·28	153·71	461·60	192·14	24
39	92·28	38·50	184·57	77·01	276·86	115·53	369·15	154·03	461·44	192·54	21
42	92·25	38·59	184·50	77·18	276·76	115·77	369·01	154·36	461·27	192·95	18
45	92·22	38·67	184·44	77·34	276·66	116·01	368·88	154·68	461·10	193·35	15
48	92·18	38·75	184·37	77·50	276·56	116·25	368·74	155·00	460·93	193·75	12
51	92·15	38·83	184·30	77·66	276·45	116·49	368·61	155·32	460·76	194·15	9
54	92·11	38·91	184·23	77·82	276·35	116·73	368·47	155·64	460·59	194·56	6
57	92·08	38·99	184·17	77·98	276·25	116·97	368·34	155·96	460·42	194·96	3
60	92·05	39·07	184·10	78·14	276·15	117·21	368·20	156·29	460·25	195·36	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

67 Deg.

22 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	556·30	224·76	649·02	262·22	741·74	299·68	834·46	337·14	927·18	374·60	60
3	556·11	225·24	648·79	262·79	741·48	300·33	834·17	337·87	926·85	375·41	57
6	555·91	225·73	648·56	263·35	741·22	300·97	833·87	338·60	926·52	376·22	54
9	555·72	226·21	648·33	263·92	740·96	301·62	833·58	339·33	926·19	377·03	51
12	555·52	226·70	648·10	264·48	740·69	302·27	833·28	340·05	925·86	377·84	48
15	555·32	227·18	647·87	265·05	740·43	302·92	832·99	340·78	925·53	378·64	45
18	555·12	227·67	647·64	265·61	740·16	303·56	832·69	341·51	925·20	379·45	42
21	554·92	228·15	647·41	266·18	739·90	304·21	832·39	342·24	924·87	380·26	39
24	554·72	228·64	647·18	266·74	739·63	304·85	832·09	342·96	924·54	381·07	36
27	554·52	229·12	646·95	267·31	739·37	305·50	831·79	343·69	924·21	381·88	33
30	554·32	229·61	646·71	267·87	739·10	306·14	831·49	344·41	923·87	382·68	30
33	554·12	230·09	646·48	268·44	738·83	306·79	831·19	345·14	923·54	383·48	27
36	553·92	230·57	646·24	269·00	738·56	307·43	830·89	345·86	923·20	384·28	24
39	553·72	231·06	646·01	269·57	738·30	308·08	830·59	346·59	922·87	385·09	21
42	553·52	231·54	645·77	270·13	738·08	308·72	830·28	347·31	922·53	385·90	18
45	553·32	232·03	645·54	270·70	737·76	309·37	829·98	348·04	922·20	386·70	15
48	553·11	232·51	645·30	271·26	737·49	310·01	829·67	348·76	921·86	387·51	12
51	552·91	233·00	645·06	271·82	737·22	310·66	829·37	349·49	921·52	388·31	9
54	552·71	233·47	644·82	272·38	736·94	311·30	829·06	350·21	921·18	389·12	6
57	552·51	233·95	644·59	272·94	736·67	311·94	828·76	350·93	920·84	389·92	3
60	552·30	234·43	644·35	273·51	736·40	312·58	828·45	351·65	920·50	390·73	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

67 Deg.

23 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	92·05	39·07	184·10	78·14	276·15	117·21	368·20	156·29	460·25	195·36	60
3	92·01	39·15	184·03	78·30	276·05	117·45	368·06	156·61	460·08	195·76	57
6	91·98	39·23	183·96	78·46	275·94	117·70	367·92	156·93	459·91	196·16	54
9	91·94	39·31	183·89	78·62	275·84	117·94	367·79	157·25	459·74	196·56	51
12	91·91	39·39	183·82	78·78	275·74	118·18	367·65	157·57	459·56	196·97	48
15	91·87	39·47	183·75	78·94	275·64	118·42	367·51	157·89	459·39	197·37	45
18	91·84	39·55	183·68	79·10	275·53	118·66	367·37	158·21	459·22	197·77	42
21	91·81	39·63	183·62	79·26	275·43	118·90	367·24	158·53	459·05	198·17	39
24	91·77	39·71	183·55	79·42	275·32	119·14	367·10	158·85	458·87	198·57	36
27	91·74	39·79	183·48	79·58	275·22	119·38	366·96	159·17	458·70	198·97	33
30	91·70	39·87	183·41	79·74	275·11	119·62	366·82	159·49	458·53	199·37	30
33	91·67	39·95	183·34	79·90	275·01	119·86	366·68	159·81	458·36	199·77	27
36	91·63	40·03	183·27	80·06	274·90	120·10	366·54	160·13	458·18	200·17	24
39	91·60	40·11	183·20	80·22	274·79	120·34	366·40	160·45	458·01	200·57	21
42	91·56	40·19	183·13	80·38	274·69	120·58	366·26	160·77	457·83	200·97	18
45	91·53	40·27	183·06	80·54	274·58	120·82	366·12	161·09	457·66	201·37	15
48	91·49	40·35	182·99	80·70	274·48	121·06	365·98	161·41	457·48	201·77	12
51	91·46	40·43	182·92	80·86	274·37	121·30	365·84	161·73	457·30	202·17	9
54	91·42	40·51	182·85	81·02	274·27	121·54	365·70	162·05	457·12	202·57	6
57	91·39	40·59	182·78	81·18	274·16	121·78	365·56	162·37	456·95	202·97	3
60	91·35	40·67	182·70	81·34	274·06	122·02	365·42	162·69	456·77	203·36	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

66 Deg.

23 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	552·30	234·43	644·35	273·51	736·40	312·58	828·45	351·65	920·50	390·73	60
3	552·10	234·91	644·11	274·07	736·13	313·22	828·15	352·37	920·16	391·53	57
6	551·89	235·40	643·87	274·63	735·85	313·86	827·84	353·10	919·82	392·33	54
9	551·68	235·88	643·63	275·19	735·58	314·50	827·53	353·82	919·48	393·14	51
12	551·47	236·36	643·39	275·75	735·30	315·15	827·22	354·54	919·13	393·94	48
15	551·27	236·84	643·15	276·31	735·03	315·79	826·91	355·26	918·79	394·74	45
18	551·06	237·32	642·91	276·88	734·75	316·43	826·60	355·99	918·44	395·54	42
21	550·86	237·80	642·67	277·44	734·48	317·07	826·29	356·71	918·10	396·34	39
24	550·65	238·28	642·42	278·00	734·20	317·71	825·98	357·43	917·75	397·14	36
27	550·44	238·76	642·18	278·56	733·92	318·35	825·67	358·15	917·40	397·94	33
30	550·23	239·24	641·93	279·12	733·64	318·99	825·35	358·87	917·05	398·74	30
33	550·02	239·72	641·69	279·68	733·36	319·63	825·04	359·59	916·71	399·54	27
36	549·81	240·20	641·45	280·24	733·08	320·27	824·72	360·31	916·36	400·34	24
39	549·60	240·68	641·21	280·80	732·80	320·91	824·41	361·03	916·01	401·14	21
42	549·39	241·16	640·96	281·36	732·52	321·55	824·09	361·75	915·66	401·94	18
45	549·18	241·64	640·72	281·92	732·24	322·19	823·78	362·47	915·31	402·74	15
48	548·97	242·12	640·47	282·48	731·96	322·83	823·46	363·19	914·95	403·54	12
51	548·76	242·60	640·22	283·04	731·68	323·47	823·14	363·91	914·60	404·34	9
54	548·55	243·08	639·97	283·60	731·40	324·11	822·82	364·62	914·25	405·14	6
57	548·34	243·56	639·73	284·16	731·12	324·75	822·51	365·34	913·90	405·94	3
60	548·12	244·04	639·48	284·71	730·83	325·38	822·19	366·06	913·54	406·73	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

66 Deg.

24 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	91·35	40·67	182·70	81·34	274·06	122·02	365·42	162·69	456·77	203·36	60
3	91·31	40·75	182·63	81·50	273·95	122·26	365·28	163·01	456·59	203·76	57
6	91·28	40·82	182·56	81·66	273·84	122·49	365·13	163·33	456·41	204·16	54
9	91·24	40·91	182·49	81·82	273·74	122·73	364·99	163·65	456·24	204·56	51
12	91·21	40·99	182·42	81·98	273·63	122·97	364·84	163·96	456·06	204·96	48
15	91·17	41·07	182·35	82·14	273·53	123·21	364·70	164·28	455·88	205·36	45
18	91·14	41·15	182·28	82·30	273·42	123·45	364·56	164·60	455·70	205·75	42
21	91·10	41·23	182·21	82·46	273·31	123·69	364·42	164·92	455·52	206·15	39
24	91·06	41·31	182·13	82·62	273·20	123·93	364·27	165·24	455·34	206·55	36
27	91·03	41·39	182·06	82·78	273·09	124·17	364·13	165·56	455·16	206·95	33
30	90·99	41·46	181·99	82·93	272·98	124·40	363·98	165·87	454·98	207·34	30
33	90·95	41·54	181·92	83·09	272·88	124·64	363·84	166·19	454·80	207·74	27
36	90·92	41·62	181·84	83·25	272·77	124·88	363·69	166·51	454·61	208·14	24
39	90·88	41·70	181·77	83·41	272·66	125·12	363·55	166·83	454·43	208·54	21
42	90·85	41·78	181·70	83·57	272·55	125·36	363·41	167·14	454·25	208·93	18
45	90·81	41·86	181·63	83·73	272·44	125·60	363·26	167·46	454·07	209·33	15
48	90·77	41·94	181·55	83·89	272·33	125·83	363·11	167·78	453·88	209·72	12
51	90·74	42·02	181·48	84·05	272·22	126·07	362·96	168·10	453·70	210·12	9
54	90·70	42·10	181·40	84·20	272·11	126·31	362·82	168·41	453·52	210·51	6
57	90·66	42·18	181·33	84·36	272·00	126·55	362·67	168·73	453·34	210·91	3
60	90·63	42·26	181·26	84·52	271·89	126·78	362·52	169·04	453·15	211·30	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

65 Deg.

24 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	548·12	244·04	639·48	284·71	730·83	325·38	822·19	366·06	913·54	406·73	60
3	547·91	244·52	639·23	285·27	730·55	326·02	821·87	366·78	913·19	407·53	57
6	547·70	244·99	638·98	285·83	730·26	326·66	821·54	367·49	912·83	408·33	54
9	547·49	245·47	638·73	286·39	729·98	327·30	821·22	368·21	912·48	409·13	51
12	547·27	245·95	638·48	286·94	729·69	327·93	820·90	368·93	912·12	409·92	48
15	547·06	246·43	638·23	287·50	729·41	328·57	820·58	369·65	911·76	410·72	45
18	546·84	246·90	637·98	288·06	729·12	329·21	820·26	370·36	911·40	411·51	42
21	546·62	247·38	637·73	288·62	728·83	329·85	819·94	371·08	911·04	412·31	39
24	546·40	247·86	637·47	289·17	728·54	330·48	819·61	371·79	910·67	413·10	36
27	546·19	248·34	637·22	289·73	728·25	331·12	819·29	372·51	910·31	413·90	33
30	545·97	248·81	636·97	290·28	727·96	331·75	818·96	373·22	909·95	414·69	30
33	545·76	249·29	636·72	290·84	727·67	332·39	818·64	373·94	909·59	415·49	27
36	545·54	249·76	636·46	291·39	727·38	333·02	818·31	374·65	909·23	416·28	24
39	545·32	250·24	636·21	291·95	727·09	333·66	817·98	375·37	908·87	417·07	21
42	545·10	250·72	635·95	292·50	726·80	334·29	817·65	376·08	908·50	417·86	18
45	544·88	251·20	635·70	293·06	726·51	334·93	817·33	376·79	908·14	418·66	15
48	544·66	251·67	635·44	293·61	726·22	335·56	817·00	377·50	907·77	419·45	12
51	544·44	252·15	635·19	294·17	725·93	336·19	816·67	378·22	907·41	420·24	9
54	544·22	252·62	634·93	294·72	725·63	336·82	816·34	378·93	907·04	421·03	6
57	544·00	253·10	634·67	295·28	725·34	337·46	816·01	379·64	906·67	421·82	3
60	543·78	253·57	634·41	295·83	725·04	338·09	815·67	380·35	906·30	422·61	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

65 Deg.

25 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	90·63	42·26	181·26	84·52	271·89	126·78	362·52	169·04	453·15	211·30	60
3	90·59	42·34	181·19	84·68	271·78	127·02	362·37	169·36	452·97	211·70	57
6	90·55	42·42	181·11	84·84	271·67	127·25	362·22	169·68	452·78	212·10	54
9	90·51	42·49	181·04	84·99	271·56	127·49	362·08	170·00	452·60	212·49	51
12	90·48	42·57	180·96	85·15	271·44	127·73	361·93	170·31	452·41	212·88	48
15	90·44	42·65	180·89	85·31	271·33	127·97	361·78	170·63	452·23	213·28	45
18	90·40	42·73	180·81	85·47	271·22	128·20	361·63	170·94	452·04	213·67	42
21	90·37	42·81	180·74	85·63	271·11	128·44	361·48	171·26	451·85	214·07	39
24	90·33	42·89	180·66	85·78	271·00	128·68	361·33	171·57	451·66	214·46	36
27	90·29	42·97	180·59	85·94	270·89	128·92	361·18	171·89	451·48	214·86	33
30	90·25	43·05	180·51	86·10	270·77	129·15	361·03	172·20	451·29	215·25	30
33	90·22	43·13	180·44	86·26	270·66	129·39	360·88	172·52	451·10	215·65	27
36	90·18	43·20	180·36	86·41	270·55	129·62	360·73	172·83	450·91	216·04	24
39	90·14	43·28	180·29	86·57	270·44	129·86	360·58	173·15	450·72	216·44	21
42	90·10	43·36	180·21	86·73	270·32	130·09	360·43	173·46	450·53	216·83	18
45	90·06	43·44	180·14	86·89	270·21	130·33	360·28	173·78	450·34	217·22	15
48	90·03	43·52	180·06	87·04	270·09	130·56	360·12	174·09	450·15	217·61	12
51	89·99	43·59	179·99	87·20	269·98	130·80	359·97	174·41	449·96	218·01	9
54	89·95	43·67	179·91	87·36	269·86	131·04	359·82	174·72	449·77	218·40	6
57	89·91	43·75	179·83	87·52	269·75	131·27	359·67	175·03	449·58	218·79	3
60	89·87	43·83	179·75	87·67	269·63	131·51	359·51	175·34	449·39	219·18	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

64 Deg.

25 Deg.

Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
543·78	253·57	634·41	295·83	725·04	338·09	815·67	380·35	906·30	422·61	60
543·56	254·04	634·15	296·38	724·75	338·73	815·34	381·06	905·93	423·40	57
543·34	254·51	633·89	296·94	724·45	339·36	815·01	381·78	905·56	424·20	54
543·12	254·99	633·63	297·49	724·16	340·00	814·68	382·49	905·19	424·99	51
542·89	255·46	633·37	298·04	723·86	340·63	814·34	383·20	904·82	425·78	48
542·67	255·94	633·11	298·60	723·56	341·26	814·01	383·91	904·45	426·57	45
542·44	256·41	632·85	299·15	723·26	341·89	813·67	384·62	904·08	427·35	42
542·22	256·89	632·59	299·70	722·96	342·52	813·34	385·33	903·71	428·14	39
542·00	257·36	632·33	300·25	722·66	343·15	813·00	386·04	903·33	428·93	36
541·78	257·83	632·07	300·80	722·36	343·78	812·66	386·75	902·96	429·72	33
541·55	258·30	631·81	301·35	722·06	344·40	812·32	387·46	902·58	430·51	30
541·32	258·77	631·55	301·90	721·76	345·03	811·98	388·17	902·21	431·30	27
541·09	259·25	631·28	302·45	721·46	345·66	811·64	388·87	901·83	432·08	24
540·87	259·72	631·02	303·00	721·16	346·29	811·30	389·58	901·45	432·87	21
540·64	260·19	630·75	303·56	720·86	346·92	810·96	390·29	901·07	433·65	18
540·42	260·67	630·49	304·11	720·56	347·55	810·62	391·00	900·69	434·44	15
540·19	261·14	630·22	304·66	720·25	348·18	810·28	391·70	900·31	435·23	12
539·96	261·61	629·96	305·21	719·95	348·81	809·94	392·41	899·93	435·92	9
539·73	262·08	629·69	305·76	719·64	349·44	809·60	393·12	899·55	436·80	6
539·50	262·55	629·42	306·31	719·34	350·07	809·26	393·83	899·17	437·59	3
539·27	263·02	629·15	306·86	719·03	350·69	808·91	394·53	898·79	438·37	0
Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

64 Deg.

26 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist.
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.
0	89·87	43·83	179·75	87·67	269·63	131·51	359·51	175·34	449·39
3	89·84	43·91	179·68	87·83	269·52	131·75	359·36	175·65	449·20
6	89·80	43·99	179·60	87·98	269·40	131·98	359·21	175·97	449·01
9	89·76	44·07	179·53	88·14	269·29	132·22	359·06	176·28	448·82
12	89·72	44·15	179·45	88·30	269·17	132·45	358·90	176·60	448·62
15	89·68	44·22	179·37	88·46	269·06	132·69	358·75	176·91	448·43
18	89·64	44·30	179·29	88·61	268·94	132·92	358·59	177·22	448·24
21	89·61	44·38	179·22	88·77	268·83	133·16	358·44	177·53	448·05
24	89·57	44·46	179·14	88·92	268·71	133·39	358·28	177·85	447·85
27	89·53	44·54	179·06	89·08	268·59	133·63	358·13	178·16	447·66
30	89·49	44·61	178·98	89·23	268·47	133·86	357·97	178·47	447·46
33	89·45	44·69	178·91	89·39	268·36	134·09	357·82	178·78	447·27
36	89·41	44·77	178·83	89·55	268·24	134·32	357·66	179·10	447·07
39	89·37	44·85	178·75	89·71	268·13	134·56	357·50	179·41	446·88
42	89·33	44·93	178·67	89·86	268·01	134·79	357·34	179·72	446·68
45	89·29	45·00	178·59	90·02	267·89	135·03	357·19	180·03	446·49
48	89·25	45·08	178·51	90·17	267·77	135·26	357·03	180·35	446·29
51	89·21	45·16	178·43	90·33	267·65	135·50	356·87	180·66	446·10
54	89·17	45·24	178·35	90·48	267·53	135·73	356·71	180·97	445·90
57	89·14	45·32	178·28	90·64	267·42	135·96	356·56	181·28	445·70
60	89·10	45·39	178·20	90·79	267·30	136·19	356·40	181·59	445·50
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist.

63 Deg.

26 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	539·27	263·02	629·15	306·86	719·03	350·69	808·91	394·53	898·79	438·37	60
3	539·04	263·49	628·88	307·41	718·73	351·32	808·57	395·24	898·41	439·15	57
6	538·81	263·96	628·61	307·95	718·42	351·95	808·22	395·94	898·02	439·93	54
9	538·58	264·43	628·34	308·50	718·11	352·58	807·88	396·65	897·64	440·71	51
12	538·35	264·90	628·07	309·05	717·80	353·20	807·53	397·35	897·25	441·50	48
15	538·12	265·37	627·81	309·60	717·49	353·83	807·18	398·06	896·87	442·28	45
18	537·89	265·84	627·54	310·14	717·18	354·45	806·83	398·76	896·48	443·06	42
21	537·66	266·31	627·27	310·69	716·87	355·08	806·49	399·47	896·10	443·84	39
24	537·42	266·78	626·99	311·24	716·56	355·70	806·14	400·17	895·71	444·63	36
27	537·19	267·25	626·72	311·79	716·25	356·33	805·79	400·88	895·32	445·41	33
30	536·96	267·71	626·45	312·33	715·94	356·95	805·44	401·58	894·93	446·19	30
33	536·73	268·18	626·18	312·88	715·63	357·58	805·09	402·28	894·54	446·97	27
36	536·49	268·65	625·90	313·43	715·32	358·20	804·73	402·98	894·15	447·75	24
39	536·26	269·12	625·63	313·97	715·01	358·83	804·38	403·68	893·76	448·53	21
42	536·02	269·59	625·36	314·52	714·69	359·45	804·03	404·38	893·37	449·31	18
45	535·79	270·06	625·09	315·07	714·38	360·08	803·68	405·08	892·98	450·09	15
48	535·55	270·52	624·81	315·61	714·06	360·70	803·32	405·78	892·58	450·87	12
51	535·31	270·99	624·53	316·16	713·75	361·32	802·97	406·48	892·19	451·65	9
54	535·07	271·46	624·25	316·70	713·43	361·94	802·61	407·19	891·79	452·43	6
57	534·84	271·93	623·98	317·25	713·12	362·57	802·26	407·89	891·40	453·21	3
60	534·60	272·39	623·70	317·79	712·80	363·19	801·90	408·59	891·00	453·99	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

63 Deg.

27 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	89·10	45·39	178·20	90·79	267·30	136·19	356·40	181·59	445·50	226·99	60
3	89·06	45·47	178·12	90·94	267·18	136·42	356·24	181·90	445·30	227·38	57
6	89·02	45·55	178·04	91·10	267·06	136·66	356·08	182·21	445·10	227·77	54
9	88·98	45·63	177·96	91·25	266·94	136·89	355·92	182·52	444·90	228·16	51
12	88·94	45·70	177·88	91·41	266·82	137·12	355·76	182·83	444·70	228·54	48
15	88·90	45·78	177·80	91·57	266·70	137·35	355·60	183·14	444·50	228·93	45
18	88·86	45·86	177·72	91·73	266·58	137·59	355·44	183·46	444·30	229·32	42
21	88·82	45·94	177·64	91·88	266·46	137·82	355·28	183·77	444·10	229·71	39
24	88·78	46·01	177·56	92·04	266·34	138·06	355·12	184·08	443·90	230·10	36
27	88·74	46·09	177·48	92·19	266·22	138·29	354·96	184·39	443·70	230·49	33
30	88·70	46·17	177·40	92·35	266·10	138·52	354·80	184·70	443·50	230·87	30
33	88·66	46·25	177·32	92·50	265·98	138·76	354·64	185·01	443·30	231·26	27
36	88·62	46·32	177·24	92·65	265·86	138·99	354·48	185·31	443·10	231·64	24
39	88·58	46·40	177·16	92·81	265·74	139·22	354·32	185·62	442·90	232·03	21
42	88·53	46·48	177·07	92·96	265·61	139·45	354·15	185·93	442·69	232·42	18
45	88·49	46·56	176·99	93·11	265·49	139·68	353·99	186·24	442·49	232·81	15
48	88·45	46·63	176·91	93·27	265·37	139·91	353·83	186·55	442·29	233·19	12
51	88·41	46·71	176·83	93·42	265·25	140·14	353·67	186·86	442·09	233·58	9
54	88·37	46·79	176·75	93·58	265·12	140·37	353·50	187·17	441·88	233·96	6
57	88·33	46·86	176·67	93·73	265·00	140·60	353·34	187·48	441·68	234·35	3
60	88·29	46·94	176·59	93·89	264·88	140·84	353·18	187·78	441·47	234·73	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

62 Deg.

27 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	534·60	272·39	623·70	317·79	712·80	363·19	801·90	408·59	891·00	453·99	60
3	534·36	272·86	623·42	318·34	712·48	363·81	801·55	409·29	890·60	454·77	57
6	534·12	273·32	623·14	318·88	712·16	364·43	801·19	409·99	890·20	455·54	54
9	533·88	273·79	622·87	319·42	711·85	365·05	800·83	410·69	889·80	456·32	51
12	533·64	274·25	622·59	319·96	711·53	365·67	800·47	411·38	889·40	457·09	48
15	533·40	274·72	622·31	320·51	711·21	366·29	800·11	412·08	889·01	457·87	45
18	533·16	275·18	622·03	321·05	710·89	366·91	799·75	412·78	888·61	458·64	42
21	532·92	275·65	621·75	321·59	710·57	367·53	799·39	413·48	888·21	459·42	39
24	532·68	276·11	621·47	322·13	710·25	368·15	799·03	414·18	887·81	460·19	36
27	532·44	276·58	621·19	322·67	709·93	368·77	798·67	414·88	887·41	460·97	33
30	532·20	277·04	620·90	323·22	709·60	369·39	798·31	415·57	887·00	461·74	30
33	531·96	277·51	620·62	323·76	709·28	370·01	797·95	416·27	886·60	462·51	27
36	531·72	277·97	620·34	324·30	708·96	370·63	797·58	416·96	886·20	463·29	24
39	531·48	278·44	620·06	324·84	708·64	371·25	797·22	417·66	885·80	464·07	21
42	531·23	278·90	619·77	325·38	708·31	371·87	796·85	418·35	885·39	464·84	18
45	530·99	279·37	619·49	325·92	707·99	372·49	796·49	419·05	884·98	465·61	15
48	530·74	279·83	619·20	326·47	707·66	373·10	796·12	419·74	884·57	466·38	12
51	530·50	280·29	618·92	327·01	707·34	373·72	795·76	420·44	884·17	467·15	9
54	530·25	280·75	618·63	327·55	707·01	374·34	795·39	421·13	883·76	467·92	6
57	530·01	281·22	618·35	328·09	706·69	374·96	795·02	421·83	883·36	468·69	3
60	529·77	281·68	618·06	328·63	706·36	375·57	794·65	422·52	882·95	469·47	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

62 Deg.

28 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	88 29	46·94	176·59	93·89	264·88	140·84	353·18	187·78	441·47	234·73	60
3	88·25	47·02	176·51	94·04	264·76	141·07	353·02	188·09	441·27	235·12	57
6	88·21	47·10	176·42	94·20	264·63	141·30	352·85	188·40	441·06	235·50	54
9	88·17	47·17	176·34	94·35	264·51	141·53	352·69	188·71	440·86	235·89	51
12	88·13	47·25	176·26	94·51	264·39	141·76	352·52	189·02	440·65	236·27	48
15	88·08	47·33	176·18	94·66	264·27	141·99	352·35	189·33	440·44	236·66	45
18	88·04	47·40	176·09	94·81	264·14	142·22	352·18	189·63	440·23	237·04	42
21	88·00	47·48	176·01	94·96	264·02	142·45	352·02	189·94	440·03	237·43	39
24	87·96	47·56	175·92	95·12	263·89	142·68	351·85	190·24	439·82	237·81	36
27	87·92	47·63	175·84	95·27	263·77	142·91	351·69	190·55	439·61	238·19	33
30	87·88	47·71	175·76	95·43	263·64	143·13	351·52	190·86	439·40	238·57	30
33	87·84	47·79	175·68	95·58	263·52	143·36	351·35	191·17	439·20	238·95	27
36	87·79	47·86	175·59	95·73	263·39	143·60	351·18	191·47	438·99	239·34	24
39	87·75	47·94	175·51	95·88	263·27	143·83	351·02	191·78	438·78	239·72	21
42	87·71	48·02	175·42	96·04	263·14	144·06	350·85	192·08	438·57	240·11	18
45	87·67	48·09	175·34	96·19	263·02	144·29	350·69	192·39	438·36	240·49	15
48	87·63	48·17	175·26	96·35	262·89	144·52	350·52	192·70	438·15	240·87	12
51	87·58	48·25	175·18	96·50	262·76	144·75	350·35	193·01	437·94	241·25	9
54	87·54	48·32	175·09	96·65	262·63	144·98	350·18	193·31	437·73	241·64	6
57	87·50	48·40	175·01	96·80	262·51	145·21	350·01	193·62	437·52	242·02	3
60	87·46	48·48	174·92	96·96	262·38	145·44	349·84	193·92	437·31	242·40	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

61 Deg.

28 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	529·77	281·68	618·06	328·63	706·36	375·57	794·65	422·52	882·95	469·47	60
3	529·52	282·14	617·77	329·17	706·03	376·19	794·28	423·22	882·54	470·24	57
6	529·27	282·60	617·48	329·70	705·70	376·80	793·91	423·91	882·12	471·01	54
9	529·03	283·06	617·20	330·24	705·37	377·42	793·54	424·60	881·71	471·78	51
12	528·78	283·53	616·91	330·78	705·04	378·04	793·17	425·29	881·30	472·55	48
15	528·53	283·99	616·62	331·32	704·71	378·66	792·80	425·98	880·89	473·32	45
18	528·28	284·45	616·33	331·86	704·38	379·27	792·43	426·67	880·47	474·08	42
21	528·03	284·91	616·04	332·40	704·05	379·89	792·06	427·36	880·06	474·85	39
24	527·78	285·37	615·75	332·93	703·71	380·50	791·68	428·06	879·64	475·62	36
27	527·54	285·83	615·46	333·47	703·38	381·11	791·31	428·75	879·23	476·39	33
30	527·29	286·29	615·16	334·01	703·05	381·72	790·93	429·44	878·81	477·15	30
33	527·04	286·75	614·87	334·55	702·71	382·33	790·56	430·13	878·40	477·92	27
36	526·79	287·21	614·58	335·08	702·38	382·95	790·18	430·82	877·98	478·69	24
39	526·54	287·67	614·29	335·62	702·05	383·56	789·81	431·51	877·56	479·46	21
42	526·28	288·13	614·00	336·15	701·71	384·17	789·43	432·20	877·14	480·22	18
45	526·03	288·59	613·71	336·69	701·38	384·78	789·05	432·89	876·72	480·99	15
48	525·78	289·05	613·41	337·22	701·04	385·40	788·67	433·57	876·30	481·76	12
51	525·53	289·51	613·12	337·76	700·70	386·01	788·29	434·26	875·88	482·52	9
54	525·27	289·96	612·82	338·29	700·37	386·62	787·91	434·95	875·46	483·28	6
57	525·02	290·42	612·53	338·83	700·03	387·23	787·53	435·64	875·04	484·04	3
60	524·77	290·88	612·23	339·36	699·69	387·84	787·15	436·33	874·62	484·80	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

61 Deg..

29 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	87·46	48·48	174·92	96·96	262·38	145·44	349·84	193·92	437·31	242·40	60
3	87·42	48·55	174·84	97·11	262·26	145·67	349·67	194·22	437·10	242·78	57
6	87·37	48·63	174·75	97·26	262·13	145·90	349·50	194·53	436·88	243·16	54
9	87·33	48·70	174·67	97·41	262·00	146·13	349·33	194·83	436·67	243·54	51
12	87·29	48·78	174·58	97·57	261·87	146·35	349·16	195·14	436·46	243·92	48
15	87·25	48·86	174·50	97·72	261·75	146·58	348·99	195·44	436·25	244·30	45
18	87·20	48·93	174·41	97·87	261·62	146·81	348·82	195·75	436·03	244·69	42
21	87·16	49·01	174·33	98·02	261·49	147·04	348·65	196·05	435·82	245·07	39
24	87·12	49·09	174·24	98·18	261·36	147·27	348·48	196·36	435·60	245·45	36
27	87·07	49·16	174·16	98·33	261·23	147·50	348·31	196·66	435·39	245·83	33
30	87·03	49·24	174·07	98·48	261·10	147·72	348·14	196·96	435·17	246·21	30
33	86·99	49·31	173·98	98·63	260·97	147·95	347·97	197·26	434·96	246·59	27
36	86·94	49·39	173·89	98·78	260·84	148·18	347·79	197·57	434·74	246·97	24
39	86·90	49·47	173·81	98·93	260·71	148·41	347·62	197·87	434·53	247·35	21
42	86·86	49·54	173·72	99·09	260·58	148·63	347·45	198·18	434·31	247·72	18
45	86·82	49·62	173·64	99·24	260·45	148·86	347·28	198·48	434·10	248·10	15
48	86·77	49·69	173·55	99·39	260·32	149·09	347·10	198·78	433·88	248·48	12
51	86·73	49·77	173·46	99·54	260·19	149·32	346·93	199·08	433·66	248·86	9
54	86·68	49·84	173·37	99·69	260·06	149·54	346·75	199·39	433·44	249·24	6
57	86·64	49·92	173·29	99·84	259·93	149·77	346·58	199·69	433·23	249·62	3
60	86·60	50·00	173·20	100·00	259·80	150·00	346.40	200·00	433·01	250·00	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

60 Deg.

29 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	524·77	290·88	612·23	339·36	699·69	387·84	787·15	436·33	874·62	484·80	60
3	524·52	291·34	611·94	339·89	699·35	388·45	786·77	437·02	874·20	485·56	57
6	524·26	291·80	611·64	340·43	699·01	389·06	786·39	437·70	873·77	486·33	54
9	524·01	292·26	611·34	340·96	698·67	389·67	786·01	438·39	873·35	487·09	51
12	523·75	292·71	611·04	341·50	698·33	390·28	785·63	439·07	872·92	487·85	48
15	523·50	293·17	610·74	342·03	697·99	390·89	785·25	439·76	872·50	488·61	45
18	523·24	293·62	610·44	342·56	697·65	391·50	784·86	440·44	872·07	489·38	42
21	522·98	294·08	610·14	343·09	697·31	392·11	784·48	441·13	871·64	490·14	39
24	522·72	294·54	609·84	343·63	696·97	392·72	784·09	441·81	871·21	490·90	36
27	522·47	295·00	609·54	344·16	696·63	393·33	783·71	442·50	870·78	491·66	33
30	522·21	295·45	609·24	344·69	696·28	393·93	783·32	443·18	870·35	492·42	30
33	521·95	295·91	608·94	345·22	695·94	394·54	782·93	443·87	869·92	493·18	27
36	521·69	296·36	608·64	345·75	695·59	395·15	782·54	444·55	869·49	493·94	24
39	521·43	296·82	608·34	346·28	695·25	395·76	782·15	445·23	869·06	494·70	21
42	521·17	297·27	608·04	346·82	694·90	396·36	781·76	445·91	868·63	495·45	18
45	520·91	297·73	607·74	347·35	694·56	396·96	781·37	446·59	868·20	496·21	15
48	520·65	298·18	607·43	347·88	694·21	397·57	780·98	447·27	867·76	496·97	12
51	520·39	298·64	607·13	348·41	693·86	398·18	780·59	447·95	867·33	497·73	9
54	520·13	299·09	606·82	348·94	693·51	398·78	780·20	448·63	866·89	498·48	6
57	519·87	299·55	606·52	349·47	693·16	399·39	779·81	449·31	866·46	499·24	3
60	519·61	300·00	606·21	350·00	692·81	400·00	779·42	450·00	866·02	500·00	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

60 Deg.

30 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	86·60	50·00	173·20	100·00	259·80	150·00	346·40	200·00	433·01	250·00	60
3	86·55	50·07	173·12	100·15	259·67	150·23	346·23	200·30	432·79	250·38	57
6	86·51	50·15	173·03	100·30	259·54	150·45	346·05	200·60	432·57	250·75	54
9	86·47	50·22	172·94	100·45	259·41	150·68	345·88	200·90	432·35	251·13	51
12	86·42	50·30	172·85	100·60	259·28	150·90	345·70	201·20	432·13	251·50	48
15	86·38	50·37	172·76	100·75	259·15	151·13	345·53	201·50	431·91	251·88	45
18	86·33	50·45	172·67	100·90	259·01	151·35	345·35	201·81	431·69	252·26	42
21	86·29	50·52	172·59	101·05	258·88	151·58	345·18	202·11	431·47	252·64	39
24	86·25	50·60	172·50	101·20	258·75	151·80	345·00	202·41	431·25	253·01	36
27	86·20	50·67	172·41	101·35	258·62	152·03	344·83	202·71	431·03	253·39	33
30	86·16	50·75	172·32	101·50	258·48	152·26	344·65	203·01	430·81	253·76	30
33	86·11	50·82	172·23	101·65	258·35	152·49	344·47	203·31	430·59	254·14	27
36	86·07	50·90	172·14	101·80	258·22	152·71	344·29	203·61	430·37	254·52	24
39	86·03	50·97	172·06	101·95	258·09	152·94	344·12	203·91	430·15	254·90	21
42	85·98	51·05	171·97	102·10	257·95	153·16	343·94	204·21	429·92	255·27	18
45	85·94	51·12	171·88	102·25	257·82	153·39	343·76	204·51	429·70	255·65	15
48	85·89	51·20	171·79	102·40	257·68	153·61	343·58	204·81	429·48	256·02	12
51	85·85	51·27	171·70	102·55	257·55	153·84	343·40	205·11	429·26	256·40	9
54	85·80	51·35	171·61	102·70	257·41	154·06	343·22	205·41	429·03	256·77	6
57	85·76	51·42	171·52	102·85	257·28	154·29	343·04	205·71	428·81	257·14	3
60	85·71	51·50	171·43	103·00	257·15	154·51	342·86	206·01	428·58	257·51	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

59 Deg.

30 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	519·61	300·00	606·21	350·00	692·81	400·00	779·42	450·00	866·02	500·00	60
3	519·35	300·45	605·91	350·53	692·47	400·60	779·03	450·68	865·59	500·76	57
6	519·09	300·90	605·60	351·05	692·12	401·20	778·63	451·36	865·15	501·51	54
9	518·83	301·35	605·30	351·58	691·77	401·80	778·24	452·04	864·71	502·26	51
12	518·56	301·81	604·99	352·11	691·41	402·41	777·84	452·71	864·27	503·01	48
15	518·30	302·26	604·68	352·64	691·06	403·01	777·45	453·39	863·83	503·76	45
18	518·03	302·71	604·37	353·16	690·71	403·62	777·05	454·07	863·39	504·52	42
21	517·77	303·16	604·06	353·69	690·36	404·22	776·66	454·75	862·95	505·27	39
24	517·50	303·61	603·75	354·22	690·01	404·82	776·26	455·43	862·51	506·03	36
27	517·24	304·06	603·45	354·75	689·66	405·42	775·86	456·11	862·07	506·78	33
30	516·97	304·52	603·14	355·27	689·30	406·03	775·46	456·78	861·62	507·53	30
33	516·71	304·97	602·83	355·80	688·95	406·63	775·06	457·46	861·18	508·28	27
36	516·44	305·42	602·52	356·32	688·59	407·23	774·66	458·13	860·74	509·04	24
39	516·17	305·87	602·21	356·85	688·24	407·83	774·26	458·81	860·30	509·79	21
42	515·90	306·33	601·89	357·38	687·88	408·43	773·86	459·48	859·85	510·54	18
45	515·64	306·78	601·58	357·91	687·52	409·03	773·46	460·16	859·40	511·29	15
48	515·37	307·23	601·27	358·43	687·16	409·63	773·06	460·83	858·95	512·04	12
51	515·10	307·68	600·96	358·95	686·81	410·23	772·66	461·51	858·51	512·79	9
54	514·83	308·13	600·64	359·47	686·45	410·83	772·25	462·18	858·06	513·54	6
57	514·57	308·58	600·33	359·99	686·09	411·43	771·85	462·86	857·61	514·29	3
60	514·30	309·02	600·01	360·52	685·73	412·03	771·45	463·53	857·16	515·04	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

59 Deg.

31 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	85·71	51·50	171·43	103·00	257·15	154·51	342·86	206·01	428·58	257·51	60
3	85·67	51·57	171·34	103·15	257·02	154·73	342·68	206·31	428·36	257·88	57
6	85·62	51·65	171·25	103·30	256·88	154·95	342·50	206·61	428·13	258·26	54
9	85·58	51·72	171·16	103·45	256·74	155·17	342·32	206·91	427·91	258·63	51
12	85·53	51·80	171·07	103·60	256·60	155·40	342·14	207·21	427·68	259·01	48
15	85·49	51·87	170·98	103·75	256·47	155·62	341·96	207·51	427·46	259·38	45
18	85·44	51·95	170·89	103·90	256·33	155·85	341·78	207·80	427·23	259·75	42
21	85·40	52·02	170·80	104·05	256·20	156·07	341·60	208·10	427·00	260·12	39
24	85·35	52·10	170·70	104·20	256·06	156·30	341·41	208·40	426·77	260·50	36
27	85·31	52·17	170·61	104·35	255·93	156·52	341·23	208·70	426·55	260·87	33
30	85·26	52·24	170·52	104·50	255·79	156·74	341·05	209·00	426·32	261·24	30
33	85·21	52·32	170·43	104·65	255·65	156·96	340·87	209·30	426·09	261·62	27
36	85·17	52·39	170·34	104·79	255·51	157·19	340·69	209·59	425·86	261·99	24
39	85·12	52·47	170·25	104·94	255·38	157·41	340·51	209·89	425·63	262·36	21
42	85·08	52·54	170·16	105·09	255·24	157·64	340·32	210·19	425·40	262·73	18
45	85·03	52·62	170·07	105·24	255·10	157·86	340·14	210·49	425·17	263·10	15
48	84·98	52·69	169·97	105·39	254·96	158·08	339·95	210·79	424·94	263·47	12
51	84·94	52·76	169·88	105·54	254·83	158·30	339·77	211·08	424·71	263·84	9
54	84·89	52·84	169·79	105·68	254·69	158·53	339·58	211·37	424·48	264·21	6
57	84·85	52·91	169·70	105·83	254·55	158·75	339·40	211·67	424·28	264·58	3
60	84·80	52·99	169·60	105·98	254·41	158·97	339·21	211·96	424·02	264·95	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

58 Deg.

31 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	514·30	309·02	600·01	360·52	685·73	412·03	771·45	463·53	857·16	515·04	60
3	514·03	309·47	599·70	361·04	685·37	412·63	771·05	464·20	856·71	515·79	57
6	513·76	309·91	599·38	361·57	685·01	413·22	770·64	464·88	856·26	516·53	54
9	513·49	310·36	599·07	362·09	684·65	413·82	770·23	465·55	855·81	517·28	51
12	513·21	310·81	598·75	362·61	684·29	414·42	769·83	466·22	855·36	518·02	48
15	512·94	311·26	598·44	363·13	683·93	415·02	769·42	466·89	854·91	518·77	45
18	512·67	311·71	598·12	363·66	683·56	415·61	769·01	467·56	854·45	519·51	42
21	512·40	312·15	597·80	364·18	683·20	416·21	768·60	468·23	854·00	520·26	39
24	512·13	312·60	597·48	364·70	682·83	416·80	768·19	468·90	853·55	521·00	36
27	511·86	313·05	597·16	365·22	682·47	417·40	767·78	469·57	853·10	521·75	33
30	511·58	313·49	596·84	365·74	682·11	418·00	767·37	470·24	852·64	522·49	30
33	511·31	313·94	596·52	366·27	681·75	418·59	766·94	470·91	852·18	523·24	27
36	511·03	314·39	596·20	366·79	681·38	419·18	766·55	471·58	851·72	523·98	24
39	510·76	314·84	595·88	367·31	681·01	419·78	766·14	472·25	851·27	524·73	21
42	510·48	315·28	595·56	367·83	680·64	420·37	765·73	472·92	850·81	525·47	18
45	510·21	315·73	595·24	368·35	680·28	420·97	765·32	473·59	850·35	526·21	15
48	509·93	316·17	594·92	368·87	679·91	421·56	764·90	474·26	849·89	526·95	12
51	509·66	316·62	594·60	369·39	679·54	422·16	764·49	474·93	849·43	527·69	9
54	509·38	317·06	594·28	369·90	679·17	422·75	764·07	475·59	848·97	528·43	6
57	509·10	317·51	593·96	370·42	678·80	423·34	763·66	476·26	848·51	529·17	3
60	508·82	317·95	593·63	370·94	678·43	423·93	763·24	476·92	848·04	529·91	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

58 Deg.

32 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	84·80	52·99	169·60	105·98	254·41	158·97	339·21	211·96	424·02	264·95	60
3	84·75	53·06	169·51	106·13	254·27	159·19	339·03	212·25	423·79	265·32	57
6	84·71	53·13	169·42	106·27	254·13	159·41	338·84	212·55	423·56	265·69	54
9	84·66	53·21	169·33	106·42	253·99	159·63	338·66	212·85	423·33	266·06	51
12	84·61	53·28	169·23	106·57	253·85	159·86	338·47	213·15	423·09	266·43	48
15	84·57	53·36	169·14	106·72	253·71	160·08	338·29	213·45	422·86	266·80	45
18	84·52	53·43	169·05	106·87	253·57	160·30	338·10	213·74	422·63	267·17	42
21	84·47	53·50	168·96	107·02	253·43	160·52	337·92	214·04	422·40	267·54	39
24	84·43	53·58	168·86	107·16	253·29	160·74	337·73	214·33	422·16	267·91	36
27	84·38	53·65	168·77	107·31	253·15	160·96	337·54	214·63	421·93	268·28	33
30	84·33	53·73	168·67	107·46	253·01	161·18	337·35	214·92	421·69	268·65	30
33	84·29	53·80	168·58	107·61	252·87	161·40	337·17	215·21	421·46	269·02	27
36	84·24	53·87	168·49	107·75	252·73	161·62	336·98	215·50	421·22	269·38	24
39	84·19	53·95	168·40	107·90	252·59	161·85	336·79	215·80	420·99	269·75	21
42	84·15	54·02	168·30	108·04	252·45	162·07	336·60	216·09	420·75	270·12	18
45	84·10	54·09	168·21	108·19	252·31	162·29	336·41	216·39	420·52	270·49	15
48	84·05	54·17	168·11	108·34	252·17	162·51	336·22	216·68	420·28	270·85	12
51	84·01	54·24	168·02	108·49	252·03	162·73	336·03	216·97	420·05	271·22	9
54	83·96	54·31	167·92	108·63	251·88	162·95	335·84	217·26	419·81	271·58	6
57	83·91	54·39	167·83	108·78	251·74	163·17	335·65	217·56	419·57	271·95	3
60	83·86	54·46	167·73	108·92	251·60	163·38	335·46	217·85	419·33	272·31	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

57 Deg.

32 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	508·82	317·95	593·63	370·94	678·43	423·93	763·24	476·92	848·04	529·91	60
3	508·55	318·39	593·31	371·46	678·06	424·52	762·82	477·58	847·58	530·65	57
6	508·27	318·83	592·98	371·97	677·69	425·11	762·40	478·25	847·11	531·39	54
9	507·99	319·27	592·66	372·49	677·32	425·70	761·99	478·92	846·65	532·13	51
12	507·71	319·72	592·33	373·01	676·95	426·30	761·57	479·59	846·19	532·87	48
15	507·43	320·16	592·01	373·53	676·58	426·89	761·15	480·25	845·73	533·61	45
18	507·15	320·61	591·68	374·04	676·20	427·48	760·73	480·91	845·26	534·35	42
21	506·87	321·05	591·36	374·56	675·83	428·07	760·31	481·57	844·79	535·09	39
24	506·59	321·49	591·03	375·07	675·46	428·66	759·89	482·24	844·32	535·82	36
27	506·31	321·93	590·70	375·59	675·09	429·25	759·47	482·90	843·86	536·56	33
30	506·03	322·37	590·37	376·10	674·71	429·84	759·05	483·56	843·39	537·30	30
33	505·75	322·81	590·04	376·62	674·34	430·43	758·63	484·23	842·92	538·04	27
36	505·47	323·26	589·71	377·13	673·96	431·01	758·20	484·89	842·45	538·77	24
39	505·19	323·70	589·38	377·65	673·58	431·60	757·78	485·55	841·98	539·51	21
42	504·90	324·14	589·05	378·16	673·20	432·19	757·36	486·21	841·51	540·24	18
45	504·62	324·58	588·72	378·68	672·83	432·78	756·94	486·89	841·04	540·97	15
48	504·33	325·02	588·39	379·19	672·45	433·36	756·51	487·53	840·56	541·70	12
51	504·05	325·46	588·06	379·71	672·07	433·95	756·08	488·19	840·09	542·44	9
54	503·77	325·90	587·73	380·22	671·69	434·53	755·65	488·85	839·61	543·17	6
57	503·49	326·34	587·40	380·73	671·31	435·12	755·23	489·51	839·14	543·90	3
60	503·20	326·78	587·07	381·24	670·93	435·71	754·80	490·17	838·67	544·63	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

57 Deg.

33 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	83·86	54·46	167·73	108·92	251·60	163·38	335·46	217·85	19·33	272·31	60
3	83·81	54·53	167·64	109·07	251·46	163·	335·27	218·14	19·09	272	57
6	83·77	54·61	167·54	109·22	251·31	163·82	335·08	218·44	18·85	273·05	54
9	83·72	54·68	167·45	109·37	251·17	164·04	334·89	218·7	18·62	273·42	51
12	83·67	54·75	167·35	109·51	251·02	164·26	334·70	219·02	18·38	273·78	48
15	83·62	54·82	167·26	109·66	250·88	164·48	334·51	219·31	18·14	274·15	45
18	83·58	54·90	167·16	109·	250·74	164·70	334·32	219	17·90	274·51	42
21	83·53	54·97	167·06	109·95	250·60	164·92	334·13	219·	17·66	274·88	39
24	83·48	55·04	166·96	110·09	250·45	165·1	333·93	220·1	17·42	275·	36
27	83·43	55·12	166·87	110·2	250·31	165·36	333·74	220·48	17·18	275	33
30	83·38	55·19	166·77	110·38	250·16	165·58	333·55	220·77	16·94	275·96	30
33	83·34	55·26	166·68	110·53	250·02	165·80	333·36	221·06	16·70	276·33	27
36	83·29	55·33	166·58	110·67	249·87	166·01	333·16	221·35	416·46	276	24
39	83·24	55·41	166·49	110·82	249·73	166·23	332·97	221·	16·22	277·06	21
42	83·19	55·48	166·39	110·96	249·58	166·45	332·78	221·93	415·97	277·42	18
45	83·14	55·55	166·29	111·11	249·44	166·67	332·59	222·22	415·73	277·78	15
48	83·09	55·62	166·19	111·25	249·29	166·88	332·39	222·51	415·49	278·1	12
51	83·05	55·70	166·10	111·40	249·15	167·10	332·20	222·	15·25	278·5	9
54	83·00	55·77	166·00	111·54	249·00	167·32	332·00	223·09	415·00	278·87	6
57	82·95	55·84	165·90	111·69	248·86	167·54	331·81	223·38	414·76	279·2	3
60	82·90	55·91	165·80	111·83	248·71	167·75	331·61	223·67	414·51	279·59	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

56 Deg.

33 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	503·20	326·78	587·07	381·24	670·93	435·71	754·80	490·17	838·67	544·63	60
3	502·92	327·22	586·74	381·76	670·55	436·29	754·37	490·83	838·19	545·36	57
6	502·63	327·66	586·40	382·27	670·17	436·88	753·94	491·49	837·71	546·10	54
9	502·34	328·10	586·07	382·79	669·79	437·46	753·51	492·15	837·24	546·83	51
12	502·05	328·53	585·73	383·30	669·41	438·05	753·08	492·80	836·76	547·56	48
15	501·77	328·97	585·40	383·81	669·03	438·63	752·65	493·46	836·28	548·29	45
18	501·48	329·41	585·06	384·32	668·64	439·21	752·22	494·12	835·80	549·02	42
21	501·19	329·85	584·72	384·83	668·26	439·79	751·79	494·78	835·32	549·75	39
24	500·90	330·28	584·39	385·34	667·87	440·38	751·36	495·43	834·84	550·48	36
27	500·62	330·72	584·05	385·85	667·49	440·96	750·93	496·09	834·36	551·21	33
30	500·33	331·16	583·71	386·36	667·10	441·54	750·49	496·74	833·88	551·93	30
33	500·04	331·60	583·38	386·87	666·72	442·12	750·06	497·40	833·40	552·66	27
36	499·75	332·03	583·04	387·38	666·33	442·70	749·62	498·05	832·91	553·39	24
39	499·46	332·47	582·70	387·89	665·95	443·29	749·19	498·71	832·43	554·12	21
42	499·17	332·90	582·36	388·39	665·56	443·87	748·75	499·36	831·95	554·84	18
45	498·88	333·34	582·02	388·90	665·17	444·45	748·32	500·01	831·47	555·57	15
48	498·58	333·77	581·68	389·40	664·78	445·03	747·88	500·66	830·98	556·29	12
51	498·29	334·21	581·34	389·91	664·39	445·61	747·45	501·32	830·50	557·02	9
54	498·00	334·64	581·00	390·42	664·00	446·19	747·01	501·97	830·01	557·74	6
57	497·71	335·08	580·66	390·92	663·61	446·77	746·57	502·62	829·52	558·47	3
60	497·42	335·51	580·32	391·43	663·22	447·35	746·13	503·27	829·03	559·19	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

56 Deg.

34 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	82 90	55·91	165·80	111·83	248·71	167·75	331·61	223·67	414·51	279·59	60
3	82·85	55·99	165·71	111·97	248·56	167·97	331·42	223·96	414·27	279·95	57
6	82·80	56·06	165·61	112·12	248·41	168·19	331·22	224·25	414·03	280·31	54
9	82·75	56·13	165·51	112·26	248·27	168·41	331·03	224·54	413·78	280·67	51
12	82·70	56·20	165·41	112·41	248·12	168·62	330·83	224·83	413·53	281·04	48
15	82·65	56·28	165·31	112·55	247·97	168·84	330·63	225·12	413·29	281·40	45
18	82·60	56·35	165·21	112·70	247·82	169·05	330·43	225·41	413·04	281·76	42
21	82·56	56·42	165·12	112·84	247·68	169·27	330·24	225·70	412·80	282·12	39
24	82·51	56·49	165·02	112·99	247·53	169·48	330·04	225·98	412·55	282·48	36
27	82·46	56·56	164·92	113·13	247·38	169·70	329·85	226·27	412·31	282·84	33
30	82·41	56·64	164·82	113·28	247·23	169·92	329·65	226·56	412·06	283·20	30
33	82·36	56·71	164·72	113·42	247·09	170·14	329·45	226·85	411·81	283·56	27
36	82·31	56·78	164·62	113·56	246·94	170·35	329·25	227·13	411·56	283·92	24
39	82·26	56·85	164·52	113·70	246·79	170·57	329·05	227·42	411·32	284·28	21
42	82·21	56·92	164·42	113·85	246·64	170·78	328·85	227·71	411·07	284·63	18
45	82·16	56·99	164·33	113·99	246·49	170·99	328·65	227·99	410·82	284·99	15
48	82·11	57·07	164·23	114·14	246·34	171·21	328·45	228·28	410·57	285·35	12
51	82·06	57·14	164·13	114·28	246·19	171·43	328·26	228·57	410·32	285·71	9
54	82·01	57·21	164·03	114·42	246·04	171·64	328·06	228·85	410·07	286·07	6
57	81·96	57·28	163·93	114·56	245·89	171·86	327·86	229·14	409·82	286·43	3
60	81·91	57·35	163·83	114·71	245·74	172·07	327·66	229·43	409·57	286·78	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Minutes.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

55 Deg.

34 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	497·42	335·51	580·32	391·43	663·22	447·35	746·13	503·27	829·03	559·19	60
3	497·13	335·94	579·98	391·93	662·83	447·93	745·69	503·92	828·54	559·91	57
6	496·83	336·38	579·64	392·44	662·44	448·51	745·25	504·57	828·05	560·63	54
9	496·54	336·81	579·30	392·94	662·05	449·09	744·81	505·22	827·56	561·35	51
12	496·24	337·24	578·95	393·45	661·66	449·66	744·37	505·87	827·07	562·08	48
15	495·95	337·67	578·61	393·95	661·27	450·24	743·93	506·52	826·58	562·80	45
18	495·65	338·11	578·26	394·46	660·87	450·82	743·48	507·17	826·09	563·52	42
21	495·36	338·54	577·92	394·96	660·48	451·40	743·04	507·82	825·60	564·24	39
24	495·06	338·97	577·57	395·47	660·09	451·97	742·60	508·47	825·11	564·96	36
27	494·77	339·40	577·23	395·97	659·70	452·55	742·16	509·12	824·62	565·68	33
30	494·47	339·84	576·88	396·48	659·30	453·12	741·71	509·76	824·12	566·40	30
33	494·18	340·27	576·54	396·98	658·90	453·70	741·27	510·41	823·63	567·12	27
36	493·88	340·70	576·19	397·49	658·50	454·27	740·82	511·05	823·13	567·84	24
39	493·58	341·13	575·85	397·99	658·11	454·85	740·37	511·70	822·64	568·56	21
42	493·28	341·56	575·50	398·49	657·71	455·42	739·92	512·35	822·14	569·27	18
45	492·99	341·99	575·15	398·99	657·32	455·99	739·48	512·99	821·64	569·99	15
48	492·69	342·42	574·80	399·49	656·92	456·57	739·03	513·64	821·14	570·71	12
51	492·39	342·85	574·45	399·99	656·52	457·14	738·58	514·29	820·65	571·43	9
54	492·09	343·28	574·10	400·50	656·12	457·71	738·13	514·93	820·15	572·14	6
57	491·79	343·71	573·75	401·00	655·72	458·28	737·68	515·57	819·65	572·86	3
60	491·49	344·14	573·40	401·50	655·32	458·86	737·23	516·21	819·15	573·57	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

55 Deg.

35 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	81·91	57·35	163·83	114·71	245·74	172·07	327·66	229·43	409·57	286·78	60
3	81·86	57·42	163·72	114·85	245·59	172·28	327·46	229·72	409·32	287·14	57
6	81·81	57·50	163·62	115·00	245·44	172·50	327·26	230·00	409·07	287·50	54
9	81·76	57·57	163·52	115·14	245·29	172·71	327·06	230·29	408·82	287·86	51
12	81·71	57·64	163·42	115·28	245·14	172·92	326·85	230·57	408·57	288·21	48
15	81·66	57·71	163·32	115·42	244·99	173·13	326·65	230·86	408·32	288·57	45
18	81·61	57·78	163·22	115·57	244·84	173·35	326·45	231·14	408·07	288·92	42
21	81·56	57·86	163·12	115·71	244·69	173·56	326·25	231·43	407·82	289·28	39
24	81·51	57·93	163·02	115·85	244·53	173·78	326·05	231·71	407·56	289·64	36
27	81·46	58·00	162·92	115·99	244·38	173·99	325·85	232·00	407·31	290·00	33
30	81·41	58·07	162·82	116·14	244·23	174·21	325·64	232·28	407·05	290·35	30
33	81·36	58·14	162·72	116·28	244·08	174·42	325·44	232·57	406·80	290·71	27
36	81·31	58·21	162·62	116·42	243·93	174·63	325·24	232·85	406·55	291·06	24
39	81·26	58·28	162·52	116·56	243·78	174·84	325·04	233·13	406·30	291·42	21
42	81·21	58·35	162·41	116·70	243·62	175·06	324·83	233·41	406·04	291·77	18
45	81·16	58·42	162·31	116·84	243·47	175·27	324·63	233·70	405·79	292·12	15
48	81·10	58·49	162·21	116·99	243·31	175·48	324·42	233·98	405·53	292·47	12
51	81·05	58·57	162·11	117·13	243·16	175·69	324·22	234·27	405·28	292·83	9
54	81·00	58·64	162·00	117·27	243·01	175·91	324·01	234·55	405·02	293·18	6
57	80·95	58·71	161·90	117·41	242·86	176·12	323·81	234·83	404·76	293·54	3
60	80·90	58·78	161·80	117·55	242·70	176·33	323·60	234·11	404·50	293·89	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

54 Deg.

35 Deg.

Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
491·49	344·14	573·40	401·50	655·32	458·86	737·23	516·21	819·15	573·57	60
491·19	344·57	573·05	402·00	654·92	459·43	736·78	516·85	818·65	574·28	57
490·88	345·00	572·70	402·50	654·51	460·00	736·33	517·50	818·14	575·00	54
490·58	345·43	572·35	403·00	654·11	460·57	735·88	518·14	817·64	575·71	51
490·28	345·85	572·00	403·50	653·71	461·14	735·42	518·78	817·14	576·43	48
489·98	346·28	571·65	404·00	653·31	461·71	734·97	519·42	816·64	577·14	45
489·68	346·71	571·29	404·50	652·90	462·28	734·52	520·07	816·13	577·85	42
489·38	347·14	570·94	405·00	652·50	462·85	734·07	520·71	815·63	578·56	39
489·07	347·57	570·58	405·50	652·10	463·42	733·61	521·35	815·12	579·28	36
488·77	348·00	570·23	406·00	651·70	464·00	733·16	522·00	814·62	580·00	33
488·46	348·42	569·88	406·49	651·29	464·57	732·70	522·64	814·11	580·71	30
488·16	348·85	569·53	406·99	650·89	465·13	732·25	523·27	813·61	581·42	27
487·86	349·27	569·17	407·49	650·48	465·70	731·79	523·91	813·10	582·13	24
487·56	349·70	568·81	407·98	650·07	466·26	731·33	524·55	812·59	582·84	21
487·25	350·12	568·45	408·48	649·66	466·83	730·87	525·18	812·08	583·54	18
486·94	350·55	568·10	408·97	649·26	467·39	730·41	525·82	811·57	584·25	15
486·63	350·97	567·74	409·47	648·85	467·96	729·95	526·46	811·06	584·95	12
486·33	351·40	567·38	409·96	648·44	468·52	729·49	527·10	810·55	585·66	9
486·02	351·82	567·03	410·46	648·03	469·09	729·03	527·73	810·04	586·37	6
485·71	352·25	566·67	410·95	647·62	469·65	728·57	528·37	809·53	587·07	3
485·40	352·67	566·31	411·45	647·21	470·22	728·11	529·00	809·01	587·78	0
Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

54 Deg.

36 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	80·90	58·78	161·80	117·55	242·70	176·33	323·60	235·11	404·50	293·89	6
3	80·85	58·85	161·70	117·69	242·55	176·54	323·40	235·39	404·25	294·24	5
6	80·80	58·92	161·59	117·83	242·39	176·75	323·19	235·67	403·99	294·59	54
9	80·74	58·99	161·49	117·97	242·24	176·96	322·99	235·95	403·74	294·94	51
12	80·69	59·06	161·39	118·12	242·08	177·18	322·78	236·24	403·48	295·30	48
15	80·64	59·13	161·29	118·26	241·93	177·39	322·58	236·52	403·22	295·65	45
18	80·59	59·20	161·18	118·40	241·77	177·60	322·37	236·80	402·96	296·00	42
21	80·54	59·27	161·08	118·54	241·62	177·81	322·16	237·08	402·70	296·35	39
24	80·49	59·34	160·97	118·68	241·46	178·02	321·95	237·36	402·44	296·70	36
27	80·43	59·41	160·87	118·82	241·31	178·23	321·75	237·64	402·18	297·05	33
30	80·38	59·48	160·77	118·96	241·15	178·44	321·54	237·92	401·92	297·41	30
33	80·33	59·55	160·67	119·10	241·00	178·65	321·33	238·20	401·66	297·76	27
36	80·28	59·62	160·56	119·24	240·84	178·86	321·12	238·48	401·40	298·11	24
39	80·23	59·69	160·46	119·38	240·69	179·07	320·92	238·76	401·14	298·46	21
42	80·18	59·76	160·35	119·52	240·53	179·28	320·71	239·04	400·88	298·81	18
45	80·12	59·83	160·25	119·66	240·37	179·49	320·50	239·32	400·62	299·16	15
48	80·07	59·90	160·14	119·80	240·21	179·70	320·29	239·60	400·36	299·51	12
51	80·02	59·97	160·04	119·94	240·06	179·91	320·08	239·88	400·10	299·86	9
54	79·97	60·04	159·93	120·08	239·90	180·12	319·87	240·16	399·84	300·21	6
57	79·92	60·11	159·83	120·22	239·75	180·33	319·66	240·44	399·58	300·56	3
60	79·86	60·18	159·72	120·36	239·59	180·54	319·45	240·72	399·31	300·90	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

53 Deg.

36 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	485·40	352·67	566·31	411·45	647·21	470·22	728·11	529·00	809·01	587·78	60
3	485·10	353·09	565·95	411·94	646·80	470·79	727·65	529·64	808·50	588·49	57
6	484·79	353·51	565·59	412·43	646·39	471·35	727·19	530·27	807·98	589·19	54
9	484·48	353·93	565·23	412·92	645·98	471·91	726·73	530·90	807·47	589·90	51
12	484·17	354·36	564·87	413·42	645·57	472·48	726·26	531·54	806·95	590·60	48
15	483·86	354·78	564·51	413·91	645·16	473·04	725·80	532·17	806·44	591·31	45
18	483·55	355·20	564·15	414·40	644·74	473·60	725·33	532·81	805·92	592·01	42
21	483·24	355·62	563·79	414·89	644·33	474·17	724·87	533·44	805·41	592·72	39
24	482·93	356·05	563·42	415·39	643·91	474·73	724·40	534·07	804·89	593·42	36
27	482·62	356·47	563·06	415·88	643·50	475·29	723·94	534·70	804·37	594·12	33
30	482·31	356·89	562·70	416·37	643·08	475·85	723·47	535·34	803·85	594·82	30
33	482·00	357·31	562·34	416·86	642·67	476·41	723·00	535·97	803·33	595·52	27
36	481·69	357·73	561·97	417·35	642·25	476·98	722·53	536·60	802·81	596·22	24
39	481·38	358·15	561·61	417·84	641·84	477·54	722·06	537·23	802·29	596·92	21
42	481·06	358·57	561·24	418·33	641·42	478·10	721·59	537·85	801·77	597·62	18
45	480·75	358·99	560·88	418·82	641·00	478·66	721·12	538·48	801·25	598·32	15
48	480·43	359·41	560·51	419·31	640·58	479·21	720·65	539·11	800·73	599·02	12
51	480·12	359·83	560·15	419·80	640·16	479·77	720·18	539·74	800·21	599·72	9
54	479·81	360·25	559·78	420·29	639·74	480·33	719·71	540·37	799·68	600·42	6
57	479·50	360·67	559·41	420·78	639·32	480·89	719·24	541·00	799·16	601·12	3
60	479·18	361·09	559·04	421·27	638·90	481·45	718·77	541·63	798·63	601·81	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

53 Deg.

37 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 50	
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	I
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	B
0	79·86	60·18	159·72	120·36	239·59	180·54	319·45	240·72	399·31	30
3	79·81	60·25	159·62	120·50	239·43	180·75	319·24	241·00	399·05	30
6	79·75	60·32	159·51	120·64	239·27	180·96	319·03	241·28	398·79	30
9	79·70	60·39	159·41	120·78	239·11	181·17	318·82	241·56	398·53	30
12	79·65	60·46	159·30	120·92	238·95	181·38	318·61	241·84	398·26	30
15	79·60	60·53	159·20	121·06	238·80	181·58	318·40	242·12	398·00	30
18	79·55	60·60	159·09	121·19	238·64	181·79	318·19	242·39	397·73	30
21	79·49	60·67	158·99	121·33	238·48	182·00	317·98	242·67	397·47	30
24	79·44	60·74	158·88	121·47	238·32	182·21	317·76	242·94	397·20	30
27	79·39	60·81	158·78	121·61	238·16	182·42	317·55	243·22	396·94	30
30	79·33	60·88	158·67	121·75	238·00	182·62	317·34	243·50	396·67	30
33	79·28	60·95	158·56	121·89	237·84	182·83	317·13	243·78	396·41	30
36	79·23	61·01	158·45	122·02	237·68	183·04	316·91	244·05	396·14	30
39	79·18	61·08	158·35	122·16	237·52	183·25	316·70	244·33	395·88	30
42	79·12	61·15	158·24	122·30	237·36	183·46	316·49	244·61	395·61	30
45	79·07	61·22	158·14	122·44	237·20	183·67	316·28	244·89	395·35	30
48	79·01	61·29	158·03	122·58	237·04	183·87	316·06	245·16	395·08	30
51	78·96	61·36	157·92	122·72	236·88	184·08	315·85	245·44	394·81	30
54	78·91	61·43	157·81	122·85	236·72	184·28	315·63	245·71	394·54	30
57	78·85	61·50	157·71	122·99	236·56	184·49	315·42	245·99	394·27	30
60	78·80	61·57	157·60	123·13	236·40	184·70	315·20	246·26	394·00	30
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	I
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	I
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 50	

52 Deg.

37 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	479·18	361·09	559·04	421·27	638·90	481·45	718·77	541·63	798·63	601·81	60
3	478·86	361·51	558·67	421·76	638·48	482·01	718·30	542·26	798·11	602·51	57
6	478·55	361·92	558·30	422·24	638·06	482·57	717·82	542·89	797·58	603·21	54
9	478·23	362·34	557·94	422·73	637·64	483·12	717·35	543·52	797·06	603·91	51
12	477·91	362·76	557·57	423·22	637·22	483·68	716·87	544·14	796·53	604·60	48
15	477·60	363·18	557·20	423·71	636·80	484·23	716·40	544·77	796·00	605·30	45
18	477·28	363·59	556·83	424·19	636·37	484·79	715·92	545·39	795·47	605·99	42
21	476·96	364·01	556·46	424·67	635·95	485·35	715·45	546·02	794·94	606·68	39
24	476·64	364·42	556·09	425·16	635·53	485·90	714·97	546·64	794·41	607·37	36
27	476·33	364·84	555·72	425·64	635·11	486·46	714·49	547·26	793·88	608·06	33
30	476·01	365·25	555·34	426·13	634·68	487·01	714·01	547·88	793·35	608·76	30
33	475·69	365·67	554·97	426·62	634·26	487·57	713·54	548·50	792·82	609·45	27
36	475·37	366·08	554·60	427·10	633·83	488·12	713·06	549·13	792·29	610·14	24
39	475·05	366·50	554·23	427·59	633·40	488·67	712·58	549·75	791·76	610·83	21
42	474·73	366·91	553·85	428·07	632·97	489·22	712·10	550·37	791·22	611·52	18
45	474·41	367·33	553·48	428·55	632·55	489·77	711·62	550·99	790·69	612·21	15
48	474·09	367·74	553·10	429·03	632·12	490·32	711·14	551·62	790·15	612·90	12
51	473·77	368·15	552·73	429·52	631·69	490·87	710·66	552·24	789·62	613·59	9
54	473·45	368·57	552·35	430·00	631·26	491·42	710·18	552·85	789·08	614·28	6
57	473·13	368·99	551·98	430·48	630·83	491·98	709·69	553·47	788·55	614·97	3
60	472·80	369·40	551·60	430·96	630·40	492·53	709·21	554·09	788·01	615·66	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

52 Deg.

38 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	78 80	61·57	157·60	123·13	236·40	184·70	315·20	246·26	394·00	307·83	60
3	78·75	61·63	157·49	123·27	236·24	184·91	314·99	246·53	393·74	308·17	57
6	78·69	61·70	157·38	123·40	236·07	185·11	314·77	246·81	393·47	308·51	54
9	78·64	61·77	157·28	123·54	235·91	185·32	314·56	247·08	393·20	308·85	51
12	78·58	61·84	157·17	123·68	235·75	185·52	314·34	247·36	392·93	309·20	48
15	78·53	61·91	157·06	123·82	235·59	185·73	314·13	247·63	392·66	309·54	45
18	78·48	61·98	156·95	123·95	235·43	185·93	313·91	247·91	392·39	309·89	42
21	78·42	62·05	156·84	124·09	235·27	186·14	313·69	248·18	392·12	310·23	39
24	78·37	62·11	156·73	124·23	235·10	186·34	313·47	248·46	391·85	310·57	36
27	78·31	62·18	156·63	124·36	234·94	186·55	313·26	248·73	391·58	310·91	33
30	78·26	62·25	156·52	124·50	234·78	186·75	313·04	249·00	391·30	311·25	30
33	78·21	62·32	156·41	124·64	234·62	186·96	312·82	249·28	391·03	311·59	27
36	78·15	62·39	156·30	124·77	234·45	187·16	312·60	249·55	390·76	311·94	24
39	78·10	62·46	156·19	124·91	234·29	187·37	312·39	249·83	390·49	312·28	21
42	78·04	62·52	156·08	125·04	234·13	187·57	312·17	250·10	390·21	312·62	18
45	77·99	62·59	155·97	125·18	233·97	187·78	311·95	250·37	389·94	312·96	15
48	77·93	62·66	155·86	125·32	233·80	187·98	311·73	250·64	389·67	313·30	12
51	77·88	62·73	155·75	125·46	233·64	188·19	311·51	250·92	389·40	313·64	9
54	77·82	62·79	155·64	125·59	233·47	188·39	311·29	251·19	389·12	313·98	6
57	77·77	62·86	155·53	125·73	233·31	188·59	311·07	251·43	388·85	314·32	3
60	77·71	62·93	155·42	125·86	233·14	188·80	310·85	251·73	388·57	314·66	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

51 Deg.

38 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	472·80	369·40	551·60	430·96	630·40	492·53	709·21	554·09	788·01	615·66	60
3	472·48	369·81	551·23	431·44	629·97	493·08	708·73	554·71	787·47	616·35	57
6	472·16	370·22	550·85	431·92	629·54	493·62	708·24	555·33	786·93	617·03	54
9	471·84	370·63	550·48	432·40	629·11	494·17	707·76	555·95	786·39	617·72	51
12	471·51	371·04	550·10	432·88	628·68	494·72	707·27	556·56	785·85	618·41	48
15	471·19	371·45	549·72	433·36	628·25	495·27	706·79	557·18	785·31	619·10	45
18	470·86	371·86	549·34	433·84	627·82	495·82	706·30	557·80	784·77	619·78	42
21	470·54	372·27	548·96	434·32	627·39	496·37	705·81	558·42	784·23	620·46	39
24	470·21	372·68	548·58	434·80	626·95	496·92	705·32	559·03	783·69	621·14	36
27	469·89	373·09	548·20	435·28	626·52	497·47	704·83	559·65	783·15	621·82	33
30	469·56	373·50	547·82	435·75	626·08	498·01	704·34	560·26	782·60	622·51	30
33	469·24	373·91	547·44	436·23	625·65	498·56	703·85	560·88	782·06	623·19	27
36	468·91	374·32	547·06	436·71	625·21	499·10	703·36	561·49	781·52	623·88	24
39	468·59	374·73	546·68	437·19	624·78	499·65	702·87	562·11	780·98	624·56	21
42	468·26	375·14	546·30	437·67	624·34	500·19	702·38	562·72	780·43	625·24	18
45	467·93	375·55	545·92	438·14	623·91	500·74	701·89	563·33	779·88	625·92	15
48	467·60	375·96	545·53	438·62	623·47	501·28	701·40	563·94	779·33	626·60	12
51	467·27	376·37	545·15	439·10	623·03	501·83	700·91	564·55	778·79	627·28	9
54	466·94	376·77	544·77	439·57	622·59	502·37	700·42	565·16	778·24	627·96	6
57	466·61	377·18	544·39	440·05	622·15	502·91	699·93	565·77	777·69	628·64	3
60	466·28	377·59	544·00	440·52	621·71	503·45	699·43	566·38	777·14	629·32	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

51 Deg.

39 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	77·71	62·93	155·42	125·86	233·14	188·80	310·85	251·73	388·57	314·66	60
3	77·66	63·00	155·31	126·00	232·98	189·00	310·63	252·00	388·30	315·00	57
6	77·60	63·07	155·20	126·13	232·81	189·20	310·41	252·27	388·02	315·34	54
9	77·55	63·13	155·09	126·27	232·65	189·41	310·19	252·54	387·75	315·67	51
12	77·49	63·20	154·98	126·40	232·48	189·61	309·97	252·81	387·47	316·01	48
15	77·44	63·27	154·87	126·54	232·32	189·81	309·75	253·08	387·20	316·35	45
18	77·38	63·34	154·76	126·67	232·15	190·01	309·53	253·35	386·92	316·69	42
21	77·33	63·40	154·65	126·81	231·99	190·21	309·31	253·62	386·64	317·03	39
24	77·27	63·47	154·54	126·94	231·82	190·42	309·09	253·89	386·36	317·36	36
27	77·22	63·54	154·43	127·08	231·65	190·62	308·87	254·16	386·09	317·70	33
30	77·16	63·61	154·32	127·21	231·48	190·82	308·65	254·43	385·81	318·03	30
33	77·11	63·67	154·21	127·35	231·32	191·02	308·43	254·70	385·54	318·37	27
36	77·05	63·74	154·10	127·48	231·15	191·22	308·20	254·97	385·25	318·71	24
39	77·00	63·81	153·99	127·62	230·99	191·42	307·98	255·24	384·98	319·04	21
42	76·94	63·88	153·88	127·75	230·82	191·63	307·76	255·50	384·70	319·38	18
45	76·88	63·94	153·77	127·89	230·65	191·83	307·54	255·77	384·42	319·72	15
48	76·83	64·01	153·65	128·02	230·48	192·03	307·31	256·04	384·14	320·05	12
51	76·77	64·08	153·54	128·16	230·32	192·23	307·09	256·31	383·86	320·39	9
54	76·72	64·14	153·43	128·29	230·15	192·43	306·86	256·58	383·58	320·73	6
57	76·66	64·21	153·32	128·42	229·98	192·63	306·64	256·85	383·30	321·06	3
60	76·60	64·28	153·21	128·55	229·81	192·83	306·41	257·11	383·02	321·39	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

50 Deg.

39 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	466·28	377·59	544·00	440·52	621·71	503·45	699·43	566·38	777·14	629·32	60
3	465·95	378·00	543·62	441·00	621·27	504·00	698·94	567·00	776·59	630·00	57
6	465·62	378·40	543·23	441·47	620·83	504·54	698·44	567·61	776·04	630·67	54
9	465·29	378·81	542·85	441·95	620·39	505·09	697·95	568·21	775·49	631·35	51
12	464·96	379·21	542·46	442·42	619·95	505·63	697·45	568·82	774·94	632·03	48
15	464·63	379·61	542·08	442·90	619·51	506·17	696·95	569·43	774·39	632·70	45
18	464·30	380·02	541·69	443·37	619·07	506·71	696·45	570·04	773·84	633·37	42
21	463·97	380·42	541·30	443·84	618·63	507·25	695·96	570·65	773·29	634·05	39
24	463·64	380·83	540·91	444·31	618·18	507·79	695·46	571·26	772·73	634·73	36
27	463·31	381·23	540·53	444·78	617·74	508·33	694·96	571·87	772·18	635·40	33
30	462·97	381·64	540·14	445·25	617·30	508·86	694·46	572·47	771·62	636·07	30
33	462·64	382·04	539·75	445·72	616·86	509·40	693·96	573·07	771·07	636·75	27
36	462·30	382·45	539·36	446·19	616·41	509·94	693·46	573·68	770·51	637·42	24
39	461·97	382·85	538·97	446·66	615·97	510·48	692·96	574·28	769·96	638·09	21
42	461·64	383·26	538·58	447·13	615·52	511·02	692·46	574·89	769·40	638·76	18
45	461·30	383·66	538·19	447·60	615·07	511·56	691·96	575·49	768·84	639·43	15
48	460·96	384·07	537·80	448·07	614·62	512·07	691·46	576·10	768·28	640·10	12
51	460·63	384·47	537·41	448·54	614·18	512·62	690·96	576·70	767·72	640·77	9
54	460·29	384·87	537·01	449·01	613·73	513·16	690·45	577·30	767·16	641·44	6
57	459·96	385·27	536·62	449·48	613·28	513·69	689·95	577·90	766·60	642·11	3
60	459·62	385·67	536·23	449·95	612·83	514·23	689·44	578·51	766·04	642·78	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Minutes.
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

50 Deg.

40 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	76·60	64·28	153·21	128·55	229·81	192·83	306·41	257·11	383·02	321·39	60
3	76·55	64·34	153·10	128·68	229·64	193·03	306·19	257·37	382·74	321·72	57
6	76·49	64·41	152·98	128·82	229·47	193·23	305·96	257·64	382·46	322·06	54
9	76·44	64·48	152·87	128·95	229·30	193·43	305·74	257·91	382·18	322·39	51
12	76·38	64·54	152·75	129·09	229·13	193·63	305·51	258·18	381·89	322·73	48
15	76·32	64·61	152·64	129·22	228·97	193·83	305·29	258·44	381·61	323·06	45
18	76·27	64·68	152·53	129·35	228·80	194·03	305·06	258·71	381·33	323·39	42
21	76·21	64·75	152·42	129·48	228·63	194·23	304·84	258·97	381·05	323·72	39
24	76·15	64·81	152·30	129·62	228·46	194·43	304·61	259·24	380·77	324·06	36
27	76·10	64·88	152·19	129·75	228·29	194·63	304·39	259·50	380·49	324·39	33
30	76·04	64·95	152·08	129·88	228·12	194·83	304·16	259·77	380·20	324·72	30
33	75·98	65·01	151·97	130·01	227·95	195·03	303·94	260·04	379·92	325·05	27
36	75·93	65·08	151·85	130·15	227·78	195·23	303·71	260·30	379·63	325·38	24
39	75·87	65·14	151·74	130·28	227·61	195·43	303·48	260·57	379·35	325·71	21
42	75·81	65·21	151·62	130·42	227·44	195·63	303·25	260·84	379·06	326·04	18
45	75·76	65·28	151·51	130·55	227·27	195·83	303·03	261·10	378·78	326·37	15
48	75·70	65·34	151·40	130·68	227·09	196·02	302·80	261·37	378·49	326·71	12
51	75·64	65·41	151·29	130·81	226·92	196·22	302·57	261·63	378·21	327·04	9
54	75·58	65·47	151·17	130·94	226·75	196·42	302·34	261·89	377·92	327·37	6
57	75·53	65·54	151·06	131·08	226·58	196·62	302·11	262·16	377·64	327·70	3
60	75·47	65·61	150·94	131·21	226·41	196·81	301·88	262·42	377·35	328·03	0
	Base.	Per.	Base,	Per,	Base,	Per,	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

49 Deg.

40 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base	
0	459·62	385·67	536·23	449·95	612·83	514·23	689·44	578·51	766·04	642·78	60
3	459·29	386·07	535·84	450·42	612·38	514·76	688·93	579·11	765·48	643·45	57
6	458·95	386·47	535·44	450·88	611·93	515·30	688·42	579·71	764·92	644·12	54
9	458·61	386·87	535·05	451·35	611·48	515·83	687·92	580·31	764·36	644·79	51
12	458·27	387·27	534·65	451·82	611·03	516·36	687·41	580·91	763·79	645·45	48
15	457·94	387·67	534·26	452·29	610·58	516·89	686·91	581·51	763·23	646·12	45
18	457·60	388·07	533·86	452·75	610·13	517·43	686·40	582·11	762·66	646·79	42
21	457·26	388·47	533·47	453·22	609·68	517·96	685·89	582·71	762·10	647·46	39
24	456·92	388·87	533·07	453·68	609·23	518·49	685·38	583·31	761·53	648·12	36
27	456·58	389·27	532·68	454·15	608·78	519·02	684·87	583·91	760·97	648·79	33
30	456·24	389·67	532·28	454·61	608·32	519·56	684·36	584·50	760·40	649·45	30
33	455·90	390·06	531·89	455·08	607·87	520·09	683·85	585·10	759·84	650·11	27
36	455·56	390·46	531·49	455·54	607·42	520·62	683·34	585·70	759·27	650·77	24
39	455·22	390·86	531·10	456·01	606·97	521·15	682·83	586·29	758·70	651·43	21
42	454·88	391·26	530·70	456·47	606·51	521·68	682·32	586·89	758·13	652·10	18
45	454·54	391·66	530·30	456·93	606·06	522·21	681·81	587·48	757·56	652·76	15
48	454·19	392·05	529·90	457·39	605·60	522·73	681·30	588·08	756·99	653·42	12
51	453·85	392·45	529·50	457·85	605·15	523·26	680·79	588·67	756·42	654·08	9
54	453·51	392·84	529·10	458·32	604·69	523·79	680·27	589·27	755·85	654·74	6
57	453·17	393·24	528·70	458·78	604·23	524·32	679·76	589·86	755·28	655·40	3
60	452·82	393·63	528·30	459·24	603·77	524·84	679·24	590·45	754·71	656·06	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

49 Deg.

41 Deg.

Minutes.	Dist. 100. Lat. Per.	Dist. 100. Dep. Base.	Dist. 200. Lat. Per.	Dist. 200. Dep. Base.	Dist. 300. Lat. Per.	Dist. 300. Dep. Base.	Dist. 400. Lat. Per.	Dist. 400. Dep. Base.	Dist. 500. Lat. Per.	Dist. 500. Dep. Base.	
0	75·47	65·61	150·94	131·21	226·41	196·81	301·88	262·42	377·35	328·03	60
3	75·41	65·67	150·83	131·34	226·24	197·01	301·65	262·68	377·07	328·36	57
6	75·36	65·74	150·71	131·47	226·06	197·21	301·42	262·95	376·78	328·69	54
9	75·30	65·80	150·60	131·60	225·89	197·41	301·19	263·21	376·49	329·01	51
12	75·24	65·87	150·48	131·73	225·72	197·60	300·96	263·47	376·20	329·34	48
15	75·19	65·93	150·37	131·86	225·55	197·80	300·73	263·73	375·92	329·67	45
18	75·13	66·00	150·25	132·00	225·38	198·00	300·50	264·00	375·63	330·00	42
21	75·07	66·07	150·14	132·13	225·21	198·20	300·27	264·26	375·34	330·33	39
24	75·01	66·13	150·02	132·26	225·03	198·39	300·04	264·52	375·05	330·65	36
27	74·95	66·20	149·91	132·39	224·86	198·59	299·81	264·78	374·77	330·98	33
30	74·89	66·26	149·79	132·52	224·68	198·78	299·58	265·04	374·48	331·31	30
33	74·84	66·33	149·68	132·65	224·51	198·98	299·35	265·30	374·19	331·64	27
36	74·78	66·39	149·56	132·78	224·34	199·17	299·12	265·57	373·90	331·96	24
39	74·72	66·46	149·44	132·91	224·17	199·37	298·89	265·83	373·61	332·29	21
42	74·66	66·52	149·32	133·04	223·99	199·56	298·65	266·09	373·32	332·61	18
45	74·60	66·59	149·21	133·17	223·82	199·76	298·42	266·35	373·03	332·94	15
48	74·55	66·65	149·09	133·30	223·64	199·95	298·19	266·61	372·74	333·26	12
51	74·49	66·72	148·98	133·43	223·47	200·15	297·96	266·87	372·45	333·59	9
54	74·43	66·78	148·86	133·56	223·29	200·34	297·72	267·13	372·15	333·91	6
57	74·37	66·85	148·74	133·69	223·12	200·54	297·49	267·39	371·86	334·24	3
60	74·31	66·91	148·62	133·82	222·94	200·73	297·26	267·65	371·57	334·56	0
	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Base. Dep.	Per. Lat.	Minutes.
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

48 Deg.

41 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	452·82	393·63	528·30	459·24	603·77	524·84	679·24	590·45	754·71	656·06	60
3	452·48	394·02	527·90	459·70	603·31	525·37	678·72	591·04	754·14	656·72	57
6	452·13	394·42	527·49	460·16	602·85	525·90	678·20	591·64	753·56	657·37	54
9	451·79	394·81	527·09	460·62	602·39	526·43	677·69	592·23	752·99	658·03	51
12	451·44	395·21	526·69	461·08	601·93	526·95	677·17	592·82	752·41	658·68	48
15	451·10	395·60	526·29	461·54	601·47	527·48	676·65	593·41	751·84	659·34	45
18	450·75	396·00	525·88	462·00	601·01	528·00	676·13	594·00	751·26	660·00	42
21	450·41	396·39	525·48	462·46	600·55	528·52	675·62	594·59	750·69	660·66	39
24	450·06	396·79	525·08	462·91	600·09	529·05	675·10	595·18	750·11	661·31	36
27	449·72	397·18	524·68	463·37	599·63	529·57	674·58	595·77	749·53	661·97	33
30	449·37	397·57	524·27	463·83	599·16	530·09	674·06	596·36	748·95	662·62	30
33	449·03	397·96	523·87	464·29	598·70	530·62	673·54	596·94	748·37	663·27	27
36	448·68	398·35	523·46	464·74	598·23	531·14	673·02	597·53	747·79	663·92	24
39	448·33	398·74	523·06	465·20	597·77	531·66	672·50	598·12	747·21	664·57	21
42	447·98	399·13	522·65	465·66	597·31	532·18	671·97	598·70	746·63	665·23	18
45	447·63	399·52	522·24	466·12	596·85	532·70	671·45	599·29	746·05	665·88	15
48	447·28	399·92	521·83	466·57	596·38	533·22	670·92	599·88	745·47	666·53	12
51	446·93	400·31	521·42	467·03	595·92	533·74	670·40	600·47	744·89	667·18	9
54	446·58	400·70	521·01	467·48	595·45	534·26	669·88	601·05	744·31	667·83	6
57	446·23	401·09	520·61	467·94	594·98	534·78	669·36	601·63	743·73	668·48	3
60	445·88	401·48	520·20	468·39	594·51	535·30	668·83	602·21	743·14	669·13	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

48 Deg.

42 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	74·31	66·91	148·62	133·82	222·94	200·73	297·26	267·65	371·57	334·56	60
3	74·26	66·98	148·51	133·95	222·77	200·92	297·03	267·91	371·28	334·88	57
6	74·20	67·04	148·39	134·08	222·59	201·12	296·79	268·17	370·98	335·21	54
9	74·14	67·11	148·28	134·21	222·42	201·31	296·56	268·43	370·69	335·53	51
12	74·08	67·17	148·16	134·34	222·24	201·51	296·32	268·68	370·40	335·86	48
15	74·02	67·24	148·04	134·47	222·06	201·70	296·09	268·94	370·11	336·18	45
18	73·96	67·30	147·92	134·60	221·88	201·90	295·85	269·20	369·81	336·50	42
21	73·90	67·37	147·81	134·73	221·71	202·09	295·62	269·46	369·52	336·82	39
24	73·84	67·43	147·69	134·86	221·53	202·29	295·38	269·72	369·23	337·15	36
27	73·79	67·49	147·57	134·99	221·36	202·48	295·15	269·98	368·94	337·47	33
30	73·73	67·56	147·45	135·11	221·18	202·67	294·91	270·23	368·64	337·79	30
33	73·67	67·62	147·34	135·24	221·00	202·86	294·68	270·49	368·35	338·11	27
36	73·61	67·69	147·22	135·37	220·83	203·06	294·44	270·75	368·05	338·43	24
39	73·55	67·75	147·10	135·50	220·65	203·25	294·20	271·01	367·75	338·75	21
42	73·49	67·82	146·98	135·63	220·47	203·44	293·96	271·26	367·46	339·08	18
45	73·43	67·88	146·86	135·76	220·30	203·63	293·73	271·52	367·16	339·40	15
48	73·37	67·94	146·74	135·88	220·12	203·83	293·49	271·77	366·86	339·72	12
51	73·31	68·01	146·63	136·01	219·94	204·02	293·25	272·03	366·57	340·04	9
54	73·25	68·07	146·51	136·14	219·76	204·21	293·01	272·28	366·27	340·36	6
57	73·19	68·14	146·39	136·27	219·58	204·40	292·78	272·54	365·97	340·68	3
60	73·13	68·20	146·27	136·40	219·40	204·60	292·54	272·80	365·67	341·00	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

47 Deg.

42 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	445·88	401·48	520·20	468·39	594·51	535·30	668·83	602·21	743·14	669·13	60
3	445·53	401·87	519·79	468·84	594·05	535·82	668·31	602·80	742·56	669·78	57
6	445·18	402·25	519·38	469·29	593·58	536·34	667·78	603·38	741·97	670·42	54
9	444·83	402·64	518·97	469·75	593·11	536·86	667·25	603·96	741·37	671·07	51
12	444·48	403·03	518·56	470·20	592·64	537·37	666·72	604·55	740·80	671·72	48
15	444·13	403·42	518·15	470·65	592·17	537·89	666·20	605·13	740·22	672·37	45
18	443·78	403·80	517·74	471·10	591·70	538·41	665·67	605·71	739·63	673·01	42
21	443·43	404·19	517·33	471·55	591·23	538·93	665·14	606·29	739·04	673·66	39
24	443·07	404·58	516·92	472·01	590·76	539·44	664·61	606·87	738·45	674·30	36
27	442·72	404·97	516·51	472·46	590·29	539·96	664·08	607·45	737·86	674·95	33
30	442·36	405·35	516·09	472·91	589·82	540·47	663·55	608·03	737·27	675·59	30
33	442·01	405·74	515·68	473·36	589·35	540·99	663·02	608·61	736·68	676·24	27
36	441·65	406·12	515·27	473·81	588·87	541·50	662·49	609·19	736·09	676·88	24
39	441·30	406·51	514·86	474·26	588·40	542·02	661·95	609·77	735·50	677·52	21
42	440·94	406·89	514·44	474·71	587·93	542·53	661·42	610·34	734·91	678·16	18
45	440·59	407·28	514·03	475·16	587·46	543·04	660·89	610·92	734·32	678·80	15
48	440·23	407·66	513·61	475·60	586·98	543·55	660·35	611·49	733·73	679·44	12
51	439·88	408·05	513·20	476·05	586·51	544·06	659·82	612·07	733·14	680·08	9
54	439·52	408·43	512·78	476·50	586·03	544·57	659·28	612·65	732·54	680·72	6
57	439·17	408·82	512·36	476·95	585·56	545·08	658·75	613·22	731·95	681·36	3
60	438·81	409·20	511·94	477·40	585·08	545·60	658·21	613·80	731·35	682·00	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

47 Deg.

43 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	73·13	68·20	146·27	136·40	219·40	204·60	292·54	272·80	365·67	341·00	60
3	73·08	68·26	146·15	136·53	219·22	204·79	292·30	273·05	365·37	341·32	57
6	73·02	68·33	146·03	136·65	219·04	204·98	292·06	273·30	365·07	341·63	54
9	72·96	68·39	145·91	136·78	218·87	205·17	291·82	273·56	364·78	341·95	51
12	72·89	68·45	145·79	136·90	218·69	205·36	291·58	273·81	364·48	342·27	48
15	72·84	68·52	145·67	137·03	218·51	205·55	291·34	274·07	364·18	342·59	45
18	72·78	68·58	145·55	137·16	218·33	205·74	291·10	274·32	363·88	342·91	42
21	72·72	68·64	145·43	137·29	218·15	205·93	290·86	274·58	363·58	343·22	39
24	72·66	68·71	145·31	137·41	217·97	206·12	290·62	274·83	363·28	343·54	36
27	72·60	68·77	145·19	137·54	217·79	206·31	290·38	275·09	362·98	343·86	33
30	72·54	68·83	145·07	137·67	217·61	206·50	290·14	275·34	362·68	344·18	30
33	72·48	68·90	144·95	137·80	217·43	206·69	289·90	275·60	362·38	344·49	27
36	72·42	68·96	144·83	137·92	217·25	206·88	289·66	275·85	362·08	344·81	24
39	72·36	69·02	144·71	138·05	217·07	207·07	289·42	276·10	361·78	345·12	21
42	72·30	69·09	144·59	138·17	216·89	207·26	289·18	276·35	361·48	345·44	18
45	72·24	69·15	144·47	138·30	216·71	207·45	288·94	276·60	361·18	345·75	15
48	72·18	69·21	144·35	138·42	216·52	207·64	288·70	276·85	360·88	346·07	12
51	72·12	69·28	144·23	138·55	216·34	207·83	288·46	277·10	360·58	346·39	9
54	72·06	69·34	144·11	138·68	216·16	208·02	288·22	277·36	360·27	346·70	6
57	72·00	69·40	143·99	138·81	215·98	208·21	287·98	277·61	359·97	347·02	3
60	71·93	69·47	143·86	138·93	215·80	208·40	287·73	277·86	359·67	347·33	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

46 Deg.

43 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	438·81	409·20	511·94	477·40	585·08	545·60	658·21	613·80	731·35	682·00	60
3	438·45	409·58	511·53	477·85	584·61	546·11	657·68	614·37	730·76	682·64	57
6	438·09	409·96	511·11	478·29	584·13	546·61	657·14	614·94	730·16	683·27	54
9	437·74	410·34	510·69	478·74	583·65	547·12	656·61	615·51	729·56	683·91	51
12	437·38	410·72	510·27	479·18	583·17	547·63	656·07	616·09	728·96	684·54	48
15	437·02	411·10	509·86	479·63	582·69	548·14	655·53	616·66	728·37	685·18	45
18	436·66	411·49	509·44	480·07	582·21	548·65	654·99	617·23	727·77	685·82	42
21	436·30	411·87	509·02	480·52	581·73	549·16	654·45	617·80	727·17	686·45	39
24	435·94	412·25	508·60	480·96	581·25	549·67	653·91	618·38	726·57	687·08	36
27	435·58	412·63	508·18	481·41	580·77	550·18	653·37	618·95	725·97	687·71	33
30	435·22	413·01	507·76	481·85	580·29	550·68	652·83	619·52	725·37	688·35	30
33	434·86	413·39	507·34	482·29	579·81	551·19	652·29	620·09	724·77	688·98	27
36	434·50	413·77	506·92	482·73	579·33	551·69	651·75	620·66	724·17	689·62	24
39	434·14	414·15	506·50	483·17	578·85	552·20	651·21	621·23	723·57	690·25	21
42	433·78	414·53	506·07	483·61	578·37	552·70	650·67	621·79	722·96	690·88	18
45	433·42	414·90	505·65	484·05	577·89	553·21	650·13	622·36	722·36	691·51	15
48	433·05	415·28	505·23	484·49	577·40	553·71	649·58	622·93	721·75	692·14	12
51	432·69	415·66	504·81	484·93	576·92	554·22	649·04	623·49	721·15	692·77	9
54	432·33	416·04	504·38	485·38	576·44	554·72	648·49	624·06	720·55	693·40	6
57	431·97	416·42	503·96	485·82	575·96	555·22	647·95	624·63	719·95	694·03	3
60	431·60	416·79	503·53	486·26	575·47	555·72	647·40	625·19	719·34	694·66	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

46 Deg.

44 Deg.

Minutes.	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	71·93	69·47	143·86	138·93	215·80	208·40	287·73	277·86	359·67	347·33	60
3	71·87	69·53	143·74	139·05	215·62	208·59	287·49	278·11	359·37	347·64	57
6	71·81	69·59	143·62	139·18	215·43	208·77	287·25	278·36	359·06	347·95	54
9	71·75	69·65	143·50	139·30	215·25	208·96	287·00	278·61	358·76	348·27	51
12	71·69	69·72	143·38	139·43	215·07	209·15	286·76	278·86	358·45	348·58	48
15	71·63	69·78	143·26	139·55	214·89	209·34	286·52	279·11	358·15	348·90	45
18	71·57	69·84	143·14	139·68	214·70	209·52	286·27	279·36	357·84	349·21	42
21	71·51	69·90	143·02	139·80	214·52	209·71	286·03	279·61	357·54	349·52	39
24	71·45	69·97	142·89	139·93	214·34	209·89	285·78	279·86	357·23	349·83	36
27	71·39	70·03	142·77	140·05	214·16	210·08	285·54	280·11	356·93	350·14	33
30	71·33	70·09	142·65	140·18	213·97	210·27	285·30	280·36	356·62	350·45	30
33	71·26	70·15	142·53	140·30	213·79	210·46	285·06	280·61	356·32	350·76	27
36	71·20	70·21	142·40	140·43	213·60	210·64	284·81	280·86	356·01	351·07	24
39	71·14	70·28	142·28	140·55	213·42	210·83	284·57	281·11	355·71	351·38	21
42	71·08	70·34	142·16	140·68	213·24	211·01	284·32	281·35	355·40	351·69	18
45	71·02	70·40	142·04	140·80	213·06	211·20	284·07	281·60	355·09	352·00	15
48	70·96	70·46	141·91	140·92	212·87	211·39	283·82	281·85	354·78	352·31	12
51	70·90	70·52	141·79	141·05	212·69	211·58	283·58	282·10	354·48	352·62	9
54	70·83	70·59	141·66	141·17	212·50	211·76	283·33	282·34	354·17	352·93	6
57	70·77	70·65	141·54	141·30	212·32	211·95	283·09	282·59	353·86	353·24	3
60	70·71	70·71	141·42	141·42	212·13	212·13	282·84	282·84	353·55	353·55	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 100.		Dist. 200.		Dist. 300.		Dist. 400.		Dist. 500.		

45 Deg.

44 Deg.

Minutes.	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		
	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	
	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	
0	431·60	416·79	503·53	486·26	575·47	555·72	647·40	625·19	719·34	694·66	60
3	431·24	417·16	503·11	486·70	574·99	556·22	646·86	625·75	718·73	695·29	57
6	430·87	417·54	502·68	487·13	574·50	556·72	646·31	626·32	718·12	695·91	54
9	430·51	417·91	502·26	487·57	574·02	557·22	645·77	626·88	717·52	696·53	51
12	430·14	418·29	501·83	488·01	573·53	557·73	645·22	627·44	716·91	697·16	48
15	429·78	418·66	501·41	488·45	573·04	558·23	644·67	628·00	716·30	697·79	45
18	429·41	419·04	500·98	488·89	572·55	558·73	644·12	628·57	715·69	698·41	42
21	429·05	419·42	500·56	489·33	572·06	559·23	643·57	629·13	715·08	699·03	39
24	428·68	419·79	500·13	489·76	571·57	559·73	643·02	629·69	714·47	699·66	36
27	428·32	420·17	499·70	490·20	571·09	560·23	642·47	630·25	713·86	700·29	33
30	427·95	420·54	499·27	490·63	570·60	560·72	641·92	630·81	713·25	700·91	30
33	427·58	420·92	498·84	491·07	570·11	561·22	641·37	631·37	712·64	701·53	27
36	427·21	421·29	498·41	491·50	569·62	561·72	640·82	631·93	712·02	702·15	24
39	426·85	421·67	497·98	491·94	569·13	562·22	640·27	632·49	711·41	702·77	21
42	426·48	422·04	497·55	492·37	568·64	562·71	639·72	633·05	710·80	703·39	18
45	426·11	422·41	497·12	492·81	568·15	563·21	639·17	633·61	710·19	704·01	15
48	425·74	422·78	496·69	493·24	567·65	563·70	638·61	634·17	709·57	704·63	12
51	425·37	423·15	496·26	493·68	567·16	564·20	638·06	634·73	708·96	705·25	9
54	425·00	423·52	495·83	494·11	566·67	564·69	637·50	635·28	708·34	705·87	6
57	424·63	423·89	495·40	494·54	566·17	565·19	636·95	635·84	707·72	706·48	3
60	424·26	424·26	494·97	494·97	565·68	565·68	636·39	636·39	707·10	707·10	0
	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Base.	Per.	Minutes.
	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	Dep.	Lat.	
	Dist. 600.		Dist. 700.		Dist. 800.		Dist. 900.		Dist. 1000.		

45 Deg.

INDEX.

A

cy of new points, 16.
ment of Improved Dial, 39,

on of true meridian to
s, 38.
tage of correct points, 16.
and its complement, 36.
of elevation or depression in
› measures, 48.
ation of Triangulation, 59.
f Squares drawn on Map, 3.
s in underground chaining, 8.
number best to use, 9.
occasional advantage of
small flag in, 9.
tion of magnetic needle, 11.

B

," order of placing, in work-
out Traverses, 25.
ines, laying out, 28.
f Computation, 30, 59.
f Verification, 31, 59.
aper for Maps, 2.

C

ss and rough surveying, 17.
deposits of Iron Ore, 74.
n to be observed in using
›er to carry points, 14.
to be frequently tested, 7.
ng, &c., 7.
ing the readings of instrument
rveying, 11.

Circuit, making, of boundary, 28.
Coal produced per acre, 75.
Colours for workings on Map, 49.
Comparison of Nos. 1 and 2 traversing computations, 36.
Comparison of Computations, 51.
Computation of "point" to connect workings, 36.
Computation of Areas, 50.
Computation of Triangulation, 60.
Conformation of boundary of property to paper, 4.
Connecting line for underground surveys, 36.
Construction of the Traverse Tables, 21.
Co-ordinates of Traversing angle, 20.
,, determination of, of an angle, 20.
,, multiplying or dividing, 23.
,, order of tabulating, in computations, 23.
,, relative position of, in working out, 25.
,, taking out the, 23, 24, 31.

D

Datum for proving chain, 7.
"Declination," recording the, 51.
Defining the co-ordinates of traversing-angle, 20, 23.
Determination of third side of triangle, 32.
,, of connecting line between "faces," 37.

Determining the traversing-angle, 20.
Determining position for the winning, 52.
Diagram-lines, traversing, explained, 18.
Difference between plotting and computation, 13, 28.
do. instance of, 14.
Diligence necessary in chaining, 8.
Directions for meridional lines, 3.
Disarrangement of points, 15.
Distance of point-marks apart, 15.
Distinguishing marks in underground surveys, 12.
Diverging lines of survey, 66.
Dividing and lining Mapping-paper, 3.
Division of Compass-Box, 19.
do. as regards traversing, 19.

E

Effects of strong sunlight on paper, 4.
,, of variation of magnetic meridian on Plans, 6.
Engine and Incline planes, 53.
Entered, everything to be shewn on Map to be, 11.
Entries in Field-Book, 10.
Escarpments, crossing steep, 29.
Examples of taking out the co-ordinates, 23, 24, 31, 32.
,, in Trigonometry, 25, 26.
,, to determine the third line of triangles, 33.
Expansion of paper from Damp, 2.
Exploring foreign countries, 66.

F

Facility divided paper affords for plotting, 4.
Finishing the Plan, 50.
Foreign countries, exploration of, 67.
,, labour not always cheap, 73.

G

Gauge to ascertain if paper panded, 4.
Gradients about works, 57.

H

Holding the "points," 16.

I

Importance of accurate Meri and Transverse lines, 4.
Importance of correct chainin
Improved dial, method of adj the, 39.
,, protractor for plottir
Improved instruments for w from True Meridian, 7, 38.
Infringement of boundaries, 3
Inking in, 49.
Instrument, setting the, 10.
,, use of, in moving "point
Instruments used in dividing ping-paper, 3.
Instruments used in Triangul 60.
Insufficiency of the meridiona frequently met with on Plan

L

Laying out the base-lines o property, 28.
,, ,, judgment and expe necessary in, 29.
,, ,, bottom of Pit, 52.
Levelling for Mining purposes,
Lining and dividing Mapping-p 3.

M

Magnetic meridian constantly able, 6.
,, needle, working with

Magnetic *versus* True meridian, 5.
Marking off "points" for plotting, 46.
Marking terminal positions of a survey, 54.
Marks to assist operation of plotting, 47.
Measure of the effect of variation, 6.
Measuring "base of computation," 30.
,, ,, of verification, 31.
Men employed in chaining, 8.
Meridional lines, 5.
Method of chaining underground, 8.
,, of determining the Traversing angle, 20.
,, of dividing Mapping paper, 3.
,, of giving "points" to headings, 13.
,, of marking turns in Field-book, 12.
,, of reading improved dial, 39.
Mineral deposits, 68.
Mineral properties, 69.
Miners and their dangers, 70.
Mountainous districts, 29.
Multiplying or dividing the co-ordinates of angles, 23.

N

Notes, entering of, in underground surveys, 9.

O

Opposite drivages, 14.
,, ,, setting out, 14.
Order of progressing in underground surveys, 11.

P

Paper for Maps, 1.
Parallel headings, 53.
"Per." order of placing, in working Traverses, 25.
Periodical surveys, 55.
Pitch and Rise of measures, 12.
Plotting survey, 44.
,, stalls, 48.
,, surface lines, 50.
Point to be given to connect underground workings, 36.
Points, holding the, 16.
,, advantage of correct, 16.
,, on stall roads, 54.
,, to be given, 13, 52.
,, disarrangement of, 15.
,, moving forward, 15.
,, proving the accuracy of new, 16.
Positions, determining, in periodical surveys, 55.
Positions on Surface, 34.

Q

Quantities of coal produced per acre, 75.
Questions to be entertained in valuing, 76.

R

Railways about works, 56, 57.
Reading the instrument, 11.
Recording the declination of Magnetic meridian, 51.
Refraction of light, 60.
Relation of Traversing-angle to "Base," 34.
Resultants of Traversing computations, 19.
Rise and pitch of measures, 12.
Rough and careless surveying, 17.
Roughly computing exhausted mineral ground, 5.
Rule for plane trigonometry, 25, 32.
Ruling the Field-book, 10.

S

Salient points of underground-workings, 27, 28.
Seasoning paper for Maps, 1.
Set-square for plotting, 45.
Setting the instrument, 10.

Shading with the brush, 49.
Siding accommodation, 56.
Sine of Traversing-angle, 25.
Spherical trigonometry, 67.
Squares for approximate computations, 51.
Steep measures, angle of elevation or depression, 48.
Surface, positions on, 34.
Surveying over mountainous districts, 29.

T

Tabular entries on Plan, 39.
Tabulating co-ordinates of angles in computations, 23.
Taking out the co-ordinates, examples of, 23, 24.
Third side of triangle, examples to determine, 33.
Timber for holding "point," 14.
Tracing mineral deposits, 68.
Traverse Tables, 89 to 179.
,, ,, construction of the, 21.
,, ,, applied to different measures, 22.
,, ,, sufficiency of, for lines of different lengths, 22.
Traversing, 17.
,, angle determined, 20.
,, ,, co-ordinates of, 20.
,, entries in Field-book, 19 20.
,, explanation of, diagram lines, 18.
,, resultants explained, 19.
Traversing-angle, to find, 34.
Traversing Computations, 30, 35.
Trespass, committal of, 32.
Triangulation, application of, to surveying, 59.
Tripod stand for instrument, 43.
True *versus* Magnetic meridian, 5.
True meridian, setting instrument to, 40.
,, ,, determination of, 41, 42.

U

Underground workings, connecting line for, 36.
Utility of Traverse Tables, 13.

V

Value of traversing in connecting workings, 27.
,, of good instruments, 45.
,, of settled mining labour, 72.
Valuing mining property, 76.
,, Rent-charge, 78.
,, immediate annuity, 78, 79.
,, do., when paid half-yearly, and when paid quarterly, 79, 80.
,, freehold property with minerals, 80, 82.
Variable, magnetic meridian constantly, 6.

W

Weakness of foreign mining enterprises, 73.
Winning, determining position for the, 52.
Working hematite deposits, 74.
Working with Magnetic needle, 6.

THE END.

LONDON, *July*, 1877.

A Catalogue of Books

INCLUDING MANY

NEW & STANDARD WORKS

IN

ENGINEERING, ARCHITECTURE, AGRICULTURE, MATHEMATICS, MECHANICS, SCIENCE, &c. &c.

PUBLISHED BY

CROSBY LOCKWOOD & CO.,

7, STATIONERS'-HALL COURT, LUDGATE HILL, E.C.

ENGINEERING, SURVEYING, &c.

Humber's New Work on Water-Supply.

A COMPREHENSIVE TREATISE on the WATER-SUPPLY of CITIES and TOWNS. By WILLIAM HUMBER, Assoc. Inst. C.E., and M. Inst. M.E. Author of "Cast and Wrought Iron Bridge Construction," &c. &c. Imp. 4to. Illustrated with 50 Double Plates, 2 Single Plates, Coloured Frontispiece, and upwards of 250 Woodcuts, and containing 400 pages of Text, elegantly and substantially half-bound in morocco. Price 6*l.* 6*s.*

List of Contents:—

I. Historical Sketch of some of the means that have been adopted for the Supply of Water to Cities and Towns.—II. Water and the Foreign Matter usually associated with it.—III. Rainfall and Evaporation.—IV. Springs and the water-bearing formations of various districts.—V. Measurement and Estimation of the Flow of Water.—VI. On the Selection of the Source of Supply.—VII. Wells.—VIII. Reservoirs.—IX. The Purification of Water.—X. Pumps.—XI. Pumping Machinery.—XII. Conduits.—XIII. Distribution of Water.—XIV. Meters, Service Pipes, and House Fittings.—XV. The Law and Economy of Water Works.—XVI. Constant and Intermittent Supply.—XVII. Description of Plates.—Appendices, giving Tables of Rates of Supply, Velocities, &c. &c., together with Specifications of several Works illustrated, among which will be found:—Aberdeen, Bideford, Canterbury, Dundee, Halifax, Lambeth, Rotherham, Dublin, and others.

OPINIONS OF THE PRESS.

"The most systematic and valuable work upon water supply hitherto produced n English, or in any other language."—*Engineer* (first notice), Nov. 3. 1876.

"Mr. Humber's work is characterised almost throughout by an exhaustiveness much more distinctive of French and German than of English technical treatises."—*Engineer* (third notice), Dec. 15, 1876.

"We can congratulate Mr. Humber on having been able to give so large an amount of information on a subject so important as the water supply of cities and towns. The plates, fifty in number, are mostly drawings of executed works, and alone would have commanded the attention of every engineer whose practice may lie in this branch of the profession."—*Builder*, Dec. 9, 1876.

Humber's Modern Engineering. First Series.

A RECORD of the PROGRESS of MODERN ENGINEERING, 1863. Comprising Civil, Mechanical, Marine, Hydraulic, Railway, Bridge, and other Engineering Works, &c. By WILLIAM HUMBER, Assoc. Inst. C.E., &c. Imp. 4to, with 36 Double Plates, drawn to a large scale, and Photographic Portrait of John Hawkshaw, C.E., F.R.S., &c. Price 3*l.* 3*s.* half morocco.

List of the Plates.

NAME AND DESCRIPTION.	PLATES.	NAME OF ENGINEER.
Victoria Station and Roof—L. B. & S. C. Rail.	1 to 8	Mr. R. Jacomb Hood, C.E.
Southport Pier	9 and 10	Mr. James Brunlees, C.E.
Victoria Station and Roof—L. C. & D. & G. W. Railways	11 to 15A	Mr. John Fowler, C.E.
Roof of Cremorne Music Hall	16	Mr. William Humber, C.E.
Bridge over G. N. Railway	17	Mr. Joseph Cubitt, C.E.
Roof of Station—Dutch Rhenish Railway	18 and 19	Mr. Euschedi, C.E.
Bridge over the Thames—West London Extension Railway	20 to 24	Mr. William Baker, C.E.
Armour Plates	25	Mr. James Chalmers, C.E.
Suspension Bridge, Thames	26 to 29	Mr. Peter W. Barlow, C.E.
The Allen Engine	30	Mr. G. T. Porter, M.E.
Suspension Bridge, Avon	31 to 33	Mr. John Hawkshaw, C.E. and W. H. Barlow, C.E.
Underground Railway	34 to 36	Mr. John Fowler, C.E.

With copious Descriptive Letterpress, Specifications, &c.

"Handsomely lithographed and printed. It will find favour with many who desire to preserve in a permanent form copies of the plans and specifications prepared for the guidance of the contractors for many important engineering works."—*Engineer.*

Humber's Modern Engineering. Second Series.

A RECORD of the PROGRESS of MODERN ENGINEERING, 1864; with Photographic Portrait of Robert Stephenson, C.E., M.P., F.R.S., &c. Price 3*l.* 3*s.* half morocco.

List of the Plates.

NAME AND DESCRIPTION.	PLATES.	NAME OF ENGINEER.
Birkenhead Docks, Low Water Basin	1 to 15	Mr. G. F. Lyster, C.E.
Charing Cross Station Roof—C. C. Railway.	16 to 18	Mr. Hawkshaw, C.E.
Digswell Viaduct—Great Northern Railway.	19	Mr. J. Cubitt, C.E.
Robbery Wood Viaduct—Great N. Railway.	20	Mr. J. Cubitt, C.E.
Iron Permanent Way	20a	—
Clydach Viaduct—Merthyr, Tredegar, and Abergavenny Railway	21	Mr. Gardner, C.E.
Ebbw Viaduct ditto ditto ditto	22	Mr. Gardner, C.E.
College Wood Viaduct—Cornwall Railway	23	Mr. Brunel.
Dublin Winter Palace Roof	24 to 26	Messrs. Ordish & Le Feuvre.
Bridge over the Thames—L. C. & D. Railw.	27 to 32	Mr. J. Cubitt, C.E.
Albert Harbour, Greenock	33 to 36	Messrs. Bell & Miller.

With copious Descriptive Letterpress, Specifications, &c.

"A *résumé* of all the more interesting and important works lately completed in Great Britain; and containing, as it does, carefully executed drawings, with full working *details, it will be* found a valuable accessory to the profession at large."—*Engineer.*

"*Mr. Humber* has done the profession good and true service, by the fine collection which he has here brought before the profession and the public."—*Practical Journal.*

Humber's Modern Engineering. Third Series.

A RECORD of the PROGRESS of MODERN ENGINEERING, 1865. Imp. 4to, with 40 Double Plates, drawn to a large scale, and Photo Portrait of J. R. M'Clean, Esq., late President of the Institution of Civil Engineers. Price 3*l.* 3*s.* half morocco.

List of Plates and Diagrams.

MAIN DRAINAGE, METROPOLIS, NORTH SIDE.

Plate 1. Map showing Interception of Sewers.—2 and 3. Middle Level Sewer. Sewer under Regent's Canal; and Junction with Fleet Ditch.—4, 5, and 6. Outfall Sewer. Bridge over River Lea. Elevation and Details.—7. Outfall Sewer. Bridge over Marsh Lane, North Woolwich Railway, and Bow and Barking Railway Junction.—8, 9, and 10. Outfall Sewer. Bridge over Bow and Barking Railway. Elevation and Details.—11 and 12. Outfall Sewer. Bridge over East London Waterworks' Feeder. Elevation and Details.—13 and 14. Outfall Sewer. Reservoir. Plan and Section.—15. Outfall Sewer. Tumbling Bay and Outlet.—16. Outfall Sewer. Penstocks.

SOUTH SIDE.

Plates 17 and 18. Outfall Sewer. Bermondsey Branch.—19, 20, 21, and 22.

MAIN DRAINAGE, METROPOLIS, *continued*—

Outfall Sewer. Reservoir and Outlet. Plan and Details.—23. Outfall Sewer. Filth Hoist.—24. Sections of Sewers (North and South Sides).

THAMES EMBANKMENT.

Plate 25. Section of River Wall.—26 and 27. Steam-boat Pier, Westminster. Elevation and Details.—28. Landing Stairs between Charing Cross and Waterloo Bridges.—29 and 30. York Gate. Front Elevation. Side Elevation and Details.—31, 32, and 33. Overflow and Outlet at Savoy Street Sewer. Details; and Penstock.—34, 35, and 36. Steam-boat Pier, Waterloo Bridge. Elevation and Details.—37. Junction of Sewers. Plans and Sections.—38. Gullies. Plans and Sections.—39. Rolling Stock.—40. Granite and Iron Forts.

With copious Descriptive Letterpress, &c.

Humber's Modern Engineering. Fourth Series.

A RECORD of the PROGRESS of MODERN ENGINEERING, 1866. Imp. 4to, with 36 Double Plates, drawn to a large scale, and Photographic Portrait of John Fowler, Esq., President of the Institution of Civil Engineers. Price 3*l.* 3*s.* half morocco.

List of the Plates and Diagrams.

NAME AND DESCRIPTION.	PLATES.	NAME OF ENGINEER.
Abbey Mills Pumping Station, Main Drainage, Metropolis	1 to 4	Mr. Bazalgette, C.E.
Barrow Docks	5 to 9	Messrs. M'Clean & Stillman, [C.E.
Manquis Viaduct, Santiago and Valparaiso Railway	10, 11	Mr. W. Loyd, C.E.
Adams' Locomotive, St. Helen's Canal Railw.	12, 13	Mr. H. Cross, C.E.
Cannon Street Station Roof	14 to 16	Mr. J. Hawkshaw, C.E.
Road Bridge over the River Moka	17, 18	Mr. H. Wakefield, C.E.
Telegraphic Apparatus for Mesopotamia	19	Mr. Siemens, C.E.
Viaduct over the River Wye, Midland Railw.	20 to 22	Mr. W. H. Barlow, C.E.
St. Germans Viaduct, Cornwall Railway	23, 24	Mr. Brunel, C.E.
Wrought-Iron Cylinder for Diving Bell	25	Mr. J. Coode, C.E.
Millwall Docks	26 to 31	Messrs. J. Fowler, C.E., and William Wilson, C.E.
Milroy's Patent Excavator	32	Mr. Milroy, C.E.
Metropolitan District Railway	33 to 38	Mr. J. Fowler, and Mr. T. M. Johnson, C.E.
Harbours, Ports, and Breakwaters	A to C	

With Copious Descriptive Letterpress, Specifications, &c.

Humber's Great Work on Bridge Construction.

A COMPLETE and PRACTICAL TREATISE on CAST and WROUGHT-IRON BRIDGE CONSTRUCTION, including Iron Foundations. In Three Parts—Theoretical, Practical, and Descriptive. By WILLIAM HUMBER, Assoc. Inst. C.E., and M. Inst. M.E. Third Edition, revised and much improved, with 115 Double Plates (20 of which now first appear in this edition), and numerous additions to the Text. In 2 vols. imp. 4to, price 6*l.* 16*s.* 6*d.* half-bound in morocco.

"A very valuable contribution to the standard literature of civil engineering. In addition to elevations, plans, and sections, large scale details are given, which very much enhance the instructive worth of these illustrations. No engineer would willingly be without so valuable a fund of information."—*Civil Engineer and Architect's Journal.*

"Mr. Humber's stately volumes lately issued—in which the most important bridges erected during the last five years, under the direction of our most eminent engineers, are drawn and specified in great detail."—*Engineer.*

"A book—and particularly a large and costly treatise like Mr. Humber's—which has reached its third edition may certainly be said to have established its own reputation."—*Engineering.*

Strains, Formulæ & Diagrams for Calculation of.

A HANDY BOOK for the CALCULATION of STRAINS in GIRDERS and SIMILAR STRUCTURES, and their STRENGTH; consisting of Formulæ and Corresponding Diagrams, with numerous Details for Practical Application, &c. By WILLIAM HUMBER, Assoc. Inst. C.E., &c. Second Edition. Fcap. 8vo, with nearly 100 Woodcuts and 3 Plates, price 7*s.* 6*d.* cloth.

"The arrangement of the matter in this little volume is as convenient as it well could be. . . . . The system of employing diagrams as a substitute for complex computations is one justly coming into great favour, and in that respect Mr. Humber's volume is fully up to the times."—*Engineering.*

"The formulæ are neatly expressed, and the diagrams good."—*Athenæum.*

"Mr. Humber has rendered a great service to the architect and engineer by producing a work especially treating on the methods of delineating the strains on iron beams, roofs, and bridges by means of diagrams."—*Builder.*

Barlow on the Strength of Materials, enlarged.

A TREATISE ON THE STRENGTH OF MATERIALS, with Rules for application in Architecture, the Construction of Suspension Bridges, Railways, &c.; and an Appendix on the Power of Locomotive Engines, and the effect of Inclined Planes and Gradients. By PETER BARLOW, F.R.S. A New Edition, revised by his Sons, P. W. BARLOW, F.R.S., and W. H. BARLOW, F.R.S., to which are added Experiments by HODGKINSON, FAIRBAIRN, and KIRKALDY; an Essay (with Illustrations) on the effect produced by passing Weights over Elastic Bars, by the Rev. ROBERT WILLIS, M.A., F.R.S. And Formulæ for Calculating Girders, &c. The whole arranged and edited by W. HUMBER, Assoc. Inst. C.E., Author of "A Complete and Practical Treatise on Cast and Wrought-Iron Bridge Construction," &c. 8vo, 400 pp., with 19 large Plates, and numerous woodcuts, 18*s.* cloth.

"The book is undoubtedly worthy of the highest commendation."—*Mining Journal.*

"*The best book* on the subject which has yet appeared. . . . . We know of *no work that so* completely fulfils its mission."—*English Mechanic.*

"*The standard* treatise upon this particular subject."—*Engineer.*

Iron and Steel.

'IRON AND STEEL': a Work for the Forge, Foundry, Factory, and Office. Containing Ready, Useful, and Trustworthy Information for Ironmasters and their Stocktakers; Managers of Bar, Rail, Plate, and Sheet Rolling Mills; Iron and Metal Founders; Iron Ship and Bridge Builders; Mechanical, Mining, and Consulting Engineers; Architects, Contractors, Builders, and Professional Draughtsmen. By CHARLES HOARE, Author of 'The Slide Rule,' &c. Eighth Edition. Revised throughout and considerably enlarged. With folding Scales of "Foreign Measures compared with the English Foot," and "fixed Scales of Squares, Cubes, and Roots, Areas, Decimal Equivalents, &c." Oblong, 32mo, leather elastic-band, 6*s.*

"We cordially recommend this book to those engaged in considering the details of all kinds of iron and steel works. . . . . It has been compiled with care and accuracy. . . . . Many useful rules and hints are given for lessening the amount of arithmetical labour which is always more or less necessary in arranging iron and steel work of all kinds, and a great quantity of useful tables for preparing estimates of weights, dimensions, strengths of structures, costs of work, &c., will be found in Mr. Hoare's book.—*Naval Science.*

Weale's Engineers' Pocket-Book.

THE ENGINEERS', ARCHITECTS', and CONTRACTORS' POCKET-BOOK (LOCKWOOD & Co.'s; formerly WEALE'S). Published Annually. In roan tuck, gilt edges, with 10 Copper-Plates and numerous Woodcuts. Price 6*s.*

"A vast amount of really valuable matter condensed into the small dimensions of a book which is, in reality, what it professes to be—a pocket-book. . . . . We cordially recommend the book.—*Colliery Guardian.*

"It contains a large amount of information peculiarly valuable to those for whose use it is compiled. We cordially commend it to the engineering and architectural professions generally."—*Mining Journal.*

Iron Bridges, Girders, Roofs, &c.

A TREATISE on the APPLICATION of IRON to the CONSTRUCTION of BRIDGES, GIRDERS, ROOFS, and OTHER WORKS; showing the Principles upon which such Structures are Designed, and their Practical Application. Especially arranged for the use of Students and Practical Mechanics, all Mathematical Formulæ and Symbols being excluded. By FRANCIS CAMPIN, C.E. Second Edition revised and corrected. With numerous Diagrams. 12mo, cloth boards, 3*s.*

"Invaluable to those who have not been educated in mathematics."—*Colliery Guardian.*

"Remarkably accurate and well written."—*Artisan.*

Mechanical Engineering.

A PRACTICAL TREATISE ON MECHANICAL ENGINEERING: comprising Metallurgy, Moulding, Casting, Forging, Tools, Workshop Machinery, Mechanical Manipulation, Manufacture of the Steam Engine, &c. &c. With an Appendix on the Analysis of Iron and Iron Ore, and Glossary of Terms. By FRANCIS CAMPIN, C.E. Illustrated with 91 Woodcuts and 28 Plates of Slotting, Shaping, Drilling, Punching, Shearing, and Riveting Machines—Blast, Refining, and Reverberatory Furnaces—Steam Engines, Governors, Boilers, Locomotives, &c. 8vo. cloth, 12*s.*

Pioneer Engineering.

PIONEER ENGINEERING. A Treatise on the Engineering Operations connected with the Settlement of Waste Lands in New Countries. By EDWARD DOBSON, Assoc. Inst. C.E., Author of "The Art of Building," &c. With numerous Plates and Wood Engravings. Crown 8vo, 10*s.* 6*d.* [*Just published.*

"A most useful handbook to engineering pioneers."—*Iron*, Dec. 2, 1876.

"The author's experience has been turned to good account, and the book is likely to be of considerable service to pioneer engineers."—*Building News.*

"Promises a great deal, and fulfils most of its promises. . . . . Of use to the colonial pioneering surveyor and engineer."—*Scotsman.*

New Iron Trades' Companion.

THE IRON AND METAL TRADES' COMPANION: Being a Calculator containing a Series of Tables upon a new and comprehensive plan for expeditiously ascertaining the value of any goods bought or sold by weight, from 1*s.* per cwt. to 112*s.* per cwt., and from one farthing per pound to one shilling per pound. Each Table extends from one pound to 100 tons; to which are appended Rules on Decimals, Square and Cube Root, Mensuration of Superficies and Solids, &c.; also Tables of Weights of Materials, and other Useful Memoranda. By THOMAS DOWNIE. Strongly bound in leather, 396 pp., price 9*s.*

"A most useful set of tables, and will supply a want, for nothing like them before existed."—*Building News*, Dec. 8, 1876.

"We have tested the calculations at random and found them correct."—*Colliery Guardian*, Dec. 1, 1876.

"Will save the possessor the trouble of making numerous intricate calculations. Although specially adapted to the iron and metal trades, the tables contained in this handy little companion will be found useful in every other business in which merchandise is bought and sold by weight."—*Railway News*, Dec. 9, 1876.

Sanitary Work.

SANITARY WORK IN THE SMALLER TOWNS AND IN VILLAGES. Comprising:—1. Some of the more Common Forms of Nuisance and their Remedies; 2. Drainage; 3. Water Supply. A useful book for Members of Local Boards and Rural Sanitary Authorities, Health Officers, Engineers, Surveyors, Builders, and Contractors. By CHARLES SLAGG, Assoc. Inst. C.E. Crown 8vo. cloth, price 5*s.* [*Just published.*

"Mr. Slagg has brought together much valuable information, and has a happy lucidity of expression; and he has been industrious in collecting data."—*Athenæum.*

"This is a very useful book, and may be safely recommended. . . . . The author, Mr. Charles Slagg, has had practical experience in the works of which he treats. There is a great deal of work required to be done in the smaller towns and villages, and this little volume will help those who are willing to do it."—*Builder.*

Steam Engine.

STEAM AND THE STEAM ENGINE, Stationary and Portable, an Elementary Treatise on. Being an Extension of Mr. John Sewell's Treatise on Steam. By D. KINNEAR CLARK, C.E., M.I.C.E., Author of "Railway Locomotives," &c. With Illustrations. 12mo, cloth, 4*s.*

"*Every essential* part of the subject is treated of competently, and in a popular style."—*Iron.*

Strains.

THE STRAINS ON STRUCTURES OF IRONWORK; with Practical Remarks on Iron Construction. By F. W. SHEILDS, M. Inst. C.E. Second Edition, with 5 plates. Royal 8vo, 5*s.* cloth.

CONTENTS.—Introductory Remarks; Beams Loaded at Centre; Beams Loaded at unequal distances between supports; Beams uniformly Loaded; Girders with triangular bracing Loaded at centre; Ditto, Loaded at unequal distances between supports; Ditto, uniformly Loaded; Calculation of the Strains on Girders with triangular Basings; Cantilevers; Continuous Girders; Lattice Girders; Girders with Vertical Struts and Diagonal Ties; Calculation of the Strains on Ditto; Bow and String Girders; Girders of a form not belonging to any regular figure; Plate Girders; Apportionments of Material to Strain; Comparison of different Girders; Proportion of Length to Depth of Girders; Character of the Work; Iron Roofs.

Construction of Iron Beams, Pillars, &c.

IRON AND HEAT, Exhibiting the Principles concerned in the Construction of Iron Beams, Pillars, and Bridge Girders, and the Action of Heat in the Smelting Furnace. By JAMES ARMOUR, C.E. Woodcuts, 12mo, cloth boards, 3*s.* 6*d.*; cloth limp, 2*s.* 6*d.*

"A very useful and thoroughly practical little volume, in every way deserving of circulation amongst working men."—*Mining Journal.*

"No ironworker who wishes to acquaint himself with the principles of his own trade can afford to be without it."—*South Durham Mercury.*

Power in Motion.

POWER IN MOTION: Horse Power, Motion, Toothed Wheel Gearing, Long and Short Driving Bands, Angular Forces, &c. By JAMES ARMOUR, C.E. With 73 Diagrams. 12mo, cloth boards, 3*s.* 6*d.*

"Numerous illustrations enable the author to convey his meaning as explicitly as it is perhaps possible to be conveyed. The value of the theoretic and practical knowledge imparted cannot well be over estimated."—*Newcastle Weekly Chronicle.*

Metallurgy of Iron.

A TREATISE ON THE METALLURGY OF IRON: containing Outlines of the History of Iron Manufacture, Methods of Assay, and Analyses of Iron Ores, Processes of Manufacture of Iron and Steel, &c. By H. BAUERMAN, F.G.S., Associate of the Royal School of Mines. With numerous Illustrations. Fourth Edition, revised and much enlarged. 12mo, cloth boards, 5*s.* 6*d.*

"Carefully written, it has the merit of brevity and conciseness, as to less important points, while all material matters are very fully and thoroughly entered into."—*Standard.*

Trigonometrical Surveying.

AN OUTLINE OF THE METHOD OF CONDUCTING A TRIGONOMETRICAL SURVEY, for the Formation of Geographical and Topographical Maps and Plans, Military Reconnaissance, Levelling, &c., with the most useful Problems in Geodesy and Practical Astronomy, and Formulæ and Tables for Facilitating their Calculation. By LIEUT-GENERAL FROME, R.E., late Inspector-General of Fortifications, &c. Fourth Edition, Enlarged, thoroughly Revised, and partly Re-written. By CAPTAIN CHARLES WARREN, R.E., F.G.S. With 19 Plates and 115 Woodcuts, *royal 8vo, price 16s.* cloth.

Practical Tunnelling.

PRACTICAL TUNNELLING: Explaining in detail the Setting out of the Works, Shaft-sinking and Heading-Driving, Ranging the Lines and Levelling under Ground, Sub-Excavating, Timbering, and the Construction of the Brickwork of Tunnels with the amount of labour required for, and the Cost of, the various portions of the work. By FREDERICK WALTER SIMMS, M. Inst. C.E., author of "A Treatise on Levelling." Third Edition, Revised and Extended, with additional chapters illustrating the Recent Practice of Tunnelling as exemplified by the St. Gothard, Mont Cenis, and other modern works, by D. KINNEAR CLARK, M. Inst. C.E. Imp. 8vo, cloth, with 21 Folding Plates and numerous Wood Engravings, price 30*s.* [*Just published.*

"It is the only practical treatise on the great art of tunnelling. Mr. Clark's work brings the exigencies of tunnel enterprise up to our own time. The great length of modern tunnels has led to a new difficulty in the art, which the last generation was ignorant of, namely, the difficulty of ventilation. In Mr. Clark's supplement we find this branch of the subject has been fully considered. Mr. Clark's additional chapters on the Mont Cenis and St. Gothard Tunnels contain minute and valuable experiences and data relating to the method of excavation by compressed air, the heading operations, rock-boring machinery, process of enlargement, ventilation in course of construction by compressed air, labour and cost, &c."—*Building News*, Dec. 8, 1876.

"The estimation in which Mr. Simms' book on tunnelling has been held for over thirty years cannot be more truly expressed than in the words of the late Professor Rankine:—'The best source of information on the subject of tunnels is Mr. F. W. Simms' work on "Practical Tunnelling."'—*The Architect*, Dec. 9, 1876.

Levelling.

A TREATISE on the PRINCIPLES and PRACTICE of LEVELLING; showing its Application to Purposes of Railway and Civil Engineering, in the Construction of Roads; with Mr. TELFORD'S Rules for the same. By FREDERICK W. SIMMS, F.G.S., M. Inst. C.E. Sixth Edition, very carefully revised, with the addition of Mr. LAW'S Practical Examples for Setting out Railway Curves, and Mr. TRAUTWINE'S Field Practice of Laying out Circular Curves. With 7 Plates and numerous Woodcuts. 8vo, 8*s.* 6*d.* cloth. *** TRAUTWINE on Curves, separate, price 5*s.*

"One of the most important text-books for the general surveyor, and there is scarcely a question connected with levelling for which a solution would be sought but that would be satisfactorily answered by consulting the volume."—*Mining Journal.*

"The text-book on levelling in most of our engineering schools and colleges."—*Engineer.*

The High-Pressure Steam Engine.

THE HIGH-PRESSURE STEAM ENGINE; an Exposition of its Comparative Merits, and an Essay towards an Improved System of Construction, adapted especially to secure Safety and Economy. By Dr. ERNST ALBAN, Practical Machine Maker, Plau, Mecklenberg. Translated from the German, with Notes, by Dr. POLE, F.R.S., M. Inst. C.E., &c. &c. With 28 fine Plates, 8vo, 16*s.* 6*d.* cloth.

"A work like this, which goes thoroughly into the examination of the high-pressure *engine, the boiler,* and its appendages, &c., is exceedingly useful, and deserves a place *in every scientific library."—Steam Shipping Chronicle.*

Hydraulics.

HYDRAULIC TABLES, CO-EFFICIENTS, and FORMULÆ for finding the Discharge of Water from Orifices, Notches, Weirs, Pipes, and Rivers. With New Formulæ, Tables, and General Information on Rain-fall, Catchment-Basins, Drainage, Sewerage, Water Supply for Towns and Mill Power. By JOHN NEVILLE, Civil Engineer, M.R.I.A. Third Edition, carefully revised, with considerable Additions. Numerous Illustrations. Cr. 8vo, 14*s.* cloth.

"Undoubtedly an exceedingly useful and elaborate compilation."—*Iron.*

"Will prove alike valuable to students and engineers in practice; its study will prevent the annoyance of avoidable failures, and assist them to select the readiest means of successfully carrying out any given work connected with hydraulic engineering."—*Mining Journal.*

Strength of Cast Iron, &c.

A PRACTICAL ESSAY on the STRENGTH of CAST IRON and OTHER METALS. By the late THOMAS TREDGOLD, Mem. Inst. C.E., Author of "Elementary Principles of Carpentry," &c. Fifth Edition, Edited by EATON HODGKINSON, F.R.S.; to which are added EXPERIMENTAL RESEARCHES on the STRENGTH and OTHER PROPERTIES of CAST IRON. By the EDITOR. The whole Illustrated with 9 Engravings and numerous Woodcuts. 8vo, 12*s.* cloth.

*** HODGKINSON'S EXPERIMENTAL RESEARCHES ON THE STRENGTH AND OTHER PROPERTIES OF CAST IRON may be had separately. With Engravings and Woodcuts. 8vo, price 6*s.* cloth.

Steam Boilers.

A TREATISE ON STEAM BOILERS: their Strength, Construction, and Economical Working. By ROBERT WILSON, late Inspector for the Manchester Steam Users' Association for the Prevention of Steam Boiler Explosions, and for the Attainment of Economy in the Application of Steam. Fourth Edition. 12mo, cloth boards, 328 pages, price 6*s.*

"We regard Mr. Wilson's treatise as the best work on boilers which has come under our notice, and we consider that all boiler makers and boiler owners should give it a place in their libraries."—*Engineering.*

"The best treatise that has ever been published on steam boilers."—*Engineer.*

"A valuable contribution to the subject of steam boiler literature. . . . . The book is full of hints which the proprietor of a steam boiler would find it to his advantage to know."—*Iron and Coal Trades Review.*

Tables of Curves.

TABLES OF TANGENTIAL ANGLES and MULTIPLES for setting out Curves from 5 to 200 Radius. By ALEXANDER BEAZELEY, M. Inst. C.E. Printed on 48 Cards, and sold in a cloth box, waistcoat-pocket size, price 3*s.* 6*d.*

"Each table is printed on a small card, which, being placed on the theodolite, leaves the hands free to manipulate the instrument—no small advantage as regards the rapidity of work. They are clearly printed, and compactly fitted into a small case for the pocket—an arrangement that will recommend them to all practical men."—*Engineer.*

"*Very handy*: a man may know that all his day's work must fall on two of these cards, which he puts into his own card-case, and leaves the rest behind."—*Athenæum.*

Earthwork.

EARTHWORK TABLES, showing the Contents in Cubic Yards of Embankments, Cuttings, &c., of Heights or Depths up to an average of 80 feet. By JOSEPH BROADBENT, C.E., and FRANCIS CAMPIN, C.E. Cr. 8vo, oblong, 5*s.* cloth.

"Creditable to both the authors and the publishers. . . . The way in which accuracy is attained, by a simple division of each cross section into three elements, two of which are constant and one variable, is ingenious."—*Athenæum.*

"Likely to be of considerable service to engineers."—*Building News.*

"Cannot fail to come into general use."—*Mining Journal.*

"These tables, which are clearly printed and easily arranged for reference, will be found to facilitate the accurate determination of the quantities of earthwork in making out estimates."—*English Mechanic.*

Surveying (Land and Marine).

LAND AND MARINE SURVEYING, in Reference to the Preparation of Plans for Roads and Railways, Canals, Rivers, Towns' Water Supplies, Docks and Harbours; with Description and Use of Surveying Instruments. By W. DAVIS HASKOLL, C.E., Author of "The Engineer's Field Book," "Examples of Bridge and Viaduct Construction," &c. Demy 8vo, price 12*s.* 6*d.* cloth, with 14 folding Plates, and numerous Woodcuts.

"A most useful and well arranged book for the aid of a student. . . . . We can strongly recommend it as a carefully-written and valuable text-book."—*Builder.*

"Mr. Haskoll has knowledge and experience, and can so give expression to it as to make any matter on which he writes, clear to the youngest pupil in a surveyor's office."—*Colliery Guardian.*

"A volume which cannot fail to prove of the utmost practical utility. . . . . It is one which may be safely recommended to all students who aspire to become clean and expert surveyors."—*Mining Journal.*

Engineering Fieldwork.

THE PRACTICE OF ENGINEERING FIELDWORK, applied to Land and Hydraulic, Hydrographic, and Submarine Surveying and Levelling. Second Edition, revised, with considerable additions, and a Supplementary Volume on WATER-WORKS, SEWERS, SEWAGE, and IRRIGATION. By W. DAVIS HASKOLL, C.E. Numerous folding Plates. Demy 8vo, 2 vols. in one, cloth boards, 1*l.* 1*s.* (published at 2*l.* 4*s.*)

Mining, Surveying and Valuing.

THE MINERAL SURVEYOR AND VALUER'S COMPLETE GUIDE, comprising a Treatise on Improved Mining Surveying, with new Traverse Tables; and Descriptions of Improved Instruments; also an Exposition of the Correct Principles of Laying out and Valuing Home and Foreign Iron and Coal Mineral Properties: to which is appended M. THOMAN'S (of the Crédit Mobilier, Paris) TREATISE on COMPOUND INTEREST and ANNUITIES, with LOGARITHMIC TABLES. By WILLIAM LINTERN, Mining and Civil Engineer. 12mo, strongly bound in cloth boards, with four Plates of Diagrams, Plans, &c., price 10*s.* 6*d.*

"Contains much valuable information given in a small compass, and which, as far as we have tested it, is thoroughly trustworthy."—*Iron and Coal Trades Review.*

"The matter, arrangement, and illustration of this work are all excellent, and make it one of the best of its kind."—*Standard.*

Fire Engineering.

FIRES, FIRE-ENGINES, AND FIRE BRIGADES. With a History of Fire-Engines, their Construction, Use, and Management; Remarks on Fire-Proof Buildings, and the Preservation of Life from Fire; Statistics of the Fire Appliances in English Towns; Foreign Fire Systems; Hints on Fire Brigades, &c., &c. By CHARLES F. T. YOUNG, C.E. With numerous Illustrations, handsomely printed, 544 pp., demy 8vo, price *1l.* 4*s.* cloth.

"We can most heartily commend this book. . . . . It is really the only English work we now have upon the subject."—*Engineering.*

"We strongly recommend the book to the notice of all who are in any way interested in fires, fire-engines, or fire-brigades."—*Mechanics' Magazine.*

Manual of Mining Tools.

MINING TOOLS. For the use of Mine Managers, Agents, Mining Students, &c. By WILLIAM MORGANS, Lecturer on Practical Mining at the Bristol School of Mines. Volume of Text. 12mo. With an Atlas of Plates, containing 235 Illustrations. 4to. Together, price 9*s.* cloth boards.

"Students in the Science of Mining, and not only they, but subordinate officials in mines, and even Overmen, Captains, Managers, and Viewers may gain practical knowledge and useful hints by the study of Mr. Morgans' Manual."—*Colliery Guardian.*

"A very valuable work, which will tend materially to improve our mining literature."—*Mining Journal.*

Common Sense for Gas-Users.

COMMON SENSE FOR GAS-USERS: a Catechism of Gas-Lighting for Householders, Gasfitters, Millowners, Architects, Engineers, &c., &c. By ROBERT WILSON, C.E., Author of "A Treatise on Steam Boilers." Crown 8vo. sewed, with Folding Plates and Wood Engravings, 2*s.* 6*d.* [*Just published.*

Gas and Gasworks.

A TREATISE on GASWORKS and the PRACTICE of MANUFACTURING and DISTRIBUTING COAL GAS. By SAMUEL HUGHES, C.E. Fourth Edition, revised by W. RICHARDS, C.E. With 68 Woodcuts, 12mo, cloth boards, 4*s.*

Waterworks for Cities and Towns.

WATERWORKS for the SUPPLY of CITIES and TOWNS, with a Description of the Principal Geological Formations of England as influencing Supplies of Water. By SAMUEL HUGHES, F.G.S., Civil Engineer. New and enlarged edition, 12mo, cloth boards, with numerous Illustrations, price 5*s.*

"One of the most convenient, and at the same time reliable works on a subject, the vital importance of which cannot be over-estimated."—*Bradford Observer.*

Coal and Coal Mining.

COAL AND COAL MINING: a Rudimentary Treatise on. By WARINGTON W. SMYTH, M.A., F.R.S., &c., Chief Inspector of the Mines of the Crown and of the Duchy of Cornwall. New edition, revised and corrected. 12mo, cloth boards, with numerous Illustrations, price 4*s.* 6*d.*

"Every portion of the volume appears to have been prepared with much care, and as an outline is given of every known coal-field in this and other countries, as well as of the two principal methods of working, the book will doubtless interest a very large number of readers."—*Mining Journal.*

Field-Book for Engineers.

THE ENGINEER'S, MINING SURVEYOR'S, and CONTRACTOR'S FIELD-BOOK. By W. DAVIS HASKOLL, Civil Engineer. Third Edition, much enlarged, consisting of a Series of Tables, with Rules, Explanations of Systems, and Use of Theodolite for Traverse Surveying and Plotting the Work with minute accuracy by means of Straight Edge and Set Square only; Levelling with the Theodolite, Casting out and Reducing Levels to Datum, and Plotting Sections in the ordinary manner; Setting out Curves with the Theodolite by Tangential Angles and Multiples with Right and Left-hand Readings of the Instrument; Setting out Curves without Theodolite on the System of Tangential Angles by Sets of Tangents and Offsets; and Earthwork Tables to 80 feet deep, calculated for every 6 inches in depth. With numerous wood-cuts, 12mo, price 12*s.* cloth.

"A very useful work for the practical engineer and surveyor. Every person engaged in engineering field operations will estimate the importance of such a work and the amount of valuable time which will be saved by reference to a set of reliable tables prepared with the accuracy and fulness of those given in this volume."—*Railway News.*

"The book is very handy, and the author might have added that the separate tables of sines and tangents to every minute will make it useful for many other purposes, the genuine traverse tables existing all the same."—*Athenæum.*

"The work forms a handsome pocket volume, and cannot fail, from its portability and utility, to be extensively patronised by the engineering profession."—*Mining Journal.*

"We strongly recommend Mr. Haskoll's 'Field Book' to all classes of surveyors."—*Colliery Guardian.*

"We know of no better field-book of reference or collection of tables than Mr. Haskoll's."—*Artizan.*

Earthwork, Measurement and Calculation of.

A MANUAL on EARTHWORK. By ALEX. J. S. GRAHAM, C.E., Resident Engineer, Forest of Dean Central Railway. With numerous Diagrams. 18mo, 2*s.* 6*d.* cloth.

"As a really handy book for reference, we know of no work equal to it; and the railway engineers and others employed in the measurement and calculation of earth work will find a great amount of practical information very admirably arranged, and available for general or rough estimates, as well as for the more exact calculations required in the engineers' contractor's offices."—*Artisan.*

Harbours.

THE DESIGN and CONSTRUCTION of HARBOURS: A Treatise on Maritime Engineering. By THOMAS STEVENSON, F.R.S.E., F.G.S., M.I.C.E. Second Edition, containing many additional subjects, and otherwise generally extended and revised. With 20 Plates and numerous Cuts. Small 4to, 15*s.* cloth.

Mathematical and Drawing Instruments.

A TREATISE ON THE PRINCIPAL MATHEMATICAL *AND* DRAWING INSTRUMENTS employed by the Engineer, *Architect,* and Surveyor. By FREDERICK W. SIMMS, M. Inst. *C.E., Author* of "Practical Tunnelling," &c. Third Edition, with *numerous Cuts.* 12mo, price 3*s.* 6*d.* cloth.

Bridge Construction in Masonry, Timber, & Iron.

EXAMPLES OF BRIDGE AND VIADUCT CONSTRUCTION OF MASONRY, TIMBER, AND IRON; consisting of 46 Plates from the Contract Drawings or Admeasurement of select Works. By W. DAVIS HASKOLL, C.E. Second Edition, with the addition of 554 Estimates, and the Practice of Setting out Works, illustrated with 6 pages of Diagrams. Imp. 4to, price *2l.* 12*s.* 6*d.* half-morocco.

"One of the very few works extant descending to the level of ordinary routine, and treating on the common every-day practice of the railway engineer. . . . A work of the present nature by a man of Mr. Haskoll's experience, must prove invaluable to hundreds. The tables of estimates appended to this edition will considerably enhance its value."—*Engineering.*

Mathematical Instruments, their Construction, &c.

MATHEMATICAL INSTRUMENTS: THEIR CONSTRUCTION, ADJUSTMENT, TESTING, AND USE; comprising Drawing, Measuring, Optical, Surveying, and Astronomical Instruments. By J. F. HEATHER, M.A., Author of "Practical Plane Geometry," "Descriptive Geometry," &c. Enlarged Edition, for the most part entirely rewritten. With numerous Wood-cuts. 12mo, cloth boards, price 5*s.*

Drawing for Engineers, &c.

THE WORKMAN'S MANUAL OF ENGINEERING DRAWING. By JOHN MAXTON, Instructor in Engineering Drawing, Royal Naval College, Greenwich, formerly of R. S. N. A., South Kensington. Third Edition, carefully revised. With upwards of 300 Plates and Diagrams. 12mo, cloth, strongly bound, 4*s.* 6*d.*

"Even accomplished draughtsmen will find in it much that will be of use to them. A copy of it should be kept for reference in every drawing office."—*Engineering.*

"Indispensable for teachers of engineering drawing."—*Mechanics' Magazine.*

Oblique Arches.

A PRACTICAL TREATISE ON THE CONSTRUCTION of OBLIQUE ARCHES. By JOHN HART. Third Edition, with Plates. Imperial 8vo, price 8*s.* cloth.

Oblique Bridges.

A PRACTICAL and THEORETICAL ESSAY on OBLIQUE BRIDGES, with 13 large folding Plates. By GEO. WATSON BUCK, M. Inst. C.E. Second Edition, corrected by W. H. BARLOW, M. Inst. C.E. Imperial 8vo, 12*s.* cloth.

"The standard text-book for all engineers regarding skew arches, is Mr. Buck's treatise, and it would be impossible to consult a better."—*Engineer.*

Pocket-Book for Marine Engineers.

A POCKET BOOK FOR MARINE ENGINEERS. Containing useful Rules and Formulæ in a compact form. By FRANK PROCTOR, A.I.N.A. Second Edition, revised and enlarged. Royal 32mo, leather, gilt edges, with strap, price 4*s.*

"We recommend it to our readers as going far to supply a long-felt want."—*Naval Science.*

"A most useful companion to all marine engineers."—*United Service Gazette.*

"Scarcely anything required by a naval engineer appears to have been forgotten."—*Iron.*

Grantham's Iron Ship-Building, enlarged.

ON IRON SHIP-BUILDING; with Practical Examples and Details. Fifth Edition. Imp. 4to, boards, enlarged from 24 to 40 Plates (21 quite new), including the latest Examples. Together with separate Text, 12mo, cloth limp, also considerably enlarged. By JOHN GRANTHAM, M. Inst. C.E., &c. Price 2*l.* 2*s.* complete.

"A thoroughly practical work, and every question of the many in relation to iron shipping which admit of diversity of opinion, or have various and conflicting personal interests attached to them, is treated with sober and impartial wisdom and good sense. . . . . As good a volume for the instruction of the pupil or student of iron naval architecture as can be found in any language."—*Practical Mechanics' Journal.*

"A very elaborate work. . . . It forms a most valuable addition to the history of iron shipbuilding, while its having been prepared by one who has made the subject his study for many years, and whose qualifications have been repeatedly recognised, will recommend it as one of practical utility to all interested in shipbuilding."—*Army and Navy Gazette.*

"Mr. Grantham's work is of great interest. . . . It is also valuable as a record of the progress of iron shipbuilding. . . . It will, we are confident, command an extensive circulation among shipbuilders in general. . . . By order of the Board of Admiralty, the work will form the text-book on which the examination in iron shipbuilding of candidates for promotion in the dockyards will be mainly based."—*Engineering.*

Weale's Dictionary of Terms.

A DICTIONARY of TERMS used in ARCHITECTURE, BUILDING, ENGINEERING, MINING, METALLURGY, ARCHÆOLOGY, the FINE ARTS, &c. By JOHN WEALE. Fifth Edition, revised and corrected by ROBERT HUNT, F.R.S., Keeper of Mining Records, Editor of "Ure's Dictionary of Arts," &c. 12mo, cloth boards, price 6*s.*

"A book for the enlightenment of those whose memory is treacherous or education deficient in matters scientific and industrial. The additions made of modern discoveries and knowledge are extensive. The result is 570 pages of concentrated essence of elementary knowledge, admirably and systematically arranged, and presented in neat and handy form."—*Iron.*

"The best small technological dictionary in the language."—*Architect.*

"A comprehensive and accurate compendium. Author, editor, and publishers deserve high commendations for producing such a useful work. We can warmly recommend such a dictionary as a standard work of reference to our subscribers. Every ironmonger should procure it—no engineer should be without it—builders and architects must admire it—metallurgists and archæologists would profit by it."—*Ironmonger.*

"The absolute accuracy of a work of this character can only be judged of after extensive consultation, and from our examination it appears very correct and very complete."—*Mining Journal.*

"There is no need now to speak of the excellence of this work; it received the approval of the community long ago. Edited now by Mr. Robert Hunt, and published in a cheap, handy form, it will be of the utmost service as a book of reference scarcely to be exceeded in value."—*Scotsman.*

Steam.

THE SAFE USE OF STEAM: containing Rules for Unprofessional Steam Users. By an ENGINEER. Third Edition. 12mo. Sewed, 6*d.*

N. B.—*This little work should be in the hands of every person having to deal with a Steam Engine of any kind.*

"*If steam-users* would but learn this little book by heart, and then hand it to *their stokers to do the* same, and see that the latter do it, boiler explosions would *become sensations by* their rarity."—*English Mechanic.*

ARCHITECTURE, &c.

Construction.

THE SCIENCE of BUILDING: An Elementary Treatise on the Principles of Construction. By E. WYNDHAM TARN, M.A., Architect. With 47 Wood Engravings. Demy 8vo. 8*s.* 6*d.* cloth.

"A very valuable book, which we strongly recommend to all students."—*Builder.*

"No architectural student should be without this hand-book."—*Architect.*

"An able digest of information which is only to be found scattered through various works."—*Engineering.*

Beaton's Pocket Estimator.

THE POCKET ESTIMATOR FOR THE BUILDING TRADES, being an easy method of estimating the various parts of a Building collectively, more especially applied to Carpenters' and Joiners' work, priced according to the present value of material and labour. By A. C. BEATON, Author of 'Quantities and Measurements.' 33 Woodcuts. Leather. Waistcoat-pocket size. 2*s.*

Beaton's Builders' and Surveyors' Technical Guide.

THE POCKET TECHNICAL GUIDE AND MEASURER FOR BUILDERS AND SURVEYORS: containing a Complete Explanation of the Terms used in Building Construction, Memoranda for Reference, Technical Directions for Measuring Work in all the Building Trades, &c., &c. By A. C. BEATON, Author of 'Quantities and Measurements.' With 19 Woodcuts. Leather. Waistcoat-pocket size. 2*s.*

Villa Architecture.

A HANDY BOOK of VILLA ARCHITECTURE; being a Series of Designs for Villa Residences in various Styles. With Detailed Specifications and Estimates. By C. WICKES, Architect, Author of "The Spires and Towers of the Mediæval Churches of England," &c. First Series, consisting of 30 Plates; Second Series, 31 Plates. Complete in 1 vol. 4to, price 2*l.* 10*s.* half morocco. Either Series separate, price 1*l.* 7*s.* each, half morocco.

"The whole of the designs bear evidence of their being the work of an artistic architect, and they will prove very valuable and suggestive to architects, students, and amateurs."—*Building News.*

House Painting.

HOUSE PAINTING, GRAINING, MARBLING, AND SIGN WRITING: a Practical Manual of. With 9 Coloured Plates of Woods and Marbles, and nearly 150 Wood Engravings. By ELLIS A. DAVIDSON, Author of 'Building Construction,' &c. Second Edition, carefully revised. 12mo, 6*s.* cloth boards.

"Many persons in the trade may profit by a study of the chapters on the 'Principles of Decorative Art,' and of what we may call the 'lessons' on drawing suitable for sign painters, writers, and decorators. These chapters will be of considerable value to the painter's apprentices, while his journeymen will certainly be interested if not benefited by their perusal. The book is freely illustrated, and has some coloured plates of woods and marbles. It contains a mass of information of use to the amateur and of value to the practical man."—*English Mechanic.*

"Deals with the practice of painting in all its parts, from the grinding of colours to varnishing and gilding."—*Architect.*

"Carefully and lucidly written, and entirely reliable."—*Builders' Weekly Reporter.*

A Book on Building.

A BOOK ON BUILDING, CIVIL AND ECCLESIASTICAL. By Sir EDMUND BECKETT, Bart., LL.D., Q.C., F.R.A.S., Author of "Clocks and Watches and Bells," &c. Crown 8vo, cloth, with Illustrations, price 7*s.* 6*d.*

"A book which is always amusing and nearly always instructive. Sir E. Beckett will be read for the raciness of his style. We are able very cordially to recommend all persons to read it for themselves. The style throughout is in the highest degree condensed and epigrammatic."—*Times*, Dec. 8, 1876.

"We commend the book to the thoughtful consideration of all who are interested in the building art."—*Builder*, Dec. 2, 1876.

"There is hardly a subject connected with either building or repairing on which sensible and practical directions will not be found, the use of which is probably destined to prevent many an annoyance, disappointment, and unnecessary expense."—*Daily News*, Nov. 28, 1876.

Architecture, Ancient and Modern.

RUDIMENTARY ARCHITECTURE, Ancient and Modern. Consisting of VITRUVIUS, translated by JOSEPH GWILT, F.S.A., &c., with 23 fine copper plates; GRECIAN Architecture, by the EARL of ABERDEEN; the ORDERS of Architecture, by W. H. LEEDS, Esq.; the STYLES of Architecture of Various Countries, by T. TALBOT BURY; The PRINCIPLES of DESIGN in Architecture, by E. L. GARBETT. In one volume, half-bound (pp. 1,100), copiously illustrated, 12*s.*

*** *Sold separately, in two vols., as follows*—

ANCIENT ARCHITECTURE. Containing Gwilt's Vitruvius and Aberdeen's Grecian Architecture. Price 6*s.* half-bound.

N.B.—*This is the only edition of VITRUVIUS procurable at a moderate price.*

MODERN ARCHITECTURE. Containing the Orders, by Leeds; The Styles, by Bury; and Design, by Garbett. 6*s.* half-bound.

The Young Architect's Book.

HINTS TO YOUNG ARCHITECTS. By GEORGE WIGHTWICK, Architect, Author of "The Palace of Architecture," &c. &c. New Edition, revised and enlarged. By G. HUSKISSON GUILLAUME, Architect. Numerous illustrations. 12mo, cloth boards, 4*s.*

"Will be found an acquisition to pupils, and a copy ought to be considered as necessary a purchase as a box of instruments."—*Architect.*

"Contains a large amount of information, which young architects will do well to acquire, if they wish to succeed in the everyday work of their profession.—*English Mechanic.*

Drawing for Builders and Students.

PRACTICAL RULES ON DRAWING for the OPERATIVE BUILDER and YOUNG STUDENT in ARCHITECTURE. By GEORGE PYNE, Author of a "Rudimentary Treatise on Perspective for Beginners." With 14 Plates, 4to, 7*s.* 6*d.* boards.

Builder's and Contractor's Price Book.

LOCKWOOD & CO.'S BUILDER'S AND CONTRACTOR'S PRICE BOOK for 1877, containing the latest prices of all kinds of Builders' Materials and Labour, and of all Trades connected *with Building*, &c., &c. The whole revised and edited by FRANCIS T. W. MILLER, Architect and Surveyor. Fcap. 8vo, *strongly half-bound*, price 4*s.*

Handbook of Specifications.

THE HANDBOOK OF SPECIFICATIONS; or, Practical Guide to the Architect, Engineer, Surveyor, and Builder, in drawing up Specifications and Contracts for Works and Constructions. Illustrated by Precedents of Buildings actually executed by eminent Architects and Engineers. Preceded by a Preliminary Essay, and Skeletons of Specifications and Contracts, &c., &c. By Professor THOMAS L. DONALDSON, M.I.B.A. With A REVIEW OF THE LAW OF CONTRACTS. By W. CUNNINGHAM GLEN, of the Middle Temple. With 33 Lithographic Plates, 2 vols., 8vo, *2l. 2s.*

"In these two volumes of 1,100 pages (together), forty-four specifications of executed works are given, including the specifications for parts of the new Houses of Parliament, by Sir Charles Barry, and for the new Royal Exchange, by Mr. Tite, M.P. Donaldson's Handbook of Specifications must be bought by all architects."—*Builder.*

Taylor and Cresy's Rome.

THE ARCHITECTURAL ANTIQUITIES OF ROME. By the late G. L. TAYLOR, Esq., F.S.A., and EDWARD CRESY, Esq. New Edition, thoroughly revised, and supplemented under the editorial care of the Rev. ALEXANDER TAYLOR, M.A. (son of the late G. L. Taylor, Esq.), Chaplain of Gray's Inn. This is the only book which gives on a large scale, and with the precision of architectural measurement, the principal Monuments of Ancient Rome in plan, elevation, and detail. Large folio, with 130 Plates, half-bound, price *3l. 3s.*

*** Originally published in two volumes, folio, at *18l. 18s.*

Specifications for Practical Architecture.

SPECIFICATIONS FOR PRACTICAL ARCHITECTURE: A Guide to the Architect, Engineer, Surveyor, and Builder; with an Essay on the Structure and Science of Modern Buildings. By FREDERICK ROGERS, Architect. With numerous Illustrations. Demy 8vo, price *15s.*, cloth. (Published at *1l. 10s.*)

*** A volume of specifications of a practical character being greatly required, and the old standard work of Alfred Bartholomew being out of print, the author, on the basis of that work, has produced the above. He has also inserted specifications of works that have been erected in his own practice.

The House-Owner's Estimator.

THE HOUSE-OWNER'S ESTIMATOR; or, What will it Cost to Build, Alter, or Repair? A Price-Book adapted to the Use of Unprofessional People as well as for the Architectural Surveyor and Builder. By the late JAMES D. SIMON, A.R.I.B.A. Edited and Revised by FRANCIS T. W. MILLER, Surveyor. With numerous Illustrations. Second Edition, with the prices carefully revised to 1875. Crown 8vo, cloth, price *3s. 6d.*

"In two years it will repay its cost a hundred times over."—*Field.*

"A very handy book for those who want to know what a house will cost to build, alter, or repair."—*English Mechanic.*

"Especially valuable to non-professional readers.—*Mining Journal.*

Useful Text-Book for Architects.

THE ARCHITECT'S GUIDE: Being a Text-book of Useful Information for Architects, Engineers, Surveyors, Contractors, Clerks of Works, &c., &c. By FREDERICK ROGERS, Architect, Author of 'Specifications for Practical Architecture,' &c. With numerous Illustrations. Crown 8vo, 6s. cloth. [Just Published

CARPENTRY, TIMBER, MECHANICS.

Tredgold's Carpentry, new and cheaper Edition.

THE ELEMENTARY PRINCIPLES OF CARPENTRY: a Treatise on the Pressure and Equilibrium of Timber Framing, the Resistance of Timber, and the Construction of Floors, Arches, Bridges, Roofs, Uniting Iron and Stone with Timber, &c. To which is added an Essay on the Nature and Properties of Timber, &c., with Descriptions of the Kinds of Wood used in Building; also numerous Tables of the Scantlings of Timber for different purposes, the Specific Gravities of Materials, &c. By THOMAS TREDGOLD, C.E. Edited by PETER BARLOW, F.R.S. Fifth Edition, corrected and enlarged. With 64 Plates (11 of which now first appear in this edition), Portrait of the Author, and several Woodcuts. In 1 vol., 4to, published at *2l. 2s.*, reduced to *1l. 5s.*, cloth.

"'Tredgold's Carpentry' ought to be in every architect's and every builder's library, and those who do not already possess it ought to avail themselves of the new issue."—*Builder.*

"A work whose monumental excellence must commend it wherever skilful carpentry is concerned. The Author's principles are rather confirmed than impaired by time, and, as now presented, combine the surest base with the most interesting display of progressive science. The additional plates are of great intrinsic value."—*Building News.*

Grandy's Timber Tables.

THE TIMBER IMPORTER'S, TIMBER MERCHANT'S, and BUILDER'S STANDARD GUIDE. By RICHARD E. GRANDY. Comprising:—An Analysis of Deal Standards, Home and Foreign, with comparative Values and Tabular Arrangements for Fixing Nett Landed Cost on Baltic and North American Deals, including all intermediate Expenses, Freight, Insurance, &c., &c.; together with Copious Information for the Retailer and Builder. Second Edition. Carefully revised and corrected. 12mo, price *3s. 6d.* cloth.

"Everything it pretends to be: built up gradually, it leads one from a forest to a treenail, and throws in, as a makeweight, a host of material concerning bricks, columns, cisterns, &c.—all that the class to whom it appeals requires."—*English Mechanic.*

"The only difficulty we have is as to what is NOT in its pages. What we have tested of the contents, taken at random, is invariably correct."—*Illustrated Builder's Journal.*

Tables for Packing-Case Makers.

PACKING-CASE TABLES; showing the number of Superficial Feet in Boxes or Packing-Cases, from six inches square and upwards. Compiled by WILLIAM RICHARDSON, Accountant. Oblong 4to, cloth, price *3s. 6d.*

"Will save much labour and calculation to packing-case makers and those who use packing-cases."—*Grocer.* "Invaluable labour-saving tables."—*Ironmonger.*

Nicholson's Carpenter's Guide.

THE CARPENTER'S NEW GUIDE; or, BOOK of LINES *for* CARPENTERS: comprising all the Elementary Principles *essential* for acquiring a knowledge of Carpentry. Founded on the *late* PETER NICHOLSON'S standard work. A new Edition, revised *by* ARTHUR ASHPITEL, F.S.A., together with Practical Rules on *Drawing, by* GEORGE PYNE. With 74 Plates, 4to, *1l. 1s.* cloth.

Dowsing's Timber Merchant's Companion.

THE TIMBER MERCHANT'S AND BUILDER'S COMPANION; containing New and Copious Tables of the Reduced Weight and Measurement of Deals and Battens, of all sizes, from One to a Thousand Pieces, and the relative Price that each size bears per Lineal Foot to any given Price per Petersburgh Standard Hundred; the Price per Cube Foot of Square Timber to any given Price per Load of 50 Feet; the proportionate Value of Deals and Battens by the Standard, to Square Timber by the Load of 50 Feet; the readiest mode of ascertaining the Price of Scantling per Lineal Foot of any size, to any given Figure per Cube Foot. Also a variety of other valuable information. By WILLIAM DOWSING, Timber Merchant. Third Edition, Revised and Corrected. Crown 8vo, 3*s.* cloth.

"Everything is as concise and clear as it can possibly be made. There can be no doubt that every timber merchant and builder ought to possess it."—*Hull Advertiser.*

Timber Freight Book.

THE TIMBER IMPORTERS' AND SHIPOWNERS' FREIGHT BOOK: Being a Comprehensive Series of Tables for the Use of Timber Importers, Captains of Ships, Shipbrokers, Builders, and all Dealers in Wood whatsoever. By WILLIAM RICHARDSON, Timber Broker. Crown 8vo, cloth, price 6*s.*

Horton's Measurer.

THE COMPLETE MEASURER; setting forth the Measurement of Boards, Glass, &c., &c.; Unequal-sided, Square-sided, Octagonal-sided, Round Timber and Stone, and Standing Timber. With just allowances for the bark in the respective species of trees, and proper deductions for the waste in hewing the trees, &c.; also a Table showing the solidity of hewn or eight-sided timber, or of any octagonal-sided column. Compiled for the accommodation of Timber-growers, Merchants, and Surveyors, Stonemasons, Architects, and others. By RICHARD HORTON. Third edition, with considerable and valuable additions, 12mo, strongly bound in leather, 5*s.*

"Not only are the best methods of measurement shown, and in some instances illustrated by means of woodcuts, but the erroneous systems pursued by dishonest dealers are fully exposed. . . . . The work must be considered to be a valuable addition to every gardener's library.—*Garden.*

Superficial Measurement.

THE TRADESMAN'S GUIDE TO SUPERFICIAL MEASUREMENT. Tables calculated from 1 to 200 inches in length, by 1 to 108 inches in breadth. For the use of Architects, Surveyors, Engineers, Timber Merchants, Builders, &c. By JAMES HAWKINGS. Fcp. 3*s.* 6*d.* cloth.

Practical Timber Merchant.

THE PRACTICAL TIMBER MERCHANT, being a Guide for the use of Building Contractors, Surveyors, Builders, &c., comprising useful Tables for all purposes connected with the Timber Trade, Marks of Wood, Essay on the Strength of Timber, Remarks on the Growth of Timber, &c. By W. RICHARDSON. [Just publi
Fcap. 8vo, 3*s.* 6*d.*, cloth.

The Mechanic's Workshop Companion.

THE OPERATIVE MECHANIC'S WORKSHOP COMPANION, and THE SCIENTIFIC GENTLEMAN'S PRACTICAL ASSISTANT. By WILLIAM TEMPLETON. Twelfth Edition, with Mechanical Tables for Operative Smiths, Millwrights, Engineers, &c.; and an Extensive Table of Powers and Roots, &c., &c. 11 Plates. 12mo, 5*s.* bound.

"As a text-book of reference, in which mechanical and commercial demands are judiciously met, TEMPLETON'S COMPANION stands unrivalled."—*Mechanics' Magazine.*

"Admirably adapted to the wants of a very large class. It has met with great success in the engineering workshop, as we can testify; and there are a great many men who, in a great measure, owe their rise in life to this little work."—*Building News.*

Engineer's Assistant.

THE ENGINEER'S, MILLWRIGHT'S, and MACHINIST'S PRACTICAL ASSISTANT; comprising a Collection of Useful Tables, Rules, and Data. Compiled and Arranged, with Original Matter, by WILLIAM TEMPLETON. 5th Edition. 18mo, 2*s.* 6*d.* cloth.

"So much varied information compressed into so small a space, and published at a price which places it within the reach of the humblest mechanic, cannot fail to command the sale which it deserves. With the utmost confidence we commend this book to the attention of our readers.—*Mechanics' Magazine.*

"A more suitable present to an apprentice to any of the mechanical trades could not possibly be made.'—*Building News.*

Designing, Measuring, and Valuing.

THE STUDENT'S GUIDE to the PRACTICE of MEASURING, and VALUING ARTIFICERS' WORKS; containing Directions for taking Dimensions, Abstracting the same, and bringing the Quantities into Bill, with Tables of Constants, and copious Memoranda for the Valuation of Labour and Materials in the respective Trades of Bricklayer and Slater, Carpenter and Joiner, Painter and Glazier, Paperhanger, &c. With 43 Plates and Woodcuts. Originally edited by EDWARD DOBSON, Architect. New Edition, re-written, with Additions on Mensuration and Construction, and useful Tables for facilitating Calculations and Measurements. By E. WYNDHAM TARN, M.A., 8vo, 10*s.* 6*d.* cloth.

"We have failed to discover anything connected with the building trade, from excavating foundations to bell-hanging, that is not fully treated upon."—*The Artisan.*

"Altogether the book is one which well fulfils the promise of its title-page, and we can thoroughly recommend it to the class for whose use it has been compiled. Mr. Tarn's additions and revisions have much increased the usefulness of the work, and have especially augmented its value to students."—*Engineering.*

Plumbing.

PLUMBING; a text-book to the practice of the art or craft of the plumber. With supplementary chapters upon house-drainage, embodying the latest improvements. By WILLIAM PATON BUCHAN, Sanitary Engineer. 12mo. cloth, with about 300 illustrations. *Price 3s. 6d.* Just published.

"*There is no* other manual in existence of the plumber's art; and the volume will *be welcomed as the* work of a practical master of his trade."—Public Health.

"*The chapters* on house-drainage may be usefully consulted, not only by plumbers, *but also by engineers* and all engaged or interested in house-building."—*Iron.*

"*A book containing* a large amount of practical information, put together in a ver *ntelligent manner,* by one who is well qualified for the task."—City Press.

MATHEMATICS, &c.

Gregory's Practical Mathematics.

MATHEMATICS for PRACTICAL MEN; being a Commonplace Book of Pure and Mixed Mathematics. Designed chiefly for the Use of Civil Engineers, Architects, and Surveyors. Part I. PURE MATHEMATICS—comprising Arithmetic, Algebra, Geometry, Mensuration, Trigonometry, Conic Sections, Properties of Curves. Part II. MIXED MATHEMATICS—comprising Mechanics in general, Statics, Dynamics, Hydrostatics, Hydrodynamics, Pneumatics, Mechanical Agents, Strength of Materials. With an Appendix of copious Logarithmic and other Tables. By OLINTHUS GREGORY, LL.D., F.R.A.S. Enlarged by HENRY LAW, C.E. 4th Edition, carefully revised and corrected by J. R. YOUNG, formerly Professor of Mathematics, Belfast College; Author of "A Course of Mathematics," &c. With 13 Plates. Medium 8vo, 1*l.* 1*s.* cloth.

"As a standard work on mathematics it has not been excelled."—*Artisan.*

"The engineer or architect will here find ready to his hand, rules for solving nearly every mathematical difficulty that may arise in his practice. The rules are in all cases explained by means of examples, in which every step of the process is clearly worked out."—*Builder.*

"One of the most serviceable books to the practical mechanics of the country. . . . . In the edition just brought out, the work has again been revised by Professor Young. He has modernised the notation throughout, introduced a few paragraphs here and there, and corrected the numerous typographical errors which have escaped the eyes of the former Editor. The book is now as complete as it is possible to make it. It is an instructive book for the student, and a Text-book for him who having once mastered the subjects it treats of, needs occasionally to refresh his memory upon them."—*Building News.*

The Metric System.

A SERIES OF METRIC TABLES, in which the British Standard Measures and Weights are compared with those of the Metric System at present in use on the Continent. By C. H. DOWLING, C. E. Second Edition, revised and enlarged. 8vo, 10*s.* 6*d.* strongly bound.

"Mr. Dowling's Tables, which are well put together, come just in time as a ready reckoner for the conversion of one system into the other."—*Athenæum.*

"Their accuracy has been certified by Prof. Airy, Astronomer-Royal."—*Builder.*

"Resolution 8.—That advantage will be derived from the recent publication of Metric Tables, by C. H. Dowling, C.E."—*Report of Section F, Brit. Assoc., Bath.*

Comprehensive Weight Calculator.

THE WEIGHT CALCULATOR; being a Series of Tables upon a New and Comprehensive Plan, exhibiting at one Reference the exact Value of any Weight from 1lb. to 15 tons, at 300 Progressive Rates, from 1 Penny to 168 Shillings per cwt., and containing 186,000 Direct Answers, which with their Combinations, consisting of a single addition (mostly to be performed at sight), will afford an aggregate of 10,266,000 Answers; the whole being *calculated* and designed to ensure Correctness and promote *Despatch.* By HENRY HARBEN, Accountant, Sheffield, Author of '*The* Discount Guide.' An entirely New Edition, carefully *revised.* Royal 8vo, strongly half-bound, 30*s.* [*Just Published.*

Comprehensive Discount Guide.

THE DISCOUNT GUIDE: comprising several Series of Tables for the use of Merchants, Manufacturers, Ironmongers, and others, by which may be ascertained the exact profit arising from any mode of using Discounts, either in the Purchase or Sale of Goods, and the method of either Altering a Rate of Discount, or Advancing a Price, so as to produce, by one operation, a sum that will realise any required profit after allowing one or more Discounts: to which are added Tables of Profit or Advance from 1½ to 90 per cent., Tables of Discount from 1¼ to 98¾ per cent., and Tables of Commission, &c., from ⅛ to 10 per cent. By HENRY HARBEN, Accountant, Author of "The Weight Calculator." New Edition, carefully Revised and Corrected. In a handsome demy 8vo. volume (544 pp.), strongly and elegantly half-bound, price £1 5*s*. [*Just published.*

Inwood's Tables, greatly enlarged and improved.

TABLES FOR THE PURCHASING of ESTATES, Freehold, Copyhold, or Leasehold; Annuities, Advowsons, &c., and for the Renewing of Leases held under Cathedral Churches, Colleges, or other corporate bodies; for Terms of Years certain, and for Lives; also for Valuing Reversionary Estates, Deferred Annuities, Next Presentations, &c., together with Smart's Five Tables of Compound Interest, and an Extension of the same to Lower and Intermediate Rates. By WILLIAM INWOOD, Architect. The 20th edition, with considerable additions, and new and valuable Tables of Logarithms for the more Difficult Computations of the Interest of Money, Discount, Annuities, &c., by M. FÉDOR THOMAN, of the Société Crédit Mobilier of Paris. 12mo, 8*s*. cloth.

"Those interested in the purchase and sale of estates, and in the adjustment of compensation cases, as well as in transactions in annuities, life insurances, &c., will find the present edition of eminent service."—*Engineering.*

"'Inwood's Tables' still maintain a most enviable reputation. The new issue has been enriched by large additional contributions by M. Fédor Thoman, whose carefully arranged Tables of Logarithms for the more Difficult Computations of the Interest of Money, Discount, Annuities, &c., cannot fail to be of the utmost utility."—*Mining Journal.*

Geometry for the Architect, Engineer, &c.

PRACTICAL GEOMETRY, for the Architect, Engineer, and Mechanic; giving Rules for the Delineation and Application of various Geometrical Lines, Figures and Curves. By E. W. TARN, M.A., Architect, Author of "The Science of Building," &c. With 164 Illustrations. Demy 8vo. 12*s*. 6*d*.

"No book with the same objects in view has ever been published in which the clearness of the rules laid down and the illustrative diagrams have been so satisfactory."—*Scotsman.*

Compound Interest and Annuities.

THEORY of COMPOUND INTEREST and ANNUITIES; with Tables of Logarithms for the more Difficult Computations of Interest, Discount, Annuities, &c., in all their Applications and Uses for Mercantile and State Purposes. With an elaborate Introduction. By FÉDOR THOMAN, of the Société Crédit Mobilier, *Paris.* 12mo, cloth, 5*s*.

"*A very powerful* work, and the Author has a very remarkable command of his subject."—*Professor A. de Morgan.*

"*We recommend it* to the notice of actuaries and accountants."—*Athenæum.*

SCIENCE AND ART.

The Military Sciences.

AIDE-MÉMOIRE to the MILITARY SCIENCES. Framed from Contributions of Officers and others connected with the different Services. Originally edited by a Committee of the Corps of Royal Engineers. Second Edition, most carefully revised by an Officer of the Corps, with many additions; containing nearly 350 Engravings and many hundred Woodcuts. 3 vols. royal 8vo, extra cloth boards, and lettered, price 4*l.* 10*s.*

"A compendious encyclopædia of military knowledge."—*Edinburgh Review.*
"The most comprehensive work of reference to the military and collateral sciences."—*Volunteer Service Gazette.*

Field Fortification.

A TREATISE on FIELD FORTIFICATION, the ATTACK of FORTRESSES, MILITARY MINING, and RECONNOITRING. By Colonel I. S. MACAULAY, late Professor of Fortification in the R. M. A., Woolwich. Sixth Edition, crown 8vo, cloth, with separate Atlas of 12 Plates, price 12*s.* complete.

Field Fortification.

HANDBOOK OF FIELD FORTIFICATION, intended for the Guidance of Officers preparing for Promotion, and especially adapted to the requirements of Beginners. By Major W. W. KNOLLYS, F.R.G.S., 93rd Sutherland Highlanders, &c. With 163 Woodcuts. Crown 8vo, 3*s.* 6*d.* cloth.

Storms.

STORMS: their Nature, Classification, and Laws, with the Means of Predicting them by their Embodiments, the Clouds. By WILLIAM BLASIUS. With Coloured Plates and numerous Wood Engravings. Crown 8vo, 10*s.* 6*d.* cloth boards.

Light-Houses.

EUROPEAN LIGHT-HOUSE SYSTEMS; being a Report of a Tour of Inspection made in 1873. By Major GEORGE H. ELLIOT, Corps of Engineers, U.S.A. Illustrated by 51 Engravings and 31 Woodcuts in the Text. 8vo, 21*s.* cloth.

Dye-Wares and Colours.

THE MANUAL of COLOURS and DYE-WARES: their Properties, Applications, Valuation, Impurities, and Sophistications. For the Use of Dyers, Printers, Dry Salters, Brokers, &c. By J. W. SLATER. Post 8vo, cloth, price 7*s.* 6*d.*

"A complete encyclopædia of the *materia tinctoria*. The information given respecting each article is full and precise, and the methods of determining the value of articles such as these, so liable to sophistication, are given with clearness, and are practical as well as valuable."—*Chemist and Druggist.*

Electricity.

A MANUAL of ELECTRICITY; including Galvanism, Magnetism, Diamagnetism, Electro-Dynamics, Magno-Electricity, and the Electric Telegraph. By HENRY M. NOAD, Ph.D., F.C.S., Lecturer on Chemistry at St. George's Hospital. Fourth Edition, entirely rewritten. Illustrated by 500 Woodcuts. 8vo, *1l. 4s.* cloth.

"The commendations already bestowed in the pages of the *Lancet* on the former editions of this work are more than ever merited by the present. The accounts given of electricity and galvanism are not only complete in a scientific sense, but, which is a rarer thing, are popular and interesting."—*Lancet.*

Text-Book of Electricity.

THE STUDENT'S TEXT-BOOK OF ELECTRICITY. By HENRY M. NOAD, Ph.D., Lecturer on Chemistry at St. George's Hospital. New Edition, revised and enlarged, with additions on Telegraphy, by G. E. PREECE, Esq. Upwards of 400 Illustrations.

[*In Preparation.*

Rudimentary Magnetism.

RUDIMENTARY MAGNETISM: being a concise exposition of the general principles of Magnetical Science, and the purposes to which it has been applied. By Sir W. SNOW HARRIS, F.R.S. New and enlarged Edition, with considerable additions by Dr. NOAD, Ph.D. With 165 Woodcuts. 12mo, cloth, *4s. 6d.*

"As concise and lucid an exposition of the phenomena of magnetism as we believe it is possible to write."—*English Mechanic.*

"Not only will the scientific student find this volume an invaluable book of reference, but the general reader will find in it as much to interest as to inform his mind. Though a strictly scientific work, its subject is handled in a simple and readable style."—*Illustrated Review.*

"There is a good index, and this volume of 412 pages may be considered the best possible manual on the subject of magnetism."—*Mechanics' Magazine.*

Chemical Analysis.

THE COMMERCIAL HANDBOOK of CHEMICAL ANALYSIS; or Practical Instructions for the determination of the Intrinsic or Commercial Value of Substances used in Manufactures, in Trades, and in the Arts. By A. NORMANDY, Author of "Practical Introduction to Rose's Chemistry," and Editor of Rose's "Treatise on Chemical Analysis." *New Edition.* Enlarged, and to a great extent re-written, by HENRY M. NOAD, Ph. D., F.R.S. With numerous Illustrations. Cr. 8vo, *12s. 6d.* cloth.

"We recommend this book to the careful perusal of every one; it may be truly affirmed to be of universal interest, and we strongly recommend it to our readers as a guide, alike indispensable to the housewife as to the pharmaceutical practitioner."—*Medical Times.*

"Will be found to be essential to the analysts appointed under the new Act. . . . In all cases the most recent results are given, and the work is well edited and carefully written."—*Nature.*

Mollusca.

A MANUAL OF THE MOLLUSCA; being a Treatise on Recent and Fossil Shells. By Dr. S. P. WOODWARD, A.L.S. *With Appendix* by RALPH TATE, A.L.S. F.G.S. With numerous *Plates* and 300 Woodcuts. Third Edition. Crown 8vo, *7s. 6d. cloth gilt.*

Clocks, Watches, and Bells.

RUDIMENTARY TREATISE on CLOCKS, and WATCHES, and BELLS. By Sir EDMUND BECKETT, Bart. (late E. B. Denison), LL.D., Q.C., F.R.A.S., Author of "Astronomy without Mathematics," &c. Sixth edition, thoroughly revised and enlarged, with numerous Illustrations. Limp cloth (No. 67, Weale's Series), 4*s.* 6*d.*; cloth boards, 5*s.* 6*d.*

"As a popular and practical treatise it is unapproached."—*English Mechanic.*

"The best work on the subject probably extant So far as we know it has no competitor worthy of the name. The treatise on bells is undoubtedly the best in the language. It shows that the author has contributed very much to their modern improvement, if indeed he has not revived this art, which was decaying here. To call it a rudimentary treatise is a misnomer, at least as respects clocks and bells. It is something more. It is the most important work of its kind in English."—*Engineering.*

"The only modern treatise on clock-making."—*Horological Journal.*

"We do not know whether to wonder most at the extraordinary cheapness of this admirable treatise on clocks, by the most able authority on such a subject, or the thorough completeness of his work. The chapter on bells is singular and amusing, and will be a real treat even to the uninitiated general reader. The illustrations, notes, and indices, make the work completely perfect of its kind."—*Standard.*

"There is probably no book in the English language on a technical subject so easy to read, and to read through, as the treatise on clocks, watches, and bells, written by the eminent Parliamentary Counsel, Mr. E. B. Denison—now Sir Edmund Beckett, Bart."—*Architect.*

Gold and Gold-Working.

THE PRACTICAL GOLD-WORKER; or, The Goldsmith's and Jeweller's Instructor. The Art of Alloying, Melting, Reducing, Colouring, Collecting and Refining. The processes of Manipulation, Recovery of Waste, Chemical and Physical Properties of Gold, with a new System of Mixing its Alloys; Solders, Enamels, and other useful Rules and Recipes, &c. By GEORGE E. GEE. Crown 8vo, cloth, 7*s.* 6*d.* [*Now Ready.*

"A good, sound, technical educator, and will be generally accepted as an authority. It gives full particulars for mixing alloys and enamels, is essentially a book for the workshop, and exactly fulfils the purpose intended."—*Horological Journal.*

"The best work yet printed on its subject for a reasonable price. We have no doubt that it will speedily become a standard book which few will care to be without."—*Jeweller and Metalworker.*

Science and Scripture.

SCIENCE ELUCIDATIVE OF SCRIPTURE, AND NOT ANTAGONISTIC TO IT; being a Series of Essays on—1. Alleged Discrepancies; 2. The Theory of the Geologists and Figure of the Earth; 3. The Mosaic Cosmogony; 4. Miracles in general—Views of Hume and Powell; 5. The Miracle of Joshua—Views of Dr. Colenso: The Supernaturally Impossible; 6. The Age of the Fixed Stars—their Distances and Masses. By Professor J. R. YOUNG, Author of "A Course of Elementary Mathematics," &c. &c. Fcap. 8vo, price 5*s.* cloth lettered.

"Distinguished by the true spirit of scientific inquiry, by great knowledge, by keen logical ability, and by a style peculiarly clear, easy, and energetic."—*Nonconformist.*

"No one can rise from its perusal without being impressed with a sense of the singular weakness of modern scepticism."—*Baptist Magazine.*

"A valuable contribution to controversial theological literature."—*City Press.*

Practical Philosophy.

A SYNOPSIS of PRACTICAL PHILOSOPHY. By the Rev. JOHN CARR, M.A., late Fellow of Trin. Coll., Cambridge. *Second Edition.* 18mo, 5*s.* cloth.

DR. LARDNER'S POPULAR WORKS.

Dr. Lardner's Museum of Science and Art.

THE MUSEUM OF SCIENCE AND ART. Edited by DIONYSIUS LARDNER, D.C.L., formerly Professor of Natural Philosophy and Astronomy in University College, London. With upwards of 1200 Engravings on Wood. In 6 Double Volumes. Price £1 1*s.*, in a new and elegant cloth binding, or handsomely bound in half morocco, 31*s.* 6*d.*

"The 'Museum of Science and Art' is the most valuable contribution that has ever been made to the Scientific Instruction of every class of society."—*Sir David Brewster in the North British Review.*

"Whether we consider the liberality and beauty of the illustrations, the charm of the writing, or the durable interest of the matter, we must express our belief that there is hardly to be found among the new books, one that would be welcomed by people of so many ages and classes as a valuable present."—*Examiner.*

*** *Separate books formed from the above, suitable for Workmen's Libraries, Science Classes, &c.*

COMMON THINGS EXPLAINED. Containing Air, Earth, Fire, Water, Time, Man, the Eye, Locomotion, Colour, Clocks and Watches, &c. 233 Illustrations, cloth gilt, 5*s.*

THE MICROSCOPE. Containing Optical Images, Magnifying Glasses, Origin and Description of the Microscope, Microscopic Objects, the Solar Microscope, Microscopic Drawing and Engraving, &c. 147 Illustrations, cloth gilt, 2*s.*

POPULAR GEOLOGY. Containing Earthquakes and Volcanoes, the Crust of the Earth, etc. 201 Illustrations, cloth gilt, 2*s.* 6*d.*

POPULAR PHYSICS. Containing Magnitude and Minuteness, the Atmosphere, Meteoric Stones, Popular Fallacies, Weather Prognostics, the Thermometer, the Barometer, Sound, &c. 85 Illustrations, cloth gilt, 2*s.* 6*d.*

STEAM AND ITS USES. Including the Steam Engine, the Locomotive, and Steam Navigation. 89 Illustrations, cloth gilt, 2*s.*

POPULAR ASTRONOMY. Containing How to Observe the Heavens. The Earth, Sun, Moon, Planets. Light, Comets, Eclipses, Astronomical Influences, &c. 182 Illustrations, 4*s.* 6*d.*

THE BEE AND WHITE ANTS: Their Manners and Habits. With Illustrations of Animal Instinct and Intelligence. 135 Illustrations, cloth gilt, 2*s.*

THE ELECTRIC TELEGRAPH POPULARISED. To render intelligible to all who can Read, irrespective of any previous Scientific Acquirements, the various forms of Telegraphy in Actual Operation. 100 Illustrations, cloth gilt, 1*s.* 6*d.*

Scientific Class-Books, by Dr. Lardner.

NATURAL PHILOSOPHY FOR SCHOOLS. By DR. LARDNER. *328 Illustrations.* Fifth Edition. 1 vol. 3*s.* 6*d.* cloth.

"*Conveys, in clear* and precise terms, general notions of all the principal divisions *of Physical Science.*"—*British Quarterly Review.*

ANIMAL PHYSIOLOGY FOR SCHOOLS. By DR. LARDNER. *With 190 Illustrations.* Second Edition. 1 vol. 3*s.* 6*d.* cloth.

"*Clearly written, well arranged,* and excellently illustrated."—*Gardeners' Chroni*

DR. LARDNER'S SCIENTIFIC WORKS.

Astronomy.

THE HANDBOOK OF ASTRONOMY. 4th Edition. Edited by EDWIN DUNKIN, F.R.S., Rl. Observatory, Greenwich. With 38 plates and upwards of 100 Woodcuts. Cr. 8vo, 9*s.* 6*d.* cloth.

"Probably no other book contains the same amount of information in so compendious and well-arranged a form."—*Athenæum.*

Animal Physics.

THE HANDBOOK OF ANIMAL PHYSICS. With 520 Illustrations. New edition, small 8vo, cloth, 7*s.* 6*d.* 732 pages.

"We have no hesitation in cordially recommending it."—*Educational Times.*

Electric Telegraph.

THE ELECTRIC TELEGRAPH. New Edition. By E. B. BRIGHT, F.R.A.S. 140 Illustrations. Small 8vo, 2*s.* 6*d.* cloth.

"One of the most readable books extant on the Electric Telegraph."—*Eng. Mechanic.*

LARDNER'S COURSE OF NATURAL PHILOSOPHY.

Mechanics.

THE HANDBOOK OF MECHANICS. Enlarged and almost rewritten by BENJAMIN LOEWY, F.R.A.S. With 378 Illustrations. Post 8vo, 6*s.* cloth.

"The perspicuity of the original has been retained, and chapters which had become obsolete, have been replaced by others of more modern character. The explanations throughout are studiously popular, and care has been taken to show the application of the various branches of physics to the industrial arts, and to the practical business of life."—*Mining Journal.*

Heat.

THE HANDBOOK OF HEAT. Edited and almost entirely Re-written by BENJAMIN LOEWY, F.R.A.S. etc. 117 Illustrations. Post 8vo, 6*s.* cloth. [*Just published.*

"The style is always clear and precise, and conveys instruction without leaving any cloudiness or lurking doubts behind."—*Engineering.*

Hydrostatics and Pneumatics.

THE HANDBOOK of HYDROSTATICS and PNEUMATICS. New Edition, Revised and Enlarged by BENJAMIN LOEWY, F.R.A.S. With 236 Illustrations. Post 8vo, 5*s.* cl. [*Just published.*

"For those 'who desire to attain an accurate knowledge of physical science without the profound methods of mathematical investigation,' this work is not merely intended, but well adapted."—*Chemical News.*

Electricity, Magnetism, and Acoustics.

THE HANDBOOK of ELECTRICITY, MAGNETISM, and ACOUSTICS. New Edition. Edited by GEO. CAREY FOSTER, B.A., F.C.S. With 400 Illustrations. Post 8vo, 5*s.* cloth.

"The book could not have been entrusted to any one better calculated to preserve the terse and lucid style of Lardner, while correcting his errors and bringing up his work to the present state of scientific knowledge."—*Popular Science Review.*

Optics.

THE HANDBOOK OF OPTICS. New Edition. Edited by T. OLVER HARDING, B.A. 298 Illustrations. Post 8vo, 5*s.* cloth.

"Written by one of the ablest English scientific writers, beautifully and elaborately illustrated."—*Mechanic's Magazine.*

*** *The above* 5 *Vols. form* A COMPLETE COURSE OF NATURAL PHILOSOPHY.

Geology and Genesis Harmonised.

THE TWIN RECORDS of CREATION; or, Geology and Genesis, their Perfect Harmony and Wonderful Concord. By GEORGE W. VICTOR LE VAUX. With numerous Illustrations. Fcap. 8vo, price 5*s.* cloth.

"We can recommend Mr. Le Vaux as an able and interesting guide to a popular appreciation of geological science."—*Spectator.*

"The author combines an unbounded admiration of science with an unbounded admiration of the Written Record."—*London Review.*

Geology, Physical.

PHYSICAL GEOLOGY. (Partly based on Major-General Portlock's Rudiments of Geology.) By RALPH TATE, A.L.S., F.G.S. Numerous Woodcuts. 12mo, 2*s.*

Geology, Historical.

HISTORICAL GEOLOGY. (Partly based on Major-General Portlock's Rudiments of Geology.) By RALPH TATE, A.L.S., F.G.S. Numerous Woodcuts. 12mo, 2*s.* 6*d.*

*** *Or* PHYSICAL *and* HISTORICAL GEOLOGY, *bound in One Volume, price* 5*s.*

Wood-Carving.

INSTRUCTIONS in WOOD-CARVING, for Amateurs; with Hints on Design. By A LADY. In emblematic wrapper, handsomely printed, with Ten large Plates, price 2*s.* 6*d.*

"The handicraft of the wood-carver, so well as a book can impart it, may be learnt from 'A Lady's' publication."—*Athenæum.*

"A real *practical guide.* It is very complete."—*Literary Churchman.*

"The directions given are plain and easily understood, and it forms a very good introduction to the practical part of the carver's art."—*English Mechanic.*

Popular Work on Painting.

PAINTING POPULARLY EXPLAINED; with Historical Sketches of the Progress of the Art. By THOMAS JOHN GULLICK, Painter, and JOHN TIMBS, F.S.A. Second Edition, revised and enlarged. With Frontispiece and Vignette. In small 8vo, 6*s.* cloth.

*** *This Work has been adopted as a Prize-book in the Schools of Art at South Kensington.*

"A work that may be advantageously consulted. Much may be learned, even by those who fancy they do not require to be taught, from the careful perusal of this unpretending but comprehensive treatise."—*Art Journal.*

"A valuable book, which supplies a want. It contains a large amount of original matter, agreeably conveyed, and will be found of value, as well by the young artist seeking information as by the general reader. We give a cordial welcome to the book, and augur for it an increasing reputation."—*Builder.*

Grammar of Colouring.

A GRAMMAR OF COLOURING, applied to Decorative Painting and the Arts. By GEORGE FIELD. New edition, enlarged and adapted to the use of the Ornamental Painter and Designer, by ELLIS A. DAVIDSON. With new Coloured Diagrams and numerous Engravings on Wood. 12mo, 3*s.* cloth boards.

"One of the most useful of student's books, and probably the best known of the few we have on the subject."—*Architect.*

"The book is a most useful *résumé* of the properties of pigments."—Builder.

"This treatise forms a most valuable *vade mecum* for the ornamental painter and designer."—*Scotsman.*

Delamotte's Works on Illumination & Alphabets.

A PRIMER OF THE ART OF ILLUMINATION; for the use of Beginners: with a Rudimentary Treatise on the Art, Practical Directions for its Exercise, and numerous Examples taken from Illuminated MSS., printed in Gold and Colours. By F. DELAMOTTE. Small 4to, price 9*s*. Elegantly bound, cloth antique.

"A handy book, beautifully illustrated; the text of which is well written, and calculated to be useful. . . . The examples of ancient MSS. recommended to the student, which, with much good sense, the author chooses from collections accessible to all, are selected with judgment and knowledge, as well as taste."—*Athenæum.*

ORNAMENTAL ALPHABETS, ANCIENT and MEDIÆVAL; from the Eighth Century, with Numerals; including Gothic, Church-Text, large and small, German, Italian, Arabesque, Initials for Illumination, Monograms, Crosses, &c. &c., for the use of Architectural and Engineering Draughtsmen, Missal Painters, Masons, Decorative Painters, Lithographers, Engravers, Carvers, &c. &c. &c. Collected and engraved by F. DELAMOTTE, and printed in Colours. Royal 8vo, oblong, price 4*s*. cloth.

"A well-known engraver and draughtsman has enrolled in this useful book the result of many years' study and research. For those who insert enamelled sentences round gilded chalices, who blazon shop legends over shop-doors, who letter church walls with pithy sentences from the Decalogue, this book will be useful."—*Athenæum.*

EXAMPLES OF MODERN ALPHABETS, PLAIN and ORNAMENTAL; including German, Old English, Saxon, Italic, Perspective, Greek, Hebrew, Court Hand, Engrossing, Tuscan, Riband, Gothic, Rustic, and Arabesque; with several Original Designs, and an Analysis of the Roman and Old English Alphabets, large and small, and Numerals, for the use of Draughtsmen, Surveyors, Masons, Decorative Painters, Lithographers, Engravers, Carvers, &c. Collected and engraved by F. DELAMOTTE, and printed in Colours. Royal 8vo, oblong, price 4*s*. cloth.

"To artists of all classes, but more especially to architects and engravers, this very handsome book will be invaluable. There is comprised in it every possible shape into which the letters of the alphabet and numerals can be formed, and the talent which has been expended in the conception of the various plain and ornamental letters is wonderful."—*Standard.*

MEDIÆVAL ALPHABETS AND INITIALS FOR ILLUMINATORS. By F. DELAMOTTE, Illuminator, Designer, and Engraver on Wood. Containing 21 Plates, and Illuminated Title, printed in Gold and Colours. With an Introduction by J. WILLIS BROOKS. Small 4to, 6*s*. cloth gilt.

"A volume in which the letters of the alphabet come forth glorified in gilding and all the colours of the prism interwoven and intertwined and intermingled, sometimes with a sort of rainbow arabesque. A poem emblazoned in these characters would be only comparable to one of those delicious love letters symbolized in a bunch of flowers well selected and cleverly arranged."—*Sun.*

THE EMBROIDERER'S BOOK OF DESIGN; containing Initials, *Emblems*, Cyphers, Monograms, Ornamental Borders, Ecclesiastical Devices, Mediæval and Modern Alphabets, and National *Emblems.* Collected and engraved by F. DELAMOTTE, printed in Colours. Oblong royal 8vo, 2*s*. 6*d*. in ornamental bo

AGRICULTURE, &c.

Youatt and Burn's Complete Grazier.

THE COMPLETE GRAZIER, and FARMER'S and CATTLE-BREEDER'S ASSISTANT. A Compendium of Husbandry. By WILLIAM YOUATT, ESQ., V.S. 11th Edition, enlarged by ROBERT SCOTT BURN, Author of "The Lessons of My Farm," &c. One large 8vo volume, 784 pp. with 215 Illustrations. 1*l.* 1*s.* half-bd.

"The standard and text-book, with the farmer and grazier."—*Farmer's Magazine*

"A treatise which will remain a standard work on the subject as long as British agriculture endures."—*Mark Lane Express.*

Spooner on Sheep.

SHEEP; THE HISTORY, STRUCTURE, ECONOMY, AND DISEASES OF. By W. C. SPOONER, M.R.V.C., &c. Third Edition, considerably enlarged; with numerous fine engravings, including some specimens of New and Improved Breeds. Fcp. 8vo, 366 pp., price 6*s.* cloth.

"The book is decidedly the best of the kind in our language."—*Scotsman.*

"Mr. Spooner has conferred upon the agricultural class a lasting benefit by embodying in this work the improvements made in sheep stock by such men as Humphreys, Rawlence, Howard, and others."—*Hampshire Advertiser.*

"The work should be in possession of every flock-master."—*Banbury Guardian.*

Scott Burn's System of Modern Farming.

OUTLINES OF MODERN FARMING. By R. SCOTT BURN. Soils, Manures, and Crops—Farming and Farming Economy, Historical and Practical—Cattle, Sheep, and Horses—Management of the Dairy, Pigs, and Poultry, with Notes on the Diseases of Stock—Utilisation of Town-Sewage, Irrigation, and Reclamation of Waste Land. New Edition. In 1 vol. 1250 pp., half-bound, profusely illustrated, price 12*s.*

"There is sufficient stated within the limits of this treatise to prevent a farmer from going far wrong in any of his operations."—*Observer.*

Horton's Underwood and Woodland Tables.

TABLES FOR PLANTING AND VALUING UNDERWOOD AND WOODLAND; also Lineal, Superficial, Cubical, Wages, Marketing, and Decimal Tables. Together with Tables for Converting Land-measure from one denomination to another, and instructions for Measuring Round Timber. By RICHARD HORTON. 12mo. 2*s.* strongly bound in leather.

Good Gardening.

A PLAIN GUIDE TO GOOD GARDENING; or, How to Grow Vegetables, Fruits, and Flowers. With Practical Notes on Soils, Manures, Seeds, Planting, Laying-out of Gardens and Grounds, and on the various kinds of Garden Structures. By SAMUEL WOOD (late gardener to Sir B. P. Wrey, Bart.), Author of 'Gardening for the Cottage.' Second Edition, with very considerable Additions, &c., and numerous Illustrations. Crown 8vo, pp. 416, cloth elegant, price 5*s.*

"A very good book, and one to be highly recommended as a practical guide. The practical directions are excellent."—*Athenæum.*

"A thoroughly useful guidebook for the amateur gardener who may want to make his plot of land not merely pretty, but useful and profitable."—*Daily Telegraph.*

Ewart's Land Improver's Pocket-Book.

THE LAND IMPROVER'S POCKET-BOOK OF FORMULÆ, TABLES, and MEMORANDA, required in any Computation relating to the Permanent Improvement of Landed Property. By JOHN EWART, Land Surveyor and Agricultural Engineer. Royal 32mo, oblong, leather, gilt edges, with elastic band, 4*s*.

"Admirably calculated to serve its purpose."—*Scotsman.*
"A compendious and handy little volume."—*Spectator.*

Hudson's Tables for Land Valuers.

THE LAND VALUER'S BEST ASSISTANT: being Tables, on a very much improved Plan, for Calculating the Value of Estates. With Tables for reducing Scotch, Irish, and Provincial Customary Acres to Statute Measure; also, Tables of Square Measure, and of the Dimensions of an Acre by which the Contents of any Plot of Ground may be ascertained without the expense of a regular Survey; &c. By R. HUDSON, C.E. New Edition, royal 32mo, oblong, leather, gilt edges, with elastic band, 4*s*.

"Of incalculable value to the country gentleman and professional man."—*Farmer's Journal.*

Complete Agricultural Surveyor's Pocket-Book.

THE LAND VALUER'S AND LAND IMPROVER'S COMPLETE POCKET-BOOK; consisting of the above two works bound together, leather, gilt edges, with strap, 7*s*. 6*d*.

☞ *The above forms an unequalled and most compendious Pocket Vade-mecum for the Land Agent and Agricultural Engineer.*

"We consider Hudson's book to be the best ready-reckoner on matters relating to the valuation of land and crops we have ever seen, and its combination with Mr. Ewart's work greatly enhances the value and usefulness of the latter-mentioned. . . It is most useful as a manual for reference to those for whom it is intended."—*North of England Farmer.*

The Management of Estates.

LANDED ESTATES MANAGEMENT: Treating of the Varieties of Lands, Peculiarities of its Farms, Methods of Farming, the Setting-out of Farms and their Fields, Construction of Roads, Fences, Gates, and Farm Buildings, of Waste or Unproductive Lands, Irrigation, Drainage, Plantation, &c. By R. SCOTT BURN, Fcp. 8vo. numerous Illustrations, 3*s*. 6*d*. [*Now Ready.*

Scott Burn's Introduction to Farming.

THE LESSONS of MY FARM: a Book for Amateur Agriculturists, being an Introduction to Farm Practice, in the Culture of Crops, the Feeding of Cattle, Management of the Dairy, Poultry, and Pigs, and in the Keeping of Farm-work Records. By ROBERT SCOTT BURN. With numerous Illustrations. Fcp. 6*s*. cloth.

"A most complete introduction to the whole round of farming practice."—*John Bull.*

The Laws of Mines and Mining Companies.

A PRACTICAL TREATISE on the LAW RELATING to MINES and MINING COMPANIES. By WHITTON ARUNDELL, Attorney-at-Law. Crown 8vo, 4*s*. cloth.

"*A Complete Epitome of the Laws of this Country.*"

EVERY MAN'S OWN LAWYER; a Handy-Book of the Principles of Law and Equity. By A BARRISTER. 14th Edition, Revised to the end of last Session. Including a Summary of the Judicature Acts, and the principal Acts of the past Session, viz.—The Act for Amending the Law Relating to Crossed Cheques, The Merchant Shipping Act, The Vivisection or Cruelty to Animals Amendment Act, The Rivers' Pollution Prevention Act. The Wild-Fowl Preservation Act, &c., &c. With Notes and References to the Authorities. Crown 8vo, price 6*s.* 8*d.* (saved at every consultation), strongly bound.

COMPRISING THE LAWS OF

BANKRUPTCY—BILLS OF EXCHANGE—CONTRACTS AND AGREEMENTS—COPYRIGHT—DOWER AND DIVORCE—ELECTIONS AND REGISTRATION—INSURANCE—LIBEL AND SLANDER—MORTGAGES—SETTLEMENTS—STOCK EXCHANGE PRACTICE—TRADE MARKS AND PATENTS—TRESPASS, NUISANCES, ETC.—TRANSFER OF LAND, ETC.—WARRANTY—WILLS AND AGREEMENTS, ETC. Also Law for Landlord and Tenant—Master and Servant—Workmen and Apprentices—Heirs, Devisees, and Legatees—Husband and Wife—Executors and Trustees—Guardian and Ward—Married Women and Infants—Partners and Agents—Lender and Borrower—Debtor and Creditor—Purchaser and Vendor—Companies and Associations—Friendly Societies—Clergymen, Churchwardens—Medical Practitioners, &c.—Bankers—Farmers—Contractors—Stock and Share Brokers—Sportsmen and Gamekeepers—Farriers and Horse-Dealers—Auctioneers, House-Agents—Innkeepers, &c.—Pawnbrokers—Surveyors—Railways and Carriers, &c. &c.

"No Englishman ought to be without this book."—*Engineer.*

"What it professes to be—a complete epitome of the laws of this country, thoroughly intelligible to non-professional readers."—*Bell's Life.*

Auctioneer's Assistant.

THE APPRAISER, AUCTIONEER, BROKER, HOUSE AND ESTATE AGENT, AND VALUER'S POCKET ASSISTANT, for the Valuation for Purchase, Sale, or Renewal of Leases, Annuities, and Reversions, and of property generally; with Prices for Inventories, &c. By JOHN WHEELER, Valuer, &c. Third Edition, enlarged, by C. NORRIS. Royal 32mo, cloth, 5*s.*

"A neat and concise book of reference, containing an admirable and clearly-arranged list of prices for inventories, and a very practical guide to determine the value of furniture, &c."—*Standard.*

Pawnbroker's Legal Guide.

THE PAWNBROKER'S, FACTOR'S, and MERCHANT'S GUIDE to the LAW of LOANS and PLEDGES. By H. C. FOLKARD, Esq., Barrister-at-Law, Author of the "Law of Slander and Libel," &c. With Additions and Corrections to 1876. 12mo, cloth boards, price 3*s.* 6*d.*

House Property.

HANDBOOK OF HOUSE PROPERTY: a Popular and Practical Guide to the Purchase, Mortgage, Tenancy, and Compulsory Sale of Houses and Land; including the Law of Dilapidations and *Fixtures;* with Explanations and Examples of all kinds of Valuations, and useful Information and Advice on Building. By EDWARD LANCE TARBUCK, Architect and Surveyor. 12mo, 5*s.* cloth boards.

"*We are glad* to be able to recommend it."—*Builder.*

"*The advice is* thoroughly practical."—*Law Journal.*

Bradbury, Agnew, & Co., Printers, Whitefriars, London.

Weale's Rudimentary Series

PHILADELPHIA, 1876.

THE PRIZE MEDAL

Was awarded to the Publishers for

Books: Rudimentary Scientific,

"WEALE'S SERIES," ETC.

A NEW LIST OF

WEALE'S SERIES

RUDIMENTARY SCIENTIFIC, EDUCATIONAL, AND CLASSICAL.

LONDON, 1862.

THE PRIZE MEDAL

Was awarded to the Publishers of

"WEALE'S SERIES."

These popular and cheap Series of Books, now comprising nearly Three Hundred distinct works in almost every department of Science, Art, and Education, are recommended to the notice of Engineers, Architects, Builders, Artisans, and Students generally, as well as to those interested in Workmen's Libraries, Free Libraries, Literary and Scientific Institutions, Colleges, Schools, Science Classes, &c., &c.

N.B.—In ordering from this List it is recommended, as a means of facilitating business and obviating error, to quote the numbers affixed to the volumes, as well as the titles and prices.

*** The books are bound in limp cloth, unless otherwise stated.

RUDIMENTARY SCIENTIFIC SERIES.

ARCHITECTURE, BUILDING, ETC.

No.

16. *ARCHITECTURE—ORDERS*—The Orders and their Æsthetic Principles. By W. H. Leeds. Illustrated. 1s. 6d.

17. *ARCHITECTURE—STYLES*—The History and Description of the Styles of Architecture of Various Countries, from the Earliest to the Present Period. By T. Talbot Bury, F.R.I.B.A., &c. Illustrated. 2s.

*** Orders and Styles of Architecture, *in One Vol.*, 3s. 6d.

18. *ARCHITECTURE—DESIGN*—The Principles of Design in Architecture, as deducible from Nature and exemplified in the Works of the Greek and Gothic Architects. By E. L. Garbett, Architect. Illustrated. 2s.

* *The three preceding Works, in One handsome Vol., half bound, entitled* "Modern Architecture," *Price* 6s.

22. *THE ART OF BUILDING*, Rudiments of. General Principles of Construction, Materials used in Building, Strength and Use of Materials, Working Drawings, Specifications, and Estimates. By Edward Dobson, M.R.I.B.A., &c. Illustrated. 2s.

23. *BRICKS AND TILES*, Rudimentary Treatise on the Manufacture of; containing an Outline of the Principles of Brickmaking. By Edward Dobson, M.R.I.B.A. With Additions by C. Tomlinson, F.R.S. Illustrated.

Architecture, Building, etc., *continued.*

25. *MASONRY AND STONECUTTING*, Rudimentary Treatise on; in which the Principles of Masonic Projection and their application to the Construction of Curved Wing-Walls, Domes, Oblique Bridges, and Roman and Gothic Vaulting, are concisely explained. By EDWARD DOBSON, M.R.I.B.A., &c. Illustrated with Plates and Diagrams. 2s. 6d.

44. *FOUNDATIONS AND CONCRETE WORKS*, a Rudimentary Treatise on; containing a Synopsis of the principal cases of Foundation Works, with the usual Modes of Treatment, and Practical Remarks on Footings, Planking, Sand, Concrete, Béton, Pile-driving, Caissons, and Cofferdams. By E. DOBSON, M.R.I.B.A., &c. Fourth Edition, revised by GEORGE DODD, C.E. Illustrated. 1s. 6d.

42. *COTTAGE BUILDING.* By C. BRUCE ALLEN, Architect. Eleventh Edition, revised and enlarged. Numerous Illustrations. 1s. 6d.

45. *LIMES, CEMENTS, MORTARS, CONCRETES, MASTICS*, PLASTERING, &c. By G. R. BURNELL, C.E. Ninth Edition. 1s. 6d.

57. *WARMING AND VENTILATION*, a Rudimentary Treatise on; being a concise Exposition of the General Principles of the Art of Warming and Ventilating Domestic and Public Buildings, Mines, Lighthouses, Ships, &c. By CHARLES TOMLINSON, F.R.S., &c. Illustrated. 3s.

83**. *CONSTRUCTION OF DOOR LOCKS.* Compiled from the Papers of A. C. HOBBS, Esq., of New York, and Edited by CHARLES TOMLINSON, F.R.S. To which is added, a Description of Fenby's Patent Locks, and a Note upon IRON SAFES by ROBERT MALLET, M.I.C.E. Illus. 2s. 6d.

111. *ARCHES, PIERS, BUTTRESSES, &c.:* Experimental Essays on the Principles of Construction in; made with a view to their being useful to the Practical Builder. By WILLIAM BLAND. Illustrated. 1s. 6d.

116. *THE ACOUSTICS OF PUBLIC BUILDINGS;* or, The Principles of the Science of Sound applied to the purposes of the Architect and Builder. By T. ROGER SMITH, M.R.I.B.A., Architect. Illustrated. 1s. 6d.

124. *CONSTRUCTION OF ROOFS*, Treatise on the, as regards Carpentry and Joinery. Deduced from the Works of ROBISON, PRICE, and TREDGOLD. Illustrated. 1s. 6d.

127. *ARCHITECTURAL MODELLING IN PAPER*, the Art of. By T. A. RICHARDSON, Architect. Illustrated. 1s. 6d.

128. *VITRUVIUS—THE ARCHITECTURE OF MARCUS VITRUVIUS POLLO.* In Ten Books. Translated from the Latin by JOSEPH GWILT, F.S.A., F.R.A.S. With 23 Plates. 5s.

130. *GRECIAN ARCHITECTURE*, An Inquiry into the Principles of Beauty in; with a Historical View of the Rise and Progress of the Art in Greece. By the EARL OF ABERDEEN. 1s.

*** *The two Preceding Works in One handsome Vol., half bound, entitled* "ANCIENT ARCHITECTURE." *Price 6s.*

132. *DWELLING-HOUSES*, a Rudimentary Treatise on the Erection of. By S. H. BROOKS, Architect. New Edition, with Plates. 2s. 6d.

156. *QUANTITIES AND MEASUREMENTS*, How to Calculate and Take them in Bricklayers', Masons', Plasterers', Plumbers', Painters', Paperhangers', Gilders', Smiths', Carpenters', and Joiners' Work. By A. C. BEATON, Architect and Surveyor. New and Enlarged Edition. Illus. 1s. 6d.

175. *LOCKWOOD & CO.'S BUILDER'S AND CONTRACTOR'S* PRICE BOOK, for 1877, containing the latest Prices of all kinds of Builders' Materials and Labour, and of all Trades connected with Building: Lists of the Members of the Metropolitan Board of Works, of Districts, District Officers, and District Surveyors, and the Metropolitan Bye-laws. Edited by FRANCIS T. W. MILLER, Architect and Surveyor. 3s. 6d.

182. *CARPENTRY AND JOINERY*—THE ELEMENTARY PRINCIPLES OF CARPENTRY. Chiefly composed from the Standard Work of THOMAS TREDGOLD, C.E. With Additions from the Works of the most Recent Authorities, and a TREATISE ON JOINERY by E. WYNDHAM TARN, M.A. Numerous Illustrations. 3s. 6d.

Architecture, Building, etc., *continued.*

182*. *CARPENTRY AND JOINERY. ATLAS* of 35 Plates to accompany the foregoing book. With Descriptive Letterpress. 4to. 6s.

187. *HINTS TO YOUNG ARCHITECTS.* By GEORGE WIGHTWICK. New, Revised, and enlarged Edition. By G. HUSKISSON GUILLAUME, Architect. With numerous Woodcuts. 3s. 6d.

188. *HOUSE PAINTING, GRAINING, MARBLING, AND SIGN WRITING:* A Practical Manual of. With 9 Coloured Plates of Woods and Marbles, and nearly 150 Wood Engravings. By ELLIS A. DAVIDSON. Second Edition, carefully revised, 5s. [*Just published.*

189. *THE RUDIMENTS OF PRACTICAL BRICKLAYING.* In Six Sections: General Principles; Arch Drawing, Cutting, and Setting; Pointing; Paving, Tiling, Materials; Slating and Plastering; Practical Geometry, Mensuration, &c. By ADAM HAMMOND. Illustrated. 1s. 6d.

191. *PLUMBING.* A Text-Book to the Practice of the Art or Craft of the Plumber. With Chapters upon House Drainage, embodying the latest Improvements. Containing about 300 Illustrations. By W. P. BUCHAN, Sanitary Engineer. 3s. [*Just published.*

192. *THE TIMBER IMPORTER'S, TIMBER MERCHANT'S,* and BUILDER'S STANDARD GUIDE; comprising copious and valuable Memoranda for the Retailer and Builder. By RICHARD E. GRANDY. Second Edition, Revised. 3s.

CIVIL ENGINEERING, ETC.

13. *CIVIL ENGINEERING,* the Rudiments of; for the Use of Beginners, for Practical Engineers, and for the Army and Navy. By HENRY LAW, C.E. Including a Section on Hydraulic Engineering, by GEORGE R. BURNELL, C.E. 5th Edition, with Notes and Illustrations by ROBERT MALLET, A.M., F.R.S. Illustrated with Plates and Diagrams. 5s.

29. *THE DRAINAGE OF DISTRICTS AND LANDS.* By G. DRYSDALE DEMPSEY, C.E. New Edition, enlarged. Illustrated. 1s. 6d.

30. *THE DRAINAGE OF TOWNS AND BUILDINGS.* By G. DRYSDALE DEMPSEY, C.E. New Edition. Illustrated. 2s. 6d.
*** *With "Drainage of Districts and Lands," in One Vol.,* 3s. 6d.

31. *WELL-DIGGING, BORING, AND PUMP-WORK.* By JOHN GEORGE SWINDELL, Assoc. R.I.B.A. New Edition, revised by G. R. BURNELL, C.E. Illustrated. 1s. 6d.

35. *THE BLASTING AND QUARRYING OF STONE,* for Building and other Purposes. With Remarks on the Blowing up of Bridges. By Gen. Sir JOHN BURGOYNE, Bart., K.C.B. Illustrated. 1s. 6d.

43. *TUBULAR AND OTHER IRON GIRDER BRIDGES.* Particularly describing the BRITANNIA and CONWAY TUBULAR BRIDGES. With a Sketch of Iron Bridges, and Illustrations of the Application of Malleable Iron to the Art of Bridge Building. By G. D. DEMPSEY, C.E. New Edition, with Illustrations. 1s. 6d.

62. *RAILWAY CONSTRUCTION,* Elementary and Practical Instruction on. By Sir MACDONALD STEPHENSON, C.E. New Edition, enlarged by EDWARD NUGENT, C.E. Plates and numerous Woodcuts. 3s.

80*. *EMBANKING LANDS FROM THE SEA,* the Practice of. Treated as a Means of Profitable Employment for Capital. With Examples and Particulars of actual Embankments, and also Practical Remarks on the Repair of old Sea Walls. By JOHN WIGGINS, F.G.S. New Edition, with Notes by ROBERT MALLET, F.R.S. 2s.

81. *WATER WORKS,* for the Supply of Cities and Towns. With a Description of the Principal Geological Formations of England as influencing Supplies of Water; and Details of Engines and Pumping Machinery for *raising* Water. By SAMUEL HUGHES, F.G.S., C.E. New Edition revised and enlarged, with numerous Illustrations. 4s.

82**. *GAS WORKS,* and the Practice of Manufacturing and Distributing *Coal Gas.* By SAMUEL HUGHES, C.E. New Edition, revised by RICHARDS, C.E. Illustrated. 3s. 6d.

Civil Engineering, etc., *continued.*

117. *SUBTERRANEOUS SURVEYING;* an Elementary and Practical Treatise on. By THOMAS FENWICK. Also the Method of Conducting Subterraneous Surveys without the Use of the Magnetic Needle, and other modern Improvements. By THOMAS BAKER, C.E. Illustrated. 2s. 6d.

118. *CIVIL ENGINEERING IN NORTH AMERICA,* a Sketch of. By DAVID STEVENSON, F.R.S.E., &c. Plates and Diagrams. 3s.

121. *RIVERS AND TORRENTS.* With the Method of Regulating their Courses and Channels. By Professor PAUL FRISI, F.R.S., of Milan. To which is added, AN ESSAY ON NAVIGABLE CANALS. Translated by Major-General JOHN GARSTIN, of the Bengal Engineers. Plates. 2s. 6d.

MECHANICAL ENGINEERING, ETC.

33. *CRANES,* the Construction of, and other Machinery for Raising Heavy Bodies for the Erection of Buildings, and for Hoisting Goods. By JOSEPH GLYNN, F.R.S., &c. Illustrated. 1s. 6d.

34. *THE STEAM ENGINE,* a Rudimentary Treatise on. By Dr. LARDNER. Illustrated. 1s. 6d.

59. *STEAM BOILERS:* their Construction and Management. By R. ARMSTRONG, C.E. Illustrated. 1s. 6d.

63. *AGRICULTURAL ENGINEERING:* Farm Buildings, Motive Power, Field Machines, Machinery, and Implements. By G. H. ANDREWS, C.E. Illustrated. 3s.

67. *CLOCKS, WATCHES, AND BELLS,* a Rudimentary Treatise on. By Sir EDMUND BECKETT (late EDMUND BECKETT DENISON, LL.D., Q.C.). A new, Revised, and considerably Enlarged Edition (the 6th), with very numerous Illustrations. 4s. 6d. [*Just published.*

77*. *THE ECONOMY OF FUEL,* particularly with Reference to Reverbatory Furnaces for the Manufacture of Iron, and to Steam Boilers. By T. SYMES PRIDEAUX. 1s. 6d.

82. *THE POWER OF WATER,* as applied to drive Flour Mills, and to give motion to Turbines and other Hydrostatic Engines. By JOSEPH GLYNN, F.R.S., &c. New Edition, Illustrated. 2s.

98. *PRACTICAL MECHANISM,* the Elements of; and Machine Tools. By T. BAKER, C.E. With Remarks on Tools and Machinery, by J. NASMYTH, C.E. Plates. 2s. 6d.

114. *MACHINERY,* Elementary Principles of, in its Construction and Working. Illustrated by numerous Examples of Modern Machinery for different Branches of Manufacture. By C. D. ABEL, C.E. 1s. 6d.

15. *ATLAS OF PLATES.* Illustrating the above Treatise. By C. D. ABEL, C.E. 7s. 6d.

125. *THE COMBUSTION OF COAL AND THE PREVENTION* OF SMOKE, Chemically and Practically Considered. With an Appendix. By C. WYE WILLIAMS, A.I.C.E. Plates. 3s.

139. *THE STEAM ENGINE,* a Treatise on the Mathematical Theory of, with Rules at length, and Examples for the Use of Practical Men. By T. BAKER, C.E. Illustrated. 1s. 6d.

162. *THE BRASS FOUNDER'S MANUAL;* Instructions for Modelling, Pattern-Making, Moulding, Turning, Filing, Burnishing, Bronzing, &c. With copious Receipts, numerous Tables, and Notes on Prime Costs and Estimates. By WALTER GRAHAM. Illustrated. 2s. 6d.

164. *MODERN WORKSHOP PRACTICE,* as applied to Marine, *Land,* and Locomotive Engines, Floating Docks, Dredging Machines, *Bridges,* Cranes, Ship-building, &c., &c. By J. G. WINTON. Illustrated. 3s.

165. *IRON AND HEAT,* exhibiting the Principles concerned in the Construction of Iron Beams, Pillars, and Bridge Girders, and the Action of Heat in the Smelting Furnace. By J. ARMOUR, C.E. 2s. 6d.

Mechanical Engineering, etc., *continued.*

166. *POWER IN MOTION:* Horse-Power, Motion, Toothed-Wheel Gearing, Long and Short Driving Bands, Angular Forces. By JAMES ARMOUR, C.E. With 73 Diagrams. 2s. 6d.

167. *THE APPLICATION OF IRON TO THE CONSTRUCTION* OF BRIDGES, GIRDERS, ROOFS, AND OTHER WORKS. Showing the Principles upon which such Structures are designed, and their Practical Application. By FRANCIS CAMPIN, C.E. Second Edition, revised and corrected. Numerous Woodcuts. 2s. 6d.

171. *THE WORKMAN'S MANUAL OF ENGINEERING* DRAWING. By JOHN MAXTON, Engineer, Instructor in Engineering Drawing, Royal Naval College, Greenwich, formerly of R.S.N.A., South Kensington. Third Edition. Illustrated with 7 Plates and nearly 350 Woodcuts. 3s. 6d.

190. *STEAM AND THE STEAM ENGINE*, Stationary and Portable. An elementary treatise on. Being an extension of Mr. John Sewell's "Treatise on Steam." By D. KINNEAR CLARK, C.E., M.I.C.E. Author of "Railway Machinery," "Railway Locomotives," &c., &c. With numerous Illustrations. 3s. 6d. [*Just published.*

SHIPBUILDING, NAVIGATION, MARINE ENGINEERING, ETC.

51. *NAVAL ARCHITECTURE*, the Rudiments of; or, an Exposition of the Elementary Principles of the Science, and their Practical Application to Naval Construction. Compiled for the Use of Beginners. By JAMES PEAKE, School of Naval Architecture, H.M. Dockyard, Portsmouth. Fourth Edition, corrected, with Plates and Diagrams. 3s. 6d.

53*. *SHIPS FOR OCEAN AND RIVER SERVICE*, Elementary and Practical Principles of the Construction of. By HAKON A. SOMMERFELDT, Surveyor of the Royal Norwegian Navy. With an Appendix. 1s.

53**. *AN ATLAS OF ENGRAVINGS* to Illustrate the above. Twelve large folding plates. Royal 4to, cloth. 7s. 6d.

54. *MASTING, MAST-MAKING, AND RIGGING OF SHIPS*, Rudimentary Treatise on. Also Tables of Spars, Rigging, Blocks; Chain, Wire, and Hemp Ropes, &c., relative to every class of vessels. Together with an Appendix of Dimensions of Masts and Yards of the Royal Navy of Great Britain and Ireland. By ROBERT KIPPING, N.A. Fourteenth Edition. Illustrated. 2s.

54*. *IRON SHIP-BUILDING.* With Practical Examples and Details for the Use of Ship Owners and Ship Builders. By JOHN GRANTHAM, Consulting Engineer and Naval Architect. Fifth Edition, with important Additions. 4s.

54**. *AN ATLAS OF FORTY PLATES* to Illustrate the above. Fifth Edition. Including the latest Examples, such as H.M. Steam Frigates "Warrior," "Hercules," "Bellerophon;" H.M. Troop Ship "Serapis," Iron Floating Dock, &c., &c. 4to, boards. 38s.

55. *THE SAILOR'S SEA BOOK:* a Rudimentary Treatise on Navigation. I. How to Keep the Log and Work it off. II. On Finding the Latitude and Longitude. By JAMES GREENWOOD, B.A., of Jesus College, Cambridge. To which are added, Directions for Great Circle Sailing; an Essay on the Law of Storms and Variable Winds; and Explanations of Terms used in Ship-building. Ninth Edition, with several Engravings and Coloured Illustrations of the Flags of Maritime Nations. 2s.

80. *MARINE ENGINES, AND STEAM VESSELS*, a Treatise on. Together with Practical Remarks on the Screw and Propelling Power, as used in the Royal and Merchant Navy. By ROBERT MURRAY, C.E., *Engineer*-Surveyor to the Board of Trade. With a Glossary of Technical *Terms*, and their Equivalents in French, German, and Spanish. Fifth Edition *revised* and enlarged. Illustrated. 3s.

Shipbuilding, Navigation, etc., *continued.*

83*bis*. *THE FORMS OF SHIPS AND BOATS:* Hints, Experimentally Derived, on some of the Principles regulating Ship-building. By W. BLAND. Sixth Edition, revised, with numerous Illustrations and Models. 1s. 6d.

99. *NAVIGATION AND NAUTICAL ASTRONOMY*, in Theory and Practice. With Attempts to facilitate the Finding of the Time and the Longitude at Sea. By J. R. YOUNG, formerly Professor of Mathematics in Belfast College. Illustrated. 2s. 6d.

100*. *TABLES* intended to facilitate the Operations of Navigation and Nautical Astronomy, as an Accompaniment to the above Book. By J. R. YOUNG. 1s. 6d.

106. *SHIPS' ANCHORS*, a Treatise on. By GEORGE COTSELL, N.A. Illustrated. 1s. 6d.

149. *SAILS AND SAIL-MAKING*, an Elementary Treatise on. With Draughting, and the Centre of Effort of the Sails. Also, Weights and Sizes of Ropes; Masting, Rigging, and Sails of Steam Vessels, &c., &c. Tenth Edition, enlarged, with an Appendix. By ROBERT KIPPING, N.A., Sailmaker, Quayside, Newcastle. Illustrated. 2s. 6d.

155. *THE ENGINEER'S GUIDE TO THE ROYAL AND* MERCANTILE NAVIES. By a PRACTICAL ENGINEER. Revised by D. F. M'CARTHY, late of the Ordnance Survey Office, Southampton. 3s.

PHYSICAL SCIENCE, NATURAL PHILOSOPHY, ETC.

1. *CHEMISTRY*, for the Use of Beginners. By Professor GEORGE FOWNES, F.R.S. With an Appendix, on the Application of Chemistry to Agriculture. 1s.

2. *NATURAL PHILOSOPHY*, Introduction to the Study of; for the Use of Beginners. By C. TOMLINSON, Lecturer on Natural Science in King's College School, London. Woodcuts. 1s. 6d.

4. *MINERALOGY*, Rudiments of; a concise View of the Properties of Minerals. By A. RAMSAY, Jun. Woodcuts and Steel Plates. 3s.

6. *MECHANICS*, Rudimentary Treatise on; being a concise Exposition of the General Principles of Mechanical Science, and their Applications. By CHARLES TOMLINSON, Lecturer on Natural Science in King's College School, London. Illustrated. 1s. 6d.

7. *ELECTRICITY;* showing the General Principles of Electrical Science, and the purposes to which it has been applied. By Sir W. SNOW HARRIS, F.R.S., &c. With considerable Additions by R. SABINE, C.E., F.S.A. Woodcuts. 1s. 6d.

7*. *GALVANISM*, Rudimentary Treatise on, and the General Principles of Animal and Voltaic Electricity. By Sir W. SNOW HARRIS. New Edition, revised, with considerable Additions, by ROBERT SABINE, C.E., F.S.A. Woodcuts. 1s. 6d.

8. *MAGNETISM;* being a concise Exposition of the General Principles of Magnetical Science, and the Purposes to which it has been applied. By Sir W. SNOW HARRIS. New Edition, revised and enlarged by H. M. NOAD, Ph.D., Vice-President of the Chemical Society, Author of "A Manual of Electricity," &c., &c. With 165 Woodcuts. 3s. 6d.

1. *THE ELECTRIC TELEGRAPH;* its History and Progress; with Descriptions of some of the Apparatus. By R. SABINE, C.E., F.S.A., &c. Woodcuts. 3s.

12. *PNEUMATICS*, for the Use of Beginners. By CHARLES TOMLINSON. Illustrated. 1s. 6d.

72. *MANUAL OF THE MOLLUSCA*; a Treatise on Recent and *Fossil* Shells. By Dr. S. P. WOODWARD, A.L.S. With Appendix by RALPH TATE, A.L.S., F.G.S. With numerous Plates and 300 Woodcuts. *6s. 6d.* Cloth boards, 7s. 6d.

Physical Science, Natural Philosophy, etc., *continued.*

79**. *PHOTOGRAPHY*, Popular Treatise on; with a Description of the Stereoscope, &c. Translated from the French of D. VAN MONCKHOVEN, by W. H. THORNTHWAITE, Ph.D. Woodcuts. 1s. 6d.

96. *ASTRONOMY.* By the Rev. R. MAIN, M.A., F.R.S., &c. New and enlarged Edition, with an Appendix on "Spectrum Analysis." Woodcuts. 1s. 6d.

97. *STATICS AND DYNAMICS*, the Principles and Practice of; embracing also a clear development of Hydrostatics, Hydrodynamics, and Central Forces. By T. BAKER, C.E. 1s. 6d.

138. *TELEGRAPH*, Handbook of the; a Manual of Telegraphy, Telegraph Clerks' Remembrancer, and Guide to Candidates for Employment in the Telegraph Service. By R. BOND. Fourth Edition, revised and enlarged: to which is appended, QUESTIONS on MAGNETISM, ELECTRICITY, and PRACTICAL TELEGRAPHY, for the Use of Students, by W. MCGREGOR, First Assistant Superintendent, Indian Gov. Telegraphs. Woodcuts. 3s.

143. *EXPERIMENTAL ESSAYS.* By CHARLES TOMLINSON. I. On the Motions of Camphor on Water. II. On the Motion of Camphor towards the Light. III. History of the Modern Theory of Dew. Woodcuts. 1s.

173. *PHYSICAL GEOLOGY*, partly based on Major-General PORTLOCK'S "Rudiments of Geology." By RALPH TATE, A.L.S., &c. Numerous Woodcuts. 2s.

174. *HISTORICAL GEOLOGY*, partly based on Major-General PORTLOCK'S "Rudiments." By RALPH TATE, A.L.S., &c. Woodcuts. 2s. 6d.

173 & 174. *RUDIMENTARY TREATISE ON GEOLOGY*, Physical and Historical. Partly based on Major-General PORTLOCK'S "Rudiments of Geology." By RALPH TATE, A.L.S., F.G.S., &c., &c. Numerous Illustrations. In One Volume. 4s. 6d.

183 & 184. *ANIMAL PHYSICS*, Handbook of. By DIONYSIUS LARDNER, D.C.L., formerly Professor of Natural Philosophy and Astronomy in University College, London. With 520 Illustrations. In One Volume, cloth boards. 7s. 6d.

*** *Sold also in Two Parts, as follows:—*

183. ANIMAL PHYSICS. By Dr. LARDNER. Part I., Chapter I—VII. 4s.
184. ANIMAL PHYSICS. By Dr. LARDNER. Part II. Chapter VIII—XVIII. 3s.

MINING, METALLURGY, ETC.

117. *SUBTERRANEOUS SURVEYING*, Elementary and Practical Treatise on, with and without the Magnetic Needle. By THOMAS FENWICK, Surveyor of Mines, and THOMAS BAKER, C.E. Illustrated. 2s. 6d.

133. *METALLURGY OF COPPER*; an Introduction to the Methods of Seeking, Mining, and Assaying Copper, and Manufacturing its Alloys. By ROBERT H. LAMBORN, Ph.D. Woodcuts. 2s. 6d.

134. *METALLURGY OF SILVER AND LEAD.* A Description of the Ores; their Assay and Treatment, and valuable Constituents. By Dr. R. H. LAMBORN. Woodcuts. 2s

135. *ELECTRO-METALLURGY;* Practically Treated. By ALEXANDER WATT, F.R.S.S.A. New Edition, enlarged. Woodcuts. 2s. 6d.

172. *MINING TOOLS*, Manual of. For the Use of Mine Managers, Agents, Students, &c. Comprising Observations on the Materials from, and Processes by, which they are manufactured; their Special Uses, Applications, Qualities, and Efficiency. By WILLIAM MORGANS, Lecturer on Mining at the Bristol School of Mines. 2s. 6d.

172*. *MINING TOOLS, ATLAS* of Engravings to Illustrate the *above, containing* 235 Illustrations of Mining Tools, drawn to Scale. *4s. 6d.*

Mining, Metallurgy, etc., *continued.*

176. *METALLURGY OF IRON*, a Treatise on the. Containing Outlines of the History of Iron Manufacture, Methods of Assay, and Analyses of Iron Ores, Processes of Manufacture of Iron and Steel, &c. By H. BAUERMAN, F.G.S., Associate of the Royal School of Mines. Fourth Edition, revised and enlarged, with numerous Illustrations. 4s. 6d.

180. *COAL AND COAL MINING:* A Rudimentary Treatise on. By WARINGTON W. SMYTH, M.A., F.R.S., &c., Chief Inspector of the Mines of the Crown and of the Duchy of Cornwall. New Edition, revised and corrected. With numerous Illustrations. 3s. 6d.

EMIGRATION.

154. *GENERAL HINTS TO EMIGRANTS.* Containing Notices of the various Fields for Emigration. With Hints on Preparation for Emigrating, Outfits, &c., &c. With Directions and Recipes useful to the Emigrant. With a Map of the World. 2s.

157. *THE EMIGRANT'S GUIDE TO NATAL.* By ROBERT JAMES MANN, F.R.A.S., F.M.S. Second Edition, carefully corrected to the present Date. Map. 2s.

159. *THE EMIGRANT'S GUIDE TO AUSTRALIA, New South Wales, Western Australia, South Australia, Victoria, and Queensland.* By the Rev. JAMES BAIRD, B.A. Map. 2s. 6d.

160. *THE EMIGRANT'S GUIDE TO TASMANIA and NEW ZEALAND.* By the Rev. JAMES BAIRD, B.A. With a Map. 2s.

159 & 160. *THE EMIGRANT'S GUIDE TO AUSTRALASIA.* By the Rev. J. BAIRD, B.A. Comprising the above two volumes, 12mo, cloth boards. With Maps of Australia and New Zealand. 5s.

AGRICULTURE.

29. *THE DRAINAGE OF DISTRICTS AND LANDS.* By G. DRYSDALE DEMPSEY, C.E. Illustrated. 1s. 6d.
*** *With "Drainage of Towns and Buildings," in One Vol., 3s. 6d.*

63. *AGRICULTURAL ENGINEERING:* Farm Buildings, Motive Powers and Machinery of the Steading, Field Machines, and Implements. By G. H. ANDREWS, C.E. Illustrated. 3s.

66. *CLAY LANDS AND LOAMY SOILS.* By Professor DONALDSON. 1s.

131. *MILLER'S, MERCHANT'S, AND FARMER'S READY* RECKONER, for ascertaining at sight the value of any quantity of Corn, from One Bushel to One Hundred Quarters, at any given price, from £1 to £5 per quarter. Together with the approximate values of Millstones and Millwork, &c. 1s.

140. *SOILS, MANURES, AND CROPS.* (Vol. 1. OUTLINES OF MODERN FARMING.) By R. SCOTT BURN. Woodcuts. 2s.

141. *FARMING AND FARMING ECONOMY,* Notes, Historical and Practical, on. (Vol. 2. OUTLINES OF MODERN FARMING.) By R. SCOTT BURN. Woodcuts. 3s.

142. *STOCK; CATTLE, SHEEP, AND HORSES.* (Vol. 3. OUTLINES OF MODERN FARMING.) By R. SCOTT BURN. Woodcuts. 2s. 6d.

145. *DAIRY, PIGS, AND POULTRY,* Management of the. By R. SCOTT BURN. With Notes on the Diseases of Stock. (Vol. 4. OUTLINES OF MODERN FARMING.) Woodcuts. 2s.

146. *UTILIZATION OF SEWAGE, IRRIGATION, AND* RECLAMATION OF WASTE LAND. (Vol. 5. OUTLINES OF MODERN FARMING.) By R. SCOTT BURN. Woodcuts. 2s. 6d.

*** *Nos. 140-1-2-5-6,* in One Vol., handsomely half-bound, entitled "OUTLINES OF MODERN FARMING." By ROBERT SCOTT BURN. Price 12s.

177. *FRUIT TREES,* The Scientific and Profitable Culture of. From the French of DU BREUIL, Revised by GEO. GLENNY. 187 Woodcuts. 3s. 6d.

FINE ARTS.

20. *PERSPECTIVE FOR BEGINNERS.* Adapted to Young Students and Amateurs in Architecture, Painting, &c. By GEORGE PYNE, Artist. Woodcuts. 2s.

40 & 41. *GLASS STAINING;* or, Painting on Glass, The Art of. Comprising Directions for Preparing the Pigments and Fluxes, laying them upon the Glass, and Firing or Burning in the Colours. From the German of Dr. GESSERT. To which is added, an Appendix on THE ART OF ENAMELLING, &c., with THE ART OF PAINTING ON GLASS. From the German of EMANUEL OTTO FROMBERG. In One Volume. 2s. 6d.

69. *MUSIC,* A Rudimentary and Practical Treatise on. With numerous Examples. By CHARLES CHILD SPENCER. 2s. 6d.

71. *PIANOFORTE,* The Art of Playing the. With numerous Exercises and Lessons. Written and Selected from the Best Masters, by CHARLES CHILD SPENCER. 1s. 6d.

181. *PAINTING POPULARLY EXPLAINED,* including Fresco, Oil, Mosaic, Water Colour, Water-Glass, Tempera, Encaustic, Miniature, Painting on Ivory, Vellum, Pottery, Enamel, Glass, &c. With Historical Sketches of the Progress of the Art by THOMAS JOHN GULLICK, assisted by JOHN TIMBS, F.S.A. Third Edition, revised and enlarged, with Frontispiece and Vignette. 5s.

186. *A GRAMMAR OF COLOURING,* applied to Decorative Painting and the Arts. By GEORGE FIELD. New Edition, enlarged and adapted to the Use of the Ornamental Painter and Designer. By ELLIS A. DAVIDSON, Author of "Drawing for Carpenters," &c. With two new Coloured Diagrams and numerous Engravings on Wood. 2s. 6d.

ARITHMETIC, GEOMETRY, MATHEMATICS, ETC.

32. *MATHEMATICAL INSTRUMENTS,* a Treatise on; in which their Construction and the Methods of Testing, Adjusting, and Using them are concisely Explained. By J. F. HEATHER, M.A., of the Royal Military Academy, Woolwich. Original Edition, in 1 vol., Illustrated. 1s. 6d.

*** *In ordering the above, be careful to say, "Original Edition," or give the number in the Series* (32) *to distinguish it from the Enlarged Edition in* 3 *vols.* (*Nos.* 168-9-70.)

60. *LAND AND ENGINEERING SURVEYING,* a Treatise on; with all the Modern Improvements. Arranged for the Use of Schools and Private Students; also for Practical Land Surveyors and Engineers. By T. BAKER, C.E. New Edition, revised by EDWARD NUGENT, C.E. Illustrated with Plates and Diagrams. 2s.

61*. *READY RECKONER FOR THE ADMEASUREMENT OF* LAND. By ABRAHAM ARMAN, Schoolmaster, Thurleigh, Beds. To which is added a Table, showing the Price of Work, from 2s. 6d. to £1 per acre, and Tables for the Valuation of Land, from 1s. to £1,000 per acre, and from one pole to two thousand acres in extent, &c., &c. 1s. 6d.

76. *DESCRIPTIVE GEOMETRY,* an Elementary Treatise on; with a Theory of Shadows and of Perspective, extracted from the French of G. MONGE. To which is added, a description of the Principles and Practice of Isometrical Projection; the whole being intended as an introduction to the Application of Descriptive Geometry to various branches of the Arts. By J. F. HEATHER, M.A. Illustrated with 14 Plates. 2s.

178. *PRACTICAL PLANE GEOMETRY:* giving the Simplest Modes of Constructing Figures contained in one Plane and Geometrical Construction of the Ground. By J. F. HEATHER, M.A. With 215 Woodcuts. 2s.

179. *PROJECTION:* Orthographic, Topographic, and Perspective; giving the various Modes of Delineating Solid Forms by Constructions on a Single Plane Surface. By J. F. HEATHER, M.A. [*In preparation*

*** *The above three volumes will form a* COMPLETE ELEMENTARY COURSE OF MATHEMATICAL DRAWING.

Arithmetic, Geometry, Mathematics, etc., *continued.*

83. *COMMERCIAL BOOK-KEEPING.* With Commercial Phrases and Forms in English, French, Italian, and German. By JAMES HADDON, M.A., Arithmetical Master of King's College School, London. 1s.

84. *ARITHMETIC,* a Rudimentary Treatise on: with full Explanations of its Theoretical Principles, and numerous Examples for Practice. For the Use of Schools and for Self-Instruction. By J. R. YOUNG, late Professor of Mathematics in Belfast College. New Edition, with Index. 1s. 6d.

84* A KEY to the above, containing Solutions in full to the Exercises, together with Comments, Explanations, and Improved Processes, for the Use of Teachers and Unassisted Learners. By J. R. YOUNG. 1s. 6d.

85. *EQUATIONAL ARITHMETIC,* applied to Questions of Interest,
85*. Annuities, Life Assurance, and General Commerce; with various Tables by which all Calculations may be greatly facilitated. By W. HIPSLEY. 2s.

86. *ALGEBRA,* the Elements of. By JAMES HADDON, M.A., Second Mathematical Master of King's College School. With Appendix, containing miscellaneous Investigations, and a Collection of Problems in various parts of Algebra. 2s.

86* A KEY AND COMPANION to the above Book, forming an extensive repository of Solved Examples and Problems in Illustration of the various Expedients necessary in Algebraical Operations. Especially adapted for Self-Instruction. By J. R. YOUNG. 1s. 6d.

88. *EUCLID,* THE ELEMENTS OF: with many additional Propositions
89. and Explanatory Notes: to which is prefixed, an Introductory Essay on Logic. By HENRY LAW, C.E. 2s. 6d.

*** *Sold also separately, viz.:—*

88. EUCLID, The First Three Books. By HENRY LAW, C.E. 1s.

89. EUCLID, Books 4, 5, 6, 11, 12. By HENRY LAW, C.E. 1s. 6d.

90. *ANALYTICAL GEOMETRY AND CONIC SECTIONS,* a Rudimentary Treatise on. By JAMES HANN, late Mathematical Master of King's College School, London. A New Edition, re-written and enlarged by J. R. YOUNG, formerly Professor of Mathematics at Belfast College. 2s.

91. *PLANE TRIGONOMETRY,* the Elements of. By JAMES HANN, formerly Mathematical Master of King's College, London. 1s.

92. *SPHERICAL TRIGONOMETRY,* the Elements of. By JAMES HANN. Revised by CHARLES H. DOWLING, C.E. 1s.

*** *Or with "The Elements of Plane Trigonometry," in One Volume,* 2s.

93. *MENSURATION AND MEASURING,* for Students and Practical Use. With the Mensuration and Levelling of Land for the Purposes of Modern Engineering. By T. BAKER, C.E. New Edition, with Corrections and Additions by E. NUGENT, C.E. Illustrated. 1s. 6d.

94. *LOGARITHMS,* a Treatise on; with Mathematical Tables for facilitating Astronomical, Nautical, Trigonometrical, and Logarithmic Calculations; Tables of Natural Sines and Tangents and Natural Cosines. By HENRY LAW, C.E. Illustrated. 2s. 6d.

101*. *MEASURES, WEIGHTS, AND MONEYS OF ALL NATIONS,* and an Analysis of the Christian, Hebrew, and Mahometan Calendars. By W. S. B. WOOLHOUSE, F.R.A.S., &c. 1s. 6d.

102. *INTEGRAL CALCULUS,* Rudimentary Treatise on the. By HOMERSHAM COX, B.A. Illustrated. 1s.

103. *INTEGRAL CALCULUS,* Examples on the. By JAMES HANN, late of King's College, London. Illustrated. 1s.

101. *DIFFERENTIAL CALCULUS,* Examples of the. By W. S. B. WOOLHOUSE, F.R.A.S., &c. 1s. 6d.

104. *DIFFERENTIAL CALCULUS,* Examples and Solutions of the. By JAMES HADDON, M.A. 1s.

Arithmetic, Geometry, Mathematics, etc., *continued.*

105. *MNEMONICAL LESSONS.* — GEOMETRY, ALGEBRA, AND TRIGONOMETRY, in Easy Mnemonical Lessons. By the Rev. THOMAS PENYNGTON KIRKMAN, M.A. 1s. 6d.

136. *ARITHMETIC*, Rudimentary, for the Use of Schools and Self-Instruction. By JAMES HADDON, M.A. Revised by ABRAHAM ARMAN. 1s. 6d.

137. A KEY TO HADDON'S RUDIMENTARY ARITHMETIC. By A. ARMAN. 1s. 6d.

147. *ARITHMETIC*, STEPPING-STONE TO; being a Complete Course of Exercises in the First Four Rules (Simple and Compound), on an entirely new principle. For the Use of Elementary Schools of every Grade. Intended as an Introduction to the more extended works on Arithmetic. By ABRAHAM ARMAN. 1s.

148. A KEY TO STEPPING-STONE TO ARITHMETIC. By A. ARMAN. 1s.

158. *THE SLIDE RULE, AND HOW TO USE IT;* containing full, easy, and simple Instructions to perform all Business Calculations with unexampled rapidity and accuracy. By CHARLES HOARE, C.E. With a Slide Rule in tuck of cover. 3s.

168. *DRAWING AND MEASURING INSTRUMENTS.* Including—I. Instruments employed in Geometrical and Mechanical Drawing, and in the Construction, Copying, and Measurement of Maps and Plans. II. Instruments used for the purposes of Accurate Measurement, and for Arithmetical Computations. By J. F. HEATHER, M.A., late of the Royal Military Academy, Woolwich, Author of "Descriptive Geometry," &c., &c. Illustrated. 1s. 6d.

169. *OPTICAL INSTRUMENTS.* Including (more especially) Telescopes, Microscopes, and Apparatus for producing copies of Maps and Plans by Photography. By J. F. HEATHER, M.A. Illustrated. 1s. 6d.

170. *SURVEYING AND ASTRONOMICAL INSTRUMENTS.* Including—I. Instruments Used for Determining the Geometrical Features of a portion of Ground. II. Instruments Employed in Astronomical Observations. By J. F. HEATHER, M.A. Illustrated. 1s. 6d.

*** *The above three volumes form an enlargement of the Author's original work, "Mathematical Instruments: their Construction, Adjustment, Testing, and Use," the Eleventh Edition of which is on sale, price 1s. 6d. (See No. 32 in the Series.)*

168.) 169.) 170.) *MATHEMATICAL INSTRUMENTS.* By J. F. HEATHER, M.A. Enlarged Edition, for the most part entirely re-written. The 3 Parts as above, in One thick Volume. With numerous Illustrations. 4s. 6d.

185. *THE COMPLETE MEASURER;* setting forth the Measurement of Boards, Glass, &c., &c.; Unequal-sided, Square-sided, Octagonal-sided, Round Timber and Stone, and Standing Timber. With just Allowances for the Bark in the respective species of Trees, and proper deductions for the waste in hewing the trees, &c.; also a Table showing the solidity of hewn or eight-sided timber, or of any octagonal-sided column. Compiled for the accommodation of Timber-growers, Merchants, and Surveyors, Stonemasons, Architects, and others. By RICHARD HORTON. Third Edition, with considerable and valuable additions. 4s. [*Just published.*

LEGAL TREATISES.

50. *THE LAW OF CONTRACTS FOR WORKS AND SERVICES.* By DAVID GIBBONS. Third Edition, revised and considerably enlarged. 3s. [*Just published.*

151. *A HANDY BOOK ON THE LAW OF FRIENDLY, INDUSTRIAL & PROVIDENT BUILDING & LOAN SOCIETIES.* With copious Notes. By NATHANIEL WHITE, of H.M. Civil Service. 1s.

163. *THE LAW OF PATENTS FOR INVENTIONS;* and the Protection of Designs and Trade Marks. By E. W. CAMPIN, Barrister-at-Law. 2s.

MISCELLANEOUS VOLUMES.

36. *A DICTIONARY OF TERMS used in ARCHITECTURE, BUILDING, ENGINEERING, MINING, METALLURGY, ARCHÆOLOGY, the FINE ARTS, &c.* By JOHN WEALE. Fifth Edition. Revised by ROBERT HUNT, F.R.S., Keeper of Mining Records. Numerous Illustrations. 5s.

112. *MANUAL OF DOMESTIC MEDICINE.* By R. GOODING, B.A., M.B. Intended as a Family Guide in all Cases of Accident and Emergency. 2s.

112*. *MANAGEMENT OF HEALTH.* A Manual of Home and Personal Hygiene. By the Rev. JAMES BAIRD, B.A. 1s.

113. *FIELD ARTILLERY ON SERVICE.* By TAUBERT, Captain Prussian Artillery. Translated by Lieut.-Col. H. H. MAXWELL. 1s. 6d.

113*. *SWORDS, AND OTHER ARMS.* By Col. MAREY. Translated by Col. H. H. MAXWELL. With Plates. 1s.

150. *LOGIC,* Pure and Applied. By S. H. EMMENS. Third Edition. 1s. 6d.

152. *PRACTICAL HINTS FOR INVESTING MONEY.* With an Explanation of the Mode of Transacting Business on the Stock Exchange. By FRANCIS PLAYFORD, Sworn Broker. 1s. 6d.

153. *SELECTIONS FROM LOCKE'S ESSAYS ON THE HUMAN UNDERSTANDING.* With Notes by S. H. EMMENS. 2s.

193. *HANDBOOK OF FIELD FORTIFICATION,* intended for the Guidance of Officers Preparing for Promotion, and especially adapted to the requirements of Beginners. By Major W. W. KNOLLYS, F.R.G.S., 93rd Sutherland Highlanders, &c. With 163 Woodcuts. 3s.

194. *THE HOUSEHOLD AND ITS MANAGEMENT:* Being a Guide to Housekeeping, Practical Cookery, Pickling and Preserving, Household Work, Dairy Management, the Table and Dessert, Cellarage of Wines, Home-brewing and Wine-making, the Boudoir and Dressing-room, Travelling, Stable Economy, Gardening Operations, &c. By AN OLD HOUSEKEEPER. 3s. 6d.

EDUCATIONAL AND CLASSICAL SERIES.

HISTORY.

1. **England, Outlines of the History of;** more especially with reference to the Origin and Progress of the English Constitution. A Text Book for Schools and Colleges. By WILLIAM DOUGLAS HAMILTON, F.S.A., of Her Majesty's Public Record Office. Fourth Edition, revised. Maps and Woodcuts. 5s.; cloth boards, 6s.

5. **Greece, Outlines of the History of;** in connection with the Rise of the Arts and Civilization in Europe. By W. DOUGLAS HAMILTON, of University College, London, and EDWARD LEVIEN, M.A., of Balliol College, Oxford. 2s. 6d.; cloth boards, 3s. 6d.

7. **Rome, Outlines of the History of:** from the Earliest Period to the Christian Era and the Commencement of the Decline of the Empire. By EDWARD LEVIEN, of Balliol College, Oxford. Map, 2s. 6d.; cl. bds. 3s. 6d.

9. **Chronology of History, Art, Literature, and Progress,** *from* the Creation of the World to the Conclusion of the Franco-German *War. The* Continuation by W. D. HAMILTON, F.S.A., of Her Majesty's *Record Office.* 3s.; cloth boards, 3s. 6d.

50. **Dates and Events in English History,** for the use of *Candidates* in Public and Private Examinations. By the Rev. E. RAND. 1

ENGLISH LANGUAGE AND MISCELLANEOUS.

11. **Grammar of the English Tongue,** Spoken and Written. With an Introduction to the Study of Comparative Philology. By HYDE CLARKE, D.C.L. Third Edition. 1s.

11*. **Philology:** Handbook of the Comparative Philology of English, Anglo-Saxon, Frisian, Flemish or Dutch, Low or Platt Dutch, High Dutch or German, Danish, Swedish, Icelandic, Latin, Italian, French, Spanish, and Portuguese Tongues. By HYDE CLARKE, D.C.L. 1s.

12. **Dictionary of the English Language,** as Spoken and Written. Containing above 100,000 Words. By HYDE CLARKE, D.C.L. 3s. 6d.; cloth boards, 4s. 6d.; complete with the GRAMMAR, cloth bds., 5s. 6d.

48. **Composition and Punctuation,** familiarly Explained for those who have neglected the Study of Grammar. By JUSTIN BRENAN. 16th Edition. 1s.

49. **Derivative Spelling-Book:** Giving the Origin of Every Word from the Greek, Latin, Saxon, German, Teutonic, Dutch, French, Spanish, and other Languages; with their present Acceptation and Pronunciation. By J. ROWBOTHAM, F.R.A.S. Improved Edition. 1s. 6d.

51. **The Art of Extempore Speaking:** Hints for the Pulpit, the Senate, and the Bar. By M. BAUTAIN, Vicar-General and Professor at the Sorbonne. Translated from the French. Sixth Edition, carefully corrected. 2s. 6d.

52. **Mining and Quarrying,** with the Sciences connected therewith. First Book of, for Schools. By J. H. COLLINS, F.G.S., Lecturer to the Miners' Association of Cornwall and Devon. 1s.

53. **Places and Facts in Political and Physical Geography,** for Candidates in Public and Private Examinations. By the Rev. EDGAR RAND, B.A. 1s.

54. **Analytical Chemistry,** Qualitative and Quantitative, a Course of. To which is prefixed, a Brief Treatise upon Modern Chemical Nomenclature and Notation. By WM. W. PINK, Practical Chemist, &c., and GEORGE E. WEBSTER, Lecturer on Metallurgy and the Applied Sciences, Nottingham. 2s.

THE SCHOOL MANAGERS' SERIES OF READING BOOKS,

Adapted to the Requirements of the New Code. Edited by the Rev. A. R. GRANT, Rector of Hitcham, and Honorary Canon of Ely; formerly H.M. Inspector of Schools.

INTRODUCTORY PRIMER, 3d.

	s.	d.		s.	d.
FIRST STANDARD	0	6	FOURTH STANDARD	1	2
SECOND "	0	10	FIFTH "	1	6
THIRD "	1	0	SIXTH "	1	6

LESSONS FROM THE BIBLE. Part I. Old Testament. 1s.

LESSONS FROM THE BIBLE. Part II. New Testament, to which is added THE GEOGRAPHY OF THE BIBLE, for very young Children. By Rev. C. THORNTON FORSTER. 1s. 2d. *** Or the Two Parts in One Volume. 2s.

FRENCH.

24. **French Grammar.** With Complete and Concise Rules on the Genders of French Nouns. By G. L. STRAUSS, Ph.D. 1s.

25. **French-English Dictionary.** Comprising a large number of New Terms used in Engineering, Mining, on Railways, &c. By ALFRED ELWES. 1s. 6d.

26. **English-French Dictionary.** By ALFRED ELWES. 2s.

25, 26. **French Dictionary** (as above). Complete, in One Vol., 3s. cloth boards, 3s. 6d. *** Or with the GRAMMAR, cloth boards, 4s. 6d.

French, *continued.*

47. French and English Phrase Book: containing Introductory Lessons, with Translations, for the convenience of Students; several Vocabularies of Words, a Collection of suitable Phrases, and Easy Familiar Dialogues. 1s.

GERMAN.

39. German Grammar. Adapted for English Students, from Heyse's Theoretical and Practical Grammar, by Dr. G. L. STRAUSS. 1s.

40. German Reader: A Series of Extracts, carefully culled from the most approved Authors of Germany; with Notes, Philological and Explanatory. By G. L. STRAUSS, Ph.D. 1s.

41. German Triglot Dictionary. By NICHOLAS ESTERHAZY, S. A. HAMILTON. Part I. English-German-French. 1s.

42. German Triglot Dictionary. Part II. German-French-English. 1s.

43. German Triglot Dictionary. Part III. French-German-English. 1s.

41-43. German Triglot Dictionary (as above), in One Vol. 3s.; cloth boards, 4s. *** Or with the GERMAN GRAMMAR, cloth boards, 5s.

ITALIAN.

27. Italian Grammar, arranged in Twenty Lessons, with a Course of Exercises. By ALFRED ELWES. 1s.

28. Italian Triglot Dictionary, wherein the Genders of all the Italian and French Nouns are carefully noted down. By ALFRED ELWES. Vol. 1. Italian-English-French. 2s.

30. Italian Triglot Dictionary. By A. ELWES. Vol. 2. English-French-Italian. 2s.

32. Italian Triglot Dictionary. By ALFRED ELWES. Vol. 3. French-Italian-English. 2s.

28,30, 32. Italian Triglot Dictionary (as above). In One Vol., 6s.; cloth boards, 7s. 6d. *** Or with the ITALIAN GRAMMAR, cloth bds., 8s. 6d.

SPANISH AND PORTUGUESE.

34. Spanish Grammar, in a Simple and Practical Form. With a Course of Exercises. By ALFRED ELWES. 1s. 6d.

35. Spanish-English and English-Spanish Dictionary. Including a large number of Technical Terms used in Mining, Engineering, &c., with the proper Accents and the Gender of every Noun. By ALFRED ELWES. 4s.; cloth boards, 5s. *** Or with the GRAMMAR, cloth boards, 6s.

55. Portuguese Grammar, in a Simple and Practical Form. With a Course of Exercises. By ALFRED ELWES, Author of "A Spanish Grammar," &c. 1s. 6d. [*Just published.*

HEBREW.

46*. Hebrew Grammar. By Dr. BRESSLAU. 1s. 6d.

44. Hebrew and English Dictionary, Biblical and Rabbinical; containing the Hebrew and Chaldee Roots of the Old Testament Post-Rabbinical Writings. By Dr. BRESSLAU. 6s. *** Or with the GRAMMAR, 7s.

46. *English* and Hebrew Dictionary. By Dr. BRESSLAU. 3s.

44,46. *Hebrew* Dictionary (as above), in Two Vols., complete, with 46*. the GRAMMAR, cloth boards, 12s.

LATIN.

19. **Latin Grammar.** Containing the Inflections and Elementary Principles of Translation and Construction. By the Rev. THOMAS GOODWIN, M.A., Head Master of the Greenwich Proprietary School. 1s.

20. **Latin-English Dictionary.** Compiled from the best Authorities. By the Rev. THOMAS GOODWIN, M.A. 2s.

22. **English-Latin Dictionary;** together with an Appendix of French and Italian Words which have their origin from the Latin. By the Rev. THOMAS GOODWIN, M.A. 1s. 6d.

20,22. **Latin Dictionary** (as above). Complete in One Vol., 3s. 6d.; cloth boards, 4s. 6d. *** Or with the GRAMMAR, cloth boards, 5s. 6d.

LATIN CLASSICS. With Explanatory Notes in English.

1. **Latin Delectus.** Containing Extracts from Classical Authors, with Genealogical Vocabularies and Explanatory Notes, by HENRY YOUNG, lately Second Master of the Royal Grammar School, Guildford. 1s.

2. **Cæsaris Commentarii de Bello Gallico.** Notes, and a Geographical Register for the Use of Schools, by H. YOUNG. 2s.

12. **Ciceronis Oratio pro Sexto Roscio Amerino.** Edited, with an Introduction, Analysis, and Notes Explanatory and Critical, by the Rev. JAMES DAVIES, M.A. 1s.

14. **Ciceronis Cato Major, Lælius, Brutus, sive de Senectute, de Amicitia, de Claris Oratoribus Dialogi.** With Notes by W. BROWNRIGG SMITH, M.A., F.R.G.S. 2s.

3. **Cornelius Nepos.** With Notes. Intended for the Use of Schools. By H. YOUNG. 1s.

6. **Horace;** Odes, Epode, and Carmen Sæculare. Notes by H. YOUNG. 1s. 6d.

7. **Horace;** Satires, Epistles, and Ars Poetica. Notes by W. BROWNRIGG SMITH, M.A., F.R.G.S. 1s. 6d.

21. **Juvenalis Satiræ.** With Prolegomena and Notes by T. H. S. ESCOTT, B.A., Lecturer on Logic at King's College, London. 1s. 6d.

16. **Livy:** History of Rome. Notes by H. YOUNG and W. B. SMITH, M.A. Part 1. Books i., ii., 1s. 6d.

16*. ——— Part 2. Books iii., iv., v., 1s. 6d.

17. ——— Part 3 Books xxi., xxii., 1s. 6d.

8. **Sallustii Crispi Catalina et Bellum Jugurthinum.** Notes Critical and Explanatory, by W. M. DONNE, B.A., Trinity College, Cambridge. 1s. 6d.

10. **Terentii Adelphi, Hecyra, Phormio.** Edited, with Notes, Critical and Explanatory, by the Rev. JAMES DAVIES, M.A. 2s.

9. **Terentii Andria et Heautontimorumenos.** With Notes, Critical and Explanatory, by the Rev. JAMES DAVIES, M.A. 1s. 6d.

11. **Terentii Eunuchus, Comœdia.** Edited, with Notes, by the Rev. JAMES DAVIES, M.A. 1s. 6d. Or the Adelphi, Andria, and Eunuchus, 3 vols. in 1, cloth boards, 6s.

4. **Virgilii Maronis Bucolica et Georgica.** With Notes on the Bucolics by W. RUSHTON, M.A., and on the Georgics by H. YOUNG. 1s. 6d.

5. **Virgilii Maronis Æneis.** Notes, Critical and Explanatory, by H. YOUNG. 2s.

19. **Latin Verse Selections,** from Catullus, Tibullus, Propertius, and Ovid. Notes by W. B. DONNE, M.A., Trinity College, Cambridge. 2s.

20. **Latin Prose Selections,** from Varro, Columella, Vitruvius, *Seneca, Quintilian,* Florus, Velleius Paterculus, Valerius Maximus Suetonius, Apuleius, &c. Notes by W. B. DONNE, M.A. 2s.

☞ *Other Volumes are in Preparation.*

GREEK.

14. **Greek Grammar,** in accordance with the Principles and Philological Researches of the most eminent Scholars of our own day. By HANS CLAUDE HAMILTON. 1s. 6d.

15,17. **Greek Lexicon.** Containing all the Words in General Use, with their Significations, Inflections, and Doubtful Quantities. By HENRY R. HAMILTON. Vol. 1. Greek-English, 2s.; Vol. 2. English-Greek, 2s. Or the Two Vols. in One, 4s.: cloth boards, 5s.

14,15,17. **Greek Lexicon** (as above). Complete, with the GRAMMAR, in One Vol., cloth boards, 6s.

GREEK CLASSICS. With Explanatory Notes in English.

1. **Greek Delectus.** Containing Extracts from Classical Authors, with Genealogical Vocabularies and Explanatory Notes, by H. YOUNG. New Edition, with an improved and enlarged Supplementary Vocabulary, by JOHN HUTCHISON, M.A., of the High School, Glasgow. 1s.

30. **Æschylus: Prometheus Vinctus: The Prometheus Bound.** From the Text of DINDORF. Edited, with English Notes, Critical and Explanatory, by the Rev. JAMES DAVIES, M.A. 1s.

32. **Æschylus: Septem Contra Thebes: The Seven against Thebes.** From the Text of DINDORF. Edited, with English Notes, Critical and Explanatory, by the Rev. JAMES DAVIES, M.A. 1s.

40. **Aristophanes: Acharnians.** Chiefly from the Text of C. H. WEISE. With Notes, by C. S. T. TOWNSHEND, M.A. 1s. 6d.

26. **Euripides: Alcestis.** Chiefly from the Text of DINDORF. With Notes, Critical and Explanatory, by JOHN MILNER, B.A. 1s.

23. **Euripides: Hecuba and Medea.** Chiefly from the Text of DINDORF. With Notes, Critical and Explanatory, by W. BROWNRIGG SMITH, M.A., F.R.G.S. 1s. 6d.

14-17. **Herodotus,** The History of, chiefly after the Text of GAISFORD. With Preliminary Observations and Appendices, and Notes, Critical and Explanatory, by T. H. L. LEARY, M.A., D.C.L.
- Part 1. Books i., ii. (The Clio and Euterpe), 2s.
- Part 2. Books iii., iv. (The Thalia and Melpomene), 2s.
- Part 3. Books v.-vii. (The Terpsichore, Erato, and Polymnia), 2s.
- Part 4. Books viii., ix. (The Urania and Calliope) and Index, 1s. 6d.

5-12. **Homer,** The Works of. According to the Text of BAEUMLEIN. With Notes, Critical and Explanatory, drawn from the best and latest Authorities, with Preliminary Observations and Appendices, by T. H. L. LEARY, M.A., D.C.L.

THE ILIAD:
- Part 1. Books i. to vi., 1s. 6d.
- Part 2. Books vii. to xii., 1s. 6d.
- Part 3. Books xiii. to xviii., 1s. 6d.
- Part 4. Books xix. to xxiv., 1s. 6d.

THE ODYSSEY:
- Part 1. Books i. to vi., 1s. 6d.
- Part 2. Books vii. to xii., 1s. 6d.
- Part 3. Books xiii. to xviii., 1s. 6d.
- Part 4. Books xix. to xxiv., and Hymns, 2s.

4. **Lucian's Select Dialogues.** The Text carefully revised, with Grammatical and Explanatory Notes, by H. YOUNG. 1s.

13. **Plato's Dialogues: The Apology of Socrates, the Crito,** and the Phædo. From the Text of C. F. HERMANN. Edited with Notes, Critical and Explanatory, by the Rev. JAMES DAVIES, M.A. 2s.

18. **Sophocles: Œdipus Tyrannus.** Notes by H. YOUNG. 1s.

20. **Sophocles: Antigone.** From the Text of DINDORF. Notes, *Critical* and Explanatory, by the Rev. JOHN MILNER, B.A. 2s.

41. ***Thucydides:*** History of the Peloponnesian War. Notes by H. YOUNG. Book 1. 1s.

2, 3. ***Xenophon's Anabasis;*** or, The Retreat of the Ten Thousand. *Notes and a* Geographical Register, by H. YOUNG. Part 1. Books i. to iii., 1s. Part 2. Books iv. to vii., 1s.

42. ***Xenophon's Panegyric on Agesilaus.*** Notes and Introduction by LL. F. W. JEWITT. 1s. 6d.

☞ *Other Volumes are in Preparation.*